



Maximo

Work Order Details (Tr)

Org ID: MTA Site: LTRAIL

WO # 2850270 Semi Annual Switch Inspection 04-14-2017

Rotted timbers:

- 9 - 9' 1 - 10' 2 - 11' 1 - 13' 3 - 15' RH curved point worn in tip area 1 rotted machine timber Frog micro cracking/ pitted, sidewear going to #1 track 1/8" wear on risor

Alias: 083NMOWSW-1A Asset: 1262024 Serial Number: Service Address: 1155 344 West North Ave, Baltimore MD Meters: Chain Markers North, 083 Location: CMN083 Manufacturer: License: Status: OPERATING Type: FLEET

Meters: Cl: Description Unit of Measure Last Reading Date Last Reading Mileage Meter:

Cl:

Table with 4 columns: Site, Priority, Work Type, Status, Parent, Person Group, GL Account

Table with 6 columns: Job Plan, Job Desc, Supervisor, Lead, Owner, Owner Group, Service, Service Group, Classification

Table with 8 columns: Sched Start, Sched Finish, Target Start, Target Finish, Actual Start, Actual Finish, Report Date, Reported By, Requestor of



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850270 Semi Annual Switch Inspection
04-14-2017

Rotted timbers:

- 9 - 9'
- 1 - 10'
- 2 - 11'
- 1 - 13'
- 3 - 15'

RH curved point worn in tip area
 1 rotted machine timber
 Frog micro cracking/ pitted, sidewear going to #1 track
 1/8" wear on risor

Work:	Warranty Situation Present?	N	Part Failure:
	PM Num:	47325	

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	Semi Annual Switch Inspection			



Work Order Details (Tr)

Org ID: MTA
 Site: LTRAIL

WO # 2850270 - Semi Annual Switch Inspection
 04-14-2017

Rotted timbers:

- 9 - 9'
- 1 - 10'
- 2 - 11'
- 1 - 13'
- 3 - 15'

RH curved point worn in tip area
 1 rotted machine timber
 Frog micro cracking/ pitted, sidewear going to #1 track
 1/8" wear on risor

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			GLAM						N	00:00	01:00	39.44
AREPAIR			TSCHISLI						N	00:00	01:00	39.44
LEAD			WBRYAN						N	00:00	01:00	42.05
Total Actual Labor:												120.93



MEI - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850270 Semi Annual Switch Inspection
04-14-2017

Rotted timbers:

- 9 - 9'
 - 1 - 10'
 - 2 - 11'
 - 1 - 13'
 - 3 - 15'
- RH curved point worn in tip area
1 rotted machine timber
Frog micro cracking/ pitted, sidewear going to #1 track
1/8" wear on risor

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	Performed inspection according to LR MOW procedure	CLOSE						N

Date Completed

Completed By

Supervisor



Work Order Details (Tr)

Org ID: MTA
 Site: LTRAIL

WO # 2850272 Semi Annual Switch Inspection
 04-14-2017

LH curved stock rail not seated
 RH curved point micro cracking/ shelled, starting to break out
 RH curved point chipped back 16", pieces of point break off, sidewear
 Rotted timbers:
 1 - 10'
 1 - 11'
 1 - 12'
 Frog battered/ pitted/ sidewear
 Throat area battered/ pitted
 1/16" wear on risor
 2 loose bolts east guard rail

Alias: 083NMOWSW-1B	Track switch,L,8,FACING	Location: CMN083	Chain Markers North, 083	Status: OPERATING
Asset: 1254944	Year:	Manufacturer:	Type: FLEET	
Serial Number:		License:		
Service Address: 1155 344 West North Ave, Baltimore MD				

Meters: Cl: Description Unit of Measure Last Reading Date Last Reading Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start: 4/28/17	
Target Finish: 4/28/17	
Actual Start: 4/14/17	
Actual Finish: 4/14/17	
Report Date: 4/1/17	
Reported By: MTACRON	
Requestor of	

Site: LTRAIL
Priority: 1
Work Type: PM
Status: CLOSE
Parent:
Person Group: MTA527
GL Account: J05-#####-05270-#####-0901-#####-#####-####-#####-000-30-00

Job Plan: 2688
Job Desc: Semi Annual Switch Inspection
Supervisor:
Lead: JREAVES3
Owner:
Owner Group:
Service:
Service Group:
Classification: 2732

Work Order Details (Tr)

Org ID: MTA
 Site: LTRAIL

WO # 2850272 Semi Annual Switch Inspection
 04-14-2017

LH curved stock rail not seated
 RH curved point micro cracking/ shelled, starting to break out
 RH curved point chipped back 16", pieces of point break off, sidewear
 Rotted timbers:
 1 - 10'
 1 - 11'
 1 - 12'
 Frog battered/ pitted/ sidewear
 Throat area battered/ pitted
 1/16" wear on risor
 2 loose bolts east guard rail

Work:		Warranty/ Situation Present?	N	Part Failure:	
		PM Num:	47326		

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	Semi Annual Switch Inspection			



Work Order Details (Tr)

Org ID: MTA
 Site: LTRAIL

WO # 2850272 Semi Annual Switch Inspection
 04-14-2017

LH curved stock rail not seated
 RH curved point micro cracking/shelled, starting to break out
 RH curved point chipped back 16", pieces of point break off, sidewear
 Rotted timbers:
 1 - 10'
 1 - 11'
 1 - 12'
 Frog battered/ pitted/ sidewear
 Throat area battered/ pitted
 1/16" wear on risor
 2 loose bolts east guard rail

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			GLAM						N	00:00	01:00	39.44
AREPAIR			TSCHISLI						N	00:00	01:00	39.44
LEAD			WBRYAN						N	00:00	01:00	42.05
Total Actual Labor:												120.93



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850272 Semi Annual Switch Inspection
04-14-2017

LH curved stock rail not seated
RH curved point micro cracking/ shelled, starting to break out
RH curved point chipped back 16", pieces of point break off, sidewear
Rotted timbers:
1 - 10'
1 - 11'
1 - 12'
Frog battered/ pitted/ sidewear
Throat area battered/ pitted
1/16" wear on risor
2 loose bolts east guard rail

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	Performed inspection according to LR MOW procedure	CLOSE						N

Date Completed

Completed By

Supervisor



Work Order Details (Tr)

Org ID: MTA
 Site: LTRAIL

WO # 2850272 Semi Annual Switch Inspection
 04-14-2017

LH curved stock rail not seated
 RH curved point micro cracking/shelled, starting to break out
 RH curved point chipped back 16", pieces of point break off, sidewear
 Rotted timbers:
 1 - 10'
 1 - 11'
 1 - 12'
 Frog battered/ pitted/ sidewear
 Throat area battered/ pitted
 1/16" wear on risor
 2 loose bolts east guard rail

Alias: 083NMOWSW-1B	Track switch, L, 8, FACING	Location: CMN083	Chain Markers North, 083	Status: OPERATING
Asset: 1254944	Year:	Manufacturer:	Type: FLEET	
Serial Number:		License:		
Service Address: 1155 344 West North Ave, Baltimore MD				

Meters: Cl: Description Unit of Measure Last Reading Date Last Reading Mileage Meter:

Sched Start:	Site: LTRAIL	Job Plan: 2688
Sched Finish:	Priority: 1	Job Desc: Semi Annual Switch Inspection
Target Start: 4/28/17	Work Type: PM	Supervisor:
Target Finish: 4/28/17	Status: CLOSE	Lead: JREAVES3
Actual Start: 4/14/17	Parent:	Owner:
Actual Finish: 4/14/17	Person Group: MTA527	Owner Group:
Report Date: 4/11/17	GL Account: J05-#####-05270-#####-0901-#####-	Service:
Reported By: MTACRON	#####-#####-#####-	Service Group:
Requestor of	#####-000-30-00	Classification: 2732



MD - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850272 Semi Annual Switch Inspection
04-14-2017

- LH curved stock rail not seated
- RH curved point micro cracking/ shelled, starting to break out
- RH curved point chipped back 16", pieces of point break off, sidewear
- Rotted timbers:
 - 1 - 10'
 - 1 - 11'
 - 1 - 12'
- Frog battered/ pitted/ sidewear
- Throat area battered/ pitted
- 1/16" wear on risor
- 2 loose bolts east guard rail

Work:		Warranty Situation Present?	N	Part Failure:	
		PM Num:	47326		

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	Semi Annual Switch Inspection			



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850272 Semi Annual Switch Inspection
04-14-2017

LH curved stock rail not seated
RH curved point micro cracking/ shelled, starting to break out
RH curved point chipped back 16", pieces of point break off, sidewear
Rotted timbers:
1 - 10'
1 - 11'
1 - 12'
Frog battered/ pitted/ sidewear
Throat area battered/ pitted
1/16" wear on risor
2 loose bolts east guard rail

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			GLAM						N		00:00	01:00	39.44
AREPAIR			TSCHISLI						N		00:00	01:00	39.44
LEAD			WBRYAN						N		00:00	01:00	42.05
Total Actual Labor:											120.93		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850272 Semi Annual Switch Inspection
04-14-2017

LH curved stock rail not seated
RH curved point micro cracking/ shelled, starting to break out
RH curved point chipped back 16", pieces of point break off, sidewear
Rotted timbers:
1 - 10'
1 - 11'
1 - 12'
Frog battered/ pitted/ sidewear
Throat area battered/ pitted
1/16" wear on risor
2 loose bolts east guard rail

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	Performed inspection according to LR MOW procedure	CLOSE						N

Date Completed

Completed By

Supervisor



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850270
Semi Annual Switch Inspection
04-14-2017

Rotted timbers:

- 9 - 9'
- 1 - 10'
- 2 - 11'
- 1 - 13'
- 3 - 15'
- RH curved point worn in tip area
- 1 rotted machine timber
- Frog micro cracking/ pitted, sidewear going to #1 track
- 1/8" wear on risor

Alias: 083NMOWSW-1A	Track switch,equilateral, 5,FACING, TRAILING	Location: CMN083	Chain Markers North, 083	Status: OPERATING
Asset: 1262024	Year:	Manufacturer:	Type: FLEET	
Serial Number:		License:		
Service Address: 1155 344 West North Ave, Baltimore MD				

Meters: CI: Description Unit of Measure Last Reading Date Last Reading Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start: 4/28/17	
Target Finish: 4/28/17	
Actual Start: 4/14/17	
Actual Finish: 4/14/17	
Report Date: 4/1/17	
Reported By: MTACRON	
Requestor of	

Site: LTRAIL
Priority: 1
Work Type: PM
Status: CLOSE
Parent:
Person Group: MTA527
GL Account: J05-#####-05270-#####-0901-#####-#####-#####-000-30-00

Job Plan: 2688
Job Desc: Semi Annual Switch Inspection
Supervisor:
Lead: JREAVES3
Owner:
Owner Group:
Service:
Service Group:
Classification: 2732



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850270 Semi Annual Switch Inspection
04-14-2017

Rotted timbers:

- 9 - 9'
- 1 - 10'
- 2 - 11'
- 1 - 13'
- 3 - 15'

RH curved point worn in tip area
 1 rotted machine timber
 Frog micro cracking/ pitted, sidewear going to #1 track
 1/8" wear on risor

Work:		Warranty Situation Present?	N	Part Failure:	
		PM Num:	47325		

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	Semi Annual Switch Inspection			



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850270 Semi Annual Switch Inspection
04-14-2017

Rotted timbers:

- 9 - 9'
- 1 - 10'
- 2 - 11'
- 1 - 13'
- 3 - 15'

RH curved point worn in tip area
 1 rotted machine timber
 Frog micro cracking/ pitted, sidewear going to #1 track
 1/8" wear on risor

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR		GLAM							N		00:00	01:00	39.44
AREPAIR		TSCHISLI							N		00:00	01:00	39.44
LEAD		WBRYAN							N		00:00	01:00	42.05
Total Actual Labor:											120.93		



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2850270 Semi Annual Switch Inspection
04-14-2017

Rotted timbers:

- 9 - 9'
- 1 - 10'
- 2 - 11'
- 1 - 13'
- 3 - 15'
- RH curved point worn in tip area
- 1 rotted machine timber
- Frog micro cracking/ pitted, sidewear going to #1 track
- 1/8" wear on risor

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	Performed inspection according to LR MOW procedure	CLOSE						N

Date Completed

Completed By

Supervisor