TRACK INSPECTION REPORTING FORM

Name Woodrow Greenwood Date 08/12/2013 Page 1 of 1

(Please Print)

Watchman Miller Brandon

Inspected From Huntvalley To Lutherville W.O Number 1179486

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	No new defects noted in area.

Were Switch In the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO_____

Reason for special Inspection ? _____

Woodrow Greenwood

Track Inspector Signature

Supervisory Cretification M. Boyle

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1179486	TEAM ONE - SECT 1: HV/LU - CM 902N TO	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type *	PM	
Location	CHAIN_MARK	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group *	MTA527		Maintenance Alert?		

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	210.32
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	08/09/13 04:09:49 PM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-#####-052		

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task *	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 1 of 1 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	WGREENWOOD	✓	08/12/13	07:00:00 A	03:00:00 F	8:00	26.29	N	N/A

Labor

Task		Start Date	08/12/13	Warranty?	N
Labor	WGREENWOOD	Start Time	07:00:00 A	Qualification Met?	N/A
Regular Hours	8:00	End Date	08/12/13	Approved?	✓
Component		End Time	03:00:00 F	Timer Status	
Position		Rate	26.29	Craft	AREPAIR
Reason for Repair		Line Cost	210.32	Skill Level	
Work Accomplished		Type	WORK		
Part Failure					
Memo					

Outside Labor		Premium Pay		Charge Information	
Outside?		Premium Pay Code		GL Debit Account	J05-#####-052
Vendor		Premium Pay Hours		GL Credit Account	
Contract		Premium Pay Rate		Location	CHAIN_MARK
Revision		Premium Rate Type		Asset	
				Alias	
				Recorded as Received	

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

R Miller

Name W Greenwood Date 08/13/2013 Page 1 of 1

(Please Print)

Watchman Brandon W.O Number 1180688

Inspected From Cultural Center To

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	Sink hole at cultural center Station is slightly out of surface from the sink hole problem.

Were Switch in the area of Inspected ***Yes*** _____ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes ✓ NO ___

SPECIAL INSPECTION Yes ____ NO ✓

Reason for special Inspection ? _____

Weedrow Greenwood

Track Inspector Signature

Supervisory Cretification _____

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1180688	TEAM ONE - SECT 3: CS/CY/PENN - CM 23	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type *	PM	
Location	CHAIN_MARK(	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group *	MTA527		Maintenance Alert?		

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	210.32
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	08/11/13 03:32:25 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-#####-052		

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 1 of 1 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	WGREENWOOD	✓	08/13/13	07:00:00 A	03:00:00 P	8:00	26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Line G LAM (Please Print) Date 8/15/13 Page 1 of 1

Watchman W BRYANT W O Number 1179476

Inspected From HV To Lutherville

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	NO NEW Defects Noted IN AREA

Were Switch In the area of Inspected ***Yes*** ✓ ***NO***

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes NO ✓

SPECIAL INSPECTION Yes NO ✓

Reason for special Inspection ?

Track Inspector Signature Thomas J Schul

Supervisory Cretification

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1179476	TEAM TWO - SECT 1: HV/LU - CM 902N TO	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type *	PM	
Location	CHAIN_MARKI	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group *	MTA527		Maintenance Alert?		

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	08/09/13 04:09:16 PM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-#####-052		

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

ıbor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	WBRYANT	✓	08/15/13	05:00:00 A	01:00:00 F	8:00	26.29	N	N/A
	GLAM	✓	08/15/13	05:00:00 A	01:00:00 F	8:00	26.29	N	N/A

Labor

Task		Start Date	08/15/13	Warranty?	N
Labor	WBRYANT	Start Time	05:00:00 A	Qualification Met?	N/A
Regular Hours	8:00	End Date	08/15/13	Approved?	✓
Component		End Time	01:00:00 F	Timer Status	
Position		Rate	26.29	Craft	AREPAIR
Reason for Repair		Line Cost	210.32	Skill Level	
Work Accomplished		Type	WORK		
Part Failure					
Memo					

Outside Labor		Premium Pay		Charge Information	
Outside?		Premium Pay Code		GL Debit Account	J05-#####-052
Vendor		Premium Pay Hours		GL Credit Account	
Contract		Premium Pay Rate		Location	CHAIN_MARKI
Revision		Premium Rate Type		Asset	
				Alias	
				Recorded as Received	

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

J Brockmeyer
Line W Greenwood Date 08/15/2013 Page 1 of 1
(Please Print)
Watchman J Small W.O Number 1179483
Inspected From Lutherville To Coldspring

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	No new defects noted in area.

Were Switch in the area of Inspected ***Yes*** ✓ ***NO***

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?
Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO_____

Reason for special Inspection ? _____

Woodrow Greenwood
Track Inspector Signature

Supervisory Cretification M. Bayles

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1179483	TEAM ONE - SECT 2: LU/CS - CM 586N TO	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type*	PM	
Location	CHAIN_MARK	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group*	MTA527		Maintenance Alert?		

Work Details

Component		Total Planned Cost	0.00	
Position		Total Actual Cost	210.32	
Reason for Repair		Repair Limit Amount		
Work Accomplished		Reported By	MTACRON	
Part Failure		Reported Date	08/09/13 04:09:40 PM	
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-#####-052			

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 1 of 1 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	WGREENWOOD	✓	08/15/13	07:00:00 A	03:00:00 P	8:00	26.29	N	N/A

Labor

Task		Start Date	08/15/13	Warranty?	N
Labor	WGREENWOOD	Start Time	07:00:00 A	Qualification Met?	N/A
Regular Hours	8:00	End Date	08/15/13	Approved?	✓
Component		End Time	03:00:00 P	Timer Status	
Position		Rate	26.29	Craft	AREPAIR
Reason for Repair		Line Cost	210.32	Skill Level	
Work Accomplished		Type	WORK		
Part Failure					
Memo					

Outside Labor		Premium Pay		Charge Information	
Outside?		Premium Pay Code		GL Debit Account	J05-#####-052
Vendor		Premium Pay Hours		GL Credit Account	
Contract		Premium Pay Rate		Location	CHAIN_MARK
Revision		Premium Rate Type		Asset	
				Alias	
				Recorded as Received	

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name G. LAM (Please Print) Date 8/16/2013 Page 2 of 2

Watchman BRYANT W.O Number 1179347

Inspected From M/AVE YD To

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	No new Defects noted in YD

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

Track Inspector Signature G Lam

Supervisory Cretification [signature]

TRACK INSPECTION REPORTING FORM

Name G. LAM (Please Print) Date 8/17/2013 Page 1 of 1

Watchman W BRYANT W.O Number 1179423

Inspected From LINTHICUM To CROMWELL + BWI

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	NO NEW Defects NOTED IN AREA

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

G Lam

Track Inspector Signature

Supervisory Cretification M Boyle

Work Order Tracking (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Work Order Plans Actuals Related Records Safety Plan Log Failure Reporting Specifications

Work Order 1179423 TEAM TWO - SECT 5: LINT/CROM - CM 355 Site LTRAIL Status COMP
Asset Alias

Children of Work Order 1179423 Filter

Tasks for Work Order 1179423 Filter 1 - 2 of 2 Downlo

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N	NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N	NONE	COMP

N

Labor Materials Services Tools Repair Orders

Labor Filter 1 - 3 of 3 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER	☑	08/17/13	06:00:00 A	02:00:00 F	8:00	26.29	N	N/A
	WBRYANT	☑	08/17/13	06:00:00 A	02:00:00 F	8:00	26.29	N	N/A
	GLAM	☑	08/17/13	06:00:00 A	02:00:00 F	8:00	26.29	N	N/A

Select Labor Select Planned Labor New