Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2629995 (2RA-JH) METRO MOW WEEKLY TRACK INSPECTION WA

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 10/21/16 04:18:47 AM

Reported By: MTACRON

Phone:

Reported Date: 10/21/16 04:18:47 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter 0 - 0 of 0

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TME2 (TRACK METRO EAST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013793 (HOLD)	MOW-B00	2	BOTH	MOW-080	CM	MOW-B01	0	30	0	50	0	7/21/15
2 RAJH Water/Trash Condition 030-050+00E	TUNNEL			TRASH AND DEBRIS		TUNNEL DRAIN						
2083378 (INPRG)	MOW-R00	2	BOTH	MOW-022	CM	MOW-R01	0	46	0	50	0	9/12/15
2 RAJH Clips Broken/Plates & Rail Deteriorated 046E - 050E	RAIL			DETERIORATING		RUNNING RAIL						
2043307 (MONITOR)	MOW-R00	3	SOUTH	MOW-069	CM	MOW-R01	0	56	0	56	0	8/12/15
2 RAJH Rail Sideworn (27-32 Deg) 056E-064E	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
1673460 (APPR)	MOW-R00	1	THIRD RAIL	MOW-046	CM	MOW-C02	0	68	10	68	10	10/15/14
2 RAJH Coverbrd Missng 20' JH 1A 068+10E	RAIL			MISSING		COVERBOARD						

Number of Records: 4

Oct 24, 2016 12:26 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMEX (TRACK METRO EAST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2552817 (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	65	0	65	0	8/25/16
1 JHRA diamond frog mushroomed over 65+00	RAIL			BATTERED		FROG						
2493058 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	67	0	67	0	7/21/16
1 JHRA frog point 1b pitted/battered	RAIL			BATTERED		FROG						
2449051 (APPR)	MOW-R00	3	BOTH	MOW-013	CM	MOW-T06	0	68	40	68	40	6/15/16
2 RAJH frog point chipped 3A	RAIL			CHIPPED / PITTED		FROG						
2449070 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	69	0	69	0	6/15/16
2 RAJH frog point battered 1A	RAIL			BATTERED		FROG						
2043020 (MONITOR)	MOW-R00	2	RIGHT	MOW-069	CM	MOW-T01	0	70	0	70	0	8/12/15
2 RAJH RH Stock Rail Side Worn (25 Deg) JH 1A	RAIL			SIDE WEAR (RAIL)		STOCK RAIL						
2059899 (COMP)	MOW-M00	2	BOTH	MOW-016	CM	MOW-T09	0	70	0	70	0	8/26/15
1 JHRA Frog Riser Cracked JH 3B	TRACK MISCELLANEOUS			CRACKED / SPLIT		FROG GUARD						
2493055 (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	70	6	70	6	7/21/16
1 JHRA JH 3B frog point battered	RAIL			BATTERED		FROG						
2014923 (APPR)	MOW-M00	1	LEFT	MOW-044	CM	MOW-T12	0	70	20	70	30	7/22/15
2 RAJH LH Switch Point Fastener Blocks Loose (4) JH 1A	TRACK MISCELLANEOUS			LOOSE / SLACK		SPACER BLOCK BOLT						
2573519 (WAPPR)	MOW-M00	2	WEST		CM	MOW-T06	0	75	0	75	0	9/8/16
1 JHRA blocks missing wing of frog	TRACK MISCELLANEOUS					FROG						
2573518 (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-R09	0	79	0	79	0	9/8/16
1 JHRA brace plate loose 1B 079	TRACK MISCELLANEOUS			LOOSE / SLACK		RESTRAINING RAIL BRACE						

Number of Records: 10

Oct 24, 2016 12:[illegible] AM
created by yv[illegible]
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2541444 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-Q00	0	10	0	10	0	8/16/16
2 RAJH trah 010+0	RIGHT OF WAY			TRASH AND DEBRIS		RIGHT OF WAY						
2541451 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-Q00	0	32	0	32	0	8/16/16
2 RAJH trash 32+0	RIGHT OF WAY			TRASH AND DEBRIS		RIGHT OF WAY						
2218384 (APPR)	MOW-B00	2	SOUTH	MOW-042	CM	MOW-L02	0	34	0	34	0	12/17/15
2 RAJH Water Leak (S) 034+00W	TUNNEL			LEAKING		TUNNEL LEAK						
2541446 (APPR)	MOW-L00	3	BOTH	MOW-042	CM	MOW-L02	0	34	0	34	0	8/16/16
2 JHRA water leak 34+00	LEAKS			LEAKING		TUNNEL LEAK						
2571332 (APPR)	MOW-L00	4	SOUTH	MOW-042	CM	MOW-R01	0	34	0	34	0	9/7/16
2 RAJH water leak on rail 034	LEAKS			LEAKING		RUNNING RAIL						
2597312 (APPR)	MOW-B00	4	SOUTH	MOW-017	CM	MOW-B00	0	46	0	46	0	9/28/16
2 RAJH DOOR OFF HINDGES 046	TUNNEL			DAMAGED HARDWARE		TUNNEL						
2571330 (APPR)	MOW-M00	2	BOTH	MOW-084	CM	MOW-M02	0	54	0	56	0	9/7/16
2 RAJH light out 054-056	TRACK MISCELLANEOUS			WATER CONDITIONS		ETS BOX / LIGHT						
2202890 (APPR)	MOW-M00	3	BOTH	MOW-018	CM	MOW-X17	0	67	0	68	60	12/5/15
2 RAJH Concrete Deteriorating 068+60-067W	TRACK MISCELLANEOUS			DEFECTIVE - NO LONGER FUNCTIONING		CONCRETE TIE RAIL SEAT PAD						
2015095 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C02	0	67	10	68	5	7/22/15
2 RAJH Coverboard Missing/Bracket Damaged 068+05-067+10	TRACK MISCELLANEOUS			MISSING		COVERBOARD						
2013849 (APPR)	MOW-L00	1	BOTH	MOW-004	CM	MOW-B00	0	72	10	72	10	7/21/15
2 RAJH Drain Blocked 072+10W	LEAKS			BLOCKAGE		TUNNEL						
2060168 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	79	10	79	10	8/26/15
2 RAJH Coverboard Sagging/Burnt/ Arcing 079+10	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						

Oct 24, 2016 12:26 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013854 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-C02	0	80	20	80	20	7/21/15
2 RAJH Coverboard Sagging 080+20W	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2060167 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	81	50	81	50	8/26/15
2 RAJH Coverboard Sagging 081+50	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2013808 (HOLD)	MOW-B00	2	BOTH	MOW-004	CM	MOW-B01	0	89	80	90	20	7/21/15
2RAJH Trough Blockage 089+80W-090+20W	TUNNEL			BLOCKAGE		TUNNEL DRAIN						
2025642 (MONITOR)	MOW-R00	2	NORTH	MOW-013	CM	MOW-R01	0	90	0	100	0	7/31/15
2 RAJH Running Rail Head Chipped/ Pitted/Gouged 100-090	RAIL			CHIPPED / PITTED		RUNNING RAIL						
2013887 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	93	0	93	0	7/21/15
2 RAJH Coverboard Sagging 093+00	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2202882 (APPR)	MOW-X00	2	NORTH	MOW-016	CM	MOW-X17	0	96	10	96	10	12/5/15
2 RAJH Two Block Tie Broken (N) 096+10	TIES			CRACKED / SPLIT		CONCRETE TIE RAIL SEAT PAD						
2202878 (APPR)	MOW-G00	2	BOTH	MOW-009	CM	MOW-X08	0	101	90	101	90	12/5/15
2 RAJH LB Foster Pads Concrete Base Broken 101+90	GROUT PADS			BROKEN/SHEARED		CONCRETE G10 PAD						
2015099 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	102	70	102	70	7/22/15
2 RAJH Coverboard Bracket Broken/Hardware Missing 102+70	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2292436 (APPR)	MOW-B00	1	PLATFORM	MOW-042	CM	MOW-B00	0	107	80	107	80	2/18/16
2 RA-JH west end of upton water leak track 2	TUNNEL			LEAKING		TUNNEL						
2013856 (APPR)	MOW-L00	1	BOTH	MOW-004	CM	MOW-B01	0	110	0	108	0	7/21/15
2 RAJH Drain Blocked 110-108	LEAKS			BLOCKAGE		TUNNEL DRAIN						

Oct 24, 2016 12:[illegible] AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013890 (APPR)	MOW-R00	1	BOTH	MOW-022	CM	MOW-R01	0	156	40	156	40	7/21/15
2 RAJH Running Rail Deteriorated 156+40	RAIL			DETERIORATING		RUNNING RAIL						
2013895 (APPR)	MOW-M00	1	THIRD RAIL	MOW-084	CM	MOW-C01	0	163	20	163	20	7/21/15
2 RAJH Insulator Cup Smoking (Wet) 163+20	TRACK MISCELLANEOUS			WATER CONDITIONS		INSULATOR						
2060123 (MONITOR)	MOW-R00	3	NORTH	MOW-069	CM	MOW-R01	0	165	0	170	0	8/26/15
2 RAJH Rail Side Worn (30 Deg) / Top Worn (1/4") 170-165	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2060139 (MONITOR)	MOW-R00	3	NORTH	MOW-014	CM	MOW-R01	0	165	65	165	80	8/26/15
2 RAJH Rail Deteriorated / Corroded 165+80165+65	RAIL			CORRODED		RUNNING RAIL						
2571328 (APPR)	MOW-R00	2	NORTH	MOW-076	CM	MOW-R01	0	165	70	165	70	9/7/16
2 RAJH head wear 165+20	RAIL			TOP WEAR (RAIL)		RUNNING RAIL						
2268178 (APPR)	MOW-F00	1	SOUTH	MOW-014	CM	MOW-F05	0	165	80	165	80	1/30/16
2 RAJH Pandrol Clips Broken (3 Consec) 165+80	FASTENERS			CORRODED		CLIP						
2619185 (APPR)	MOW-M00	2	BOTH	MOW-046	CM	MOW-F05	0	165	80	165	80	10/13/16
2 RAJH pandrol clips missing 165	TRACK MISCELLANEOUS			MISSING		CLIP						
2433283 (APPR)	MOW-R00		NORTH	MOW-014	CM	MOW-R01	0	165	90	165	90	6/1/16
rail corroded	RAIL			CORRODED		RUNNING RAIL						
2541458 (APPR)	MOW-M00	3	BOTH	MOW-046	CM	MOW-F05	0	173	0	173	0	8/16/16
2 JHRA clips off 173+0	TRACK MISCELLANEOUS			MISSING		CLIP						
2198166 (INPRG)	MOW-R00	3	BOTH		CM	MOW	0	181	48	181	48	12/2/15
2 RAJH warp (-2.00 - 8ft) at cm#181+48 (Holland Report) URGENT	RAIL					MAINTENANCE OF WAY						

Oct 24, 2016 12:26 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2554632 (APPR)	MOW-M00	3	THIRD RAIL	MOW-017	PM	MOW-C03	0	184	0	184	0	8/26/16
2 RAJH brocken bracket 184	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2597297 (APPR)	MOW-F00	4	BOTH	MOW-014	CM	MOW-F05	0	193	0	193	0	9/28/16
2 RAJH broken and corroded left hand clips 193	FASTENERS			CORRODED		CLIP						
2088344 (APPR)	MOW-M00	2	SOUTH	MOW-016	CM	MOW-B03	0	194	20	194	20	9/16/15
2 RAJH Tunnel Wall Section Broken 194+20	TRACK MISCELLANEOUS			CRACKED / SPLIT		TUNNEL STRUCTURE						
2013861 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-C02	0	208	50	208	50	7/21/15
2 RAJH Coverboard Sagging 208+50	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2571765 (APPR)	MOW-R00	3	NORTH	MOW-069	CM	MOW-R01	0	220	0	226	0	9/7/16
2 RAJH side worn rail 220-226	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2063554 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	221	35	221	35	8/29/15
2 RAJH 3rd Rail Metal Bracket Broken/Bent 221+35	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2062903 (APPR)	MOW-C00	2	THIRD RAIL	MOW-002	CM	MOW-C06	0	221	45	221	45	8/28/15
2 RAJH 3rd Rail End Approach Joint Burnt/Arcing 221+45	CONTACT RAIL			ARCING		END APPROACH						
2626213 (APPR)	MOW-R00	2	BOTH	MOW-025	CM	MOW-R01	0	221	80	221	80	10/18/16
2 RAJH engine burns with crackes 221+80	RAIL			ENGINE BURN FRACTURE (EBF)		RUNNING RAIL						
2554631 (APPR)	MOW-C00	2	THIRD RAIL	MOW-008	CM	MOW-B08	0	224	0	224	0	8/26/16
2 RAJH expansion joint needs grinded 224	CONTACT RAIL			BROKEN COLLECTOR SHOES		THIRD RAIL EXPANSION JOINT						
2043032 (APPR)	MOW-G00	3	BOTH	MOW-022	CM	MOW-G00	0	224	20	224	10	8/12/15
2 RAJH Direct Fixation Pad Deteriorating 224+20-224+10	GROUT PADS			DETERIORATING		GROUT PADS						

Oct 24, 2016 12 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departmer f Transportation
Maryland Transit dministration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2141689 (APPR)	MOW-M00	2	BOTH	MOW-081	CM	MOW-Q03	0	233	90	233	90	10/23/15
2 RAJH Vegetation Overgrowth Fouling ML1/2 233+90W	TRACK MISCELLANEOUS			VEGETATION (EXCESSIVE GROWTH)		ROW VEGETATION						
2554630 (APPR)	MOW-R00	2	SOUTH	MOW-025	CM	MOW-R01	0	238	0	238	0	8/26/16
2 RAJH engine burn on rail 238	RAIL			ENGINE BURN FRACTURE (EBF)		RUNNING RAIL						
2014946 (APPR)	MOW-R00	2	NORTH	MOW-069	CM	MOW-R01	0	241	0	241	0	7/22/15
2 RAJH Rail Side Worn (N) (25 Deg) 241+00	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2013860 (APPR)	MOW-Q00	1	NORTH	MOW-081	CM	MOW-Q03	0	248	0	248	0	7/21/15
2 RAJH Vegatation Obstructing CM Sign 248	RIGHT OF WAY			VEGETATION (EXCESSIVE GROWTH)		ROW VEGETATION						
2041956 (MONITOR)	MOW-R00	2	SOUTH	MOW-069	CM	MOW-R01	0	260	0	266	0	8/11/15
2 RAJH Rail Side Worn 260 - 266	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2597289 (APPR)	MOW-R00	3	SOUTH	MOW-069	CM	MOW-R00	0	262	0	266	0	9/28/16
2 RAJH CURB WEAR 262+00 266+00	RAIL			SIDE WEAR (RAIL)		RAIL						
2571760 (APPR)	MOW-Q00	3	BOTH	MOW-080	CM	MOW-Q00	0	266	0	270	0	9/7/16
2 RAJH trash in track 266-270	RIGHT OF WAY			TRASH AND DEBRIS		RIGHT OF WAY						
2014146 (COMP)	MOW-F00	2	BOTH	MOW-046	CM	MOW-F05	0	268	0	236	0	7/21/15
2 RAJH Pandrol Clips Missing 268 - 236+00	FASTENERS			MISSING		CLIP						
2013781 (HOLD)	MOW-M00	2	NORTH	MOW-046	CM	MOW-M09	0	272	10	272	10	7/21/15
2 RAJH Crosswalk Board Missing 272+10	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						
2043011 (MONITOR)	MOW-R00	2	SOUTH	MOW-069	CM	MOW-R01	0	278	25	278	28	8/12/15
2 RAJH Rail Side Worn (S) (25 Deg) 278+25	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013863 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-C02	0	307	50	307	50	7/21/15
2 RAJH Coverboard Sagging 307+50	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2017725 (APPR)	MOW-M00	1	SOUTH	MOW-081	CM	MOW-Q03	0	328	0	328	5	7/24/15
2 RAJH Vegetation / Sight Restriction 328 - 328+05	TRACK MISCELLANEOUS			VEGETATION (EXCESSIVE GROWTH)		ROW VEGETATION						

Number of Records: 53

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2053299 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA RH Switch Point Chipped / Pitted CC 3B	RAIL			CHIPPED / PITTED		SWITCH POINT						
2053301 (MONITOR)	MOW-R00	2	LEFT	MOW-069	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA LH Switch Point Chipped / Pitted CC 3B	RAIL			SIDE WEAR (RAIL)		SWITCH POINT						
2017699 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	7	50	7	50	7/24/15
1 JHRA 3rd Rail Side Approach Hardware Missing CC 1B 007+50	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
2573520 (APPR)	MOW-M00	2	BOTH	MOW-018	CM	MOW-M02	0	8	0	8	0	9/9/16
1 JHRA lights out charles interlocking 008	TRACK MISCELLANEOUS			DEFECTIVE - NO LONGER FUNCTIONING		ETS BOX / LIGHT						
2571333 (APPR)	MOW-M00	3	BOTH	MOW-080	CM	MOW-B01	0	10	0	14	0	9/7/16
2 RAJH trash 10-14	TRACK MISCELLANEOUS			TRASH AND DEBRIS		TUNNEL DRAIN						
2493075 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-B01	0	66	0	70	0	7/21/16
2 RAJH trash build up 070-066	RIGHT OF WAY			TRASH AND DEBRIS		TUNNEL DRAIN						
2030698 (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R08	0	66	80	66	80	8/3/15
1 JHRA IJ Battered BH-3B 066+80W	RAIL					INSULATED JOINT						
2014043 (HOLD)	MOW-X00	2	BOTH	MOW-062	CM	MOW-X00	0	67	70	68	50	7/21/15
2 RAJH Ties PumpIng BH 068+50 - 067+70W	TIES			PUMPING		TIES						
2449048 (APPR)	MOW-M00	3	THIRD RAIL	MOW-017	CM	MOW-C03	0	68	70	68	70	6/15/16
2 RAJH switch point battered	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2013791 (HOLD)	MOW-M00	2	SOUTH	MOW-046	CM	MOW-M09	0	69	0	69	0	7/21/15
2 RAJH Crosswalk Missing BH 3A 069+00W	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						

Oct 24, 2016 12:26 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030709 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/3/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						
2549819 (APPR)	MOW-R00	2	BOTH	MOW-003	PM	MOW-T06	0	230	0	230	0	8/23/16
1 JHRA frog 1B needs grinding 230	RAIL			BATTERED		FROG						

Number of Records: 12

MTA Maryland

Maryland Departm of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

Inspection Completed? [✓] Yes [ ] No If No Why? _____

Item	Exception Chain Marker No. From	Exception Chain Marker No. To	Track No.	Position N/S	Switch No.	Codes Comp.	Codes Defect	Priority	Alias
1									
2		NO	NEW		DEFECT				
3									
4									
5									
6									
7									
8									

Notes: _____

Track Walker: ALVIN JEFFERSON (Print) — Alvin Jefferson (Sign) — Date: 10-25-16

(Print) — (Sign) — Date: _____

(Print) — (Sign) — Date: _____

Watchman: Curtis Chandler (Print) — C J Chandler (Sign) — Date: 10-25-16

Track Inspection Supervisor: (Print) — (Sign) — Date: _____

Oct 24, 2016 12:26 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2630013 (1JH-RA) METRO MOW WEEKLY TRACK INSPECTION WA

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 10/21/16 04:19:04 AM

Reported By: MTACRON

Phone:

Reported Date: 10/21/16 04:19:04 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cis Filter 0 - 0 of 0

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TME1 (TRACK METRO EAST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2469281 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	7	0	7	0	7/1/16
1 JHRA frog point battered 1A	RAIL			BATTERED		FROG						
2015100 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C02	0	36	65	36	65	7/22/15
1 JHRA Coverboard Broken / Bracket Missing 036+65E	TRACK MISCELLANEOUS			MISSING		COVERBOARD						
2033296 (MONITOR)	MOW-R00	2	SOUTH	MOW-013	CM	MOW-T02	0	67	60	67	60	8/5/15
1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	RAIL			CHIPPED / PITTED		LEAD OR CLOSURE RAIL						
2013865 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-R08	0	67	70	67	70	7/21/15
1 JHRA Restraining Rail IJ Bolts Loose 067+70E	TRACK MISCELLANEOUS			LOOSE / SLACK		INSULATED JOINT						

Number of Records: 4

Oct 24, 2016 12:23 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMEX (TRACK METRO EAST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2552817 (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	65	0	65	0	8/25/16
1 JHRA diamond frog mushroomed over 65+00	RAIL			BATTERED		FROG						
2493058 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	67	0	67	0	7/21/16
1 JHRA frog point 1b pitted/battered	RAIL			BATTERED		FROG						
2449051 (APPR)	MOW-R00	3	BOTH	MOW-013	CM	MOW-T06	0	68	40	68	40	6/15/16
2 RAJH frog point chipped 3A	RAIL			CHIPPED / PITTED		FROG						
2449070 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	69	0	69	0	6/15/16
2 RAJH frog point battered 1A	RAIL			BATTERED		FROG						
2043020 (MONITOR)	MOW-R00	2	RIGHT	MOW-069	CM	MOW-T01	0	70	0	70	0	8/12/15
2 RAJH RH Stock Rail Side Worn (25 Deg) JH 1A	RAIL			SIDE WEAR (RAIL)		STOCK RAIL						
2059899 (COMP)	MOW-M00	2	BOTH	MOW-016	CM	MOW-T09	0	70	0	70	0	8/26/15
1 JHRA Frog Riser Cracked JH 3B	TRACK MISCELLANEOUS			CRACKED / SPLIT		FROG GUARD						
2493055 (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	70	6	70	6	7/21/16
1 JHRA JH 3B frog point battered	RAIL			BATTERED		FROG						
2014923 (APPR)	MOW-M00	1	LEFT	MOW-044	CM	MOW-T12	0	70	20	70	30	7/22/15
2 RAJH LH Switch Point Fastener Blocks Loose (4) JH 1A	TRACK MISCELLANEOUS			LOOSE / SLACK		SPACER BLOCK BOLT						
2573519 (WAPPR)	MOW-M00	2	WEST		CM	MOW-T06	0	75	0	75	0	9/8/16
1 JHRA blocks missing wing of frog	TRACK MISCELLANEOUS					FROG						
2573518 (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-R09	0	79	0	79	0	9/8/16
1 JHRA brace plate loose 1B 079	TRACK MISCELLANEOUS			LOOSE / SLACK		RESTRAINING RAIL BRACE						

Number of Records: 10

Oct 24, 2016 12:[illegible] AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2043305 (INPRG)	MOW-X00	2	BOTH	MOW-022	CM	MOW-X00	0	13	85	13	85	8/12/15
1 JHRA Two Block Tie Deteriorating (N) 013+85W	TIES			DETERIORATING		TIES						
2043299 (INPRG)	MOW-X00	2	BOTH	MOW-022	CM	MOW-X00	0	15	75	15	75	8/12/15
1 JHRA Two Block Tie Deteriorating (N) 015+75W	TIES			DETERIORATING		TIES						
2013812 (HOLD)	MOW-G00	2	BOTH	MOW-016	CM	MOW-X08	0	18	60	18	60	7/21/15
1 JHRA Fastener Pad Cracked/ Broken (6) 018+60W	GROUT PADS			CRACKED / SPLIT		CONCRETE G10 PAD						
2469642 (APPR)	MOW-X00	2	BOTH	MOW-016	CM	MOW-X00	0	18	85	18	85	7/1/16
1 JHRA	TIES			CRACKED / SPLIT		TIES						
2106086 (APPR)	MOW-L00	1	BOTH	MOW-004	CM	MOW-B01	0	53	0	59	0	9/30/15
1 JHRA Drain Clogged/Fouled (600') 053W-059W	LEAKS			BLOCKAGE		TUNNEL DRAIN						
2080337 (APPR)	MOW-C00	3	THIRD RAIL	MOW-014	CM	MOW-C05	0	68	70	68	90	9/10/15
1 JHRA 3rd Rail Severely Corroded 068+70 - 068+90	CONTACT RAIL			CORRODED		THIRD RAIL						
2618075 (APPR)	MOW-B00	1	BOTH	MOW-042	CM	MOW-L02	0	68	80	68	80	10/12/16
1 JHRA water leak 068+80	TUNNEL			LEAKING		TUNNEL LEAK						
2030720 (APPR)	MOW-R00	1	NORTH	MOW-003	CM	MOW-R08	0	69	35	69	35	8/3/15
1 JHRA IJ Battered BH 1B 069+35W	RAIL			BATTERED		INSULATED JOINT						
2468951 (APPR)	MOW-C00	2	THIRD RAIL	MOW-014	CM	MOW-C05	0	73	0	73	0	7/1/16
1 JHRA Third rail corrosion	CONTACT RAIL			CORRODED		THIRD RAIL						
2106102 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	107	15	107	15	9/30/15
1 JHRA Coverboard Bracket Broken 107+15	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						

Oct 24, 2016 12:23 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2014921 (APPR)	MOW-M00	3	THIRD RAIL	MOW-010	CM	MOW-C01	0	140	70	140	90	7/22/15
1 JHRA Insulator Cup Burnt (4) 140+70 -140+90	TRACK MISCELLANEOUS			BURNT (LUMBER)		INSULATOR						
2015378 (APPR)	MOW-R00	1	SOUTH	MOW-014	CM	MOW-R01	0	141	0	141	0	7/22/15
1 JHRA Rail Web/Base Deteriorated (S) 141+00	RAIL			CORRODED		RUNNING RAIL						
2015388 (APPR)	MOW-R00	1	THIRD RAIL	MOW-014	CM	MOW-C05	0	141	0	141	0	7/22/15
1 JHRA 3rd Rail Corroded 141+00	RAIL			CORRODED		THIRD RAIL						
2106112 (APPR)	MOW-C00	1	THIRD RAIL	MOW-061	CM	MOW-C05	0	148	0	148	0	9/30/15
1 JHRA 3rd Rail Unseated/Out of Insulator Cups 148+00	CONTACT RAIL			POOR SUPPORT		THIRD RAIL						
2106126 (APPR)	MOW-R00	2	NORTH	MOW-014	CM	MOW-R00	0	154	0	165	0	9/30/15
1 JHRA Rail Web/Base Corroded (N) 154-165	RAIL			CORRODED		RAIL						
2051473 (MONITOR)	MOW-C00	2	THIRD RAIL	MOW-014	CM	MOW-C05	0	158	0	166	0	8/19/15
1 JHRA 3rd Rail Deteriorated 158 -166+00	CONTACT RAIL			CORRODED		THIRD RAIL						
2208896 (APPR)	MOW-X00	2	BOTH	MOW-016	CM	MOW-X17	0	158	40	158	40	12/10/15
1 JHRA Two Block Tie Broken 158+40W	TIES			CRACKED / SPLIT		CONCRETE TIE RAIL SEAT PAD						
2208897 (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-M01	0	160	0	160	0	12/10/15
1 JHRA Chain Marker Sign 160NW Loose/Hanging	TRACK MISCELLANEOUS			LOOSE / SLACK		CHAIN MARKER						
2212343 (APPR)	MOW-F00	3	BOTH	MOW-022	CM	MOW-F05	0	160	0	170	0	12/12/15
1 JHRA Pandrol Clips Broken/ Deteriorating 160W-170W	FASTENERS			DETERIORATING		CLIP						
2106138 (APPR)	MOW-X00	1	BOTH	MOW-016	CM	MOW-X00	0	161	25	161	25	9/30/15
1 JHRA Two Block Tie Broken 161+25	TIES			CRACKED / SPLIT		TIES						

Oct 24, 2016 12:[illegible] AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2015101 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	194	90	195	25	7/22/15
1 JHRA Coverboard Brackets Missing 194+90 & 195+25	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
2043013 (MONITOR)	MOW-R00	2	NORTH	MOW-015	CM	MOW-R01	0	202	0	214	0	8/12/15
1 JHRA Rail Corrugation (N) 202 - 214+00	RAIL			CORRUGATED		RUNNING RAIL						
2013741 (APPR)	MOW-P00	1	BOTH	MOW-044	CM	MOW-P00	0	237	50	237	50	7/21/15
1 JHRA Shim Plate Loose 237+50	PLATES			LOOSE / SLACK		PLATES						
2017722 (APPR)	MOW-P00	2	BOTH	MOW-018	CM	MOW-P00	0	238	0	268	0	7/24/15
1 JHRA LB Foster Plates Deteriorating 238 - 268	PLATES			DEFECTIVE - NO LONGER FUNCTIONING		PLATES						
2030745 (APPR)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	248	10	248	10	8/3/15
1 JHRA Shim Plate Missing 248+10W	PLATES			MISSING		PLATES						
2549815 (APPR)	MOW-M00	3	SOUTH	MOW-044	PM	MOW-C02	0	262	0	272	0	8/23/16
1 JHRA coverboard bent 262-272	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2014064 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	267	50	272	0	7/21/15
1 JHRA Coverboard Brackets Bent 267+50 - 272	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2030747 (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R01	0	274	0	274	0	8/3/15
1 JHRA Rail Side Worn (22 Deg) 274+00	RAIL					RUNNING RAIL						

Number of Records: 28

Oct 24, 2016 12:23 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2053299 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA RH Switch Point Chipped / Pitted CC 3B	RAIL			CHIPPED / PITTED		SWITCH POINT						
2053301 (MONITOR)	MOW-R00	2	LEFT	MOW-069	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA LH Switch Point Chipped / Pitted CC 3B	RAIL			SIDE WEAR (RAIL)		SWITCH POINT						
2017699 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	7	50	7	50	7/24/15
1 JHRA 3rd Rail Side Approach Hardware Missing CC 1B 007+50	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
2573520 (APPR)	MOW-M00	2	BOTH	MOW-018	CM	MOW-M02	0	8	0	8	0	9/9/16
1 JHRA lights out charles interlocking 008	TRACK MISCELLANEOUS			DEFECTIVE - NO LONGER FUNCTIONING		ETS BOX / LIGHT						
2571333 (APPR)	MOW-M00	3	BOTH	MOW-080	CM	MOW-B01	0	10	0	14	0	9/7/16
2 RAJH trash 10-14	TRACK MISCELLANEOUS			TRASH AND DEBRIS		TUNNEL DRAIN						
2493075 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-B01	0	66	0	70	0	7/21/16
2 RAJH trash build up 070-066	RIGHT OF WAY			TRASH AND DEBRIS		TUNNEL DRAIN						
2030698 (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R08	0	66	80	66	80	8/3/15
1 JHRA IJ Battered BH-3B 066+80W	RAIL					INSULATED JOINT						
2014043 (HOLD)	MOW-X00	2	BOTH	MOW-062	CM	MOW-X00	0	67	70	68	50	7/21/15
2 RAJH Ties PumpIng BH 068+50 - 067+70W	TIES			PUMPING		TIES						
2449048 (APPR)	MOW-M00	3	THIRD RAIL	MOW-017	CM	MOW-C03	0	68	70	68	70	6/15/16
2 RAJH switch point battered	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2013791 (HOLD)	MOW-M00	2	SOUTH	MOW-046	CM	MOW-M09	0	69	0	69	0	7/21/15
2 RAJH Crosswalk Missing BH 3A 069+00W	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						

Oct 24, 2016 12 \M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030709 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/3/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						
2549819 (APPR)	MOW-R00	2	BOTH	MOW-003	PM	MOW-T06	0	230	0	230	0	8/23/16
1 JHRA frog 1B needs grinding 230	RAIL			BATTERED		FROG						

Number of Records: 12

Oct 24, 2016 12:23 AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

Inspection Completed? [✓] Yes [ ] No If No Why? _____

Item	Exception Chain Marker No. From	Exception Chain Marker No. To	Track No.	Position N/S	Switch No.	Codes Comp.	Codes Defect	Priority	Alias
1	045+00	—	1	S	—	R01	D06	1	TME1
2	034+00	035+00	1			M01	D02	3	TME2
3	008	010+00	1			M06	D03	5	TME1
4									
5									
6									
7									
8									

Notes: Water leak on rail
Clog Drain - Trash
LITES OUT

Track Walker: John T. Williams (Print) — J.T. Williams (Sign) — Date: 10/26/16

(Print) — (Sign) — Date:

(Print) — (Sign) — Date:

Watchman: Joe Brockneyer (Print) — Joe Brockneyer (Sign) — Date: 10-26-16

Track Inspection Supervisor: (Print) — (Sign) — Date: 12.11.16

Oct 24, 2016 12:[illegible] AM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Work Order Tracking (Tr)

Find Work Order Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2617164 VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 10/12/16 04:16:24 AM

Reported By: MTACRON

Phone:

Reported Date: 10/12/16 04:16:24 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cis Filter 0 - 0 of 0

VEHICLE TRACK INSPECTION REPORTING FORM

Name D. Byrd (Please Print) **Date** 10/30/16 **Page** 1 of 1

Inspected From JH **To** OM **ML #** 2 **WO #** 2617164

Item	Exception Chain Marker No. From	Exception Chain Marker No. To	Track No.	Rail N/S	Switch No.	Codes Comp.	Codes Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	652	654								
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS
	Pumping track need to be tamp

Trackwalkers Signature

Supervisory Certification