Work Order Tracking (Tr) Bull

Find Work Order Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2511827 VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

* Work Type: PM

Status: WSCH

Status Date: 08/03/16 04:14:13 AM

Reported By: MTACRON

Phone:

Reported Date: 08/03/16 04:14:13 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore City: BALTIMOF

Formatted Address: State/Province: MD

VEHICLE TRACK INSPECTION REPORTING FORM

Name Curtis Chandler (Please Print) **Date** 8/16/16 **Page** 1 of 1

Inspected From OM **To** JH **ML #** 1+2 **WO #** 2511827

Item	Exception Chain Marker No. From	To	Track No.	Rail N/S	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	221+35		2	S		C18	D03	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item	COMMENTS

Curtis Chandler
Trackwalkers Signature

Supervisory Certification

Work Order Tracking (Tr)

Find Work Order Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2533724 (1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 08/12/16 04:19:58 AM

Reported By: MTACRON

Phone:

Reported Date: 08/12/16 04:19:58 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and CIs

Filter 0 - 0 of 0

Maryland Departme[illegible]f Transportation
Maryland Transit[illegible]dministration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2106102 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	107	15	107	15	9/30/15
1 JHRA Coverboard Bracket Broken 107+15	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2014921 (APPR)	MOW-M00	1	THIRD RAIL	MOW-010	CM	MOW-C01	0	140	70	140	90	7/22/15
1 JHRA Insulator Cup Burnt (4) 140+70 -140+90	TRACK MISCELLANEOUS			BURNT (LUMBER)		INSULATOR						
2015378 (APPR)	MOW-R00	1	SOUTH	MOW-014	CM	MOW-R01	0	141	0	141	0	7/22/15
1 JHRA Rail Web/Base Deteriorated (S) 141+00	RAIL			CORRODED		RUNNING RAIL						
2015388 (APPR)	MOW-R00	1	THIRD RAIL	MOW-014	CM	MOW-C05	0	141	0	141	0	7/22/15
1 JHRA 3rd Rail Corroded 141+00	RAIL			CORRODED		THIRD RAIL						
2106112 (APPR)	MOW-C00	1	THIRD RAIL	MOW-061	CM	MOW-C05	0	148	0	148	0	9/30/15
1 JHRA 3rd Rail Unseated/Out of Insulator Cups 148+00	CONTACT RAIL			POOR SUPPORT		THIRD RAIL						
2106126 (APPR)	MOW-R00	2	NORTH	MOW-014	CM	MOW-R00	0	154	0	165	0	9/30/15
1 JHRA Rail Web/Base Corroded (N) 154-165	RAIL			CORRODED		RAIL						
2208896 (APPR)	MOW-X00	2	BOTH	MOW-016	CM	MOW-X17	0	158	40	158	40	12/10/15
1 JHRA Two Block Tie Broken 158+40W	TIES			CRACKED / SPLIT		CONCRETE TIE RAIL SEAT PAD						
2208897 (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-M01	0	160	0	160	0	12/10/15
1 JHRA Chain Marker Sign 160NW Loose/Hanging	TRACK MISCELLANEOUS			LOOSE / SLACK		CHAIN MARKER						
2212343 (APPR)	MOW-F00	3	BOTH	MOW-022	CM	MOW-F05	0	160	0	170	0	12/12/15
1 JHRA Pandrol Clips Broken/ Deteriorating 160W-170W	FASTENERS			DETERIORATING		CLIP						
2106138 (APPR)	MOW-X00	1	BOTH	MOW-016	CM	MOW-X00	0	161	25	161	25	9/30/15
1 JHRA Two Block Tie Broken 161+25	TIES			CRACKED / SPLIT		TIES						

Aug 16, 2016 3:23 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2015101 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	194	90	195	25	7/22/15
1 JHRA Coverboard Brackets Missing 194+90 & 195+25	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
2043013 (MONITOR)	MOW-R00	2	NORTH	MOW-015	CM	MOW-R01	0	202	0	214	0	8/12/15
1 JHRA Rail Corrugation (N) 202 - 214+00	RAIL			CORRUGATED		RUNNING RAIL						
2013746 (COMP)	MOW-R00	2	BOTH	MOW-046	CM	MOW-F05	0	230	0	230	0	7/21/15
1 JHRA Saddles Loose (5) Pandrols Missing PO1B	RAIL			MISSING		CLIP						
2013748 (COMP)	MOW-R00	2	NORTH	MOW-025	CM	MOW-R01	0	230	0	230	0	7/21/15
1 JHRA Running Rail Wheel Burns (N) 230+00	RAIL			ENGINE BURN FRACTURE (EBF)		RUNNING RAIL						
2017718 (COMP)	MOW-R00	2	SOUTH	MOW-013	CM	MOW-R08	0	230	90	230	90	7/24/15
1 JHRA Insulated Joint Chipped (S) 230+90	RAIL			CHIPPED / PITTED		INSULATED JOINT						
2021953 (COMP)	MOW-M00	1	BOTH	MOW-044	CM	MOW-X17	0	232	0	235	0	7/28/15
1 JHRA LB Foster Anchor Bolts Loose 235-332	TRACK MISCELLANEOUS			LOOSE / SLACK		CONCRETE TIE RAIL SEAT PAD						
2013893 (COMP)	MOW-R00	1	BOTH	MOW-025	CM	MOW-R01	0	234	90	234	90	7/21/15
1 JHRA Running Rail Wheel Burns (N/S) 234+90	RAIL			ENGINE BURN FRACTURE (EBF)		RUNNING RAIL						
2013896 (COMP)	MOW-R00	2	BOTH	MOW-056	CM	MOW-R00	0	236	0	242	0	7/21/15
1 JHRA Gage Tight (56 3/8") 236 - 242+00	RAIL			OUT OF GAGE		RAIL						
2013741 (APPR)	MOW-P00	1	BOTH	MOW-044	CM	MOW-P00	0	237	50	237	50	7/21/15
1 JHRA Shim Plate Loose 237+50	PLATES			LOOSE / SLACK		PLATES						
2017722 (APPR)	MOW-P00	2	BOTH	MOW-018	CM	MOW-P00	0	238	0	268	0	7/24/15
1 JHRA LB Foster Plates Deteriorating 238 - 268	PLATES			DEFECTIVE - NO LONGER FUNCTIONING		PLATES						

Aug 16, 2016 3:[illegible]M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme[illegible]f Transportation
Maryland Transit[illegible]dministration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030745 (APPR)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	248	10	248	10	8/3/15
1 JHRA Shim Plate Missing 248+10W	PLATES			MISSING		PLATES						
2014064 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	267	50	272	0	7/21/15
1 JHRA Coverboard Brackets Bent 267+50 - 272	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2030747 (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R01	0	274	0	274	0	8/3/15
1 JHRA Rail Side Worn (22 Deg) 274+00	RAIL					RUNNING RAIL						

Number of Records: 23

Aug 16, 2016 3:23 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013775 (COMP)	MOW-R00	2	BOTH	MOW-062	CM	MOW-R08	0	227	40	227	40	7/21/15
2 RAJH IJ Out of Crosslevel / Pumping / Mud PO 227+40	RAIL			PUMPING		INSULATED JOINT						
2017775 (COMP)	MOW-R00	2	BOTH	MOW-059	CM	MOW-R00	0	227	40	231	30	7/24/15
2 RAJH Interlocking Out of Surface PO 231+30-227+40	RAIL			OUT OF SURFACE		RAIL						
2014045 (COMP)	MOW-T00	3	BOTH	MOW-059	CM	MOW-T00	0	228	0	232	0	7/21/15
1 JHRA Interlocking Out of Surface PO 228-232+00	TURNOUTS SWITCHES			OUT OF SURFACE		TURNOUTS / SWITCHES						
2014955 (COMP)	MOW-X00	3	BOTH	MOW-063	CM	MOW-X02	0	228	40	228	40	7/22/15
2 RAJH 14' Frog Timber Rotted PO 5B 228+40	TIES			ROTTED		SWITCH TIES						
2017777 (COMP)	MOW-T00	1	LEFT	MOW-085	CM	MOW-T03	0	228	70	228	90	7/24/15
2 RAJH LH Switch Point Wheel Burns PO 5B 228+70 - 228+90	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2097064 (COMP)	MOW-M00	1	BOTH	MOW-017	CM	MOW-T07	0	228	70	228	70	9/23/15
2 RAJH Heel Block Bolts (2) / Washer Broken (1) PO 5B 228+70	TRACK MISCELLANEOUS			DAMAGED HARDWARE		HEEL BLOCK BOLTS						
2014958 (COMP)	MOW-M00	1	LEFT	MOW-044	CM	MOW-R09	0	228	75	228	75	7/22/15
2 RAJH Switch Point Stop Braces Loose PO 5B 228+75	TRACK MISCELLANEOUS			LOOSE / SLACK		RESTRAINING RAIL BRACE						
2014145 (COMP)	MOW-R00	1	LEFT	MOW-025	CM	MOW-T01	0	229	0	229	0	7/21/15
2 RAJH Stock Rail Wheel Burns PO 5B 229+00	RAIL			ENGINE BURN FRACTURE (EBF)		STOCK RAIL						
2017793 (COMP)	MOW-R00	2	BOTH	MOW-003	CM	MOW-T06	0	229	0	229	0	7/24/15
2 RAJH Frog Point/Riser Battered PO 1A 229	RAIL			BATTERED		FROG						

Maryland Departme[illegible]f Transportation
Maryland Transi[illegible]dministration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2041954 (COMP)	MOW-R00	2	RIGHT	MOW-025	CM	MOW-T03	0	229	0	229	0	8/11/15
1 JHRA RH Switch Point Wheel Burns PO 3B 229	RAIL			ENGINE BURN FRACTURE (EBF)		SWITCH POINT						
2058572 (COMP)	MOW-M00	1	BOTH	MOW-044	CM	MOW-M00	0	229	0	229	0	8/25/15
1 JHRA Front Rod Nut Loose PO 3B 229+00	TRACK MISCELLANEOUS			LOOSE / SLACK		TRACK MISCELLANEOUS						
2017780 (COMP)	MOW-R00	1	LEFT	MOW-025	CM	MOW-T01	0	229	10	229	30	7/24/15
2RAJH CM 229+10 - 229+30, Sw# PO-1A, 5 wheel burns on left hand straight switch point.	RAIL			ENGINE BURN FRACTURE (EBF)		STOCK RAIL						
2017781 (COMP)	MOW-T00	1	RIGHT	MOW-085	CM	MOW-T03	0	229	10	229	20	7/24/15
2 RAJH Switch Point Wheel Burns(4) PO 1A 229+10 - 229+20	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2192028 (COMP)	MOW-M00	2	LEFT	MOW-046	CM	MOW-T05	0	229	10	229	10	11/27/15
2 RAJH Switch Point Strap Bolts Missing PO 5B 229+10	TRACK MISCELLANEOUS			MISSING		SWITCH POINT GUARD BOLT (HOUSE TOP)						
2017678 (COMP)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	229	70	229	70	7/24/15
1 JHRA Adjustable Brace Plate Missing 229+70 PO-3B	PLATES			MISSING		PLATES						
2017696 (COMP)	MOW-M00	1	BOTH	MOW-046	CM	MOW-R02	0	229	70	229	70	7/24/15
1 JHRA Guard Rail Screw Spikes Missing PO 3B	TRACK MISCELLANEOUS			MISSING		GUARD RAIL						
2034599 (COMP)	MOW-M00	1	BOTH	MOW-046	CM	MOW-T06	0	229	75	229	75	8/6/15
2 RAJH Frog Joint Bolt Missing PO 1A 229+75	TRACK MISCELLANEOUS			MISSING		FROG						
2050074 (COMP)	MOW-R00	2	BOTH	MOW-076	CM	MOW-T06	0	230	0	230	0	8/18/15
1 JHRA Frog Point/Riser Worn PO 1B	RAIL			TOP WEAR (RAIL)		FROG						

Aug 16, 2016 3:23 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme f Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2080383 (COMP)	MOW-P00	1	BOTH	MOW-046	CM	MOW-P01	0	230	15	230	15	9/10/15
1 JHRA Insulated Tie Plate Missing 230+15	PLATES			MISSING		STANDARD TIE PLATE						
2014968 (COMP)	MOW-P00	1	BOTH	MOW-046	CM	MOW-P05	0	230	20	230	20	7/22/15
2 RAJH Frog Plate Missing PO 3A 230+20	PLATES			MISSING		FROG PLATE						
2017716 (COMP)	MOW-M00	2	BOTH	MOW-046	CM	MOW-X22	0	230	20	230	20	7/24/15
1 JHRA Guard Rail Screw Spikes Missing PO 1B	TRACK MISCELLANEOUS			MISSING		SCREW SPIKE						
2014972 (COMP)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	230	55	230	55	7/22/15
2 RAJH Heel Block Tie Plate Missing PO 3A 230+55	PLATES			MISSING		PLATES						
2077038 (COMP)	MOW-T00	1	BOTH	MOW-055	CM	MOW-T00	0	230	70	230	70	9/8/15
1 JHRA #3 Switch Rod Striking Timber PO 1B 230+70	TURNOUTS SWITCHES			OUT OF ADJUSTMENT		TURNOUTS / SWITCHES						
2246787 (COMP)	MOW-M00	1	BOTH	MOW-044	CM	MOW-T13	0	230	80	230	80	1/9/16
1 JHRA Front Rod Nut Loose PO 1B 230+80	TRACK MISCELLANEOUS			LOOSE / SLACK		SWITCH ROD						
2017784 (COMP)	MOW-T00	2	BOTH	MOW-085	CM	MOW-T03	0	230	84	230	84	7/24/15
2 RAJH Closure Rail/Switch Points Wheel Burns PO 3A	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2014978 (COMP)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C03	0	230	85	230	85	7/22/15
2 RAJH Insulator Cup & Bracket Loose PO 3A 230+85	TRACK MISCELLANEOUS			LOOSE / SLACK		COVER BOARD BRACKET						
2017785 (COMP)	MOW-R00	2	BOTH	MOW-003	CM	MOW-T01	0	230	90	230	90	7/24/15
2 RAJH Standard Joint/Stock Rail Battered PO 3A 230+90	RAIL			BATTERED		STOCK RAIL						

Aug 16, 2016 3:2 M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme f Transportation
Maryland Transit dministration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030726 (COMP)	MOW-R00	2	RIGHT	MOW-025	CM	MOW-T01	0	230	90	230	90	8/3/15
1 JHRA RH Stock Rail Wheel Burns PO 1B 230+90	RAIL			ENGINE BURN FRACTURE (EBF)		STOCK RAIL						
2110269 (COMP)	MOW-M00	1	NORTH	MOW-044	CM	MOW-R07	0	230	90	230	90	10/1/15
2 RAJH Standard Joint Huck Bolts Loose (2) 230+90 PO 3A	TRACK MISCELLANEOUS			LOOSE / SLACK		JOINT BAR BOLT						
2014982 (COMP)	MOW-R00	2	BOTH	MOW-059	CM	MOW-T01	0	231	0	231	0	7/22/15
2 RAJH Stock Rail Out of Surface PO 7B 231+00	RAIL			OUT OF SURFACE		STOCK RAIL						
2013845 (COMP)	MOW-T00	2	BOTH	MOW-062	CM	MOW-T03	0	231	10	231	10	7/21/15
2 RAJH Switch Point/Stock Rail Pumping (S) PO 7B 231+10	TURNOUTS SWITCHES			PUMPING		SWITCH POINT						
2110263 (COMP)	MOW-M00	2	BOTH	MOW-017	CM	MOW-T11	0	231	50	231	50	10/1/15
2 RAJH Frog Wing Bolt Broken PO 7B 231+50	TRACK MISCELLANEOUS			DAMAGED HARDWARE		FROG BOLT						
2013904 (COMP)	MOW-T00	2	BOTH	MOW-059	CM	MOW-X00	0	231	65	231	65	7/21/15
2 RAJH Frog Screw Spikes Missing/ Frog Wing Battered PO 7B 231+65	TURNOUTS SWITCHES			OUT OF SURFACE		TIES						
2118885 (COMP)	MOW-X00	3	BOTH	MOW-062	CM	MOW-Q04	0	233	90	233	90	10/8/15
2 RAJH Out of Surface/Pumping 233+90	TIES			PUMPING		ROW BALLAST						

Number of Records: 34

Aug 16, 2016 3:23 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

MTA Maryland

Maryland Departme[illegible]f Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

Inspection Completed? ☐ Yes ☐ No If No Why? _____

Item	Exception Chain Marker No.		Track	Position	Switch	Codes		Priority	Alias
	From	To	No.	N/S	No.	Comp.	Defect		
1	262	272	1	S	—	Coverboard	Bent.	3	TMWX
2									
3									
4									
5									
6									
7									
8									

Notes: Coverboard Bent.

Track Walker: [signature] Print [signature] Sign Date: 8-17-16

[signature] Print [signature] Sign Date: 8/17/2016

Print Sign Date:

Watchman: Print Sign Date:

Track Inspection Supervisor: Nick Pepper Print [signature] Sign Date: 9.6.16

Aug 16, 2016 3:2[illegible]M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Work Order Tracking (Tr)

Find Work Order Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2533697 (2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 08/12/16 04:19:37 AM

Reported By: MTACRON

Phone:

Reported Date: 08/12/16 04:19:36 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cis Filter 0 - 0 of 0

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2060168 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	79	10	79	10	8/26/15
2 RAJH Coverboard Sagging/Burnt/ Arcing 079+10	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2013854 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-C02	0	80	20	80	20	7/21/15
2 RAJH Coverboard Sagging 080+20W	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2433286 (COMP)	MOW-R00	3	SOUTH	MOW-069	CM	MOW-R01	0	81	0	102	0	6/1/16
2 RAJH running rail is side worn	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2060167 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	81	50	81	50	8/26/15
2 RAJH Coverboard Sagging 081+50	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2013808 (HOLD)	MOW-B00	2	BOTH	MOW-004	CM	MOW-B01	0	89	80	90	20	7/21/15
2RAJH Trough Blockage 089+80W-090+20W	TUNNEL			BLOCKAGE		TUNNEL DRAIN						
2025642 (MONITOR)	MOW-R00	2	NORTH	MOW-013	CM	MOW-R01	0	90	0	100	0	7/31/15
2 RAJH Running Rail Head Chipped/ Pitted/Gouged 100-090	RAIL			CHIPPED / PITTED		RUNNING RAIL						
2013887 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	93	0	93	0	7/21/15
2 RAJH Coverboard Sagging 093+00	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2202882 (APPR)	MOW-X00	2	NORTH	MOW-016	CM	MOW-X17	0	96	10	96	10	12/5/15
2 RAJH Two Block Tie Broken (N) 096+10	TIES			CRACKED / SPLIT		CONCRETE TIE RAIL SEAT PAD						
2202878 (APPR)	MOW-G00	2	BOTH	MOW-009	CM	MOW-X08	0	101	90	101	90	12/5/15
2 RAJH LB Foster Pads Concrete Base Broken 101+90	GROUT PADS			BROKEN/SHEARED		CONCRETE G10 PAD						
2015099 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	102	70	102	70	7/22/15
2 RAJH Coverboard Bracket Broken/Hardware Missing 102+70	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						

Aug 16, 2016 3:30 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme[illegible]of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2292436 (APPR)	MOW-B00	1	PLATFORM	MOW-042	CM	MOW-B00	0	107	80	107	80	2/18/16
2 RA-JH west end of upton water leak track 2	TUNNEL			LEAKING		TUNNEL						
2013856 (APPR)	MOW-L00	1	BOTH	MOW-004	CM	MOW-B01	0	110	0	108	0	7/21/15
2 RAJH Drain Blocked 110-108	LEAKS			BLOCKAGE		TUNNEL DRAIN						
2013890 (APPR)	MOW-R00	1	BOTH	MOW-022	CM	MOW-R01	0	156	40	156	40	7/21/15
2 RAJH Running Rail Deteriorated 156+40	RAIL			DETERIORATING		RUNNING RAIL						
2433131 (COMP)	MOW-M00	4	THIRD RAIL	MOW-022	CM	MOW-C01	0	163	0	163	0	6/1/16
isulator cup	TRACK MISCELLANEOUS			DETERIORATING		INSULATOR						
2013895 (APPR)	MOW-M00	1	THIRD RAIL	MOW-084	CM	MOW-C01	0	163	20	163	20	7/21/15
2 RAJH Insulator Cup Smoking (Wet) 163+20	TRACK MISCELLANEOUS			WATER CONDITIONS		INSULATOR						
2268178 (APPR)	MOW-F00	1	SOUTH	MOW-014	CM	MOW-F05	0	165	80	165	80	1/30/16
2 RAJH Pandrol Clips Broken (3 Consec) 165+80	FASTENERS			CORRODED		CLIP						
2433283 (APPR)	MOW-R00		NORTH	MOW-014	CM	MOW-R01	0	165	90	165	90	6/1/16
rail corroded	RAIL			CORRODED		RUNNING RAIL						
2198166 (INPRG)	MOW-R00	3	BOTH		CM	MOW	0	181	48	181	48	12/2/15
2 RAJH warp (-2.00 - 8ft) at cm#181+48 (Holland Report) URGENT	RAIL					MAINTENANCE OF WAY						
2489928 (APPR)	MOW-R00	4	BOTH	MOW-022	CM	MOW-R01	0	192	60	192	60	7/19/16
2 RAJH deteriorating rail 20 pandrals missing	RAIL			DETERIORATING		RUNNING RAIL						
2088344 (APPR)	MOW-M00	2	SOUTH	MOW-016	CM	MOW-B03	0	194	20	194	20	9/16/15
2 RAJH Tunnel Wall Section Broken 194+20	TRACK MISCELLANEOUS			CRACKED / SPLIT		TUNNEL STRUCTURE						

Maryland

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013861 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-C02	0	208	50	208	50	7/21/15
2 RAJH Coverboard Sagging 208+50	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2063554 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	221	35	221	35	8/29/15
2 RAJH 3rd Rail Metal Bracket Broken/Bent 221+35	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2062903 (APPR)	MOW-C00	2	THIRD RAIL	MOW-002	CM	MOW-C06	0	221	45	221	45	8/28/15
2 RAJH 3rd Rail End Approach Joint Burnt/Arcing 221+45	CONTACT RAIL			ARCING		END APPROACH						
2043032 (APPR)	MOW-G00	2	BOTH	MOW-022	CM	MOW-G00	0	224	20	224	10	8/12/15
2 RAJH Direct Fixation Pad Deteriorating 224+20-224+10	GROUT PADS			DETERIORATING		GROUT PADS						
2014053 (COMP)	MOW-G00	2	BOTH	MOW-062	CM	MOW-G02	0	226	60	226	70	7/21/15
2 RAJH Concrete Pad Pumping 226+70 - 226+60	GROUT PADS			PUMPING		CONTINUOUS GROUT PAD						
2017792 (COMP)	MOW-X00	1	BOTH	MOW-016	CM	MOW-X00	0	227	40	227	40	7/24/15
2 RAJH Concrete Tie Cracked PO 227+40	TIES			CRACKED / SPLIT		TIES						
2489927 (COMP)	MOW-X00	4	BOTH	MOW-062	CM	MOW-X00	0	228	0	232	0	7/19/16
2 RAJH ties pumping mud condition	TIES			PUMPING		TIES						
2014950 (COMP)	MOW-R00	2	SOUTH	MOW-003	CM	MOW-R01	0	228	30	228	50	7/22/15
2 RAJH Wheel Burns (7) (S) PO 228+50-228+30	RAIL			BATTERED		RUNNING RAIL						
2017776 (COMP)	MOW-R00	1	SOUTH	MOW-025	CM	MOW-R01	0	229	90	229	90	7/24/15
2 RAJH Wheel Burns (6) (S) PO 229+90	RAIL			ENGINE BURN FRACTURE (EBF)		RUNNING RAIL						
2013792 (COMP)	MOW-R00	2	BOTH	MOW-062	CM	MOW-R08	0	232	45	232	45	7/21/15
2 RAJH Mud Condition/Low Joint PO 232+45	RAIL			PUMPING		INSULATED JOINT						

Aug 16, 2016 3:30 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme[illegible]of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2141689 (APPR)	MOW-M00	2	BOTH	MOW-081	CM	MOW-Q03	0	233	90	233	90	10/23/15
2 RAJH Vegetation Overgrowth Fouling ML1/2 233+90W	TRACK MISCELLANEOUS			VEGETATION (EXCESSIVE GROWTH)		ROW VEGETATION						
2014946 (APPR)	MOW-R00	2	NORTH	MOW-069	CM	MOW-R01	0	241	0	241	0	7/22/15
2 RAJH Rail Side Worn (N) (25 Deg) 241+00	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2013860 (APPR)	MOW-Q00	1	NORTH	MOW-081	CM	MOW-Q03	0	248	0	248	0	7/21/15
2 RAJH Vegatation Obstructing CM Sign 248	RIGHT OF WAY			VEGETATION (EXCESSIVE GROWTH)		ROW VEGETATION						
2041956 (MONITOR)	MOW-R00	2	SOUTH	MOW-069	CM	MOW-R01	0	250	0	260	0	8/11/15
2 RAJH Rail Side Worn 260 - 250	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2014146 (APPR)	MOW-F00	2	BOTH	MOW-046	CM	MOW-F05	0	268	0	236	0	7/21/15
2 RAJH Pandrol Clips Missing 268 - 236+00	FASTENERS			MISSING		CLIP						
2013781 (HOLD)	MOW-M00	2	NORTH	MOW-046	CM	MOW-M09	0	272	10	272	10	7/21/15
2 RAJH Crosswalk Board Missing 272+10	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						
2471518 (COMP)	MOW-M00	2	SOUTH	MOW-046	CM	MOW-M09	0	272	11	272	11	7/2/16
2 JHRA cat walk missing	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						
2043011 (MONITOR)	MOW-R00	2	SOUTH	MOW-069	CM	MOW-R01	0	278	25	278	28	8/12/15
2 RAJH Rail Side Worn (S) (25 Deg) 278+25	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2471512 (COMP)	MOW-F00	1	SOUTH	MOW-046	CM	MOW-F05	0	282	20	282	30	7/2/16
2 RAJH 6 missing clips	FASTENERS			MISSING		CLIP						
2013863 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-C02	0	307	50	307	50	7/21/15
2 RAJH Coverboard Sagging 307+50	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						

Aug 16, 2016 3:[illegible]M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2017725 (APPR)	MOW-M00	1	SOUTH	MOW-081	CM	MOW-Q03	0	328	0	328	5	7/24/15
2 RAJH Vegetation / Sight Restriction 328 - 328+05	TRACK MISCELLANEOUS			VEGETATION (EXCESSIVE GROWTH)		ROW VEGETATION						

Number of Records: 41

Aug 16, 2016 3:30 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013775 (COMP)	MOW-R00	2	BOTH	MOW-062	CM	MOW-R08	0	227	40	227	40	7/21/15
2 RAJH IJ Out of Crosslevel / Pumping / Mud PO 227+40	RAIL			PUMPING		INSULATED JOINT						
2017775 (COMP)	MOW-R00	2	BOTH	MOW-059	CM	MOW-R00	0	227	40	231	30	7/24/15
2 RAJH Interlocking Out of Surface PO 231+30-227+40	RAIL			OUT OF SURFACE		RAIL						
2014045 (COMP)	MOW-T00	3	BOTH	MOW-059	CM	MOW-T00	0	228	0	232	0	7/21/15
1 JHRA Interlocking Out of Surface PO 228-232+00	TURNOUTS SWITCHES			OUT OF SURFACE		TURNOUTS / SWITCHES						
2014955 (COMP)	MOW-X00	3	BOTH	MOW-063	CM	MOW-X02	0	228	40	228	40	7/22/15
2 RAJH 14' Frog Timber Rotted PO 5B 228+40	TIES			ROTTED		SWITCH TIES						
2017777 (COMP)	MOW-T00	1	LEFT	MOW-085	CM	MOW-T03	0	228	70	228	90	7/24/15
2 RAJH LH Switch Point Wheel Burns PO 5B 228+70 - 228+90	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2097064 (COMP)	MOW-M00	1	BOTH	MOW-017	CM	MOW-T07	0	228	70	228	70	9/23/15
2 RAJH Heel Block Bolts (2) / Washer Broken (1) PO 5B 228+70	TRACK MISCELLANEOUS			DAMAGED HARDWARE		HEEL BLOCK BOLTS						
2014958 (COMP)	MOW-M00	1	LEFT	MOW-044	CM	MOW-R09	0	228	75	228	75	7/22/15
2 RAJH Switch Point Stop Braces Loose PO 5B 228+75	TRACK MISCELLANEOUS			LOOSE / SLACK		RESTRAINING RAIL BRACE						
2014145 (COMP)	MOW-R00	1	LEFT	MOW-025	CM	MOW-T01	0	229	0	229	0	7/21/15
2 RAJH Stock Rail Wheel Burns PO 5B 229+00	RAIL			ENGINE BURN FRACTURE (EBF)		STOCK RAIL						
2017793 (COMP)	MOW-R00	2	BOTH	MOW-003	CM	MOW-T06	0	229	0	229	0	7/24/15
2 RAJH Frog Point/Riser Battered PO 1A 229	RAIL			BATTERED		FROG						

Maryland Departm of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2041954 (COMP)	MOW-R00	2	RIGHT	MOW-025	CM	MOW-T03	0	229	0	229	0	8/11/15
1 JHRA RH Switch Point Wheel Burns PO 3B 229	RAIL			ENGINE BURN FRACTURE (EBF)		SWITCH POINT						
2058572 (COMP)	MOW-M00	1	BOTH	MOW-044	CM	MOW-M00	0	229	0	229	0	8/25/15
1 JHRA Front Rod Nut Loose PO 3B 229+00	TRACK MISCELLANEOUS			LOOSE / SLACK		TRACK MISCELLANEOUS						
2017780 (COMP)	MOW-R00	1	LEFT	MOW-025	CM	MOW-T01	0	229	10	229	30	7/24/15
2RAJH CM 229+10 - 229+30, Sw# PO-1A, 5 wheel burns on left hand straight switch point.	RAIL			ENGINE BURN FRACTURE (EBF)		STOCK RAIL						
2017781 (COMP)	MOW-T00	1	RIGHT	MOW-085	CM	MOW-T03	0	229	10	229	20	7/24/15
2 RAJH Switch Point Wheel Burns(4) PO 1A 229+10 - 229+20	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2192028 (COMP)	MOW-M00	2	LEFT	MOW-046	CM	MOW-T05	0	229	10	229	10	11/27/15
2 RAJH Switch Point Strap Bolts Missing PO 5B 229+10	TRACK MISCELLANEOUS			MISSING		SWITCH POINT GUARD BOLT (HOUSE TOP)						
2017678 (COMP)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	229	70	229	70	7/24/15
1 JHRA Adjustable Brace Plate Missing 229+70 PO-3B	PLATES			MISSING		PLATES						
2017696 (COMP)	MOW-M00	1	BOTH	MOW-046	CM	MOW-R02	0	229	70	229	70	7/24/15
1 JHRA Guard Rail Screw Spikes Missing PO 3B	TRACK MISCELLANEOUS			MISSING		GUARD RAIL						
2034599 (COMP)	MOW-M00	1	BOTH	MOW-046	CM	MOW-T06	0	229	75	229	75	8/6/15
2 RAJH Frog Joint Bolt Missing PO 1A 229+75	TRACK MISCELLANEOUS			MISSING		FROG						
2050074 (COMP)	MOW-R00	2	BOTH	MOW-076	CM	MOW-T06	0	230	0	230	0	8/18/15
1 JHRA Frog Point/Riser Worn PO 1B	RAIL			TOP WEAR (RAIL)		FROG						

Aug 16, 2016 3:30 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2080383 (COMP)	MOW-P00	1	BOTH	MOW-046	CM	MOW-P01	0	230	15	230	15	9/10/15
1 JHRA Insulated Tie Plate Missing 230+15	PLATES			MISSING		STANDARD TIE PLATE						
2014968 (COMP)	MOW-P00	1	BOTH	MOW-046	CM	MOW-P05	0	230	20	230	20	7/22/15
2 RAJH Frog Plate Missing PO 3A 230+20	PLATES			MISSING		FROG PLATE						
2017716 (COMP)	MOW-M00	2	BOTH	MOW-046	CM	MOW-X22	0	230	20	230	20	7/24/15
1 JHRA Guard Rail Screw Spikes Missing PO 1B	TRACK MISCELLANEOUS			MISSING		SCREW SPIKE						
2014972 (COMP)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	230	55	230	55	7/22/15
2 RAJH Heel Block Tie Plate Missing PO 3A 230+55	PLATES			MISSING		PLATES						
2077038 (COMP)	MOW-T00	1	BOTH	MOW-055	CM	MOW-T00	0	230	70	230	70	9/8/15
1 JHRA #3 Switch Rod Striking Timber PO 1B 230+70	TURNOUTS SWITCHES			OUT OF ADJUSTMENT		TURNOUTS / SWITCHES						
2246787 (COMP)	MOW-M00	1	BOTH	MOW-044	CM	MOW-T13	0	230	80	230	80	1/9/16
1 JHRA Front Rod Nut Loose PO 1B 230+80	TRACK MISCELLANEOUS			LOOSE / SLACK		SWITCH ROD						
2017784 (COMP)	MOW-T00	2	BOTH	MOW-085	CM	MOW-T03	0	230	84	230	84	7/24/15
2 RAJH Closure Rail/Switch Points Wheel Burns PO 3A	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2014978 (COMP)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C03	0	230	85	230	85	7/22/15
2 RAJH Insulator Cup & Bracket Loose PO 3A 230+85	TRACK MISCELLANEOUS			LOOSE / SLACK		COVER BOARD BRACKET						
2017785 (COMP)	MOW-R00	2	BOTH	MOW-003	CM	MOW-T01	0	230	90	230	90	7/24/15
2 RAJH Standard Joint/Stock Rail Battered PO 3A 230+90	RAIL			BATTERED		STOCK RAIL						

Aug 16, 2016 3: M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Departme of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030726 (COMP)	MOW-R00	2	RIGHT	MOW-025	CM	MOW-T01	0	230	90	230	90	8/3/15
1 JHRA RH Stock Rail Wheel Burns PO 1B 230+90	RAIL			ENGINE BURN FRACTURE (EBF)		STOCK RAIL						
2110269 (COMP)	MOW-M00	1	NORTH	MOW-044	CM	MOW-R07	0	230	90	230	90	10/1/15
2 RAJH Standard Joint Huck Bolts Loose (2) 230+90 PO 3A	TRACK MISCELLANEOUS			LOOSE / SLACK		JOINT BAR BOLT						
2014982 (COMP)	MOW-R00	2	BOTH	MOW-059	CM	MOW-T01	0	231	0	231	0	7/22/15
2 RAJH Stock Rail Out of Surface PO 7B 231+00	RAIL			OUT OF SURFACE		STOCK RAIL						
2013845 (COMP)	MOW-T00	2	BOTH	MOW-062	CM	MOW-T03	0	231	10	231	10	7/21/15
2 RAJH Switch Point/Stock Rail Pumping (S) PO 7B 231+10	TURNOUTS SWITCHES			PUMPING		SWITCH POINT						
2110263 (COMP)	MOW-M00	2	BOTH	MOW-017	CM	MOW-T11	0	231	50	231	50	10/1/15
2 RAJH Frog Wing Bolt Broken PO 7B 231+50	TRACK MISCELLANEOUS			DAMAGED HARDWARE		FROG BOLT						
2013904 (COMP)	MOW-T00	2	BOTH	MOW-059	CM	MOW-X00	0	231	65	231	65	7/21/15
2 RAJH Frog Screw Spikes Missing/ Frog Wing Battered PO 7B 231+65	TURNOUTS SWITCHES			OUT OF SURFACE		TIES						
2118885 (COMP)	MOW-X00	3	BOTH	MOW-062	CM	MOW-Q04	0	233	90	233	90	10/8/15
2 RAJH Out of Surface/Pumping 233+90	TIES			PUMPING		ROW BALLAST						

Number of Records: 34

Aug 16, 2016 3:3 M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

MTA Maryland

Maryland Departme[illegible]f Transportation
Maryland Transit [illegible]ministration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

Inspection Completed? ☐ Yes ☐ No If No Why? _____

Item	Exception Chain Marker No.		Track	Position	Switch	Codes		Priority	Alias
	From	To	No.	N/S	No.	Comp.	Defect		
1									
2									
3									
4									
5									
6									
7									
8									

Notes: All stations need to be cleaned RA - WCS - Mond. Penn - Upton - SC - Charles - Shot Tower - John Hopkins

Track Walker: [signature] Print — John T. Willm[illegible] Sign — Date: 8-18-16

Print — Sign — Date:

Print — Sign — Date:

Watchman: Print — Sign — Date:

Track Inspection Supervisor: Nick Pepper Print — [signature] Sign — Date: 9.6.16

Aug 16, 2016 3:30 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2