Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2675373 VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 11/23/16 04:14:08 AM

Reported By: MTACRON

Phone:

Reported Date: 11/23/16 04:14:08 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cis Filter 0 - 0 of 0

VEHICLE TRACK INSPECTION REPORTING FORM

Name Daniel Bynd (Please Print) **Date** 12/5/2016 **Page** 1 of 1

Inspected From OM To JH **ML #** 2 **WO #** 2675373

	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	N/S	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.		NO								
9.										
10.			New							
11.										
12.										
13.										
14.				No Defects						
15.										
16.							Found			
17.										
18.										
19.										
20.										

Item	COMMENTS

Trackwalkers Signature

Supervisory Certification

Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2688613 (2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 12/02/16 04:16:25 AM

Reported By: MTACRON

Phone:

Reported Date: 12/02/16 04:16:25 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter 0 - 0 of 0

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2541444 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-Q00	0	10	0	10	0	8/16/16
2 RAJH trah 010+0	RIGHT OF WAY			TRASH AND DEBRIS		RIGHT OF WAY						
2541451 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-Q00	0	32	0	32	0	8/16/16
2 RAJH trash 32+0	RIGHT OF WAY			TRASH AND DEBRIS		RIGHT OF WAY						
2218384 (APPR)	MOW-B00	2	SOUTH	MOW-042	CM	MOW-L02	0	34	0	34	0	12/17/15
2 RAJH Water Leak (S) 034+00W	TUNNEL			LEAKING		TUNNEL LEAK						
2541446 (APPR)	MOW-L00	3	BOTH	MOW-042	CM	MOW-L02	0	34	0	34	0	8/16/16
2 JHRA water leak 34+00	LEAKS			LEAKING		TUNNEL LEAK						
2571332 (APPR)	MOW-L00	4	SOUTH	MOW-042	CM	MOW-R01	0	34	0	34	0	9/7/16
2 RAJH water leak on rail 034	LEAKS			LEAKING		RUNNING RAIL						
2597312 (APPR)	MOW-B00	4	SOUTH	MOW-017	CM	MOW-B00	0	46	0	46	0	9/28/16
2 RAJH DOOR OFF HINDGES 046	TUNNEL			DAMAGED HARDWARE		TUNNEL						
2571330 (APPR)	MOW-M00	2	BOTH	MOW-084	CM	MOW-M02	0	54	0	56	0	9/7/16
2 RAJH light out 054-056	TRACK MISCELLANEOUS			WATER CONDITIONS		ETS BOX / LIGHT						
2202890 (APPR)	MOW-M00	3	BOTH	MOW-018	CM	MOW-X17	0	67	0	68	60	12/5/15
2 RAJH Concrete Deteriorating 068+60-067W	TRACK MISCELLANEOUS			DEFECTIVE - NO LONGER FUNCTIONING		CONCRETE TIE RAIL SEAT PAD						
2015095 (APPR)	MOW-M00	4	THIRD RAIL	MOW-046	CM	MOW-C02	0	67	10	68	5	7/22/15
2 RAJH Coverboard Missing/Bracket Damaged 068+05-067+10	TRACK MISCELLANEOUS			MISSING		COVERBOARD						
2013849 (APPR)	MOW-L00	1	BOTH	MOW-004	CM	MOW-B00	0	72	10	72	10	7/21/15
2 RAJH Drain Blocked 072+10W	LEAKS			BLOCKAGE		TUNNEL						
2060168 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	79	10	79	10	8/26/15
2 RAJH Coverboard Sagging/Burnt/ Arcing 079+10	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						

Dec 3, 2016 12:26 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2053299 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA RH Switch Point Chipped / Pitted CC 3B	RAIL			CHIPPED / PITTED		SWITCH POINT						
2053301 (MONITOR)	MOW-R00	2	LEFT	MOW-069	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA LH Switch Point Chipped / Pitted CC 3B	RAIL			SIDE WEAR (RAIL)		SWITCH POINT						
2017699 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	7	50	7	50	7/24/15
1 JHRA 3rd Rail Side Approach Hardware Missing CC 1B 007+50	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
2573520 (APPR)	MOW-M00	2	BOTH	MOW-018	CM	MOW-M02	0	8	0	8	0	9/9/16
1 JHRA lights out charles interlocking 008	TRACK MISCELLANEOUS			DEFECTIVE - NO LONGER FUNCTIONING		ETS BOX / LIGHT						
2571333 (APPR)	MOW-M00	3	BOTH	MOW-080	CM	MOW-B01	0	10	0	14	0	9/7/16
2 RAJH trash 10-14	TRACK MISCELLANEOUS			TRASH AND DEBRIS		TUNNEL DRAIN						
2493075 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-B01	0	66	0	70	0	7/21/16
2 RAJH trash build up 070-066	RIGHT OF WAY			TRASH AND DEBRIS		TUNNEL DRAIN						
2030698 (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R08	0	66	80	66	80	8/3/15
1 JHRA IJ Battered BH-3B 066+80W	RAIL					INSULATED JOINT						
2014043 (HOLD)	MOW-X00	2	BOTH	MOW-062	CM	MOW-X00	0	67	70	68	50	7/21/15
2 RAJH Ties Pumping BH 068+50 - 067+70W	TIES			PUMPING		TIES						
2449048 (APPR)	MOW-M00	3	THIRD RAIL	MOW-017	CM	MOW-C03	0	68	70	68	70	6/15/16
2 RAJH switch point battered	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2013791 (HOLD)	MOW-M00	2	SOUTH	MOW-046	CM	MOW-M09	0	69	0	69	0	7/21/15
2 RAJH Crosswalk Missing BH 3A 069+00W	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						

Dec 3, 2016 12:[illegible]M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030709 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/3/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						
2549819 (APPR)	MOW-R00	2	BOTH	MOW-003	PM	MOW-T06	0	230	0	230	0	8/23/16
1 JHRA frog 1B needs grinding 230	RAIL			BATTERED		FROG						

Number of Records: 12

Dec 3, 2016 12:26 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

Inspection Completed? [✓] Yes [ ] No If No Why? _____

Item	Exception Chain Marker No. From	Exception Chain Marker No. To	Track No.	Position N/S	Switch No.	Codes Comp.	Codes Defect	Priority	Alias
1									
2									
3									
4									
5									
6									
7									
8									

Notes: No New Defects

Track Walker: Joe Brockmeyer (Print) — Joe Brockmeyer (Sign) — Date: 12-6-16

(Print) — (Sign) — Date:

(Print) — (Sign) — Date:

Watchman: John Willis (Print) — (Sign) — Date: 12-6-16

Track Inspection Supervisor: Nick Pepper (Print) — (Sign) — Date: 12.7.16

Dec 3, 2016 12:[illegible]M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2688625 (1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 12/02/16 04:16:38 AM

Reported By: MTACRON

Phone:

Reported Date: 12/02/16 04:16:37 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cis Filter 0 - 0 of 0

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TME2 (TRACK METRO EAST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013793 (HOLD)	MOW-B00	2	BOTH	MOW-080	CM	MOW-B01	0	30	0	50	0	7/21/15
2 RAJH Water/Trash Condition 030-050+00E	TUNNEL			TRASH AND DEBRIS		TUNNEL DRAIN						
2083378 (INPRG)	MOW-R00	2	BOTH	MOW-022	CM	MOW-R01	0	46	0	50	0	9/12/15
2 RAJH Clips Broken/Plates & Rail Deteriorated 046E - 050E	RAIL			DETERIORATING		RUNNING RAIL						
2043307 (MONITOR)	MOW-R00	3	SOUTH	MOW-069	CM	MOW-R01	0	56	0	56	0	8/12/15
2 RAJH Rail Sideworn (27-32 Deg) 056E-064E	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
1673460 (APPR)	MOW-R00	1	THIRD RAIL	MOW-046	CM	MOW-C02	0	68	10	68	10	10/15/14
2 RAJH Coverbrd Missng 20' JH 1A 068+10E	RAIL			MISSING		COVERBOARD						

Number of Records: 4

Dec 3, 2016 12:26 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMEXJH (TRACK METRO EAST CROSSOVER JOHN HOPKINS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2493058 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	67	0	67	0	7/21/16
1 JHRA frog point 1b pitted/battered	RAIL			BATTERED		FROG						
2665965 (APPR)	MOW-R00	2	G5	MOW-013	CM	MOW-T09	0	67	0	67	0	11/15/16
1 JHRA point in diamond chipped and pitted 67+00	RAIL			CHIPPED / PITTED		FROG GUARD						
2449051 (APPR)	MOW-R00	3	BOTH	MOW-013	CM	MOW-T06	0	68	40	68	40	6/15/16
2 RAJH frog point chipped 3A	RAIL			CHIPPED / PITTED		FROG						
2449070 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	69	0	69	0	6/15/16
2 RAJH frog point battered 1A	RAIL			BATTERED		FROG						
2043020 (MONITOR)	MOW-R00	2	RIGHT	MOW-069	CM	MOW-T01	0	70	0	70	0	8/12/15
2 RAJH RH Stock Rail Side Worn (25 Deg) JH 1A	RAIL			SIDE WEAR (RAIL)		STOCK RAIL						
2493055 (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	70	6	70	6	7/21/16
1 JHRA JH 3B frog point battered	RAIL			BATTERED		FROG						
2014923 (APPR)	MOW-M00	1	LEFT	MOW-044	CM	MOW-T12	0	70	20	70	30	7/22/15
2 RAJH LH Switch Point Fastener Blocks Loose (4) JH 1A	TRACK MISCELLANEOUS			LOOSE / SLACK		SPACER BLOCK BOLT						
2573519 (WAPPR)	MOW-M00	2	WEST		CM	MOW-T06	0	75	0	75	0	9/8/16
1 JHRA blocks missing wing of frog	TRACK MISCELLANEOUS					FROG						
2573518 (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-R09	0	79	0	79	0	9/8/16
1 JHRA brace plate loose 1B 079	TRACK MISCELLANEOUS			LOOSE / SLACK		RESTRAINING RAIL BRACE						

Number of Records: 9

Dec 3, 2016 12:[illegible]M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TME1 (TRACK METRO EAST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2469281 (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	7	0	7	0	7/1/16
1 JHRA frog point battered 1A	RAIL			BATTERED		FROG						
2651904 (APPR)	MOW-B00	5	BOTH	MOW-065	CM	MOW-B00	0	8	0	8	0	11/3/16
1 JHRA lites out 008+00	TUNNEL			SAFETY HAZARD		TUNNEL						
2015100 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C02	0	36	65	36	65	7/22/15
1 JHRA Coverboard Broken / Bracket Missing 036+65E	TRACK MISCELLANEOUS			MISSING		COVERBOARD						
2651902 (APPR)	MOW-L00	1	SOUTH	MOW-042	CM	MOW-L02	0	45	0	45	0	11/3/16
1 JHRA water leak on rail 45+00	LEAKS			LEAKING		TUNNEL LEAK						
2033296 (MONITOR)	MOW-R00	2	SOUTH	MOW-013	CM	MOW-T02	0	67	60	67	60	8/5/15
1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	RAIL			CHIPPED / PITTED		LEAD OR CLOSURE RAIL						
2013865 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-R08	0	67	70	67	70	7/21/15
1 JHRA Restraining Rail IJ Bolts Loose 067+70E	TRACK MISCELLANEOUS			LOOSE / SLACK		INSULATED JOINT						
2665961 (APPR)	MOW-R00	2	NORTH	MOW-003	CM	MOW-R08	0	68	0	68	0	11/15/16
1 JHRA IJ battered chipped and pitted 68+00	RAIL			BATTERED		INSULATED JOINT						

Number of Records: 7

Dec 3, 2016 12:22 PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2053299 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA RH Switch Point Chipped / Pitted CC 3B	RAIL			CHIPPED / PITTED		SWITCH POINT						
2053301 (MONITOR)	MOW-R00	2	LEFT	MOW-069	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA LH Switch Point Chipped / Pitted CC 3B	RAIL			SIDE WEAR (RAIL)		SWITCH POINT						
2017699 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	7	50	7	50	7/24/15
1 JHRA 3rd Rail Side Approach Hardware Missing CC 1B 007+50	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
2573520 (APPR)	MOW-M00	2	BOTH	MOW-018	CM	MOW-M02	0	8	0	8	0	9/9/16
1 JHRA lights out charles interlocking 008	TRACK MISCELLANEOUS			DEFECTIVE - NO LONGER FUNCTIONING		ETS BOX / LIGHT						
2571333 (APPR)	MOW-M00	3	BOTH	MOW-080	CM	MOW-B01	0	10	0	14	0	9/7/16
2 RAJH trash 10-14	TRACK MISCELLANEOUS			TRASH AND DEBRIS		TUNNEL DRAIN						
2493075 (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-B01	0	66	0	70	0	7/21/16
2 RAJH trash build up 070-066	RIGHT OF WAY			TRASH AND DEBRIS		TUNNEL DRAIN						
2030698 (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R08	0	66	80	66	80	8/3/15
1 JHRA IJ Battered BH-3B 066+80W	RAIL					INSULATED JOINT						
2014043 (HOLD)	MOW-X00	2	BOTH	MOW-062	CM	MOW-X00	0	67	70	68	50	7/21/15
2 RAJH Ties PumpIng BH 068+50 - 067+70W	TIES			PUMPING		TIES						
2449048 (APPR)	MOW-M00	3	THIRD RAIL	MOW-017	CM	MOW-C03	0	68	70	68	70	6/15/16
2 RAJH switch point battered	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2013791 (HOLD)	MOW-M00	2	SOUTH	MOW-046	CM	MOW-M09	0	69	0	69	0	7/21/15
2 RAJH Crosswalk Missing BH 3A 069+00W	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						

Dec 3, 2016 12:[illegible]M
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2030709 (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/3/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						
2549819 (APPR)	MOW-R00	2	BOTH	MOW-003	PM	MOW-T06	0	230	0	230	0	8/23/16
1 JHRA frog 1B needs grinding 230	RAIL			BATTERED		FROG						

Number of Records: 12

Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N

Inspection Completed? [✓] Yes [ ] No If No Why? _____

Item	Exception Chain Marker No. From	Exception Chain Marker No. To	Track No.	Position N/S	Switch No.	Codes Comp.	Codes Defect	Priority	Alias
1	007+00		1		1B	505	D16	3	TMX
2									
3									
4									
5									
6									
7									
8									

Notes: 3 punched blocks and clips is missing on 1B frog

Track Walker: Curtis Chandler (Print) — [signature] (Sign) — Date: 12/6/16

Print _____ Sign _____ Date: _____

Print _____ Sign _____ Date: _____

Watchman: David Bynum (Print) — [signature] (Sign) — Date: 12/6/16

Track Inspection Supervisor: Nick Pepper (Print) — [signature] (Sign) — Date: 12.7.16

Dec 3, 2016 12:2[illegible] PM
created by yv
filename: mta_right_of_way_inspectors.rptdesign v2

Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2694169 VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

* Work Type: PM

Status: WSCH

Status Date: 12/07/16 04:15:39 AM

Reported By: MTACRON

Phone:

Reported Date: 12/07/16 04:15:39 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cis Filter 0 - 0 of 0

VEHICLE TRACK INSPECTION REPORTING FORM

Name Daniel Byrd Jr **Date** 12-10-2016 **Page** 1 of 1
(Please Print)

Inspected From OM To JH **ML #** 1 **WO #** 2694169

	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	N/S	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	66.2	66.2	1	S		SOL	Low	Y	N	
2.	60.8	60.8	1	S/N		C03	Cover Board	S	N	
3.	59.8	59.8	1	S/N		C03	Cover Board	S	N	
4.	59.2	59.2	1	S/N		C10	Insulated Joint	S	N	
5.	57.0	57.0	1	S/N		D26	Out of Surface	S	N	
6.	57.2	56.8	1	S/N		C03	Cover Board	S	N	
7.	52.0	52.0	1	S/N		C03	Cover Board	S	N	
8.	52.0	52.0	1	S/N		D26	Low Bonded Joint	S	N	
9.	42.2	41.2	1	S/N		D26	Surface Curve	S	N	
10.	36.0	36.0	1	S/N		C03	Missing	S	N	
11.	35.0	35.0	1	S/N		C03	Missing	S	N	
12.	34.8	34.4	1	S/N		D14	Low Ballast	S	N	
13.	20.2	20.2	1	S/N		C03	Missing	S	N	
14.	18.6	18.4	1	S/N		C03	Missing	S	N	
15.	16.2	16.2	1	S/N		C03	Missing	S	N	
16.	15.8	15.8	1	S/N		C03	Missing	S	N	
17.	13.2	14.2	1	S/N		—	Dirty	S	N	
18.	07.0	07.6	1	S/N		—	Dirty	S	N	
19.										
20.										

Item **COMMENTS**

Coverboard is missing - Insulated joint and curve need surfacing -

Trackwalkers Signature

Supervisory Certification

Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2694169 VEHICLE METRO MOW WEEKLY TRACK INSPECTION

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 12/07/16 04:15:39 AM

Reported By: MTACRON

Phone:

Reported Date: 12/07/16 04:15:39 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cis

Filter 0 - 0 of 0

VEHICLE TRACK INSPECTION REPORTING FORM

Name Daniel Byrd Jr (Please Print) **Date** 12-11-2016 **Page** 1 of 1

Inspected From OM **To** JH **ML #** 2 **WO #** 2694169

	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	N/S	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	57.8	57.8	2	S		C03	Missing	S	N	
2.	47.8	47.2	2	S		M06	Light	S	N	
3.	46	46	2	S		C03	Missing	S	N	
4.	38	38	2	S		C03	Missing	S	N	
5.	34.4	34	2	S		C03	Missing	S	N	
6.	23.4	24.4	2	S		C03	Missing	S	N	
7.	22.2	22.2	2	S		M06	Lighter	S	N	
8.	18.2	18.4	2	S		C03	Missing	S	N	
9.	16.4	16.2	2	S		C03	Missing	S	N	
10.	09.6	09.6	2	S		C03	Missing	S	N	
11.	05.6	05.6	2	S		C03	Missing	S	N	
12.										
13.										
14.										
15.										
16.										
17.										
18.										
19.										
20.										

Item **COMMENTS**

Coverboard is missing - Light are out all through the Tunnel - Low IJ at Modonough Rd - Stations Need to Be Clean At RA-CS

Daniel Byrd Jr
Trackwalkers Signature

Supervisory Certification