Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278621 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		MPOLLAF				10	N		08:00	00:00	210.32
											Total Actual Labor:	210.32

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278621 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	APPR						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name Michael L Pollard Date 2-7-18 Page 1 of 1

Watchman _____ WO# 3278621

Inspection From Listhicum To Camden yards

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

Riding inspection complete

No new defects noted in area

inspection complete

Were switches in area inspected? YES ✓ NO _____

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

Track Inspectors Signature

Supervisory Certification

2/8/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3278624 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/8/18
Target Finish:	2/8/18
Actual Start:	2/7/18
Actual Finish:	2/7/18
Report Date:	2/3/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278624 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Log

Date	Class	Created By	Subject	Description	Long Description
2/7/18	WORKORDER	GLAM		track inspection	switch 104 bwi 2 rail braces not seated properly under head of rail. aviation blvd xing tracks 1=2 sunken and asphalt broken up around crossings.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278624 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278624 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

C

Light Rail MOW

Daily Track Inspection

Name G LAM Date 2/7/18 Page ____ of ____

Watchman A RAbette WO# 3278624

Inspection From Linthicum To Cromwell BWI

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.				E/W	104	S308	324		Y	
2.	CM86		1+2	E/W		M305	329		Y	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	2 RAIL BRACES NOT SEATED UNDER head of RAIL.
2	AVIATION BLVD both TRACKS SUNK, Also Asphalt BROKEN up.

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

G Lam
Track Inspectors Signature

Supervisory Certification

2/8/18
Date

C

Light Rail MOW

Daily Track Inspection

Name G LAM Date 2/7/18 Page ____ of ____

Watchman A RAbette WO# 3278624

Inspection From Linthicum To Cromwell BWI

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.				E/W	104	S308	324		Y	
2.	CM86		1+2	E/W		M305	329		Y	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	2 RAIL BRACES NOT SEATED UNDER head of RAIL.
2	AVIATION BLVD both TRACKS SUNK, Also Asphalt BROKEN up.

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

G Lam
Track Inspectors Signature

Supervisory Certification

2/8/18
Date

C

Light Rail MOW

Daily Track Inspection

Name Michael L Pollard Date 2-7-18 Page 1 of 1

Watchman _____ WO# 3278621

Inspection From Linthicum To Camden yards

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding inspection complete
	No new defects noted in area
	inspection complete

Were switches in area inspected? YES ✓ NO _____

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

Track Inspectors Signature

Supervisory Certification

2/8/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3278621 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Alias:		Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/8/18
Target Finish:	2/8/18
Actual Start:	2/7/18
Actual Finish:	2/7/18
Report Date:	2/3/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48479

Job Plan:	2959
Job Desc:	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278621 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Log

Date	Class	Created By	Subject	Description	Long Description
2/7/18	WORKORDER	MPOLLARD		track inspection	Riding inspection due to inclement weather no new defects noted in the area . Inspection complete

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278621 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
												Total Actual Labor:	210.32

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278621 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	APPR						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name Michael L Pollard Date 2-7-18 Page 1 of 1

Watchman _____ WO# 3278621

Inspection From Listhicum To Camden yards

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding inspection complete
	No new defects noted in area
	inspection complete

Were switches in area inspected? YES ✓ NO _____

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

Track Inspectors Signature

Supervisory Certification

2/8/18
Date

Light Rail MOW

Daily Track Inspection

Name Michael L Pollard Date 2-7-18 Page 1 of 1

Watchman _____ WO# 3278621

Inspection From Listhicum To Camden yards

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding inspection complete
	No new defects noted in area
	inspection complete

Were switches in area inspected? YES ✓ NO _____

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

Track Inspectors Signature

Supervisory Certification

2/8/18
Date

Light Rail MOW

Daily Track Inspection

Name Michael L Pollard Date 2-7-18 Page 1 of 1

Watchman _____ WO# 3278621

Inspection From Linthicum To Camden yards

	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W.O
Items	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ems	Comments
	Riding inspection complete
	no new defects noted in area
	inspection complete

Were switches in area inspected? YES ✓ NO _____

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

[signature] Track Inspectors Signature

[signature] Supervisory Certification

2/8/18 Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330009 Attachment work order TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330009 Attachment work order TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Related Records

WO	Description	Class	Status	Relationship
3278624	Attachment work order TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

C

Light Rail MOW

Daily Track Inspection

Name G LAM Date 2/7/18 Page ____ of ____

Watchman A RAbette WO# 3278624

Inspection From Linthicum To Cromwell BWI

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.				E/W	104	S308	324		Y	
2.	CM86		1+2	E/W		M305	329		Y	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	2 RAIL BRACES NOT SEATED UNDER HEAD of RAIL.
2	AVIATION BLVD both TRACKS SUNK, Also Asphalt BROKEN up.

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

G Lam
Track Inspectors Signature

Supervisory Certification

2/8/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3278624 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/8/18
Target Finish:	2/8/18
Actual Start:	2/7/18
Actual Finish:	2/7/18
Report Date:	2/3/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278624 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Log

Date	Class	Created By	Subject	Description	Long Description
2/7/18	WORKORDER	GLAM		track inspection	switch 104 bwi 2 rail braces not seated properly under head of rail. aviation blvd xing tracks 1=2 sunken and asphalt broken up around crossings.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278624 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Related Records

WO	Description	Class	Status	Relationship
3330009	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278624 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3329971 Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Alias:		Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3329971 **Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S**

Related Records

WO	Description	Class	Status	Relationship
3278621	Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3329971 Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3329971 **Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S**

Related Records

WO	Description	Class	Status	Relationship
3278621	Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3329971 Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3329971 **Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S**

Related Records

WO	Description	Class	Status	Relationship
3278621	Attachment work order TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name Michael L Pollard Date 2-7-18 Page 1 of 1

Watchman _____ WO# 3278621

Inspection From Listhicum To Camden yards

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding inspection complete
	No new defects noted in area
	inspection complete

Were switches in area inspected? YES ✓ NO _____

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

Track Inspectors Signature

Supervisory Certification

2/8/18
Date