Light Rail MOW

Daily Track Inspection

Name Pollard Date 10-19-17 Page 1 of 1

Watchman Lam WO# 3126956

Inspection From Hunt Valley 900+00 To Lutherville 585+00

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.	839+15		0			M305	329	Y	N	
2.					837	S305	322	Y	N	
3.	836+55		1			R301	340	Y	N	
4.	834+50		1			R301	340	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	Premier Pads is down 1 3/4" and is pumping with the rails 5/8" (ppm)
2	1 Loose Frog bolt in the Heel of the Frog.
3	wheel burns on east and west rails starting to break out
4	wheel burns on east and west rails starting to break out
	Inspection complete COPY

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Track Inspector's Signature

Supervisory Certification

10/20/17
Date

Light Rail MOW

Daily Track Inspection

Name S SELL Date 10-19-17 Page ____ of ____

Watchman A RABETE WO# 3126984

Inspection From LAWRENCEVILLE To COLD SPRING

	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W.O
Items	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	NO NEW DEFECTS NOTED IN AREA
	NO CHANGE IN PREVIOUSLY NOTED DEFECTS

COPY

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection S Sell

Track Inspectors Signature

Supervisory Certification

10/20/17
Date

Light Rail MOW

Daily Track Inspection

Name S SELL Date 10-19-17 Page ____ of ____

Watchman A RABETTE WO# 3126984

Inspection From LUTHERVILLE To COLD SPRING

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	NO NEW DEFECTS NOTED IN AREA
	NO CHANGE IN PREVIOUSLY NOTED DEFECTS

COPY

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

S Sell
Track Inspectors Signature

Supervisory Certification

10/20/17
Date

Light Rail MOW

Daily Track Inspection

Name Pollard Date 10-19-17 Page 1 of 1

Watchman Lam WO# 3126956

Inspection From Hunt Valley 900+00 To Lutherville 585+00

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.	839+15		0			M305	329	Y	N	
2.					837	S305	322	Y	N	
3.	836+55		1			R301	340	Y	N	
4.	834+50		1			R301	340	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	Premier Pads is down 1 3/4" and is pumping with the rails 5/8" (approx)
2	1 Loose Frog bolt in the Heel of the Frog.
3	Wheel burns on east and west rails starting to break out
4	Wheel burns on east and west rails starting to break out
	Inspection complete COPY

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Track Inspectors Signature

Supervisory Certification

10/20/17
Date

Light Rail MOW

Daily Track Inspection

Name Pollard Date 10-20-17 Page 1 of 2

Watchman Lam WO#

Inspection From Coldspring N 235+00 To Camden yards S 16+00

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.					70-3	S305	322	Y	N	
2.					70-3	S307	31 P	S	N	
3.	13+05	12+30	2			M306	311	Y	N	
4.	S 12+30		1							
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	1 Loose Frog bolt
2	one Loose nut on rod coming from switch machine, and the rod's shield is missing.
3	Concrete around surrounding running rail deteriorating.
4	Concrete chunk sitting up causing trip hazard
	inspection complete

COPY

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES NO ✓

Reason for Inspection

Track Inspectors Signature

Supervisory Certification

10/23/17
Date

Light Rail MOW

Daily Track Inspection

Name Pollard Date 10 20 17 Page 2 of 2

Watchman Lam WO#

Inspection From Penn Line To

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	No new defects noted
	inspection complete

COPY

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES NO ✓

Reason for Inspection

Track Inspectors Signature

Supervisory Certification

10/23/17
Date

Light Rail MOW

Daily Track Inspection

Name: Billard Date: 10-21-17 Page 1 of 2

Watchman: Lam WO#: 3131656

Inspection From: Lathicum S355+00 To: Cromwell S488+00

Items	Exception Chain Marker No. From	Exception Chain Marker No. To	Track No.	Rail E/W	Switch No.	Codes Comp.	Codes Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	No New defects noted
	Inspection complete

COPY

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Track Inspectors Signature Supervisory Certification 10/23/17 Date

Light Rail MOW

Daily Track Inspection

Name Pollard Date 10-21-17 Page 2 of 2

Watchman Lam WO# 3131656

Inspection From Camp Meade To Thurgood Marshall / BWI

BWI 0+00 BWI 115+0

	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W.O
Items	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	No New defect found
	inspection complete

COPY

Were switches in area inspected? YES ✓ NO ____

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

[signature] Track Inspectors Signature

[signature] Supervisory Certification

10/23/17 Date