MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2677255 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	11/28/16
Target Finish:	11/28/16
Actual Start:	11/28/16
Actual Finish:	11/28/16
Report Date:	11/25/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2677255 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
3330383	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36

Total Actual Labor: 427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2677255 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330383 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attached Work Order)
no new defects noted in area

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330383 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attached Work Order)
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
2677255	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

lame A. Rabette G. Lam Date 11-28-16 Page of
(Please Print)
Watchman A. Rabette G. Lam WO # 2677255

...spected From Hunt Valley To Lutherville

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
tem	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

tem Comments

No New Defects Noted in Area.

'ere switches in the area inspected? Yes ✓ No

this a Special Inspection? Yes No ✓

eason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

11/29/16
Date

COPY

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2679203 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

11/29/16

Riding Inspection due to inclement weather.

No New Noted Defects in Area.

Track Inspection Complete.

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	12/1/16
Target Finish:	12/1/16
Actual Start:	11/29/16
Actual Finish:	11/29/16
Report Date:	11/27/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty	N

Job Plan:	2955
Job Desc:	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2679203 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

11/29/16

Riding Inspection due to inclement weather.

No New Noted Defects in Area.

Track Inspection Complete.

Situation Present?	
PM Num:	48476

Part Failure:

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2679203 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

11/29/16

Riding Inspection due to inclement weather.

No New Noted Defects in Area.

Track Inspection Complete.

Related Records

WO	Description	Class	Status	Relationship
3330396	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		MPOLLAF			GEN	10		N		08:00	00:00	210.32
20	AREPAIR		RNELSOI			GEN	10		N		08:00	00:00	210.32
												Total Actual Labor:	420.64

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2679203 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

11/29/16

Riding Inspection due to inclement weather.

No New Noted Defects in Area.

Track Inspection Complete.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330396 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)

11/29/16

Riding Inspection due to inclement weather.

No New Noted Defects in Area.

Track Inspection Complete.

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-######-000-30-00
Warranty	N

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330396 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)

11/29/16

Riding Inspection due to inclement weather.

No New Noted Defects in Area.

Track Inspection Complete.

Situation Present?	
PM Num:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330396 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)

11/29/16

Riding Inspection due to inclement weather.

No New Noted Defects in Area.

Track Inspection Complete.

Related Records

WO	Description	Class	Status	Relationship
2679203	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Name R. Nelson (Please Print) Date 11-29-16 Page 1 of 1

Watchman M. Pollard WO # 2679203

Inspected From Lutherville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding Inspection due to
	Inclement Weather
	No New Defects Noted in Area

Were switches in the area Inspected? Yes ____ No ✓

Was this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Richard Nelson — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

11/30/16 — Date

COPY

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2678391

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Riding inspection due to inclement weather .

No new defects noted in the area.

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155	344 West North Ave, Baltimore MD			

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	12/1/16
Target Finish:	12/1/16
Actual Start:	11/30/16
Actual Finish:	11/30/16
Report Date:	11/26/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48479

Job Plan:	2959
Job Desc:	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2678391

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Riding inspection due to inclement weather .

No new defects noted in the area.

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2678391

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Riding inspection due to inclement weather .

No new defects noted in the area.

Related Records

WO	Description	Class	Status	Relationship
3330392	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
												Total Actual Labor:	210.32

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2678391

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Riding inspection due to inclement weather .

No new defects noted in the area.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330392

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order)
Riding inspection due to inclement weather .

No new defects noted in the area.

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330392

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order)
Riding inspection due to inclement weather .

No new defects noted in the area.

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330392

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order)
Riding inspection due to inclement weather .

No new defects noted in the area.

Related Records

WO	Description	Class	Status	Relationship
2678391	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Name Billard (Please Print) Date 11-30-2016 Page 1 of 1

Watchman _____ WO # 2678391

Inspected From Linthicum To Camden yards

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection inclement weather
	No new defects noted in area
	Track inspection complete

Were switches in the area inspected? Yes ✓ No _____

Was this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Michael L Ball — Track Inspectors Signature

James Reaver — Supervisory Certification

12/1/16 — Date

COPY

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2678394 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
no new defects noted in area,,rain.

Alias:		Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:		Mileage Meter:		

Sched Start:	
Sched Finish:	
Target Start:	12/1/16
Target Finish:	12/1/16
Actual Start:	11/30/16
Actual Finish:	11/30/16
Report Date:	11/26/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-############-0901-########-######## #### #### ######-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/ BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2678394 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
no new defects noted in area,,rain.

Related Records

WO	Description	Class	Status	Relationship
3330395	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2678394 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

no new defects noted in area,,rain.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330395 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD (Attached Work Order)
no new defects noted in area,,rain.

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155	344 West North Ave, Baltimore MD			

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330395 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD (Attached Work Order)
no new defects noted in area,,rain.

Related Records

WO	Description	Class	Status	Relationship
2678394	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

ame A. Rabette G. Lam Date 11-30-16 Page ____ of ____

(Please Print)

Watchman A. Rabette G. Lam WO # 2678394

...pected From Linthicum To Cromwell – BWI

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
tem	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

tem Comments

Riding Inspection — Rain

ere switches in the area inspected? Yes ____ No ✓

this a Special Inspection? Yes ____ No ✓

eason for Special Inspection? ____

A. Rabette — Track Inspectors Signature

James Reuse — Supervisory Certification

12/1/16 — Date

COPY