MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2707380 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
no new defects noted in area

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	12/22/16
Target Finish:	12/22/16
Actual Start:	12/20/16
Actual Finish:	12/20/16
Report Date:	12/18/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2707380 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
3331666	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2707380 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
no new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331666 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attached Work Order)
no new defects noted in area

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331666 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attached Work Order)
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
2707380	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Name A. Rabette G. Lam Date 12-20-16 Page ____ of ____

(Please Print)

Watchman A. Rabette G. Lam WO # 2707380

Inspected From Coldspring To Camden – Penn

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area.

COPY

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 12/21/16

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2707283 **TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N**

Riding inspection due lack of manpower . Visual inspection done.

Track inspection complete

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: **Description** **Unit of Measure** **Last Reading Date** **Last Reading**

CI: **Mileage Meter:**

Sched Start:	
Sched Finish:	
Target Start:	12/22/16
Target Finish:	12/22/16
Actual Start:	12/20/16
Actual Finish:	12/20/16
Report Date:	12/18/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-#### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48476

Job Plan:	2955
Job Desc:	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2707283

TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Riding inspection due lack of manpower . Visual inspection done.

Track inspection complete

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2707283 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

Riding inspection due lack of manpower . Visual inspection done.

Track inspection complete

Related Records

WO	Description	Class	Status	Relationship
3331665	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
												Total Actual Labor:	210.32

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2707283

TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Riding inspection due lack of manpower . Visual inspection done.

Track inspection complete

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331665 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)
Riding inspection due lack of manpower . Visual inspection done.

Track inspection complete

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331665

TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)
Riding inspection due lack of manpower . Visual inspection done.

Track inspection complete

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331665

TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)
Riding inspection due lack of manpower . Visual inspection done.

Track inspection complete

Related Records

WO	Description	Class	Status	Relationship
2707283	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Name Billord (Please Print) Date 12-20-2016 Page 1 of 1

Watchman _____ WO # 2707283

Inspected From Hunt Valley To Lutherville

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection due to Lockout manpower
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Track Inspectors Signature _____ Supervisory Certification _____ Date 12/21/16

- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2700892 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

12/17/16

Inclement Weather - Ice Storm

No Trains running in the late AM hours, limited service in the PM

Riding Inspection in the PM

No New Defects Noted in Area

Inspection Complete

Alias:		Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	12/21/16
Target Finish:	12/21/16
Actual Start:	12/17/16
Actual Finish:	12/17/16
Report Date:	12/13/16
Reported By:	MTACRON

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-

Job Plan:	2961
Job Desc:	TEAM TWO - SECT 5: LINT/CROM/ BWI CM 355S TO 488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2700892 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

12/17/16

Inclement Weather - Ice Storm

No Trains running in the late AM hours, limited service in the PM

Riding Inspection in the PM

No New Defects Noted in Area

Inspection Complete

Requestor of Work:	

	######## #### #### - ###### -000-30-00
Warranty Situation Present?	N
PM Num:	48481

Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2700892 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

12/17/16

Inclement Weather - Ice Storm

No Trains running in the late AM hours, limited service in the PM

Riding Inspection in the PM

No New Defects Noted in Area

Inspection Complete

Related Records

WO	Description	Class	Status	Relationship
3331625	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		GLAM			GEN	20		N		00:00	11:30	453.50
20	AREPAIR		RNELSOI			GEN	20		N		08:00	03:00	328.63
												Total Actual Labor:	782.13

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2700892 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

12/17/16

Inclement Weather - Ice Storm

No Trains running in the late AM hours, limited service in the PM

Riding Inspection in the PM

No New Defects Noted in Area

Inspection Complete

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor