Name Pollard (Please Print) Date 12-23-2011 Page 1 of 2

Watchman Lam WO # 2705235

Inspected From Coldspring To Camden yard

Penn Line

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	209+80		1	E+W		J301	332	Y	N	
2.					207-36	S305	305	Y	N	
3.	123+50		2			S305	305	Y	N	
4.	123+60		1			S305	305	Y	N	
5.					91-1	S305	305	Y	N	
6.	Pratt and	Howard	1	W		R301	303	R	N	
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	IJ pumping East + west rail
2	New chip in Frog point
3	North Frog in diamond chipped + pitted and has micro Fractures
4	South Frog in diamond area has chunk missing 9" back
	From Point it measures ½" W x ¾" L x ¼" D and has a chunk
	missing From rison (East) measuring 1" L x ¾" W x ⅛" d
5	Chipped area in west rison 1" x 1½" x ⅛"
6	Running rail broke
	Track inspection complete

Were switches in the area inspected? Yes ✓ No ____

COPY

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

[signature] Track Inspectors Signature

James Reaver Supervisory Certification

12/24/16 Date

Name Pollard, Lam (Please Print) Date 12/22/16 Page 2 of 2

Watchman _____ WO # 2705235

Inspected From North Ave Yard To _____

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted in are
	Yard inspection complete

COPY

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Track Inspectors Signature: [signature] Supervisory Certification: [signature] Date: 12/23/16

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2709892 **TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD**

Riding inspection due to inclement weather.

Track inspection complete

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	12/28/16
Target Finish:	12/28/16
Actual Start:	12/24/16
Actual Finish:	12/24/16
Report Date:	12/20/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48481

Job Plan:	2961
Job Desc:	TEAM TWO - SECT 5: LINT/CROM/ BWI CM 355S TO 488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2709892 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Riding inspection due to inclement weather.

Track inspection complete

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2709892 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Riding inspection due to inclement weather.

Track inspection complete

Related Records

WO	Description	Class	Status	Relationship
3331667	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		GLAM				10		N		00:00	08:00	315.48
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
												Total Actual Labor:	525.80

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2709892 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Riding inspection due to inclement weather.

Track inspection complete

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331667 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD (Attached Work Order)
Riding inspection due to inclement weather.

Track inspection complete

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155	344 West North Ave, Baltimore MD			

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331667 **TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD (Attached Work Order)**

Riding inspection due to inclement weather.

Track inspection complete

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331667 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD (Attached Work Order)

Riding inspection due to inclement weather.

Track inspection complete

Related Records

WO	Description	Class	Status	Relationship
2709892	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Name Pollard (Please Print) Date 12-24-2016 Page 1 of 1

Watchman Lom WO # 2709892

Inspected From Linthicum To Cromwell Blvd

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection due to inclement weather
	No New defects noted

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

[signature] Track Inspectors Signature

James Reaver Supervisory Certification

12/25/16 Date