MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331671 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attached Work Order)
no new defects noted in area

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331671 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attached Work Order)
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
2713860	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

ıme A. Rabette G. Lam Date 12-26-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2713860

ected From Hunt Valley To Lutherville

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
em	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
0.										
1.										
2.										

em Comments

No New Defects Noted in Area.

COPY

ıre switches in the area inspected? Yes ✓ No ____

his a Special Inspection? Yes ____ No ✓

ason for Special Inspection? ____

Track Inspectors Signature

Supervisory Certification

12/27/16
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2715649 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
no new defects noted in area

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	12/29/16
Target Finish:	12/29/16
Actual Start:	12/27/16
Actual Finish:	12/27/16
Report Date:	12/25/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2715649 **TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
3331690	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36

Total Actual Labor: 427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2715649 **TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**
no new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331690 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attached Work Order)
no new defects noted in area

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## ####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331690 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attached Work Order)
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
2715649	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

ıme A. Rabette G. Lam Date 12-27-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 271-~~3901~~ 5649

ɔected From Coldspring To Camden - Penn

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
em	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
0.										
1.										
2.										

em Comments

No New Defects Noted in Area.

COPY

ıre switches in the area inspected? Yes ✓ No ____

ıis a Special Inspection? Yes ____ No ✓

ason for Special Inspection? ____

Track Inspectors Signature

Supervisory Certification

12/28/16
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2714945 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
no new defects noted in area

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: **Description** **Unit of Measure** **Last Reading Date** **Last Reading**

CI: **Mileage Meter:**

Sched Start:	
Sched Finish:	
Target Start:	12/29/16
Target Finish:	12/29/16
Actual Start:	12/28/16
Actual Finish:	12/28/16
Report Date:	12/24/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2714945 **TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD**
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
3331687	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		GLAM						N		08:00	00:00	210.32
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2714945 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
no new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

ıme A. Rabette G. Lam Date 12-28-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2714945

ected From Linthicum To Cromwell – BWI

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
am	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
0.										
1.										
2.										

em Comments

No New Defects Noted in Area.

COPY

re switches in the area inspected? Yes ✓ No ____

his a Special Inspection? Yes ____ No ✓

ison for Special Inspection? ____

A. Rabette
Track Inspectors Signature

James Reaver
Supervisory Certification

12/29/16
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331686 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order) inspection complete.

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331686 **TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order) inspection complete.**

Related Records

WO	Description	Class	Status	Relationship
2714942	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

ıme A. Rabette G. Lam Date 12-28-16 Page ____ of ____

(Please Print)

Watchman A. Rabette G. Lam WO # 2714942

ected From Camden To Linthicum

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
em	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
0.										
1.										
2.										

em Comments

Riding Inspection

COPY

ıre switches in the area inspected? Yes ____ No ✓

his a Special Inspection? Yes ____ No ✓

ason for Special Inspection? ____

Arthur Rabette — Track Inspectors Signature

James Reaver — Supervisory Certification

12/29/16 — Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2713857 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
riding inspection -rain

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	12/29/16
Target Finish:	12/29/16
Actual Start:	12/29/16
Actual Finish:	12/29/16
Report Date:	12/23/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48473

Job Plan:	2954
Job Desc:	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2713857 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
riding inspection -rain

Related Records

WO	Description	Class	Status	Relationship
3331670	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2713857 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
riding inspection -rain

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331670 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)
riding inspection -rain

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331670 **TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)**
riding inspection -rain

Related Records

WO	Description	Class	Status	Relationship
2713857	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

ıme A. Rabette G. Lam Date 12-29-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2713857

ɔected From Lutherville To Coldspring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
em	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
0.										
1.										
2.										

em Comments

Riding Inspection — Rain

COPY

re switches in the area inspected? Yes ____ No ✓

ıis a Special Inspection? Yes ____ No ✓

ıson for Special Inspection? ____

Track Inspectors Signature

Supervisory Certification

12/30/16
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2720149 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD

12/30/16

Switch # 207-3B, Trk2 = Frog point is cracked and chipped.

CM 071+70N, Trk 2, east rail = Chip in the north frog of the diamond at Mount Royal has another piece of metal missing measuring 1-1/2" long X 1/4" wide X 1/16" deep. Frog point is also severely battered, needs welding ASAP.

CM 010+50, Trk 1, west rail = Running rail BROKEN at Howard and Pratt streets. A chunk of metal is missing out of the head of the rail measuring 2" wide X 1/2" long X 1/2" deep.

Switch # 16-1B, Trk 1 = Head block tie (wood) is burnt from a switch fire.

CM PL 006+30 - PL 006+50, east rail = Gage in area is wide, up to 57-3/8 of an inch.

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading

CI: **Mileage Meter:**

Sched Start:	
Sched Finish:	
Target Start:	1/6/17
Target Finish:	1/6/17
Actual Start:	12/30/16
Actual Finish:	12/30/16

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527

Job Plan:	2957
Job Desc:	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD
Supervisor:	
Lead:	JREAVES3
Owner:	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Report Date:	12/30/16
Reported By:	MTACRON
Requestor of Work:	

GL Account:	J05-#####-05270-##########-0901-########-######## ####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48478

Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2720149 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD

12/30/16

Switch # 207-3B, Trk2 = Frog point is cracked and chipped.

CM 071+70N, Trk 2, east rail = Chip in the north frog of the diamond at Mount Royal has another piece of metal missing measuring 1-1/2" long X 1/4" wide X 1/16" deep. Frog point is also severely battered, needs welding ASAP.

CM 010+50, Trk 1, west rail = Running rail BROKEN at Howard and Pratt streets. A chunk of metal is missing out of the head of the rail measuring 2" wide X 1/2" long X 1/2" deep.

Switch # 16-1B, Trk 1 = Head block tie (wood) is burnt from a switch fire.

CM PL 006+30 - PL 006+50, east rail = Gage in area is wide, up to 57-3/8 of an inch.

Related Records

WO	Description	Class	Status	Relationship
3331692	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		GLAM			GEN	10	N		00:00	08:00	315.48
20	AREPAIR		RNELSOI			GEN	10	N		08:00	00:00	210.32
											Total Actual Labor:	525.80

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2720149 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD

12/30/16

Switch # 207-3B, Trk2 = Frog point is cracked and chipped.

CM 071+70N, Trk 2, east rail = Chip in the north frog of the diamond at Mount Royal has another piece of metal missing measuring 1-1/2" long X 1/4" wide X 1/16" deep. Frog point is also severely battered, needs welding ASAP.

CM 010+50, Trk 1, west rail = Running rail BROKEN at Howard and Pratt streets. A chunk of metal is missing out of the head of the rail measuring 2" wide X 1/2" long X 1/2" deep.

Switch # 16-1B, Trk 1 = Head block tie (wood) is burnt from a switch fire.

CM PL 006+30 - PL 006+50, east rail = Gage in area is wide, up to 57-3/8 of an inch.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331692 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD (Attached Work Order)

12/30/16

Switch # 207-3B, Trk2 = Frog point is cracked and chipped.

CM 071+70N, Trk 2, east rail = Chip in the north frog of the diamond at Mount Royal has another piece of metal missing measuring 1-1/2" long X 1/4" wide X 1/16" deep. Frog point is also severely battered, needs welding ASAP.

CM 010+50, Trk 1, west rail = Running rail BROKEN at Howard and Pratt streets. A chunk of metal is missing out of the head of the rail measuring 2" wide X 1/2" long X 1/2" deep.

Switch # 16-1B, Trk 1 = Head block tie (wood) is burnt from a switch fire.

CM PL 006+30 - PL 006+50, east rail = Gage in area is wide, up to 57-3/8 of an inch.

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:		**Site:**	LTRAIL	**Job Plan:**	
Sched Finish:		**Priority:**	1	**Job Desc:**	
Target Start:		**Work Type:**	LOG	**Supervisor:**	
Target Finish:		**Status:**	WAPPR	**Lead:**	JREAVES3
Actual Start:		**Parent:**		**Owner:**	
Actual Finish:		**Person Group:**	MTA527	**Owner Group:**	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Report Date:	3/16/18
Reported By:	TSAVAGE
Requestor of Work:	

GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331692 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD (Attached Work Order)

12/30/16

Switch # 207-3B, Trk2 = Frog point is cracked and chipped.

CM 071+70N, Trk 2, east rail = Chip in the north frog of the diamond at Mount Royal has another piece of metal missing measuring 1-1/2" long X 1/4" wide X 1/16" deep. Frog point is also severely battered, needs welding ASAP.

CM 010+50, Trk 1, west rail = Running rail BROKEN at Howard and Pratt streets. A chunk of metal is missing out of the head of the rail measuring 2" wide X 1/2" long X 1/2" deep.

Switch # 16-1B, Trk 1 = Head block tie (wood) is burnt from a switch fire.

CM PL 006+30 - PL 006+50, east rail = Gage in area is wide, up to 57-3/8 of an inch.

Related Records

WO	Description	Class	Status	Relationship
2720149	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor