TRACK INSPECTION REPORTING FORM

Name J. Greenwood Date 09/23/2013 Page 1 of 1

(Please Print)

Watchman R Nelson W.O Number 1226137

Inspected From Huntvalley To Luthervill

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	No new defects noted in area.

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes ✓ NO _____

SPECIAL INSPECTION Yes_____ NO_____

Reason for special Inspection ? _____

Woodrow Greenwood

Track Inspector Signature

Supervisory Cretification

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

BMXAA4591E - Status change(s) completed successfully.

Find: Select Action

Quick Reporting Specifications

Work Order	1226137	TEAM ONE - SECT 1: HV/LU - CM 902N TO	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type*	PM	
Location	CHAIN_MARKI	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group*	MTA527		Maintenance Alert?		

Work Details

Component		Total Planned Cost	0.00	
Position		Total Actual Cost	420.64	
Reason for Repair		Repair Limit Amount		
Work Accomplished		Reported By	MTACRON	
Part Failure		Reported Date	09/20/13 03:30:59 AM	
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-#####-052			

Asset Details

Primary Meter

Multiple Assets,Locations and Cfs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

Labor Materials Tools Failure Reporting

Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	WGREENWOOD	☑	09/23/13	07:00:00 /	03:00:00 F	8:00		26.29	N	N/A
	RNELSON1	☑	09/23/13	07:00:00 /	03:00:00 F	8:00		26.29	N	N/A

TRACK INSPECTION REPORTING FORM

Name W Greenwood Date 09/24/2013 Page 1 of 1

(Please Print)

Watchman R Nelson W.O Number 1228005

Inspected From Coldspring To Camden

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
1	Broken rail at south high block Lexington market station is expanding and contracting with weather changes.
2	Concrete barrier at chain marker 62 south next to track one is leaning towards track

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** ____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes ____ NO ✓

SPECIAL INSPECTION Yes ____ NO ✓

Reason for special Inspection ? ____

Woodrow Greenwood

Track Inspector Signature

Supervisory Cretification ____

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1228005	TEAM ONE - SECT 3: CS/CY/PENN - CM 23	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP
Asset			Priority	1
Alias			Work Type*	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	
Work Location			Warranty Situation Present?	N
Work Group*	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	09/22/13 03:23:36 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-#####-052		

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	RNELSON1	☑	09/24/13	07:00:00 A	03:00:00 P	8:00		26.29	N	N/A
	WGREENWOOD	☑	09/24/13	07:00:00 A	03:00:00 P	8:00		26.29	N	N/A

Save Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name T SCHISLER, W BRYANT (Please Print) Date 9/24/2013 Page 1 of 1

Watchman G LAM W.O Number 1227922

Inspected From LUTHERVILLE To COCA SPRING

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.	556+25N			1	BOTH	—	W 301	332	Y	
2.	556+25N			2	BOTH	—	W 301	332	Y	
3.	545+90N			1	BOTH	—	W 301	332	Y	
4.	491+85N			2	BOTH	—	W 301	332	Y	
5.	458+40N	457+15N		2	BOTH	—	W 301	316	Y	
6.										
7.										
8.										
9.										

Item	COMMENTS
1	SEMINARY X-ING, SOUTH END #1 TRACK, 6 TIES PUMPING 3/4" UNDERLOAD
2	SEMINARY X-ING, SOUTH END #2 TRACK 7 TIES PUMPING 1/2" UNDERLOAD
3	BRIDGE APPROACH NORTH END, PUMPING 1/2" UNDERLOAD, 6 TIES
4	9 TIES IN A ROW, PUMPING 3/4" UNDERLOAD, ALSO SMALL SINKHOLE STARTING
	EAST RAIL, BOTTOM OF BERM

Were Switch in the area of Inspected ***Yes*** X ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO X

SPECIAL INSPECTION Yes_____ NO X

Reason for special Inspection ? _____

Track Inspector Signature Supervisory Cretification_____

Thomas J Schisler

Quick Reporting (Tr)

Bulletins (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order 1227922 TEAM TWO - SECT 2: LU/CS - CM 586N TO
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARKI LT Rail Chain Markers
Work Location
Work Group * MTA527

Site LTRAIL
Status APPR
Priority 1
Work Type * PM
Crew
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-#####-052

Total Planned Cost 0.00
Total Actual Cost 630.96
Repair Limit Amount
Reported By MTACRON
Reported Date 09/22/13 03:21:22 AM

Asset Details
Primary Meter
Multiple Assets,Locations and CIs Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task *	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	APPR
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	APPR

New Row

Labor Materials Tools Failure Reporting

Filter 1 - 3 of 3 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	GLAM	✓	09/24/13	06:00:00 A	02:00:00 F	8:00		26.29	N	N/A
	WBRYANT	✓	09/24/13	06:00:00 A	02:00:00 F	8:00		26.29	N	N/A
	TSCHISLER	✓	09/24/13	06:00:00 A	02:00:00 F	8:00		26.29	N	N/A

Labor

Task
Labor * GLAM Garey Lam
Regular Hours * 8:00
Component
Position
Reason for Repair
Work Accomplished
Part Failure
Memo

Start Date * 09/24/13
Start Time * 06:00:00 A
End Date 09/24/13
End Time 02:00:00 F
Rate * 26.29
Line Cost 210.32
Type * WORK

Warranty? N
Qualification Met? N/A
Approved? ✓
Timer Status
Craft * AREPAIR
Skill Level

Outside Labor
Outside?
Vendor
Contract
Revision

Premium Pay
Premium Pay Code
Premium Pay Hours
Premium Pay Rate
Premium Rate Type

Charge Information
GL Debit Account J05-#####-052
GL Credit Account
Location CHAIN_MARKI
Asset
Alias
Recorded as Received

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name G LAM Date 9/25/13 Page 1 of 1

(Please Print)

Watchman BRYANT W.O Number 1227272

Inspected From Linthicum To CAMDEN

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.	188	184	SAME	2	W	-	R305	303	Y	N
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	1 CM 184 THERE ARE 7 BROKEN BOLTS THAT hold BRACE
	TO TIE AND VARIOUS OTHER BROKEN BOLTS. HOWEVER
	THESE ARE 7 IN ROW.

Were Switch in the area of Inspected ***Yes*** _____ ***NO*** ✓

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes ✓ NO _____

SPECIAL INSPECTION Yes _____ NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

G Lam

Supervisory Cretification

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1227272	TEAM TWO - SECT 4: CY/LINT - CM 16S TC	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type *	PM	
Location	CHAIN_MARKI	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group *	MTA527		Maintenance Alert?		

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	0.00
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	09/21/13 03:36:05 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-#####-052		

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	WBRYANT	✓	09/25/13	05:00:00 A		0:00		26.29	N	N/A
	GLAM	✓	09/25/13	05:00:00 A		0:00		26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name W Greenwood Date 09/25/2013 Page 1 of 1

(Please Print)

Watchman _____ W.O Number 1227275

Inspected From Linthicum To BWI Cromwell

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	No new defects noted in area.

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

Wardlaw Greenwood

Track Inspector Signature

Supervisory Cretification [signature]

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1227275	TEAM ONE - SECT 5 - CM 355S/488S AND	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	CLOSE	
Asset			Priority	1	
Alias			Work Type	PM	
Location	CHAIN_MARK	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group	MTA527		Maintenance Alert?		

Work Details

Component			Total Planned Cost	0.00
Position			Total Actual Cost	210.32
Reason for Repair			Repair Limit Amount	
Work Accomplished			Reported By	MTACRON
Part Failure			Reported Date	09/21/13 03:36:07 AM
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-#####-052			

Asset Details

Primary Meter

Multiple Assets,Locations and Cls Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	CLOSE
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	CLOSE

New Row

Labor Materials Tools Failure Reporting

Filter 1 - 1 of 1 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	WGREENWOOD	✓	09/25/13	07:00:00 A	03:00:00 P	8:00		26.29	N	N/A

Batch Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name G. LAM BRYANT Date 9/26/2013 Page 1 of 1

(Please Print)

Watchman BYRD W.O Number 1226127

Inspected From HV To Lutherville

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	NO NEW DEFECTS NOTED IN AREA.

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

Track Inspector Signature

G Lam

Supervisory Cretification_____

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order 1226127 TEAM TWO - SECT 1: HV/LU - CM 902N TO
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARKI ILT Rail Chain Markers
Work Location
Work Group * MTA527

Site LTRAIL
Status COMP
Priority 1
Work Type * PM
Crew
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-#####-052

Total Planned Cost 0.00
Total Actual Cost 420.64
Repair Limit Amount
Reported By MTACRON
Reported Date 09/20/13 03:30:50 AM

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	WBRYANT	✓	09/26/13	05:00:00 A	01:00:00 F	8:00		26.29	N	N/A
	GLAM	✓	09/26/13	05:00:00 A	01:00:00 F	8:00		26.29	N	N/A

Labor

Task
Labor * WBRYANT Walter Bryant
Regular Hours * 8:00
Component
Position
Reason for Repair
Work Accomplished
Part Failure
Memo

Start Date * 09/26/13
Start Time * 05:00:00 A
End Date 09/26/13
End Time 01:00:00 F
Rate * 26.29
Line Cost 210.32
Type * WORK

Warranty? N
Qualification Met? N/A
Approved? ✓
Timer Status
Craft * AREPAIR
Skill Level

Outside Labor

Outside?
Vendor
Contract
Revision

Premium Pay

Premium Pay Code
Premium Pay Hours
Premium Pay Rate
Premium Rate Type

Charge Information

GL Debit Account J05-#####-052
GL Credit Account
Location CHAIN_MARKI
Asset
Alias
Recorded as Received

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name W Greenwood Date 09/26/2013 Page 1 of 1

(Please Print)

Watchman R Nelson W.O Number 1226134

Inspected From Lutherville To Coldspring

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	No new defects noted in area.

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

Woodrow Greenwood

Track Inspector Signature

Supervisory Cretification M Boyt

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1226134	TEAM ONE - SECT 2: LU/CS - CM 586N TO	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type*	PM	
Location	CHAIN_MARK	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group*	MTA527		Maintenance Alert?		

Work Details

Component			Total Planned Cost	0.00
Position			Total Actual Cost	210.32
Reason for Repair			Repair Limit Amount	
Work Accomplished			Reported By	MTACRON
Part Failure			Reported Date	09/20/13 03:30:56 AM
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-#####-052			

Asset Details

Primary Meter

Multiple Assets,Locations and Cis Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Filter 1 - 1 of 1 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	WGREENWOOD	☑	09/26/13	07:00:00 A	03:00:00 P	8:00		26.29	N	N/A

Save Labor Add Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name W Greenwood Date 09/7 2013 Page 1 of 1

Watchman (Please Print) D Byrd W.O Number 1226063

Inspected From Linthicum To Camden

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	No new defects noted in area

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

Woodrow Greenwood

Track Inspector Signature

Supervisory Cretification M Boyle

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1226063	TEAM ONE - SECT 4: CY/LINT - CM 16S TC	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type*	PM	
Location	CHAIN_MARK	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group*	MTA527		Maintenance Alert?	☐	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	210.32
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	09/20/13 03:29:58 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-#####-052		

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Filter 1 - 1 of 1 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	WGREENWOOD		09/27/13	07:00:00 A	03:00:00 P	8:00		26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORTING FORM

Name G LAM (Please Print) Date 9/27/13 Page 1 of 2

Watchman W BRYANT W.O Number 1225948

Inspected From CS To CAMDEN PENN

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	NO NEW Defects NOTED IN AREA

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** ____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes____ NO ✓

SPECIAL INSPECTION Yes____ NO ✓

Reason for special Inspection ? ____

G Lam

Track Inspector Signature

Supervisory Cretification

TRACK INSPECTION REPORTING FORM

Name G LAM (Please Print) Date 9/27/2013 Page 2 of 2

Watchman BRYANT W.O Number 1225948

Inspected From N/AVE YD To

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	NO Defects noted in YD

Were Switch in the area of Inspected ***Yes*** ✓ ***NO***

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

G Lam

Track Inspector Signature

Supervisory Cretification_____

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1225948	TEAM TWO - SECT 3 - CM 235N/16S AND	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type*	PM	
Location	CHAIN_MARKI	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group*	MTA527		Maintenance Alert?		

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	09/20/13 03:28:31 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-#####-052		

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

Labor Materials Tools Failure Reporting

Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	WBRYANT	☑	09/27/13	05:00:00 /	01:00:00 F	8:00		26.29	N	N/A
	GLAM	☑	09/27/13	05:00:00 /	01:00:00 F	8:00		26.29	N	N/A

Select Labor Add Planned Labor Delete Row

TRACK INSPECTION REPORTING FORM

Name G. LAM (Please Print) Date 9/28/2013 Page 1 of 1

Watchman BRYANT W.O Number 1226074

Inspected From LINTICUM To CROMWELL BWI

Item	Exception Chain Marker No. From	To	W.O. Number	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	NO NEW DEFECTS NOTED IN AREA

Were Switch in the area of Inspected ***Yes*** ✓ ***NO*** _____

Were all single operating mechanism & conecting rod type switches inside area and operatated in each position ?

Yes_____ NO ✓

SPECIAL INSPECTION Yes_____ NO ✓

Reason for special Inspection ? _____

G Lam

Track Inspector Signature

Supervisory Cretification

Quick Reporting (Tr)

Bulletins: (1) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

Quick Reporting Specifications

Work Order	1226074	TEAM TWO - SECT 5: LINT/CROM - CM 355	Site	LTRAIL	
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	COMP	
Asset			Priority	1	
Alias			Work Type*	PM	
Location	CHAIN_MARK	LT Rail Chain Markers	Crew		
Work Location			Warranty Situation Present?	N	
Work Group*	MTA527		Maintenance Alert?	☐	

Work Details

Component			Total Planned Cost	0.00
Position			Total Actual Cost	420.64
Reason for Repair			Repair Limit Amount	
Work Accomplished			Reported By	MTACRON
Part Failure			Reported Date	09/20/13 03:30:08 AM
Parent WO				
Telematics Code				
Telematics Transaction				
GL Account	J05-#####-052			

Asset Details

Primary Meter

Multiple Assets,Locations and CIs Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

Labor Materials Tools Failure Reporting

Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	WBRYANT	☑	09/28/13	06:00:00 /	02:00:00 F	8:00		26.29	N	N/A
	GLAM	☑	09/28/13	06:00:00 /	02:00:00 F	8:00		26.29	N	N/A

Save Labor Select Planned Labor New Row