TRACK INSPECTION REPORT

Name Mike Akhir (Please Print) Date 10-1-14 Page 1 of 1

Watchman B Dawes Ka WO # 1653461

Inspected From Linthicum To Cromwell / BW1

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	BW 20		1			312	311	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Erosion of West Bank / Small Sinkhole developing.

Were switches in the area inspected? Yes Y No

Is this a Special Inspection? Yes No Y

Reason for Special Inspection?

[signature] Track Inspectors Signature

[signature] Supervisory Certification

10-1-14 Date

COPY

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 10/1/2014 Page 1 OF 1

Watchman W BRYANT WO # 1653458

Inspected From LINTHICUM To CAMDEN

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	36+61^{S}		1	BOTH	—	W301	332	Y		
2.	33+90^{S}		1	BOTH	—	W301	332	Y		
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	7 TIES IN A ROW, PUMPING 5/8" UNDERLOAD
2	10 TIES IN A ROW, PUMPING 3/4" UNDERLOAD

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M. Boyle — Supervisory Certification

10-1-14 — Date

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 10/2/14 Page 1 of 1

Watchman W BRYANT WO # 1661775

Inspected From HUNT VALLEY To LUTHERVILLE

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	898+20"		2	BOTH	—	M305	348	Y		
2.	886+10"		0	BOTH	—	M305	348	Y		
3.	865+11"		0	BOTH	—	W301	332	Y		
4.	858+00"		0	BOTH	—	W301	332	Y		
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	FLANGEWAY NEEDS TO BE CLEANED OUT OF DEBRIS (SCHWAIN RD X-ING)
2	FLANGEWAY NEEDS TO BE CLEANED OUT OF DEBRIS (SCHILLING & McCORMICK)
3	NORTH OF 141 BLOCK McCORMICK STA, 14 ties in a row PUMPING 9/16" UNDERLOAD
4	PUMPING 5/8" UNDERLOAD, 17 ties IN A ROW

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler

Track Inspectors Signature Supervisory Certification Date

COP

TRACK INSPECTION REPORT

Name Mike Atchin (Please Print) Date 10-2014 Page 1 of 1

Watchman B. Pawuska WO # 1652342

Inspected From Litterville To Cord Spring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	299 N	290 N	2	W		R301	344	Y	N	
2.	310 N	304 N	2	E		R301	344	Y	N	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Side Worn Rail
2	Side worn Rail

COPY

Were switches in the area inspected? Yes Y No

Is this a Special Inspection? Yes No Y

Reason for Special Inspection?

Track Inspectors Signature Supervisory Certification Date

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 10/3/14 Page 1 of 3

Watchman W BRYANT WO # 1661717

Inspected From COLD SPRING To CAMDEN

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

T Schisler

Track Inspectors Signature Supervisory Certification Date

COPY

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 10/4/14 Page 1 OF 2

Watchman W BRYANT WO # 1652363

Inspected From CROKIWELL To LINTHICUM

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION DUE TO RAIN
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler

Track Inspectors Signature Supervisory Certification Date

COPY

TRACK INSPECTION REPORT

Name Mike Atkin (Please Print) Date 10-5-14 Page 1 of 1

Watchman W. Bryant WO # 1661799

Inspected From Camden To Lakhimani

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS

Were switches in the area inspected? Yes X No ____

Is this a Special Inspection? Yes ____ No X

Reason for Special Inspection? ____

[signature] Track Inspectors Signature

Supervisory Certification

Date

COP

TRACK INSPECTION REPORT

Name Brandon Panuska (Please Print) Date 10/6/14 Page 1

Watchman Mike Alchin WO # 661755

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	no new deffects

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature Supervisory Certification 10.6.14 Date

COPY

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 10-07-14 Page 1

Watchman T. Schisler WO # 1663557

Inspected From Lutherville To Coldspring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection completed - No new defect's noted in area.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant
Track Inspectors Signature

Supervisory Certification

Date

TRACK INSPECTION REPORT

Name Brandon Panuske (Please Print) Date 10-7-14 Page 1

Watchman Mike Alcine WO # 1663580

Inspected From Cold Spring To Camden Yards

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new deffects

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature Supervisory Certification 10.7.14 Date

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 10-08-14 Page 1

Watchman T. Schisler WO # 1662915

Inspected From Camden To Linthicum

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection Completed - No new defect's
	noted in area.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant

Track Inspectors Signature

Supervisory Certification

Date

COPY

TRACK INSPECTION REPORT

Name Brandon Ranuskin Mike Alchin Date 10·8·14 Page 1
(Please Print)
Watchman Mike Alchin WO # 662918

Inspected From Linthicum To cromwell

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new deffects

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

[signature] ____ 10·8·14

Track Inspectors Signature Supervisory Certification Date

COP

TRACK INSPECTION REPORT

Name Brandon Panuslsca (Please Print) Date 10-9-14 Page 1

Watchman Mike Alchin WO # 661752

Inspected From Lutherville ~~Cold Spring~~ To Cold Spring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	no new defects

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

Date 10-9-14

COPY

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 10-09-14 Page 1

Watchman _____ WO # 1668707

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection - Track inspection Completed
	No new defect's noted in area

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Walter W. Bryant _____ _____

Track Inspectors Signature Supervisory Certification Date

COPY

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 10-10-14 Page 1

Watchman B. Panuska WO # 166867

Inspected From Coldspring To Camden

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	83+00-N	—	2	E	—	R-305	322	Y	N	
2.	90+00-N	—	2	E/W	—	W-391	303	Y	N	
3.			2		91-1	S-307	301-302	R	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	At Cm 83+00-N Tk 2. The joint in the U-69 Restraining rail is loose. Need 4 new bolts.
	At Cm 90+00-N, Tk 2. Two Vossloh Anchor are broken & 6 mono block ties have damage to the top of the ties. (broken Concrete).
3	Switch - 91-1 - North Track 2. The switch stand was damage. The handle is bent. Also the keeper N 1 tie was damage.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant
Track Inspectors Signature

Supervisory Certification

Date

COPY

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 10-11-14 Page 1

Watchman G. LAM WO # 1661796

Inspected From Linthicum To Cromwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection - Due to inclement weather. (Rain)
	Track inspection Completed
	No new defect's noted in area.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant

Track Inspectors Signature

Supervisory Certification

Date

COPY

TRACK INSPECTION REPORT

Name Mike Alchin (Please Print) Date 10-12-14 Page 1 of 1

Watchman B Panucke WO # 1668713

Inspected From Camden Yards To Linthicum

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects

Were switches in the area inspected? Yes X No ____

Is this a Special Inspection? Yes ____ No X

Reason for Special Inspection? ____

[signature] ____ ____

Track Inspectors Signature Supervisory Certification Date

COPY

TRACK INSPECTION REPORT

Name Mike Alchin (Please Print) Date 10-13-14 Page 1 of 1

Watchman Brandon Panuska WO # 1668702

Inspected From Hunt Valley To Lutherville

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

Date

COPY

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 10-15-14 Page 1

Watchman _____ WO # 1669719

Inspected From Camden To Linthicum

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection. inclement weather (Rain)
	Track inspection completed. No new defect's
	noted in area.

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Walter W. Bryant — Track Inspectors Signature

M. Boyd — Supervisory Certification

10-15-14 — Date

COPY

TRACK INSPECTION REPORT

Name Mike Alchia (Please Print) Date 10-15-14 Page 1 of 1

Watchman B. Panuska WO # 1669722

Inspected From Linthicum To Cromwell / BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	4325		1	E/W		R301	327	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Both Rails out of Alignment due to Previous Heat Kink. Rail need destressed. Also East rail side worn where Kink exists.

Were switches in the area inspected? Yes Y No

Is this a Special Inspection? Yes No Y

Reason for Special Inspection?

[signature] Track Inspectors Signature

[signature] Supervisory Certification

10-15-14 Date

COPY

TRACK INSPECTION REPORT

Name Brandon Parusker Mike Alchin Date 10/16/14 Page 1
(Please Print)
Watchman Mike Alchin WO # 1668699

Inspected From Lutherville To Cold Spring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO New deffect

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

10/16/14
Date

COPY