TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 11-13-14 Page 1 OF 1

Watchman W BRYANT WO # 1700772

Inspected From LINTHICUM To CAMDEN

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.			1	W	2081A	S304	340	Y		
2.	204+30S		2	E	—	W301	342	Y		
3.			1	E	423A	S304	340	Y		
4.	39+82S		1	BOTH	—	W301	332	Y		
5.	39+82		2	BOTH	—	W301	332	Y		
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	SHELLED LH PT
2	6' FROM END OF TIE, WASHING OUT
3	SHELLED RH PT
4	10 TIES IN A ROW PUMPING, 3/4" UNDERLOAD IN FRONT OF 42 1A SWITCH
5	9 TIES IN A ROW PUMPING 5/8" UNDERLOAD IN FRONT OF 42 3B SWITCH

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

Thomas J Schisler

Track Inspectors Signature Supervisory Certification Date

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 11-13-2013 Page 1 of 1

Watchman D BRYD WO # 1699520

Inspected From HUNT VALLEY To LUTHERVILLE

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✗ No

Is this a Special Inspection? Yes No ✗

Reason for Special Inspection?

T Schisler

Track Inspectors Signature Supervisory Certification Date

TRACK INSPECTION REPORT

Name Mike Alchin (Please Print) Date 11/13/14 Page 1 of 1

Watchman B Panuska WO # 1699492

Inspected From Lutherville To Cold Spring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	310 N	305 N	2	E		R 301	344	Y	N	
2.	300 N	290 N	2	W		R 301	344	Y	N	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Side Worn Rail
2	Side Worn Rail

Were switches in the area inspected? Yes X No ____

Is this a Special Inspection? Yes ____ No X

Reason for Special Inspection? ____

[signature]

Track Inspectors Signature Supervisory Certification Date

CO

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 11-14-14 Page 1 of 3

Watchman W BRYANT WO # 1699477

Inspected From CAMDEN To COLD SPRING

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.			2	BOTH	—	11301	332	Y		
2.			1+2	BOTH	—	11301	348	Y		
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	W PRESTON/PARK AVE AT HOWARD STS., 10 TIES IN A ROW PUMPING 3/4" UNDERLOAD, CONCRETE AT INTERSECTION GETTING RUBBED BY SKIRT OF TRAIN
2	FLANGEWAY NEEDS TO BE CLEANED, AT W PRESTON/PARK AVE AT HOWARD STS.

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler

Track Inspectors Signature Supervisory Certification Date

COP

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 11-14-14 Page 1

Watchman B. Pawuska WO # 1701497

Inspected From Lutherville To Cold Spring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection Completed - No new defect's noted in area.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant

Track Inspectors Signature Supervisory Certification Date

COPY

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 11-15-2014 Page 2 OF 2

Watchman W BRYANT WO # 1699523

Inspected From LINTHICUM To BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	75+25 BW		2	W	—	W301	304/306	[redacted]		
2.	85+00	87+00 BW	1+2	BOTH	—	M305	314	Y		
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	AT BWI BUSINESS PARK CENTER CROSSWALK, #2 TRACK, WEST RAIL, BASE AND WEB OF RAIL CORRODED AND VERY THIN, COULD CAUSE RAIL TO BREAK, NEEDS ATTENTION
2	AT AVIATION & TERMINAL RD X-ING, FLANGEWAY NEEDS CLEANING

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler

Track Inspectors Signature | Supervisory Certification | Date

COF

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 11-16-14 Page 1

Watchman _____ WO # 1706888

Inspected From Camden To Linthicum

Item	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection - Track inspection completed. No defects noted.

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Walter W. Bryant
Track Inspectors Signature

_____
Supervisory Certification

_____
Date

TRACK INSPECTION REPORT

Name Brandon Panuska (Please Print) Date 11/17/14 Page 1

Watchman M. Alchin WO # 706869

Inspected From Hunt Valley To Lutherville

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New defects
	Riding inspection due to rain

Were switches in the area inspected? Yes ____ No ✓

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature Supervisory Certification Date 11-18-14

CO

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 11-18-14 Page 1

Watchman T. Schisler WO # 1708632

Inspected From Lutherville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection completed
	No new defect's noted in area.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant — Track Inspectors Signature

M. Boyle — Supervisory Certification

Date

TRACK INSPECTION REPORT

Name B. Panoskar (Please Print) Date 11/18/14 Page 1

Watchman M. Alchin WO # 708677

Inspected From coldspring To camden / Penn

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO New defects

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature Supervisory Certification Date

COPY

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 11-19-14 Page 1

Watchman T. Schisler WO # 1707992

Inspected From Camden To Linthicum

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection completed
	No defect's noted in area

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant

Track Inspectors Signature

Supervisory Certification

Date

TRACK INSPECTION REPORT

Name B Panuska (Please Print) Date 11/19/14 Page 1

Watchman M. Alchin WO # 1707995

Inspected From Lithicum To Cromwell / BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO New defects

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature Supervisory Certification Date

COPY

TRACK INSPECTION REPORT

Name B. Panuska (Please Print) Date 11/20/14 Page 1

Watchman M. Alchin WO # 1706866

Inspected From Lotherville To coldspring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO New defects

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature Supervisory Certification Date

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 11-20-14 Page 1

Watchman T. Schisler WO# 1706874

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	865+00	866+00	0	E/W	—	M-305	214	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Just North of McCormick Station, Starting at the High block. The flangeway need cleaning out. its foul with debris, hit & pieces of stone.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant

Track Inspectors Signature

Supervisory Certification

Date

CO

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 11-21-14 Page 1

Watchman T. Schisler WO # 706843

Inspected From Camden To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection Completed.
	No defect's noted in area.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant

Track Inspectors Signature Supervisory Certification Date

COPY