Name W. Bryant (Please Print) Date 07-15-14 Page 1 of 1

Watchman _____ WO # 1561763

Inspected From Lutherville To Cold Spring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection - No new defect's noted
	in area. Track inspection Completed.

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Wilson W. Bryant — Track Inspectors Signature

[signature] — Supervisory Certification

07-16-14 — Date

COPY

Name T SCHISLER (Please Print) Date 7/15/2014 Page 2 of 2

Watchman D BYRD WO # 1561819

Inspected From COLD SPRING To CAMDEN

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	107+00N	111+00N	1	W	—	H306	342	Y		
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	EROSSION (NUMEROUS) DIRT + DEBRIS WASHING DOWN FROM CONRAIL'S FUXI FLO

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Supervisory Certification

7-16-14 — Date

COPY

Name T SCHISLER (Please Print) Date 7/16/14 Page 1 of 1

Watchman W BRYANT WO # 1561149

Inspected From CAMDEN To LINTHICUM

Item	Exception Chain Marker No From	To	Track No.	Rail R/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	190+50S		1+2		—	T307	303	Y		
2.	150+00S		1+2	ALL	—	W301	348	Y		
3.	172+25S		1	BOTH	—	W301	332	Y		
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	BETWEEN #1 & #2 TRACKS, BROKEN LID, IN PATAPSCO STATION
2	DEBRIS IN #1 TRACK & BETWEEN #1 & #2 TRACKS
3	10 TIES IN A ROW PUMPING 1½" UNDERGOAD

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M Boyd — Supervisory Certification

7-17-14 — Date

COPY

TRACK INSPECTION REPORT

Name M Alchin (Please Print) Date 7/16/2014 Page 1 of 1

Watchman S Sell WO # 1561152

Inspected From Linthicum To Crowmwell/BWI

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	N/S	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

Michael Alchin
Track Inspectors Signature

Supervisory Certification

7-17-2014
Date

COPY

Work Order Tracking (Tr)

Bulletins (2) Go To Reports Start Center Pro

Work Order Tracking (Tr)

Find: Select Action

List | Work Order | Plans | Actuals | Related Records | Safety Plan | Log | Failure Reporting | Specifications

Attachments

Work Order: 1561152 — TEAM ONE - SECT 5 - CM 355S/488S AND
Classification: MTA \ LTRAIL
Classification Description: MTA - LTRAIL
Asset:
Alias:
Location: CHAIN_MARK — LT Rail Chain Markers
Work Location:
Work Type*: PM
Status: COMP
Status Date: 07/16/14 04:01:44 PM
Reported By: MTACRON
Phone:
Reported Date: 07/12/14 03:57:46 AM
On Behalf Of:

Site: LTRAIL
Failure Class:
Problem Code:
Priority: 1
Asset/Location Priority:
Is Task? ☐
Parent WO:
Warranty Situation Present?: N
Maintenance Alert? ☐
Repair Order? ☐
Has Follow-up Work? ☐
Quick PM? ☐

Asset Details
Year:
Manufacturer:
Model:
Serial #:
Type:
Status:
Asset Condition:

Costs
Total Planned Cost: 0.00
Total Actual Cost: 422.32
Repair Limit Amount:
Current Asset Value:
GL Account: J05-#####-052
Accepts Charges? ☑
Charge to Store? ☐

Multiple Assets,Locations and Cis | Filter

Work Details
Job Plan: 2960 — TEAM ONE - SECT 5 - CM 355S/488S AND
PM: 48480 — TEAM ONE - SECT 5 - CM 355S/488S AND
Component:
Position:
Reason for Repair:
Work Accomplished:
Part Failure:
Warranty?: N
Reference ID:
Telematics Code:
Telematics Transaction:

Scheduling Information
Scheduled Start:
Target Start: 07/17/14 12:00:00 AM
Actual Start: 07/16/14 08:00:00 AM
Scheduled Finish:
Target Finish: 07/17/14 06:00:00 AM
Actual Finish: 07/16/14 02:00:00 PM
Time Remaining:
Duration*: 6:00
Interruptible? ☐
Predecessors:

Primary Meter
New Reading:
New Reading Date:
Meter:

Last Reading:
Last Reading Date:
Primary Reading Entered? ☐
Life To Date:

Responsibility
Supervisor:
Lead:
Crew: DAY-A

Service Group:
Work Group*: MTA527
Vendor:
Service:

TRACK INSPECTION REPORT

ame W. Bryant (Please Print) Date 07-17-14 Page 1 of 1

Watchman T. Schisler WO # 1560078

Inspected From Lutherville To Hunt Valley

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Comments

Item	
1	At CM 608+75 - North TK 2. (Tim Business Pk) the shoulder has started to erode. The area is 30' long & 4' wide. The area is marked on the ties with white arrows.
2	At CM 616+40 - North, TK 2. 7 ties need ballast. The bottom of the ties are showing.
3	At CM 617+75 - North. Clogged drain, with tree branches, leaves & other debris.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant — Track Inspectors Signature

M. Bayne — Supervisory Certification

7-18-14 — Date

COPY

TRACK INSPECTION REPORT

Name M Alchin (Please Print) Date 7/17/2014 Page 1 of 1

Watchman S Sell WO # 1560085

Inspected From Lutherville To Cold Spring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	N/S	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

Michael A Alchin — Track Inspectors Signature

M. Boyle — Supervisory Certificat on

7-17-14 — Date

COPY

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/18/14 Page 1 of 3

Watchman W BRYANT WO # 1559976

Inspected From COLD SPRING To CAMDEN

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M Bark — Supervisory Certification

7-21-14 — Date

COPY

Quick Reporting (Tr)

Bulletins (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order 1559976 TEAM TWO - SECT 3 - CM 235N/16S AND
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARKI LT Rail Chain Markers
Work Location
Work Group* MTA527

Site LTRAIL
Status COMP
Priority 1
Work Type* PM
Crew DAY-B
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-#####-052

Total Planned Cost 0.00
Total Actual Cost 420.64
Repair Limit Amount
Reported By MTACRON
Reported Date 07/11/14 03:29:22 AM

Asset Details
Primary Meter
Multiple Assets,Locations and Cls Filter Download

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER	☑	07/18/14	08:00:00 A	02:00:00 A	8:00		26.29	N	N/A
	WBRYANT	☑	07/18/14	08:00:00 /	02:00:00 F	8:00		26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORT

Name W Bryant (Please Print) Date 07-19-14 Page 1 of 2

Watchman T. Schisler WO # 1567345

Inspected From Linthicum To Cromwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection Completed. No new defect's noted in area.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant — Track Inspectors Signature

M. Brooks — Supervisory Certification

Date

COPY

Quick Reporting (Tr)

Bulletins (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order	1567345 TEAM TWO - SECT 5: LINT/CROM - CM 355	Site	LTRAIL
Classification	MTA \ LTRAIL MTA - LTRAIL	Status	COMP
Asset		Priority	1
Alias		Work Type*	PM
Location	CHAIN_MARKI LT Rail Chain Markers	Crew	DAY-B
Work Location		Warranty Situation Present?	N
Work Group*	MTA527	Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	420.64
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/18/14 03:28:44 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-~~WWW~~-052		

Asset Details

Primary Meter

Multiple Assets,Locations and Cis Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER	✓	07/19/14	08:00:00 A	02:00:00 P	8:00		26.29	N	N/A
	WBRYANT	✓	07/19/14	08:00:00 A	02:00:00 P	8:00		26.29	N	N/A

Select Labor Select Planned Labor New Row

Name S' SELL (Please Print) Date 7-20-14 Page ___ of ___

Watchman ___ WO # 1567342

Inspected From CY To LIN

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	PERFORMED RIDING INSPECTION
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ___

Is this a Special Inspection? Yes ___ No ✓

Reason for Special Inspection? ___

Track Inspectors Signature ___ Supervisory Certification ___ Date 7-21-14

COPY

Work Order Tracking (Tr)

Bulletins: (2) Go To Reports Start Center Profile Sign Out H

Find: Select Action

List Work Order Plans Actuals Related Records Safety Plan Log Failure Reporting Specifications

Work Order 1567342 TEAM ONE - SECT 4: CY/LINT - CM 16S TO Site LTRAIL Status APPR
Asset Alias

Children of Work Order 1567342 Filter Download

Tasks for Work Order 1567342 Filter 1-2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N	NONE	APPR
20	20	INSPECT TRACK PER BALT LR STANDARI			N	NONE	APPR

New Row

Labor Materials Services Tools Repair Orders

Labor Filter 1-1 of 1 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	SSELL	✓	07/20/14	08:00:00	02:00:00	8:00		26.50	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORT

Name S3ELL/M ALCHIN Date 7-21-14 Page ____ of ____
(Please Print)
Watchman M ALCHIN WO # 1567387

Inspected From HV To LUTH

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ____

s this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 7-22-14

COPY

Quick Reporting (Tr)

Bulletins (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order	1567387	TEAM ONE - SECT 1: HV/LU - CM 902N TO	Site	LTRAIL
Classification	MTA \ LTRAIL	MTA - LTRAIL	Status	APPR
Asset			Priority	1
Alias			Work Type*	PM
Location	CHAIN_MARK	LT Rail Chain Markers	Crew	DAY-A
Work Location			Warranty Situation Present?	N
Work Group*	MTA527		Maintenance Alert?	

Work Details

Component		Total Planned Cost	0.00
Position		Total Actual Cost	422.32
Reason for Repair		Repair Limit Amount	
Work Accomplished		Reported By	MTACRON
Part Failure		Reported Date	07/16/14 03:31:44 AM
Parent WO			
Telematics Code			
Telematics Transaction			
GL Account	J05-#####-052		

Asset Details

Primary Meter

Multiple Assets,Locations and Cis | Filter | Download

Tasks | Filter | 1 - 2 of 2 | Download

Sequence	Task *	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	APPR
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	APPR

New Row

Labor Materials Tools Failure Reporting

Labor | Filter | 1 - 2 of 2 | Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	MALCHIN	☑	07/21/14	08:00:00 A	02:00:00 F	8:00		26.29	N	N/A
	SSELL	☑	07/21/14	08:00:00 /	02:00:00 F	8:00		26.50	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORT

Name S SELL/M ALCHIN (Please Print) Date 7-22-14 Page ___ of ___

Watchman M ALCHIN WO # 1569263

Inspected From CS To CY/PENN

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	CM 90 W SWITCH 88-3A EAST SIDE SWITCH PT HAS 6" BY 1/4" piece chipping out

ere switches in the area inspected? Yes ✓ No ___

this a Special Inspection? Yes ___ No ✓

eason for Special Inspection? ___

Track Inspectors Signature

M. Boyle
Supervisory Certification

7-22-14
Date

COPY

Quick Reporting (Tr)

Bulletins: (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order 1569283 TEAM ONE - SECT 3: CS/CY/PENN - CM 23
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARKI LT Rail Chain Markers
Work Location
Work Group* MTA527

Site LTRAIL
Status APPR
Priority 1
Work Type* PM
Crew DAY-A
Warranty Situation Present? N
Maintenance Alert?

Work Details
Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-#####-052

Total Planned Cost 0.00
Total Actual Cost 422.32
Repair Limit Amount
Reported By MTACRON
Reported Date 07/20/14 03:30:09 AM

Asset Details
Primary Meter
Multiple Assets,Locations and Cis Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	APPR
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	APPR

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	MALCHIN	✓	07/22/14	08:00:00 A	02:00:00 F	6:00		26.29	N	N/A
	SSELL	✓	07/22/14	08:00:00 A	02:00:00 F	6:00		26.50	N	N/A

Select Labor Select Planned Labor New Row