Name W. Bryant (Please Print) Date 07-22-14 Page 1 of 1

Watchman T. Schisler WO # 1569245

Inspected From Lutherville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection completed - No new defects
	noted in area.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant — Track Inspectors Signature

M Bayer — Supervisory Certification

7-22-14 — Date

COPY

Quick Reporting (Tr)

Bulletins (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order 1569245 TEAM TWO - SECT 2: LU/CS - CM 586N TO
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARKI LT Rail Chain Markers
Work Location
Work Group* MTA527

Site LTRAIL
Status APPR
Priority 1
Work Type* PM
Crew DAY-B
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-[redacted]-052

Total Planned Cost 0.00
Total Actual Cost 420.64
Repair Limit Amount
Reported By MTACRON
Reported Date 07/20/14 03:28:35 AM

Asset Details
Primary Meter
Multiple Assets,Locations and Cis Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	APPR
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	APPR

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER	✓	07/22/14	08:00:00 /	02:00:00 F	8:00		26.29	N	N/A
	WBRYANT	✓	07/22/14	08:00:00 /	02:00:00 F	8:00		26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORT

Name S SELL / M ALCHIN (Please Print) Date 7-23-14 Page ____ of ____

Watchman M ALCHIN WO # 1568622

Inspected From LIN To Crom

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 7-28-14

COPY

TRACK INSPECTION REPORT

Name S SELL / M ALCHIN (Please Print) Date 7-23-14 Page ____ of ____

Watchman M ALCHIN WO # 1568622

Inspected From LIN To BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 7-24-14

COPY

Quick Reporting (Tr)

Bulletins (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order 1568622 TEAM ONE - SECT 5 - CM 355S/488S AND
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARKI LT Rail Chain Markers
Work Location
Work Group* MTA527

Site LTRAIL
Status COMP
Priority 1
Work Type* PM
Crew DAY-A
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-#####-052

Total Planned Cost 0.00
Total Actual Cost 422.32
Repair Limit Amount
Reported By MTACRON
Reported Date 07/19/14 04:04:26 AM

Asset Details
Primary Meter
Multiple Assets Locations and CIs Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	MALCHIN		07/23/14	08:00:00	02:00:00 F	6.00		26.29	N	N/A
	SSELL		07/23/14	08:00:00	02:00:00 F	6.00		26.50	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/23/14 Page 1 of 1.

Watchman W BRYANT. WO # 1568619

Inspected From CAMDEN To LINTHICUM

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M. Bryant — Supervisory Certification

7-24-14 — Date

COPY

Quick Reporting (Tr)

Bulletins (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order 1568619 TEAM TWO - SECT 4: CY/LINT - CM 168 TC
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARKI LT Rail Chain Markers
Work Location
Work Group* MTA527

Site LTRAIL
Status COMP
Priority 1
Work Type* PM
Crew DAY-B
Warranty Situation Present? N
Maintenance Alert?

Work Details
Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-#####-052

Total Planned Cost 0.00
Total Actual Cost 420.64
Repair Limit Amount
Reported By MTACRON
Reported Date 07/19/14 04:04:22 AM

Asset Details
Primary Meter
Multiple Assets,Locations and CIs Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	COMP
20	20	INSPECT TRACK PER BALT LR STANDARI			N			NONE	COMP

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER		07/23/14	08:00:00 /	02:00:00 F	6:00		26.29	N	N/A
	WBRYANT		07/23/14	08:00:00 /	02:00:00 F	6:00		26.29	N	N/A

Select Labor Select Planned Labor New Row

TRACK INSPECTION REPORT

Name Schuyler Bryant (Please Print) Date 7/24/14 Page ____ of ____

Watchman ____ WO # 1567377 Amended 1574124

Inspected From HV LU To ____

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	L/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new Defects

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ____

Reason for Special Inspection? ____

Track Inspectors Signature ____ Supervisory Certification M. Boyt Date 7-28-14

COPY

Quick Reporting (Tr)

Bulletins (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order 1574124 special inspection of Premeir Pads
Classification
Asset
Alias
Location LRMOW Light Rail Maintenance of Ways
Work Location LRMOWTRAC Maintenance of Ways, Light Rail Track MOW
Work Group* MTA527

Site LTRAIL
Status APPR
Priority
Work Type* PM
Crew
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account* J05-#####-052

Total Planned Cost 0.00
Total Actual Cost 420.64
Repair Limit Amount
Reported By GLAM
Reported Date 07/24/14 01:25:19 PM

Asset Details
Primary Meter
Multiple Assets,Locations and CIs Filter
Tasks Filter

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
No rows to display									

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	TSCHISLER	✓	07/24/14	08:00:00 A	02:00:00 P	8:00		26.29	N	N/A
	WBRYANT	✓	07/24/14	08:00:00 A	02:00:00 P	8:00		26.29	N	N/A

Labor

Task
Labor* TSCHISLER Thomas Schisler
Regular Hours* 8:00
Component
Position
Reason for Repair
Work Accomplished
Part Failure
Memo

Start Date* 07/24/14
Start Time* 08:00:00 A
End Date 07/24/14
End Time 02:00:00 P
Rate* 26.29
Line Cost 210.32
Type* WORK

Warranty? N
Qualification Met? N/A
Approved? ✓
Timer Status
Craft* AREPAIR
Skill Level

Outside Labor
Outside?
Vendor
Contract
Revision

Premium Pay
Premium Pay Code
Premium Pay Hours
Premium Pay Rate
Premium Rate Type

Charge Information
GL Debit Account J05-#####-052
GL Credit Account
Location LRMOW
Asset
Alias
Recorded as Received

Select Labor | Select Planned Labor | New Row

TRACK INSPECTION REPORT

Name S SELL / M ALCHIN (Please Print) Date 7-24-14 Page ___ of ___

Watchman M ALCHIN WO # 1567384

Inspected From LUTH To CS

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ___

Is this a Special Inspection? Yes ___ No ✓

Reason for Special Inspection? ___

Track Inspectors Signature — Supervisory Certification — Date 7-28-14

COPY

Quick Reporting (Tr)

Bulletins (2) Go To Reports Start Center Profile Sign Out Help

Find: Select Action

List Quick Reporting Specifications

Work Order 1567384 TEAM ONE - SECT 2: LU/CS - CM 586N TO
Classification MTA \ LTRAIL MTA - LTRAIL
Asset
Alias
Location CHAIN_MARKI LT Rail Chain Markers
Work Location
Work Group* MTA527

Site LTRAIL
Status APPR
Priority 1
Work Type* PM
Crew DAY-A
Warranty Situation Present? N
Maintenance Alert?

Work Details

Component
Position
Reason for Repair
Work Accomplished
Part Failure
Parent WO
Telematics Code
Telematics Transaction
GL Account J05-#####-052

Total Planned Cost 0.00
Total Actual Cost 422.32
Repair Limit Amount
Reported By MTACRON
Reported Date 07/18/14 03:31:39 AM

Asset Details
Primary Meter
Multiple Assets,Locations and Cis Filter

Tasks Filter 1 - 2 of 2 Download

Sequence	Task	Summary	Component	Reason for Repair	Warranty?	Route	Route Stop	Qualifications	Status
10	10	ESTABLISH ON TRACK SAFETY PER RPW			N			NONE	APPR
20	20	INSPECT TRACK PER BALT LR STANDARD			N			NONE	APPR

New Row

Labor Materials Tools Failure Reporting

Labor Filter 1 - 2 of 2 Download

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hours	Rate	Warranty?	Qualification Met?
	MALCHIN	✓	07/24/14	06:00:00 A	02:00:00 P	8:00		26.29	N	N/A
	SSELL	✓	07/24/14	06:00:00 A	02:00:00 P	8:00		26.50	N	N/A

Select Labor Select Planned Labor New Row

Name T SCHISLER (Please Print) Date 7/25/14 Page 1 of 3

Watchman W BRYANT WO # 1553390

Inspected From COLD SPRING To CAMDEN

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.				BOTH	91-3	5305	305	Y		
2.				E	91-3	5304	344	Y		
3.				BOTH	883B	5305	305	Y		
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	FROG WEAR ON RISOR, PITTED POINT, PITTED THROAT AREA, SIDE WEAR ON FROG POINT,
2	RH CV PT, HEAVY SIDE WEAR, PT WORN/ RAZOR SHARP 15" BACK, LAST 4½" PT STARTING TO CHIP
3	PITTED PT, PLUS SIDE WEAR, E JOINT, MAINLINE, N.E. OF FROG, CHIPPED IN MIDDLE OF JOINT, NEED TO DRESS
	WO # 1527906 REPLACES WO # 1553390

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T. Schisler — Track Inspectors Signature

M Boyle — Supervisory Certification

7-29-14 — Date

COPY

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/26/14 Page 1 of 2

Watchman W BRYANT WO # 1574827

Inspected From CROMWELL To LINTHICUM

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	405+75	402+50	1	W	—	M301	302	Y		
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	DRAIN HAS DEBRIS IN IT

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M. Bayton — Supervisory Certification

7-29-14 — Date

COPY

Name T SCHISLER (Please Print) Date 7/26/14 Page 2 of 2

Watchman W BRYANT WO # 1574827

Inspected From BWI To LINTHICUM

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	BWI 47+00	BWI 45+00	1	Both	—	W 301	329	Y		
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	CAMP MEADE SOUTH X-ING, BOTH RAILS 3/4" LOW

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M. Boyt — Supervisory Certification

7-29-14 — Date

COPY

TRACK INSPECTION REPORT

Name M Alchin (Please Print) Date 7/27/2014 Page 1 of 1

Watchman S Sell WO # 1574816

Inspected From Camden To Linthicum

Item	Exception Chain Marker No From	To	Track No.	Rail N/S	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects.

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-28-14
Date

COPY