Name W. Bryant T. Schisler (Please Print) Date 08-01-14 Page 1 of 3

Watchman S. Sell WO # 1574695

Inspected From Coldspring To Camden

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection Completed - No new defect's noted in area

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant — Track Inspectors Signature

Gary Lam — Supervisory Certification

8/1/14 — Date

COPY

Work Order Tracking (Tr)

Bulletins (1) Go To Reports Start Center Profile Sign Out Help

Find Work Order Select Action

List Work Order Plans Actuals Activities Measurements Axle Configuration Related Records Safety Plan Log Failure Reporting Specifications

Work Order: 1590069 TEAM TWO - SECT 5: LINT/CROM - CM 355S TO 488S Site: LTRAIL

Asset: Alias:

Children of Work Order 1590069 Filter 0 - 0 of 0

Tasks for Work Order 1590069 Filter 1 - 2 of 2

Sequence	Task	Summary	Component	Reason for Repair	Warranty
10	10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES			N
20	20	INSPECT TRACK PER BALT LR STANDARD PROCEDURE			N

Labor Materials Services Tools Repair Orders

Labor Filter 1 - 2 of 2

Task	Labor	Approved?	Start Date	Start Time	End Time	Regular Hours	Premium Pay Hou
	WBRYANT		08/02/14	06:00:00 AM	02:00:00 PM	8:00	
	TSCHISLER		08/02/14	06:00:00 AM	02:00:00 PM	8:00	

TRACK INSPECTION REPORT

Name W. Bryant (Please Print) Date 08-02-14 Page 1 of 2

Watchman T. Schisler

Inspected From Linthicum WO # 1590069

To Ckomwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item Comments

Track inspection completed. No new defects noted in area.

switches in the area inspected? Yes ✓ No

Special Inspection? Yes No ✓

for Special Inspection?

W. Bryant

k Inspectors Signature

Supervisory Certification

8/2/14

Date

COPY

TRACK INSPECTION REPORT

Name S SELL / W BRYANT (Please Print) Date 8-3-14 Page ___ of ___

Watchman W BRYANT WO # 1590074

Inspected From CY To LIN

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA
	RIDING INSPECTION DUE TO WEATHER

Were switches in the area inspected? Yes ✓ No ___

Is this a Special Inspection? Yes ___ No ✓

Reason for Special Inspection? ___

Track Inspectors Signature — Supervisory Certification: Garey Lam — Date: 8/3/14

COPY

Name S SELL (Please Print) Date 8-4-14 Page ___ of ___

Watchman M ALCHIN WO # 1589737

Inspected From HV To LUTH

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	CM.696N		1	E	698-3	5304	305	Y		
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	SWITCH 698-3 ML1 RH SW. PT. 1/8" BY 1" CRACK
	ON TIP OF POINT

Were switches in the area inspected? Yes ✓ No ___

Is this a Special Inspection? Yes ___ No ✓

Reason for Special Inspection? ___

Track Inspectors Signature — Supervisory Certification — Date 8-6-14

COPY

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 8/5/14 Page 1 of 1

Watchman W BRYANT WO # 1593555

Inspected From LUTHERVILLE To COLD SPRING

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	491+55N	492+00N	2	BOTH	—	W301	332	Y		
2.	383+00N		2	E	—	W301	311/321	Y		
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	PUMPING 3/4" UNDERLOAD
2	HILLSIDE IS LOOSE, DETERIORATING, MORE CRACKS IN HILLSIDE, MORE DIRT COMING DOWN OFF HILLSIDE - JUST SOUTH OF LAKE ROLAND, SEE WO# 1226299 FOR OTHER DETAILS

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M. Bryant — Supervisory Certification

8-6-14 — Date

COPY

TRACK INSPECTION REPORT

Name S SELL Date 8-5-14 Page ____ of ____

(Please Print)

Watchman M ALCHIN WO # 1593558

Inspected From CS To CY

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 8-6-14

COPY

Name S'SELL (Please Print) Date 8-6-14 Page ____ of ____

Watchman M ALCHIN WO # 1592574

Inspected From LIN To CROM

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature ____ Supervisory Certification ____ Date 8-7-14

COPY

Name S' SELL (Please Print) Date 8-6-14 Page 1 of

Watchman M ALCHIN WO # 1592574

Inspected From LIN To BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature Supervisory Certification Date

COPY

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 8/6/14 Page 1 of 1

Watchman W BRYANT WO # 1592571

Inspected From LINTHICUM To CAMDEN

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	267+00S	263+00S	1	BOTH	—	W301	329	Y		
2.	238+00S		1	BOTH	—	W301	332	Y		
3.	125+00	124+00	1+2	BOTH	—	W301	302	Y		
4.	115+90S		1	BOTH	—	W301	332	Y		
5.	35+00S	30+00S	1	BOTH	—	W301	329	Y		
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	NURSERY RD BRIDGE OVER PATAPSCO RIVER, FROM THE APPROACH COMING SOUTH BOUND OFF BRIDGE TO CM 267+00, 1" LOW
2	NURSERY RD BRIDGE OVER PATAPSCO RIVER, NORTH APPROACH COMING OFF EXPANSION JOINT, 11 TIES PUMPING 1/2" UNDER LOAD
3	FLANGEWAYS FULL OF SMALL STONE, DIRT & DEBRIS, WATERVIEW AVE X-ING
4	PUMPING 3/4" UNDER LOAD. 9 TIES IN A ROW
5	MOSTLY SURFACE WITH (CROSSLEVEL & PUMPING)

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

Thomas Schisler — Track Inspectors Signature

M Bruff — Supervisory Certification

8-7-14 — Date

COPY

Name S'SELL (Please Print) Date 8-7-14 Page ___ of ___

Watchman M ALCHIN WO # 1589734

Inspected From LUTH To CS

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ___

Is this a Special Inspection? Yes ___ No ✓

Reason for Special Inspection? ___

Track Inspectors Signature — Supervisory Certification — Date 8-8-14

COPY

Name T SCHISLER (Please Print) Date 8/7/14 Page 1 of 1

Watchman W BRYANT. WO # 1597793

Inspected From LINTHICUM To HUNT VALLEY

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	728+00"		1	Both	—	W301	332	Y		
2.	729+70"		1	Both	—	W301	329	Y		
3.	751+15"		1	Both	—	W301	332	Y		
4.	826+30"		1	Both	—	W301	332	Y		
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	9 TIES IN A ROW PUMPING 3/4" UNDERLOAD - SOUTH END INDUSTRY LN X-ING
2	6 TIES IN A ROW 1/2" LOW - NORTH END INDUSTRY LN X-ING
3	NORTH SIDE OF WARREN RD X-ING, PUMPING 3/4" UNDERLOAD, ALSO 1 TROUGH
	LIN NEEDS REPLACING AT SAME LOCATION
4	9 TIES IN A ROW PUMPING 3/4" UNDERLOAD

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Supervisory Certification

8-8-14 — Date

COPY

Name T SCHISLER (Please Print) Date 8/8/14 Page 1 of 2

Watchman W BRYANT WO # 1567328

Inspected From COLD SPRING To CAMDEN

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.			1	E	91-1	S 305	311	Y		
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	RH CV PT 7" FROM TIP A 2¼"L CRACK ¼"D

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No +

Reason for Special Inspection?

T Schisler
Track Inspectors Signature

Supervisory Certification

Date

COPY

Name T SCHISLER Date 8/9/14 Page 2 of 2
(Please Print)
Watchman W BRYANT WO # 1598711

Inspected From BWI BRANCH To LINTHICUM

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M. Boyt — Supervisory Certification

8-11-14 — Date

COPY

Name T SCHISLER (Please Print) Date 8/9/14 Page 1 of 2

Watchman W BRYANT WO # 1598711

Inspected From CROMWELL To LINTHICUM

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

M. Boyt — Supervisory Certification

8-11-14 — Date

COPY

Name S' SELL / W. BRYANT Date 8-10-14 Page of
(Please Print)
Watchman W. BRYANT WO # 1598714

Inspected From CY To LINT

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	CM 1245		1+2	E+W		T301	332	Y		
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	TIES PUMPING CM 1245 ML 1 + 2 TRACK APPX. 10 TIES IN LENGTH. AREA IS MARKED ADJACENT TO WATERVIEW RD CROSSING NORTH SIDE. TIES pumping 1/2 TO 3/4 INCH.

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature Supervisory Certification Date 8-11-14

COPY

TRACK INSPECTION REPORT

Name S'SELL (Please Print) Date 8-11-14 Page ___ of ___

Watchman ___ WO # 1598565

Inspected From HV To LUTH

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION
	NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes ✓ No ___

Is this a Special Inspection? Yes ___ No ✓

Reason for Special Inspection? ___

Track Inspectors Signature ___ Supervisory Certification ___ Date 8-14-14

COPY

[redacted]

TRACK INSPECTION REPORT

Name S SELL (Please Print) Date 8-12-14 Page ___ of ___

Watchman ___ WO # 1600365

Inspected From CS To CY

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION DUE TO INCLEMENT WEATHER
	NO NEW DEFECTS NOTED IN AREA.

Were switches in the area inspected? Yes ✓ No ___

Is this a Special Inspection? Yes ___ No ✓

Reason for Special Inspection? ___

Track Inspectors Signature — Supervisory Certification — Date 8-13-14

COPY

TRACK INSPECTION REPORT

Date 8/12/2014 Page 1 of 1

ame T SCHISLER
(Please Print)

WO # 1600335

Watchman

Inspected From LUTHERVILLE To COLD SPRING

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	— RIDING INSPECTION DUE TO HEAVY RAIN — NO NEW DEFECTS NOTED IN AREA

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler
Track Inspectors Signature

Supervisory Certification

8-14-14
Date

COPY

[redacted]

TRACK INSPECTION REPORT

S NATHANIEL / S SELL Date 8-13-14 Page ___ of ___
(Please Print)
Watchman S SELL WO # 1599844

Inspected From LIN To CROM

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA
	RIDING INSPECTION

Were switches in the area inspected? Yes ✓ No ___

Is this a Special Inspection? Yes ___ No ✓

Reason for Special Inspection? ___

Track Inspectors Signature — Supervisory Certification — Date 8-14-14

COPY