Name T SCHISLER (Please Print) Date 10-14-16 Page 1 of 3

Watchman M BILLARD WO # 2611355

Inspected From CAMDEN To COLD SPRING

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.			2		207 3B	5305	305	Y		
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	A FRESH CHIP (DIME SIZE X 1/8" D) OUT OF TOP OF FROG POINT

COPY

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jamie Rennie — Supervisory Certification

10/16/16 — Date

Name T SCHISLER (Please Print) Date 10-14-16 Page 2 of 3

Watchman M BLLARD WO # 2611355

Inspected From PENN LINE To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN AREA

COPY

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler
Track Inspectors Signature

Jamie Reum
Supervisory Certification

10/16/16
Date

Name T SCHISLER (Please Print) Date 10-14-16 Page 3 of 3

Watchman M BLUARD WO # 2611355

Inspected From NA YARD To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	NO NEW DEFECTS NOTED IN YARD

COPY

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

James Reaver — Supervisory Certification

10/16/16 — Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2615823

TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
No new defects found .

Track inspection complete

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	10/19/16
Target Finish:	10/19/16
Actual Start:	10/15/16
Actual Finish:	10/15/16
Report Date:	10/11/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48481

Job Plan:	2961
Job Desc:	TEAM TWO - SECT 5: LINT/CROM/ BWI CM 355S TO 488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2615823

TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

No new defects found .

Track inspection complete

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2615823

TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

No new defects found .

Track inspection complete

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		RNELSOI				10	N		08:00	00:00	210.32
20	AREPAIR		MPOLLAF				10	N		08:00	00:00	210.32
											Total Actual Labor:	420.64

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2615823

TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

No new defects found .

Track inspection complete

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Name Pollard (Please Print) Date 10-15-2016 Page 1 of 2

Watchman Nelson WO # 2615823

Inspected From Lithicom To Cromwell

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted in area
	Trac K inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

10/16/16
Date

Name Pollard (Please Print) Date 10-15-2016 Page 2 of 2

Watchman Nelson WO # 2615823

Inspected From Camp meade Rd North To Thorgood Marshall BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection complete
	Spec book on gardner rd crossing needed

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

10/16/16
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2611373 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

10 track inspection completed...

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	10/10/16
Target Finish:	10/10/16
Actual Start:	10/17/16
Actual Finish:	10/17/16
Report Date:	10/7/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## ####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2611373 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

10 track inspection completed...

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	LEAD		WBRYAN					N		08:00	00:00	224.24
	AREPAIR		ARABETT					N		08:00	00:00	217.36
											Total Actual Labor:	441.60

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2611373 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

10 track inspection completed...

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Name W. Bryant (Please Print) Date 10-17-16 Page 1 of 1

Watchman A. Rabette WO # 26 I 1373

Inspected From Hunt Valley To Luthenville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection completed
	No defect's noted.

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant — Track Inspectors Signature

James Reaver — Supervisory Certification

10/18/16 — Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2623026 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:		Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:		Mileage Meter:		

Sched Start:	
Sched Finish:	
Target Start:	10/20/16
Target Finish:	10/20/16
Actual Start:	10/18/16
Actual Finish:	10/19/16
Report Date:	10/16/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##############-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2623026 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Related Records

WO	Description	Class	Status	Relationship
3329953	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	LEAD		WBRYAN						N		08:00	00:00	224.24
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	LEAD		WBRYAN				50		N		-08:00	00:00	-224.24
	LEAD		WBRYAN						N		08:00	00:00	224.24
	AREPAIR		ARABETT				50		N		-08:00	00:00	-217.36

Total Actual Labor: 441.60

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2623026 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3329953 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3329953 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Related Records

WO	Description	Class	Status	Relationship
2623026	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Na[illegible] W. Bryant Date 10-18-16 Page 1 of 2
(Please Print)
Watchman A. Rebette WO # 2623026
Inspected From Cold Spring To Camden

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection Completed
	No new defect's noted in an-

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant
Track Inspectors Signature

James Reaver
Supervisory Certification

10/19/16
Date

Name W. Bryant (Please Print) Date 10-18-16 Page 2 of 2

Watchman A. Rabette WO # 2623026

Inspected From Penn Line To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection completed
	No new defects noted in area

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Walter W. Bryant — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

10/19/16 — Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2622040

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

1) Trk - 1 CM 302+00 Resident throwing garbage and debris over our six (6) foot fence . Debris is causing a dam to form in drainage ditch..

2) Trks 1 & 2 CM 288+00 West rails at the joints are battered .

3) SW 208 - 1A crack in the frog point measuring 4 " long .

4) SW 164 the battered straight switch point with has 5 " chunk missing from the point
area now has an additional 5 1/2 " inch chunk missing .

A twenty (20) mph speed restriction was put on by 3802 & 3814 from CM S170+00 -
160+00 track 2.

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	10/20/16

Site:	LTRAIL
Priority:	1
Work Type:	PM

Job Plan:	2959
Job Desc:	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Target Finish:	10/20/16
Actual Start:	10/19/16
Actual Finish:	10/19/16
Report Date:	10/15/16
Reported By:	MTACRON
Requestor of Work:	

Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-####### #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48479

Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2622040

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

1) Trk - 1 CM 302+00 Resident throwing garbage and debris over our six (6) foot fence . Debris is causing a dam to form in drainage ditch..

2) Trks 1 & 2 CM 288+00 West rails at the joints are battered .

3) SW 208 - 1A crack in the frog point measuring 4 " long .

4) SW 164 the battered straight switch point with has 5 " chunk missing from the point
area now has an additional 5 1/2 " inch chunk missing .

A twenty (20) mph speed restriction was put on by 3802 & 3814 from CM S170+00 -
160+00 track 2.

Related Records

WO	Description	Class	Status	Relationship
3330034	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		RNELSON				10		N		08:00	00:00	210.32
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
												Total Actual Labor:	420.64

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2622040

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

1) Trk - 1 CM 302+00 Resident throwing garbage and debris over our six (6) foot fence . Debris is causing a dam to form in drainage ditch..

2) Trks 1 & 2 CM 288+00 West rails at the joints are battered .

3) SW 208 - 1A crack in the frog point measuring 4 " long .

4) SW 164 the battered straight switch point with has 5 " chunk missing from the point
area now has an additional 5 1/2 " inch chunk missing .

A twenty (20) mph speed restriction was put on by 3802 & 3814 from CM S170+00 -
160+00 track 2.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Date Completed	Completed By	Supervisor