TRACK INSPECTION REPORT

Name R. Nelson (Please Print) Date 5/11/16 Page 1 of 1

Watchman M. Pollard WO # 2401661

Inspected From Camden Yards To Linthicum

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.			1		2149A	S305	348	Y	N	
2.	1584+00S	1582+00S	142	E		R305	344	Y	N	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Frog point cracked 5 inches back from point
2	U-frog restaining rail is wearing due to lack of lubercation.

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Richard Nelson — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

5/12/16 — Date

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 5-11-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2401664

Inspected From BWI To ____

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	39+00 BWI		2			R305	303.304	Y	N	
2.	31+00 BWI		2			R305	303-304	Y	N	
3.	31+00 BWI		1			R305	303-304	Y	N	
4.	12+00 BWI		2			R305	322-304	Y	N	
5.	12+00 BWI		1			R305	322-304	Y	N	
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Broken U-69 Restraining Bolts. 18-Total 6-in Row.
2	Broken U-69 Restraining Bolts 51-Total 7-in Row - 6 in
	Row - 5 in Row
	Broken U-69 Restraining Bolts 62 Total 6 in Row - 5 in row
	10 in Row.
4	Loose Splice Bars + Bolts U-69 Restraining Rail
	10 Loose Bars + Bolts.
5	Loose splice Bars + Bolts U-69 Restraining Rail
	14 Loose Bar + Bolts

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

COP

Track Inspectors Signature — Supervisory Certification — 5/12/16 Date

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 5-11-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 240664

Inspected From Linthicum To Cromwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new Defects Noted in Area.

COPY

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No —

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — 5/12/16 Date

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 5-10-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 240 2451

Inspected From Penn To ____

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding Inspection — Rain

COPY

Were switches in the area inspected? Yes ____ No —

Is this a Special Inspection? Yes ____ No —

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 5/11/16

TRACK INSPECTION REPORT

Name A. Rabette G Lam (Please Print) Date 5-10-16 Page ____ of ____

Watchman A. Rabette G. Lam WO # 2402451

Inspected From Coldspring To Camden

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding Inspection — Rain

COPY

Were switches in the area inspected? Yes ____ No —

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — 5/11/16 Date

TRACK INSPECTION REPORT

Name R. Nelson (Please Print) Date 5/10/16 Page 1 of 1

Watchman M. Pollard WO # 2462403

Inspected From Lutherville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	440+00N		1	E/W		W301	327	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1.	Existing defect - Track out-of-line in a 10' area in curve.
	Riding Inspection due to
	inclement weather

COPY

Were switches in the area inspected? Yes ____ No ✓

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Richard Nelson — Track Inspectors Signature

Jann Reuva — Supervisory Certification

5/11/16 — Date

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 5-9-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2399828

Inspected From Hunt Valley To Luther Ville

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	875 to N		0	E		R 305	303	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Broken U-69 Restraining Bolts.
	A count of (25) U69 Brace Bolts Broken
	2 spots 3 in a row.

COPY

Were switches in the area inspected? Yes — No ____

Is this a Special Inspection? Yes ____ No —

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — 5/10/16 Date

TRACK INSPECTION REPORT

Name A. Rabette G. Lam (Please Print) Date 5-8-16 Page ____ of ____

Watchman A. Rabette G. Lam WO # 23540055

Inspected From Howard St. To ____

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No change in Defects on Howard St.

COPY

Were switches in the area inspected? Yes ____ No ____

Is this a Special Inspection? Yes ____ No ____

Reason for Special Inspection? Rail Defects on Howard St.

Track Inspectors Signature: A. Rabette

Supervisory Certification: Jamm Reaves

Date: 5/9/16

TRACK INSPECTION REPORT

Name A. Rabette G. Lam (Please Print) Date 5-8-16 Page ____ of ____

Watchman A. Rabette G. Lam WO # 2399876

Inspected From Camden To Linthicum

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	184 too 5		2	W		R 305	303	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Broken U-69 Restraining bolts
	A count of (76) U-69 Braces Broken Bolts
	1 Spot 18 in row.
	1 Spot 14 in row.
	3 Spots 5 in row.

COPY

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 5/9/16

TRACK INSPECTION REPORT

Name Pollard, Nelson (Please Print) Date 5-7-2016 Page 2 of 2

Watchman Schisler WO # 2395775

Inspected From Campmeade Kd To KWF

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

[signature] Track Inspectors Signature

[signature] Supervisory Certification

5/8/16 Date

TRACK INSPECTION REPORT

Name Pollard Nelson (Please Print) Date 5-7-2016 Page 1 of 2

Watchman Schisler WO # 2396775

Inspected From Lithicum To Cromwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.					484-3A	F316	322	Y	N	
2.					484-3A	M307	316	Y	N	
3.					484-1A	F316	322	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	15 loose screw spikes
2	Low ballast west rail area 20'
3	14 loose screw spikes
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 5/8/16

TRACK INSPECTION REPORT

Name Pollard Nelson (Please Print) Date 5-6-2016 Page 2 of 2

Watchman Schisler WO # 2388925

Inspected From Pepsi Line To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted in area
	Track inspection complete

COPY

Were switches in the area inspected? Yes ____ No ____

Is this a Special Inspection? Yes ____ No ____

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 5/8/16

TRACK INSPECTION REPORT

Name Pollard Nelson (Please Print) Date 5-6-2016 Page 1 of 2

Watchman Schisler WO # 2388925

Inspected From Coldspring To Camden Yard

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	(R) No New defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes ____ No ____

Is this a Special Inspection? Yes ____ No ____

Reason for Special Inspection? ____

Track Inspectors Signature

Supervisory Certification

5/8/16
Date

TRACK INSPECTION REPORT

Name Pollard Nelson (Please Print) Date 5-6-2016 Page 1 of 1

Watchman Schisler WO # 235-4055

Inspected From Howard St To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No change in monitored defects.

COPY

Were switches in the area inspected? Yes ____ No ✓

Is this a Special Inspection? Yes ✓ No ____

Reason for Special Inspection? 4 broken rails

[signature] Track Inspectors Signature

[signature] Supervisory Certification

5/8/16 Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 5-5-2016 Page 1 of 1

Watchman Nelson WO # 2388974

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	866+20	865+00	0			M309	309			
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Several cracks developing in condrete surrounding
	Imbedded Track

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 5/6/16

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 5-5-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2388938

Inspected From Luther Ville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 5/6/16

TRACK INSPECTION REPORT

Name R. Welson, M. Pollard (Please Print) Date 5/5/16 Page 1 of 1

Watchman G. Lam WO # 2354055

Inspected From Howard Street To Camden Street

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	000+49N		2	W		R301	303	R	N	
2.	000+75N		2	W		R301	303	R	N	
3.	010+00N		1	E		R301	303/305	R	N	
4.	019+10N		2	W		R301	303	R	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1-3	No change in rail breaks.
4	No change in cracked rail head.

Were switches in the area inspected? Yes _____ No ✓

Is this a Special Inspection? Yes ✓ No _____

Reason for Special Inspection? Daily Inspection To monitor Howard ST. Defects

Richard Welson — Track Inspectors Signature

James Reaver — Supervisory Certification

5/6/16 — Date

TRACK INSPECTION REPORT

Name Pollard, Schisler Lam Date 5-4-2016 Page 1 of 1
(Please Print)

Watchman Labette WO # 2354055

Inspected From Howard St N 19+00 To N 00+49

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No change in defects Found
	Track inspection complete

Were switches in the area inspected? Yes _____ No ✓

Is this a Special Inspection? Yes ✓ No _____

Reason for Special Inspection? Broken rails (4)

Track Inspectors Signature: [signature] Supervisory Certification: [signature] Date: 5/5/16

TRACK INSPECTION REPORT

Name A. Rabette G. Cam Date 5-4-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Cam WO # 2390366

Inspected From BWI To ____

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — 5/5/16 Date

TRACK INSPECTION REPORT

Name A. Robette G. Lam (Please Print) Date 5-4-16 Page ____ of ____

Watchman A. Robette G. Lam WO # 2390366

Inspected From Linthicum To Cromwell

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	367+00		2	W	3621B	5305	305 301	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Frog Point Needs Welding.
	Frog Point chipped out 1/2" deep x 1" in lenght
	will be come 2 1/2" lenght.

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 5/5/16

TRACK INSPECTION REPORT

Name A. Rabette R. Nelson Date 5-3-16 Page ____ of ____
(Please Print)
Watchman A. Rabette R. Nelson WO # 2392124

Inspected From Coldspring To Camden

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area —

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 5/4/16

TRACK INSPECTION REPORT

Name A. Rabette R. Nelson (Please Print) Date 5-3-16 Page ____ of ____

Watchman A. Rabette R. Nelson WO # 2392124

Inspected From Parr To ____

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area -

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature: A. Rabette R. Nelson

Supervisory Certification: Jamie Reaver

Date: 5/4/16

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 5-3-2016 Page 1 of 1

Watchman Lam WO # 2391617

Inspected From Lutherville To Cold spring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	518+00					M307	348	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1.	Pine trees which wet lean over towards track area Fouling area.
	Track inspection complete

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification: James Reaver — Date: 5/4/16

TRACK INSPECTION REPORT

Name A. Rabette G. Lam (Please Print) Date 5-2-16 Page ____ of ____

Watchman A. Rabette G. Lam WO # 2388941

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 5/3/16

TRACK INSPECTION REPORT

Name GAREY LAM (Please Print) Date 5/1/16 Page 1 of 1

Watchman _____ WO # 2388977

Inspected From CY To LINT

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDE INSPECTION DUE TO RAIN
	NO Problems

Were switches in the area inspected? Yes _____ No ✓

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

G Lam — Track Inspectors Signature

James Reaves — Supervisory Certification

5/2/16 — Date

TRACK INSPECTION REPORT

Name Pillard (Please Print) Date 5-4-2016 Page 1 of 1

Watchman Nelson WO # 2390363

Inspected From Lanthicum To Camden yards

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	180+25		2			M309	348	U	N	
2.	157+30	152+30	1			R305	322	Y	N	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Resume sign found in track way, sign had been run over and is battered. Sign needs to be put on Catenary Pole at 175+0
2	Seven (7) U-69 splice plates have at least two (2) loose bolts on them, this appears to be a pattern that needs to be investigated.
	Track inspection complete

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Michael Pillard — Track Inspectors Signature

James Reaver — Supervisory Certification

5/5/16 — Date