TRACK INSPECTION REPORT

Name A.Rabette R.Nelson (Please Print) Date 7-26-16 Page ____ of ____

Watchman A.Rabette R.Nelson WO # 2496835

Inspected From Penn To ____

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in area.

COPY

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Arthur Rabette — Track Inspectors Signature

James Reave — Supervisory Certification

7/27/16 — Date

TRACK INSPECTION REPORT

Name A. Rabette (Please Print) Date 7-25-16 Page ____ of ____

Watchman ____ WO # 2494712

Inspected From Hunt Valley To Lutherville

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding Inspection Due to Lack of Man Power
	No New Defects Noted in Area.

COPY

Were switches in the area inspected? Yes ____ No ✓

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature: A. Rabette

Supervisory Certification: Jamie Reaver

Date: 7/26/16

TRACK INSPECTION REPORT

Name A. Rabette (Please Print) Date 7-24-16 Page ____ of ____

Watchman ____ WO # 249.4756

Inspected From Camden To Linthicum

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding Inspection
	No New Defects Noted in Area.

COPY

Were switches in the area inspected? Yes ____ No ✓

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Arthur Rabette — Track Inspectors Signature

Jann Reaver — Supervisory Certification

7/25/16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-23-2016 Page 1 of 2

Watchman Schisler WO # 2489803

Inspected From Linthicum To Cromwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-24-16
Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-23-2016 Page 2 of 2

Watchman Schisler WO # 2489803

Inspected From Camp meade To Thurgood Marshall BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	BWI 85+00	7R+00	2			R301	329	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Surfacing and aligning are needed in this area LRV
	wheels are hunting when in the curved area
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Michael Pollard — Track Inspectors Signature

Jamm Rem — Supervisory Certification

7-24-16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-22-2016 Page 3 of 3

Watchman _____ WO # 2486025

Inspected From North Ave yard To _____

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Yard inspection complete

COPY

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Track Inspectors Signature — Supervisory Certification — 7-24-16 Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-22-2016 Page 2 of 3

Watchman _____ WO # 2486005

Inspected From Penn Station To Mt Royal

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection due to manpower shortage
	Track inspection complete
	No new defects noted

COPY

Were switches in the area inspected? Yes visual ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Michael L Ball — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

7-24-16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-22-2016 Page 1 of 3

Watchman _____ WO # 2486005

Inspected From Coldspring To Camden yard

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection due to manpower shortage
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes Visual No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Michael L Pollard — Track Inspectors Signature

Jamm Reaves — Supervisory Certification

7-24-16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-21-2016 Page 1 of 1

Watchman Schisler WO # 2486018

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	859+80	859+20	0			M309	357	S	N	
2.	830+80		1			R301	329	Y	N	
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Concrete being rubbed by wheels in the curve area.
2	Running rail down 1/2"

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 7-22-16

TRACK INSPECTION REPORT

Name Mike Atchin / Neal George Date 7/21/16 Page 1 of 1
(Please Print)
Watchman WO # 2486010
Inspected From LUTHERVILLE To Cold Spring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	357N		1			M313	314	Y	N	
2.	348 N	355 N	2	W		R 301	344	R	N	
3.	310	303 N	2	E		R 301	344	R	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Foul Ballast (10 ties)
2	Side Worn Rail 28°
3	Side Worn Rail 27

COPY

Were switches in the area inspected? Yes ____ No ✓

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Michael Atchin — Track Inspectors Signature

James Reaver — Supervisory Certification

7-22-16 — Date

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/20/16 Page 1 of 2

Watchman N/A WO # 2487189

Inspected From LINTHICUM To BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION DUE TO LACK OF MAN POWER
	NO NEW DEFECTS OBSERVED

COPY

Were switches in the area inspected? Yes VISUAL ONLY X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

7-21-16 — Date

TRACK INSPECTION REPORT

Name M. Pollard (Please Print) Date 7-20-2016 Page 1 of 1

Watchman _____ WO # 2487186

Inspected From Camden yard To Lunthicum

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection due to Lack of manpower
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes _____ No _____

Is this a Special Inspection? Yes _____ No _____

Reason for Special Inspection? _____

Track Inspectors Signature — Supervisory Certification — 7/21/16 Date

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/20/16 Page 2 of 2

Watchman N/A WO # 2487189

Inspected From LINTHICUM To CROMWELL

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION TO LACK OF MAN POWER
	NO NEW DEFECTS OBSERVED

COPY

Were switches in the area inspected? Yes VISUAL ONLY X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

7-21-16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-19-2016 Page 1 of 1

Watchman _____ WO # 2487911

Inspected From Lotherville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Riding inspection No new defects noted
	Due to lack of
	manpower Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

Track Inspectors Signature _____ Supervisory Certification Jamie Beaver Date 7-20-16

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/18/16 Page 1 of 2

Watchman N/A. WO # 2487949

Inspected From COLD SPRING To CAMDEN

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION DUE TO LACK OF MAN POWER
	NO NEW DEFECTS OBSERVED

COPY

Were switches in the area inspected? Yes VISUAL ONLY X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

7-20-16 — Date

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/19/16 Page 2 of 2

Watchman N/A WO # 2487949

Inspected From PENN LINE To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION DUE TO LACK OF MANPOWER
	NO NEW DEFECTS OBSERVED

COPY

Were switches in the area inspected? Yes VISUAL ONLY x No

Is this a Special Inspection? Yes No x

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jason Reaver — Supervisory Certification

7-20-16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-18-2016 Page 1 of 1

Watchman George WO # 2486031

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	730+00	729+85	2			M307	314	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Five Fouled cribs
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-19-16
Date

TRACK INSPECTION REPORT

Name R. Nelson, M. Pollard Date 7/18/16 Page 1 of 2
(Please Print)
Watchman T. Schisler WO # 8481790
Inspected From Linthicum To Cromwell

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Richard Nelson — Track Inspectors Signature

Jamm Renn — Supervisory Certification

7-18-16 — Date

TRACK INSPECTION REPORT

Name R. Nelson, M. Pollard (Please Print) Date 7/14/16 Page 2 of 2

Watchman T. Schisler WO # 2481790

Inspected From Camp meade Road To BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	043460		2			R305	309	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1.	Crack in restraining rail weld northside of Camp meade south Road Crossing.

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Richard Nelson — Track Inspectors Signature

Jamm Rear — Supervisory Certification

7-18-16 — Date

Name R. Welson, T. Schisler Date 7/15/16 Page 1 of 2
(Please Print)
Watchman M. Pollard WO # 2468300
Inspected From Coldspring To Camden

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	200+00N	195+00N	1	W		R301	344	Y	N	
2.	200+00N	195+00N	2	W		R301	344	R	N	
3.	148+00N		1			M309	342	Y	N	
4.	124+00N		1			F320	322	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1.	Gage face angle is 26°
2	Gage face angle is 29°
3.	Water leaking from elbow seal of the drain pipe that was installed on the rock hill.
4	Two bolts in two different standard joints of the diamond are loose

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Richard Welson — Track Inspectors Signature

James Reaver — Supervisory Certification

7-16-19 — Date

Name R. Nelson, T. Schisler Date 7/15/16 Page 2 of 2
(Please Print)
Watchman M. Pollard WO # 24608300

Inspected From Penn line To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Richard Nelson
Track Inspectors Signature

Jamie Renn
Supervisory Certification

7-16-19
Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-14-2016 Page 1 of 1

Watchman Schisler WO # 2477771

Inspected From Lutherville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	537+00		1			M309	383	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Signal 535-2 signal box in trackway has no lid. Wires
	are being exposed to elements

COPY

Were switches in the area inspected? Yes — No

Is this a Special Inspection? Yes No —

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — 7-16-16 Date

Emailed system 7/16/16

TRACK INSPECTION REPORT

Name R. Nelson (Please Print) Date 7/14/16 Page 1 of 1

Watchman D. George WO #

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	780+50N		2			M305	303	Y	N	
2.	729+20N	730+00N	2	E/W		W301	329	Y	N	
3.	723+00	724+00	2	E/W		M306	355	Y	N	
4.	723+50	7	2			M301	302	Y	N	
5.			2		698	S305	305	Y	N	
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1.	Premier Rd broken Beaver Dam Road, needs cold patch.
2.	North side of Industry Lane is out-of-surface needs to be tamped ASAP.
3	Vegetation growing in Trackway.
4.	Drain is severely blocked
5.	Frog point is chipped 2 1/4 x 3/4 x 1/16

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — 7-15-16 Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-13-2014 Page 2 of 3

Watchman Schisler WO # 2478904

Inspected From Camp meade -North To Thurgood Marshall BWI

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-14-16
Date

TRACK INSPECTION REPORT

Name Pollard, Schuyler Date 7-13-2016 Page 3 of 3
(Please Print)
Watchman WO # 2478904

Inspected From Cromwell yard To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New defects noted
	Yard inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-14-16
Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-13-2016 Page 1 of 3

Watchman Schisler WO # 2478904

Inspected From Linthicum To Cromwell

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-14-16
Date

TRACK INSPECTION REPORT

Name R. Nelson (Please Print) Date 7/12/16 Page 1 of 1

Watchman M. Alchin WO # 2479738

Inspected From Lutherville To Coldspring

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	430+00N	412+00N	2	E		R301	344	R	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1.	Gage face angle is 27°

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Richard Nelson — Track Inspectors Signature

Jamm Reaver — Supervisory Certification

7-13-16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-12-2016 Page 1 of 2

Watchman Schisler WO # 2479793

Inspected From Coldspring To Camden yard

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.					88-3A					
2.					88-3B					
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Frog is battered and showing wear on the westside
	OF Frog. Guard rail has ½" wear on it
2	NO. 4 rod is rubbing against tie
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 7-14-16

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-12-2016 Page 2 of 2

Watchman Schisler WO # 2479793

Inspected From Mt Royal To Penn station

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-13-16
Date

TRACK INSPECTION REPORT

Name R. Nelson (Please Print) Date 7/11/16 Page 1 of 1

Watchman M. Pollard WO # 2477774

Inspected From Hunt Valley To Lutherville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	897+60		1+2			M306	355	Y	N	
2.	887+00		O	W		305	J301	Y	N	
3.	887+00		O	E	887	S306	322	Y	N	
4.	874+00	876+00	O+1	W		M306	355	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1.	thick vegetation at south side of Shawan Road crossing, needs to be sprayed.
2.	Insulated Joint has a chip 1½ x 1½ missing on the running surface of the rail head.
3.	4th brace on the right hand curved stock rail is not seated properly against stock rail.
4.	Vegetation needs to be sprayed.

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Richard Nelson — Track Inspectors Signature

James Rear — Supervisory Certification

7-12-16 — Date

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/10/16 Page 1 of 1

Watchman N/A WO # 2477850

Inspected From CAMDEN To LINTHICUM

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION
	NO NEW DEFECTS OBSERVED

COPY

Were switches in the area inspected? Yes VISUAL ONLY X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

James Ream — Supervisory Certification

7-11-16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-9-2016 Page 1 of 2

Watchman Nelson WO # 2473498

Inspected From Linthicum To Cromwell

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection complete
	No new defects noted

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 7-10-16

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-9-2016 Page 2 of 2

Watchman Nelson WO # 2473498

Inspected From Camp meade Rd To T.M. BWI

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	43+60		2					Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	crack in top of restraining rail has grown by 1/8", it now
	has a crack on the exterior of the restraining rail 3/4" long.
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No —

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 7-11-16

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-8-2016 Page 1 of 3

Watchman Schisler WO # 2977747

Inspected From Collspring To Camden yards

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Trackinspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes ✓ No

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-11-16
Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-8-2016 Page 3 of 3

Watchman Schisler WO # 2477747

Inspected From North Ave Yard To

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Yard inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 7-11-16

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 7-8-2016 Page 2 of 3

Watchman Schisler WO # 2477747

Inspected From Penn Station To Mt Royal

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

7-11-16
Date

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 7/7/16 Page 1 of 1

Watchman N/A WO # 2468815

Inspected From HUNT VALLEY To LUTHERVILLE

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	RIDING INSPECTION
	NO NEW DEFECTS NOTED IN AREA
	HV 99° RAIL TEMP 86° AIR TEMP 11:30 AM

COPY

Were switches in the area inspected? Yes VISUAL ONLY X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jamm Rean — Supervisory Certification

7-11-16 — Date