TRACK INSPECTION REPORT

Name R. Nelson (Please Print) Date 6/10/16 Page 1 of 3

Watchman M. Pollard WO # 24354482

Inspected From Cold Spring To Camden

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.			1		207-3A	S305	303	Y	N	
2.			2		207-3B	S305	303	Y	N	
3.			1		88-3A	J306	322	Y	N	
4.			1		88-3A	F316	loose	Y	N	
5.			2	E	70-3	S302	340	Y	N	
6.			1		90-1A	S304	305	Y	N	
7.	016+80		1	W		M305	322	Y	N	
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Frog point has a crack 3¼ inches long 5/16" down from top.
2	Frog point has a crack 4½ inchs long 5/16" down from top.
3.	2 bolts are loose on right hand guard rail.
4.	40 screw spikes are loose throughout entire.
5.	Right hand curved stock rail is shelled and pitted of the front of the undertuck.
6.	Left hand curve switch point chipped 22" back
7.	Bricks in road way at Mulberry & Howard ~~[illegible]~~ are loose & breaking

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Richard Nelson — Track Inspectors Signature

James Reaver — Supervisory Certification

6/13/16 — Date

COPY

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 6-9-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 243 ~~2543~~ 5497

Inspected From Luther Ville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

[signature] Track Inspectors Signature

James Reaver Supervisory Certification

6-10-16 Date

COPY

TRACK INSPECTION REPORT

Name T SCHISLER M POLLARD (Please Print) Date 6/9/16 Page 1 of 1

Watchman R NELSON WO # 2435557

Inspected From HUNT VALLEY To LUTHERVILLE

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	780+30N		2	BOTH	—	M305	311	Y		
2.	768+00N	762+15N	1	BOTH	—	T304	348	Y		
3.	725+00N	724+50N	1	BOTH	—	W301	325	Y		
4.	724+25N	723+40N	2	BOTH	—	W301	314/348	Y		
5.			1	BOTH	711	T302	333	Y		
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	MIDDLE PAD, END OF X-ING (BEAVER DAM RD X-ING) CONCRETE BROKEN OUT
	SHOWING REBARB
2	133 CRACKED CONCRETE TIES (WARREN RD CURVE)
3	3/4" OUT OF CROSSLEVEL
4	FOULED BALLAST PLUS VEGETATION
5	5 ROTTED 9' TIMBERS, 3 IN A ROW

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jamm Reaver — Supervisory Certification

6/10/16 — Date

COPY

TRACK INSPECTION REPORT

Name A. Rabette G. Lam (Please Print) Date 6-8-16 Page ____ of ____

Watchman A. Rabette G. Lam WO # 2436778

Inspected From Linthicum To Cromwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new Defects noted in Area

Were switches in the area inspected? Yes — No ____

Is this a Special Inspection? Yes ____ No —

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 6-9-16

COPY

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 6-8-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2436778

Inspected From BWI To ____

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area.

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 6-9-16

COPY

TRACK INSPECTION REPORT

Name T SCHISLER (Please Print) Date 6/8/16 Page 1 of 1

Watchman M POLLARD WO # 2436775

Inspected From LINTHICUM To CAMDEN

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	351+00S		2	BOTH	—	W 301	329	Y		
2.	31+00S		2	BOTH	—	J 302	348	Y		
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	JUST NORTH OF LINTHICUM, SURFACE, 3/4" LOW
2	WRONG HARDWARE, ALSO BARS ARE UPSIDE DOWN

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

6/9/16 — Date

COPY

TRACK INSPECTION REPORT

Name T SCHISLER R NELSON (Please Print) Date 6/7/16 Page 1 of 1

Watchman M POLLARD WO # 2437543

Inspected From LUTHERVILLE To COLD SPRING

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	350+00N		2	BOTH	—	W301	329	Y		
2.	345+00N		1	W	—	M301	348	Y		
3.	330+00N		1	W	—	M309	311/309	Y		
4.	262+00N	253+00	2	W	—	W301	307	Y		
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	5/8" LOW
2	ROCK FALLING OFF HILL CAUSING A BLOCKAGE IN DRAIN
3	CURB WALL (N END HT WASH. STA) DETERIORATING/CRACKED

Were switches in the area inspected? Yes X No

Is this a Special Inspection? Yes No X

Reason for Special Inspection?

T Schisler — Track Inspectors Signature

Jamie Pearce — Supervisory Certification

6/8/16 — Date

COPY

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 6-7-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2437601

Inspected From Penn To ____

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	Station		0			R301	348	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects in Area
1	Trash in Track way at Penn station

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Arthur Rabette — Track Inspectors Signature

James Reaves — Supervisory Certification

6/8/16 — Date

COPY

Name A. Rabette G. Lam (Please Print) Date 6-7-16 Page ____ of ____

Watchman A. Rabette G. Lam WO # 2437601

Inspected From Coldspring To Camden

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	225+00N	215+00N	2	E-W		R301	316	Y	N	
2.	214+00N	205+00N	2	E-W		R301	316	Y	N	
3.	193+00N		2	E		R301	316	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Low Shoulder Ballast in curve E/W
2	Low Shoulder Ballast in curve E/W
3	Low Shoulder Ballast E

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — Date 6/8/16

COPY

TRACK INSPECTION REPORT

Name A. Rabette G. Lam Date 6-6-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2435500

Inspected From Hunt Valley To Luthorville

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defect Noted in Area.

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification — 6/7/16 Date

COPY

Name A. Rabette G. Lam Date 6/5/16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2435560

Inspected From Camden To Linthicum

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new Defects noted in Area

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature: A. Rabette

Supervisory Certification: Jamm Reara

Date: 6/6/16

COPY

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 6-4-2016 Page 1 of 2

Watchman Bryant WO # 2429381

Inspected From Linthicum To Cromwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Lt Michael L Ball — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

6/5/16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 6-4-2016 Page 2 of 2

Watchman Bryant WO # 2429387

Inspected From Camp Meade North To B&I

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	Track inspection complete
	No new defects noted in area

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Michael L Pollard — Track Inspectors Signature

Jamie Reaver — Supervisory Certification

6-5-16 — Date

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 6-3-2016 Page 2 of 3

Watchman Lam WO # 2425302

Inspected From Penn Line To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted in area
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

6-5-16
Date

Name Billard (Please Print) Date 6-3-2016 Page 1 of 3

Watchman Lam WO # 2425302

Inspected From Coldspring To Camden yards

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	48+00	47+50	H2			M301	302	Y	N	
2.	26+00	25+00	2			M305	311	Y	N	
3.	2+56		2			R306	348	Y	N	
4.	1+49		2			R301	348	S	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	drains are clogged causing dirt and debris to foul the crib (15 total)
2	Concrete area surrounding Track is deteriorated to the point Rebar is showing.
3	replaced restraining rail is sitting even with running rail, should be higher than running rail
4	replaced running rail is canted
5	

COPY

Were switches in the area inspected? Yes ____ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Michael Ball — Track Inspectors Signature

James Reaves — Supervisory Certification

6-5-16 — Date

TRACK INSPECTION REPORT

Name Pollard Lam (Please Print) Date 6-3-2016 Page 3 of 3

Watchman WO # 2425302

Inspected From Northave yard To

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.					63	F316	318	S	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Screw spike in gage plate is missing.

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

6-5-16
Date

TRACK INSPECTION REPORT

Name A. Rabette G. Lam (Please Print) Date 6-2-16 Page ____ of ____

Watchman A. Rabette G. Lam WO # 2425315

Inspected From Luther Ville To Coldspring

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	363+70	365+50	1	W		W301	316	Y	N	
2.	368+81		1	W		W301	316	Y	N	
3.	376+00	370+00	1	W		W301	316	Y	N	
4.	381+56		2	E		R301	349	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	No Shoulder Ballast
2	No Berm + No Shoulder Ballast for 15 feet
3	Low Shoulder Ballast
	Rail Needs Welding Wheel Burn 3" in Lenght x 5/16" Deep. Also Pounding Hard + 3/8" side worn rail.

COPY

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature — Supervisory Certification: Jamie Reaver — Date: 6/3/16

TRACK INSPECTION REPORT

Name A. Robette G. Lam (Please Print) Date 6-1-16 Page ____ of ____

Watchman A. Robette. G. Lam WO # 2426923

Inspected From Linthicum To Cromwell

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new Defects Noted in Area.

COPY

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

Track Inspectors Signature: [signature]

Supervisory Certification: Jamie Reaver

Date: 6-2-16

TRACK INSPECTION REPORT

Name Pollard (Please Print) Date 6-1-2016 Page 1 of 1

Watchman Bryant WO # 2426920

Inspected From Linthicum To Camden yards

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.	293+00		2			R301	329	Y	N	
2.	287+00	281+80	2			M301	311	Y	N	
3.	260+10		2	W		P301	322	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	Surface area is down 1/2" and pumping 3/4"
2	Hill erosion in several areas along the drain walls
3	2 Pandrol tie plates loose with movement
	Track inspection complete

COPY

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature — Supervisory Certification — Date 6-2-16