Work Order Tracking (Tr)

BMXAA4591I - Sta

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety F

Work Order: 3065157 (2OM-RA) METRO MOW WEEKLY TRACK INSPECTION W

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CHAIN_MARK Metro Chain Markers

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 09/01/17 05:30:47 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 09/01/17 04:23:38 AM

Quick PM?

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Costs

Total Planned Cost: 0.00

Total Actual Cost: 0.00

Repair Limit Amount:

Current Asset Value:

GL Account: J05-#####-047

Work Order	Description	Work Location	Status	Reported Date
35155	2 OMRA IJ Battered (N/S) / IJ Chipped (S) OM 699+50	699W	MONITOR	12/31/15 2:28 PM
2860709	2 OMRA Coverboard Missing / End Approach 699	699W	APPR	4/7/17 6:06 PM
2017739	2 OMRA Coverboard Missing 695+50 (On Overpass)	695W	APPR	7/24/15 10:55 AM
2106108	2 OMRA Vegetation Overgrowth / Safety Issue 694 - 684+60	694W	APPR	9/30/15 7:33 AM
2053138	2 OMRA Coverboard Missing (20') 694+50	694W	APPR	8/20/15 5:32 AM
2924032	2 OMRA Ties Pumping 693+85	693W	INPRG	5/23/17 12:38 PM
2110236	2 OMRA Frog Riser Battered/ Pitted OM 3A 686+50	688WSWOM3A	MONITOR	10/1/15 3:09 PM
2014047	2 OMRA Interlocking Out of Surface OM 3A - 1A 688 - 682	688WSWOM3A	HOLD	7/21/15 3:20 PM
2618083	2 OMRA Ballast Low 688 - 692	688W	INPRG	10/12/16 9:47 PM
2044280	2 OMRA Frog Point Top Worn OM 3A 686+50	686W	APPR	8/13/15 7:23 AM
2541402	2 OMRA Out of Surface / Tie Pumping 685+40	685W	INPRG	8/16/16 3:49 PM
2652892	2 OMRA Joint Bolt Missing OM 3A 685+40	685W	APPR	12/5/16 9:48 PM
2652820	2 OMRA Contact Rail Arcing 684+30	684W	APPR	11/4/16 10:28 AM
2106117	2 OMRA IJ Battered / Burnt Crossover Rail 683+85	683W	APPR	9/30/15 7:44 AM
2711741	2 OMRA Rail Wheel Burns (3) 682+40 - 682+20	683W	APPR	12/21/16 10:07 PM
2044724	2 OMRA Frog Point Battered / Metal Flow OM 1A 684+10	682WSWOM1A	APPR	8/13/15 2:44 PM
2106127	2 OMRA Concrete Ties Pumping (6) 682+25	682W	INPRG	9/30/15 7:52 AM
2718159	2 OMRA Ties / Rail Pumpimg 682+20	682W	INPRG	12/28/16 9:45 AM
2014106	2 OMRA Insulator Cup Broken OM 681+80	681W	APPR	7/21/15 5:21 PM
2885389	2 OMRA Rail Chipped 675+00	675W	MONITOR	4/27/17 5:06 AM
2885391	2 OMRA Rail Chipped 670+75	670W	MONITOR	4/27/17 5:13 AM
31525	2 OMRA IJ Battered (2) (N/S) 669+40	669W	MONITOR	8/19/15 8:04 AM
2885392	2 OMRA Rail Out of Alignment 664+36 (N/S)	664W	APPR	4/27/17 5:20 AM
2885394	2 OMRA Rail Side Worn (27 Deg) 664+36	664W	MONITOR	4/27/17 5:29 AM
2013879	2 OMRA Ties Pumping 661+80	661W	APPR	7/21/15 1:25 PM
2254517	2 OMRA Rail Out of Surface / Pumping 658+20	658W	INPRG	1/16/16 2:26 PM
2868175	2 OMRA Rail Side Worn (N) (32 Deg) 658+18	658W	MONITOR	4/13/17 6:15 PM
2013885	2 OMRA Contact Rail Anchor Broken 656+00	656W	APPR	7/21/15 1:31 PM
2254518	2 OMRA Rail Out of Surface / Pumping / Mud 654+30	654W	INPRG	1/16/16 2:31 PM
2013881	2 OMRA Insulator Cup Plate Bolts Missing 647+35	647W	APPR	7/21/15 1:29 PM
3004328	2 OMRA Rail Chipped / Ties Pumping (5) 647+15	647W	MONITOR	7/18/17 3:19 PM
3006590	2 OMRA Rail Chipped (N) 645+80	645W	MONITOR	7/20/17 9:04 AM
2041952	2 OMRA Rail Chipped (N) 642+00	642W	MONITOR	8/11/15 3:04 PM
3006592	2 OMRA Rail Chipped/Pumping (N) 640+40-640+45	640W	MONITOR	7/20/17 9:30 AM
2089690	2 OMRA Rail Head Pitted (N) (1"x1/8") 640+40 - 640+42	640W	MONITOR	9/17/15 7:45 AM
2041950	2 OMRA Rail Chipped (N) (3) 639+20 - 639+22	639W	MONITOR	8/11/15 3:03 PM
2254521	2 OMRA Rail Head Chipped(3) (N) 638+25 - 638+45	638W	APPR	1/16/16 2:37 PM
3006627	2 OMRA Rail Chipped (3) / Pumping (N) 638+40	638W	MONITOR	7/20/17 9:52 AM
2254530	2 OMRA Rail Head Chipped (N) 637+45	637W	MONITOR	1/16/16 2:42 PM
2013761	2 OMRA Ties Pumping (N) 627+00	627W	HOLD	7/21/15 11:30 AM
2868191	2 OMRA Rail Side Worn (S) (30 Deg) 622 - 604	622W	MONITOR	4/13/17 6:37 PM
2089680	2 OMRA Rail Head Chipped (N) 618+80	618W	MONITOR	9/17/15 7:43 AM
13742	2 OMRA Vegetation Overgrowth No Clearance 614 - 599+80	614W	HOLD	7/21/15 11:04 AM

2774274	2 OMRA Ties Pumping / Out of Surface 610+55	611W	INPRG	2/8/17 8:10 AM
2014981	2 OMRA IJ Battered (N) 610+55	610W	APPR	7/22/15 6:58 AM
2014042	2 OMRA Ties Pumpling (20) 597+50	597W	HOLD	7/21/15 3:15 PM
2013760	2 OMRA Ties Pumping / Out of Alignment (N/S) 567+70 - 567+50	567W	MONITOR	7/21/15 11:29 AM
2013878	2 OMRA Ties Pumping / Mud 552+20 - 552+40	552W	APPR	7/21/15 1:23 PM
2013800	2 OMRA Restraining Rail Joint Bars Broken 552+20	552W	APPR	7/21/15 12:01 PM
2013764	2 OMRA Ties Pumping (N/S) OC 3A 532+40	532WSWOC3A	APPR	7/21/15 11:32 AM
2692085	2 OMRA Brace Plate Loose (3) OC 3A 532+20	532WSWOC3A	APPR	12/5/16 9:16 PM
2174519	2 OMRA Contact Rail Top Worn / Burnt 525+80	532W	MONITOR	11/12/15 7:00 AM
2812585	2 OMRA Out of Surface/Pumping 532+30	532W	INPRG	3/7/17 8:21 AM
2711748	2 OMRA Insulator Cup & Hardware Missing 531+20	531W	APPR	12/21/16 10:14 PM
2116500	2 OMRA Ballast Low 531+10 - 528+80	528W	INPRG	10/6/15 2:56 PM
2017738	2 OMRA Ties Pumping/Mud Condition OC 527+50 - 527+00	527W	APPR	7/24/15 10:54 AM
2924021	2 OMRA Rail Chipped (N) OC 1A 526+05	526W	APPR	5/23/17 11:38 AM
2924041	2 OMRA Brace Hardaware Missing (N) OC 1A 525+80	525WSWOC1A	APPR	5/23/17 12:51 PM
2116519	2 OMRA Frog Point Battered /Chipped/Cracked OC 1A 526+50	525WSWOC1A	APPR	10/6/15 3:05 PM
2087942	2 OMRA Stock Rail Wheel Burns OC 1A 525+75	525WSWOC1A	MONITOR	9/16/15 7:33 AM
2013739	2 OMRA Ties Spike Killed OC 1A 526+50	525WSWOC1A	APPR	7/21/15 11:00 AM
2620975	2 OMRA Rail Wheel Burns (1) (S) 523+50	521W	APPR	10/14/16 10:00 AM
2017795	2 OMRA IJ Pumping (2) 519+82	520W	APPR	7/24/15 12:11 PM
2972968	2 OMRA Rail Wheel Burns (25) (N) 521 - 520+60	520W	INPRG	6/27/17 9:09 AM
2923961	2 OMRA Mono Block Tie Broken 519+40	519W	APPR	5/23/17 10:45 AM
2923915	2 OMRA Ballast Low 517-504	517W	INPRG	5/23/17 9:57 AM
2924025	2 OMRA Rail Sideworn (S) (30 deg) 515-506	514W	APPR	5/23/17 11:57 AM
2014079	2 OMRA Contact Rail Anchor Broken 511+00	511W	APPR	7/21/15 4:08 PM
2801399	2 OMRA Out of Surface / Alignment / Mud 507+75 & 503+75	507W	INPRG	2/28/17 9:39 AM
2014074	2 OMRA Vegetation Overgrowth 498 - 479	498W	APPR	7/21/15 3:52 PM
3057136	2 OMRA Vegatation Stricking Train 495+60	495W	INPRG	8/26/17 3:02 PM
2955050	2 OMRA Vegetattion Overhanging ML 2 494+40	494W	APPR	6/13/17 3:01 PM
3063330	2 OMRA Coverboard Missing 490+30 - 489+00	490W	APPR	8/31/17 1:51 PM
2955059	2 OMRA Vegetation Overgrowth 471-470	471W	APPR	6/13/17 3:06 PM
2013901	2 OMRA Contact Rail Anchor Rods Broken 452+00	452W	APPR	7/21/15 1:51 PM
2923951	2 OMRA Ballast Low 451-443	451W	INPRG	5/23/17 10:22 AM
2013941	2 OMRA Contact Rail Mounting Plate Rubbing Concrete 446+55	446W	APPR	7/21/15 2:13 PM
2013818	2 OMRA POCKET Timbers Rotted (40) MM 1B 440+00	440WSWMM1B	APPR	7/21/15 12:20 PM
2041948	2 OMRA IJ Battered (N/S) 440+30	440W	MONITOR	8/11/15 3:02 PM
2014072	2 OMRA Switch Timber Deteriorating (12) MM 1A 438+60-438+40	439WSWMM1A	APPR	7/21/15 3:48 PM
2618089	2 OMRA Standard Joint Battered (S) MM 1A 438+95	439WSWMM1A	APPR	10/12/16 9:58 PM
2861489	2 OMRA Standard Joint Chipped/Heel of Frog (S) MM 1A 439+10	439WSWMM1A	MONITOR	4/8/17 5:20 AM
2618057	2 OMRA Frog Point & Riser Chipped MM 1A 439+00	439WSWMM1A	APPR	10/12/16 9:06 PM
2860713	2 OMRA Rail Wheel Burns (5) (N) 439+40	439W	MONITOR	4/7/17 6:29 PM
2014147	2 OMRA Out of Surface MM 1A 440+60 - 439+20	439W	APPR	7/21/15 5:45 PM
2861483	2 OMRA Joint Huck Bolt Missing (S) 438+95	438W	APPR	4/8/17 5:06 AM
2972972	2 OMRA IJ Battered (2) (N/S) MM 437+80	437W	MONITOR	3/1/13 9:11 AM

2218854	2 OMRA Rail Corrugation (N) 431 - 419	431W	APPR	12/17/15 2:53 PM
93060	2 OMRA Ties Low Ballast 430-416	430W	APPR	11/28/15 12:06 PM
2024228	2 OMRA Vegetation Overgrowth 408-414	410W	APPR	7/30/15 8:34 AM
2013768	2 OMRA Splice Plate Broken RP 387+00	387W	APPR	7/21/15 11:37 AM
2589653	2 OMRA IJ Battered 381+00	381W	APPR	9/22/16 7:36 AM
2220164	2 OMRA Safety Walkway Pad Broken (RP Station) 378+00	378W	APPR	12/18/15 8:53 AM
2013813	2 OMRA Hixson DF Pads Deteriorated (34) 377-376+50	377W	APPR	7/21/15 12:10 PM
2089700	2 OMRA IJ Battered (2) N/S RP 17 377+15 RPE	377W	INPRG	9/17/15 7:49 AM
2015383	2 OMRA Expansion Joint Point Chipped 3" 376+80	376W	APPR	7/22/15 2:49 PM
2220168	2 OMRA Rail Chipped @ Standard Joint RP East 375+50	375W	INPRG	12/18/15 9:05 AM
2905619	2 OMRA IJ / Rail Severely Chipped/Cracked (S) 375+50	375W	COMP	5/9/17 4:59 PM
2955073	2 OMRA Rail Side Worn (S) (29 deg) Crossover 375-375+80	375W	COMP	6/13/17 3:18 PM
2013822	2 OMRA Shoulder Bolt Stripped / #2 Bolt Loose (S) 376+30 RPE	374WSWRP17	APPR	7/21/15 12:30 PM
2051531	2 OMRA Frog Point Worn/Batterd RP 17 375+80 RPE	374WSWRP17	MONITOR	8/19/15 8:07 AM
2972965	2 OMRA IJ Battered/Cracked (1) (N) RP 374+80 RPE ???	374W	APPR	4/9/13 9:02 AM
2924055	2 OMRA IJ Battered/Cracked (N/S) 373+80	373W	APPR	5/23/17 1:08 PM
2220206	2 OMRA Mono Block Tie Broken 368+35	368W	APPR	12/18/15 10:34 AM
3057139	2 OMRA Ballast Low 350 - 348+20	350W	APPR	8/26/17 3:06 PM
2051534	2 OMRA Frog Tread Worn/Chipped RA 9A	348WSWRA9A	MONITOR	8/19/15 8:08 AM
3057142	2 OMRA Ballast Low 345+90 - 344+25	345W	APPR	8/26/17 3:11 PM
3057144	2 OMRA Ballast Sink Hole 345+30	345W	APPR	8/26/17 3:12 PM
2165045	2 OMRA Vegetation Overgrowth 344-339	342W	APPR	11/7/15 5:05 AM

MARYLAND DEPARTMENT OF TRANSPORTATION

MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY INSPECTION REPORT

Inspection Date: 9 - 5 - 17 **Inspection Area:** 2 OMRA ● **Walking** ○ **Riding** **Parent WO #** 3065157

Item	Exception Chain Marker Number		Track	Position	Switch	Exception Codes		Priority	Alias
	From	To	No.		No.	Component	Defect	1-5	
1	698+90	698+65	2	north		Q 01	0 65	3	TMW2
2									
3									
4									
5									
6									
7									
8									

EXCEPTION REMARKS

1	Roadway vehicle struck and damaged fence, needs to be repaired ASAP.	WO # 3072422
2		WO #
3		WO #
4		WO #
5		WO #
6		WO #
7		WO #
8		WO #

Inspection Completed? Yes ● No ○ **If No, Why?**

Richard Nelson
Track Inspector (Print)

Richard Nelson
Track Inspector (Signature)

Joesph Brockmeyer
Track Inspector (Print)

Joe Brock
Track Inspector (Signature)

Michael Achin
Watchman (Print)

Michael Achin
Watchman (Signature)

Supervisory (Signature)

Date

Page 1

Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety F

Work Order: 3066129 (1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CHAIN_MARK Metro Chain Markers

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 09/01/17 05:38:23 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 09/01/17 04:31:18 AM

Quick PM?

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Costs

Total Planned Cost: 0.00

Total Actual Cost: 0.00

Repair Limit Amount:

Current Asset Value:

GL Account: J05-#####-047

MARYLAND DEPARTMENT OF TRANSPORTATION

MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY INSPECTION REPORT

Inspection Date: 9-6-17 **Inspection Area:** 1 JHRA ● Walking ○ Riding **Parent WO #** 3066129

Item	Exception Chain Marker Number		Track	Position	Switch	Exception Codes		Priority	Alias
	From	To	No.		No.	Component	Defect	1-5	
1	069+70	069+90	1	N/S	JH-3B	P04	P-044	2	TME1
2	068+45		1	West End	Diamond	T11	F-044	2	TME1
3	057+00		1	S		F01	F-016	2	TME1
4	045+10	045+20	1	N		R01	R-014	2	TME1
5	040+30	036+60	1	S		R01	R-069	2	TME1
6	007+65		1	N/S	CC-1B	T06	T-051	2	TMW1
7									
8									

EXCEPTION REMARKS

1	17. Loose and broken Anchor bolts for Fasteners, North + South rail JH-3B	WO # 3076704
2	Frog bolt loose	WO # 3076710
3	2 Lord pad. cracked + split	WO # 3076721
4	Water damaged rail	WO # 3076759
5	Side worn 26° Angle wear South rail	WO # 3076761
6	Frog point needs grinding	WO # 3076762
7		WO #
8		WO #

Inspection Completed? Yes ● No ○ **If No, Why?**

Joe Brockmeyer
Track Inspector (Print)

Joe Brockmeyer
Track Inspector (Signature)

Track Inspector (Print)

Track Inspector (Signature)

Richard Nelson
Watchman (Print)

Richard Nelson
Watchman (Signature)

Page ____

Work Order	Description	Work Location	Status	Reported Date
!939033	1 JHRA Coverboard Missing 003E	003E	APPR	6/1/17 2:44 PM
!02 99	1 JHRA RH Switch Point Chipped / Pitted CC 3B	004WSWCC3B	MONITOR	8/20/15 7:55
!053301	1 JHRA LH Switch Point Chipped / Pitted CC 3B	004WSWCC3B	MONITOR	8/20/15 7:59 AM
!939043	1 JHRA Coverboard Missing 005E	005E	APPR	6/1/17 2:51 PM
!694291	1 JHRA Pandrol Clips / Fasteners Missing CC 1B 007W	007WSWCC1B	APPR	12/7/16 6:45 AM
!015112	1 JHRA Coverboard Missing 10' CC 007+10W	007WSWCC1B	APPR	7/22/15 8:38 AM
!767245	1 JHRA Pandrol Fasteners Missing 009+00W	009W	APPR	2/2/17 9:06 AM
!043305	1 JHRA Two Block Tie Deteriorating (N) 013+85W	013W	MONITOR	8/12/15 3:07 PM
!043299	1 JHRA Two Block Tie Deteriorating (N) 015+75W	015W	MONITOR	8/12/15 3:03 PM
!017699	1 JHRA Contact Rail Side Approach Hardware Missing CC 1B 007+50W	017W	APPR	7/24/15 9:01 AM
!013812	1 JHRA Fastener Pad Cracked/Broken (6) 018+60W	018W	HOLD	7/21/15 12:10 PM
!939074	1 JHRA Coverboard Missing 020+30W	020W	APPR	6/1/17 3:06 PM
!735166	1 JHRA Drain Fouled 034+00E	034E	MONITOR	1/10/17 10:41 AM
!015100	1 JHRA Coverboard Broken / Bracket Missing 036+65E	036E	APPR	7/22/15 8:15 AM
!212310	1 JHRA Rail Corroded (N) 037+20W	037W	MONITOR	12/12/15 7:08 AM
!651902	1 JHRA Tunnel Water Leak 045+00E	045E	MONITOR	11/3/16 8:12 PM
!212324	1 JHRA Rail Base Corroded (N) 045+70-046+30W	045W	MONITOR	12/12/15 7:15 AM
!106086	1 JHRA Drain Clogged / Fouled (600') 053W-059W	053W	MONITOR	9/30/15 7:26 AM
!106077	1 JHRA Rail Corrugation/Pitted/Gouged (S) 053W-059W	053W	MONITOR	9/30/15 7:21 AM
!106032	1 JHRA Lord Pads Defective / Gauge Rods Installed 062E - 057E	062E	MONITOR	9/30/15 6:13 AM
!030698	1 JHRA IJ Battered BH 3B 066+80W	066WSWBH3B	MONITOR	8/3/15 6:16 AM
!493058	1 JHRA Frog Point Battered JH 1B 067E	067ESWJH1B	APPR	7/21/16 2:34 PM
!033 6	1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	067ESWJH1B	MONITOR	8/5/15 3:16
!013865	1 JHRA Restraining Rail IJ Bolts Loose 067+70E	067ESWJH1B	APPR	7/21/15 1:07 PM
!573518	1 JHRA Brace Plate Loose JH 1B	067ESWJH1B	APPR	9/8/16 11:56 PM
!665961	1 JHRA IJ Battered/ Pitted / Chipped 68+00E	068E	APPR	11/15/16 8:08 AM
!877848	2 RAJH 1 JHRA West Frog Cracked / JH Diamond 068+40E	068E	MONITOR	4/21/17 6:09 AM
!618075	1 JHRA Tunnel Water Leak 068+80W	068W	MONITOR	10/12/16 9:23 PM
!080337	1 JHRA Contact Rail Corroded 068+70 - 068+90W	068W	APPR	9/10/15 7:56 AM
!030709	1 JHRA Switch Point Chipped BH 1B 069+30W	069WSWBH1B	MONITOR	8/3/15 6:34 AM
!030720	1 JHRA IJ Battered BH 1B 069+35W	069WSWBH1B	APPR	8/3/15 6:40 AM
!493055	1 JHRA Frog Point Battered JH 3B 070+06E	070ESWJH3B	APPR	7/21/16 2:31 PM
!015104	1 JHRA Coverboard Missing 069+10E - 068+40E	070ESWJH3B	APPR	7/22/15 8:28 AM
!212327	1 JHRA Rail Head Pitted (S) 070W - 081W	070W	APPR	12/12/15 7:19 AM
!106039	1 JHRA Gauge Rods (4) / Two Block Ties 071W - 071+15	071W	APPR	9/30/15 6:34 AM
!468951	1 JHRA Contact Rail Corrosion 073W	073W	APPR	7/1/16 4:31 AM
!573519	1 JHRA Frog Wing Blocks Missing 075+00E	075E	APPR	9/8/16 11:59 PM
!015107	1 JHRA Coverboard Missing (60') 078W	078W	APPR	7/22/15 8:31 AM
!212336	1 JHRA Rail Side Worn (Tangent) 084+10 - 084+30W	084W	APPR	12/12/15 7:25 AM
!939069	1 JHRA Coverboard Missing 087W	087W	APPR	6/1/17 3:04 PM
!212341	1 JHRA Rail Corrugation 089 - 089+20W	089W	APPR	12/12/15 7:29 AM
!106102	1 JHRA Coverboard Bracket Broken 107+15	107W	APPR	9/30/15 7:30 AM
!039357	1 JHRA Station Concrete Wall/Ceiling Cracked 107+80	107W	WAPPR	8/12/17 9:46 AM
!774280	1 JHRA Drain Clogged 108- 114+60	108W	MONITOR	2/8/17 8:21
!844	1 JHRA Drain Fouled 116-119+00	116W	MONITOR	3/28/17 3:23 PM
!939065	1 JHRA Coverboard Missing 138+20	138W	APPR	6/1/17 3:01 PM

Work Order	Description	Work Location	Status	Reported Date
2939033	1 JHRA Coverboard Missing 003E	003E	APPR	6/1/17 2:44 PM
2053299	1 JHRA RH Switch Point Chipped / Pitted CC 3B	004WSWCC3B	MONITOR	8/20/15 7:55
2053301	1 JHRA LH Switch Point Chipped / Pitted CC 3B	004WSWCC3B	MONITOR	8/20/15 7:59 AM
2939043	1 JHRA Coverboard Missing 005E	005E	APPR	6/1/17 2:51 PM
2694291	1 JHRA Pandrol Clips / Fasteners Missing CC 1B 007W	007WSWCC1B	APPR	12/7/16 6:45 AM
2015112	1 JHRA Coverboard Missing 10' CC 007+10W	007WSWCC1B	APPR	7/22/15 8:38 AM
2767245	1 JHRA Pandrol Fasteners Missing 009+00W	009W	APPR	2/2/17 9:06 AM
2043305	1 JHRA Two Block Tie Deteriorating (N) 013+85W	013W	MONITOR	8/12/15 3:07 PM
2043299	1 JHRA Two Block Tie Deteriorating (N) 015+75W	015W	MONITOR	8/12/15 3:03 PM
2017699	1 JHRA Contact Rail Side Approach Hardware Missing CC 1B 007+50W	017W	APPR	7/24/15 9:01 AM
2013812	1 JHRA Fastener Pad Cracked/Broken (6) 018+60W	018W	HOLD	7/21/15 12:10 PM
2939074	1 JHRA Coverboard Missing 020+30W	020W	APPR	6/1/17 3:06 PM
2735166	1 JHRA Drain Fouled 034+00E	034E	MONITOR	1/10/17 10:41 AM
2015100	1 JHRA Coverboard Broken / Bracket Missing 036+65E	036E	APPR	7/22/15 8:15 AM
2212310	1 JHRA Rail Corroded (N) 037+20W	037W	MONITOR	12/12/15 7:08 AM
2651902	1 JHRA Tunnel Water Leak 045+00E	045E	MONITOR	11/3/16 8:12 PM
2212324	1 JHRA Rail Base Corroded (N) 045+70-046+30W	045W	MONITOR	12/12/15 7:15 AM
2106086	1 JHRA Drain Clogged / Fouled (600') 053W-059W	053W	MONITOR	9/30/15 7:26 AM
2106077	1 JHRA Rail Corrugation/Pitted/Gouged (S) 053W-059W	053W	MONITOR	9/30/15 7:21 AM
2106032	1 JHRA Lord Pads Defective / Gauge Rods Installed 062E - 057E	062E	MONITOR	9/30/15 6:13 AM
2030698	1 JHRA IJ Battered BH 3B 066+80W	066WSWBH3B	MONITOR	8/3/15 6:16 AM
2493058	1 JHRA Frog Point Battered JH 1B 067E	067ESWJH1B	APPR	7/21/16 2:34 PM
2037296	1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	067ESWJH1B	MONITOR	8/5/15 3:16
2013865	1 JHRA Restraining Rail IJ Bolts Loose 067+70E	067ESWJH1B	APPR	7/21/15 1:07 PM
2573518	1 JHRA Brace Plate Loose JH 1B	067ESWJH1B	APPR	9/8/16 11:56 PM
2665961	1 JHRA IJ Battered/ Pitted / Chipped 68+00E	068E	APPR	11/15/16 8:08 AM
2877848	2 RAJH 1 JHRA West Frog Cracked / JH Diamond 068+40E	068E	MONITOR	4/21/17 6:09 AM
2618075	1 JHRA Tunnel Water Leak 068+80W	068W	MONITOR	10/12/16 9:23 PM
2080337	1 JHRA Contact Rail Corroded 068+70 - 068+90W	068W	APPR	9/10/15 7:56 AM
2030709	1 JHRA Switch Point Chipped BH 1B 069+30W	069WSWBH1B	MONITOR	8/3/15 6:34 AM
2030720	1 JHRA IJ Battered BH 1B 069+35W	069WSWBH1B	APPR	8/3/15 6:40 AM
2493055	1 JHRA Frog Point Battered JH 3B 070+06E	070ESWJH3B	APPR	7/21/16 2:31 PM
2015104	1 JHRA Coverboard Missing 069+10E - 068+40E	070ESWJH3B	APPR	7/22/15 8:28 AM
2212327	1 JHRA Rail Head Pitted (S) 070W - 081W	070W	APPR	12/12/15 7:19 AM
2106039	1 JHRA Gauge Rods (4) / Two Block Ties 071W - 071+15	071W	APPR	9/30/15 6:34 AM
2468951	1 JHRA Contact Rail Corrosion 073W	073W	APPR	7/1/16 4:31 AM
2573519	1 JHRA Frog Wing Blocks Missing 075+00E	075E	APPR	9/8/16 11:59 PM
2015107	1 JHRA Coverboard Missing (60') 078W	078W	APPR	7/22/15 8:31 AM
2212336	1 JHRA Rail Side Worn (Tangent) 084+10 - 084+30W	084W	APPR	12/12/15 7:25 AM
2939069	1 JHRA Coverboard Missing 087W	087W	APPR	6/1/17 3:04 PM
2212341	1 JHRA Rail Corrugation 089 - 089+20W	089W	APPR	12/12/15 7:29 AM
2106102	1 JHRA Coverboard Bracket Broken 107+15	107W	APPR	9/30/15 7:30 AM
3039357	1 JHRA Station Concrete Wall/Ceiling Cracked 107+80	107W	WAPPR	8/12/17 9:46 AM
2774280	1 JHRA Drain Clogged 108- 114+60	108W	MONITOR	2/8/17 8:21
2844309	1 JHRA Drain Fouled 116-119+00	116W	MONITOR	3/28/17 3:23 PM
2939065	1 JHRA Coverboard Missing 138+20	138W	APPR	6/1/17 3:01 PM

3018167	1 JHRA Tunnel Water Leak 139+75	139W	APPR	7/29/17 2:44 PM
2014921	1 JHRA Insulator Cup Burnt (4) 140+70 -140+90	140W	APPR	7/22/15 5:41 AM
20 8	1 JHRA Rail Web/Base Corroded / Deteriorated (S) 141+00	141W	APPR	7/22/15 2:44 [illegible]
2015388	1 JHRA Contact Rail Corroded 141+00	141W	APPR	7/22/15 2:54 PM
2106112	1 JHRA Contact Rail Out of Insulator Cups 148+00	148W	APPR	9/30/15 7:38 AM
2106121	1 JHRA Rail Web/Base Corroded (N) 151+50	151W	MONITOR	9/30/15 7:47 AM
2106126	1 JHRA Rail Web/Base/Head Corroded (N) 154-165	154W	APPR	9/30/15 7:51 AM
3018179	1 JHRA Rail Top/Side Worn (N) 15/16 Combined 157+50	157W	APPR	7/29/17 3:04 PM
2844913	1 JHRA Insulator Cup Arcing 158+20	158W	MONITOR	3/28/17 3:30 PM
2051473	1 JHRA Contact Rail Base Deteriorated/Corroded 158 - 158+60	158W	MONITOR	8/19/15 7:34 AM
2208896	1 JHRA Two Block Tie Broken 158+40W	158W	APPR	12/10/15 3:58 PM
2015102	1 JHRA Coverboard Missing (60') 158 -158+60	158W	APPR	7/22/15 8:19 AM
2208898	1 JHRA Rail Pitted / Water Condition 160+60W	160W	APPR	12/10/15 4:07 PM
2208897	1 JHRA Chain Marker Sign Loose 160W	160W	APPR	12/10/15 4:02 PM
2212343	1 JHRA Pandrol Clips Broken/Deteriorating 160-166W	160W	APPR	12/12/15 7:36 AM
2087964	1 JHRA Running Rail Deteriorated (S) 154 -165	160W	MONITOR	9/16/15 7:42 AM
2106138	1 JHRA Two Block Tie Broken 161+25	161W	APPR	9/30/15 8:01 AM
2015114	1 JHRA Coverboard Missing (70') 162-162+50 &162+70-162+90	162W	APPR	7/22/15 8:42 AM
3018185	1 JHRA Contact Rail Corroded / Cup Melted 162+30	162W	APPR	7/29/17 3:48 PM
2212357	1 JHRA Rail Head Pitted (N/S) 160 - 167	163W	APPR	12/12/15 7:58 AM
2212351	1 JHRA Rail Side Worn 3/8" (23 Deg) 163 - 171	163W	APPR	12/12/15 7:44 AM
3018198	1 JHRA Coverboard Sagging 183+30	183W	APPR	7/29/17 4:55 PM
3018194	1 JHRA Rail Base Corroded 183-186+50W	183W	MONITOR	7/29/17 4:41 PM
30 9	1 JHRA Tunnel Water Leak 183+00	183W	APPR	7/29/17 4:19 [illegible]
3018200	1 JHRA Tunnel Water Leak (N) 188+00	188W	MONITOR	7/29/17 5:09 PM
3018201	1 JHRA Coverboard Sagging 195+20	195W	APPR	7/29/17 5:16 PM
2015101	1 JHRA Coverboard Brackets Missing 194+90 & 195+25	195W	APPR	7/22/15 8:17 AM
3018204	1 JHRA Coverboard Sagging 197+75	197W	APPR	7/29/17 5:20 PM
2967792	1 JHRA Contact Rail Base Deteriorated 197 - 197+20	197W	MONITOR	6/23/17 7:15 AM
3028283	1 JHRA Two Block Tie Broken 201+45	201W	APPR	8/3/17 2:51 PM
3028334	1 JHRA Two Block Tie Broken 202+05	202W	APPR	8/3/17 3:18 PM
2043013	1 JHRA Rail Corrugation (N) 202 - 214+00	202W	MONITOR	8/12/15 7:55 AM
2967793	1 JHRA Track Right of Way Fouled 212-217	212W	APPR	6/23/17 7:32 AM
2141689	2 RAJH 1 JHRA Vegetation Overgrowth ML1/2 233+90W	233W	APPR	10/23/15 2:34 PM
2013741	1 JHRA Shim Plate Loose 237+50	237W	APPR	7/21/15 11:01 AM
2017722	1 JHRA LB Foster Pads Deteriorating 238 - 268	238W	APPR	7/24/15 9:46 AM
2967794	1 JHRA Rail Side Worn (28-32 deg) 248+55-256	248W	MONITOR	6/23/17 7:40 AM
2030745	1 JHRA Shim Plate Missing 248+10W	248W	APPR	8/3/15 6:55 AM
2999780	1 JHRA Vegetation Obstruction 256 - 260	256W	APPR	7/15/17 7:43 AM
2014064	1 JHRA Coverboard Brackets Bent 267+50 - 272	267W	APPR	7/21/15 3:40 PM
2030747	1 JHRA Rail Side Worn (25 Deg) 274+00	274W	MONITOR	8/3/15 6:59 AM
2939059	1 JHRA Coverboard Missing 290+10	290W	APPR	6/1/17 2:58 PM
2939054	1 JHRA Coverboard Missing 306+00	306W	APPR	6/1/17 2:55 PM
2204238	1 JHRA Warp (-1.96"-37') cm#330+13 (Holland Report) URGENT	330W	WAPPR	12/7/15 5:42 AM
22 3	1 JHRA Warp (-1.83"-13') cm#330+41 (Holland Report) URGENT	330W	WAPPR	12/7/15 5:32 AM

Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety F

Work Order: 3065997 (1RA-OM) METRO MOW WEEKLY TRACK INSPECTION W

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CHAIN_MARK Metro Chain Markers

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 09/01/17 05:36:33 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 09/01/17 04:30:17 AM

Quick PM?

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Costs

Total Planned Cost: 0.00

Total Actual Cost: 0.00

Repair Limit Amount:

Current Asset Value:

GL Account: J05-#####-047

MARYLAND DEPARTMENT OF TRANSPORTATION

MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY INSPECTION REPORT

Inspection Date: 09 - 07 - 17 **Inspection Area:** 1 RAOM ● **Walking** ○ **Riding** **Parent WO #** 3065997

Item	Exception Chain Marker Number		Track	Position	Switch	Exception Codes		Priority	Alias
	From	To	No.		No.	Component	Defect	1-5	
1	529+50		1	North	OC - 3B	P-04	044 / 041 / 070	3	TMW1
2	529+50		1	Both	OC - 3B	X-02	022 / 072 / 063	3	TMW1
3									
4									
5									
6									
7									
8									

EXCEPTION REMARKS

1	5 ties in-a-row the switch plates are loose and moving under the switch point.	WO # 2961262
2	5 switch ties in-a-row under the switch point are deteriorated.	WO # 2961262
3		WO #
4		WO #
5		WO #
6		WO #
7		WO #
8		WO #

Inspection Completed? Yes ● No ○ **If No, Why?**

Michael Alchin
Track Inspector (Print)

Track Inspector (Signature)

Richard Nelson
Track Inspector (Print)

Track Inspector (Signature)

Joesph Brockmeyer
Watchman (Print)

Watchman (Signature)

Supervisory (Signature)

Date

Page ___

Work	Description	Work Location	Status	Reported Date
2692854	1 RAOM Splice Plate Broken 340+00	340W	APPR	12/6/16 6:38 AM
2 372	1 RAOM Mono Block Tie Broken (Hixson Type) 341+00	341W	APPR	1/20/16 2:56 PM
2254547	1 RAOM 10' Buffer Rail Chipped at Joint 342+20	342W	MONITOR	1/16/16 3:13 PM
2801372	1 RAOM Ballast Low 344+40-346+60	344W	APPR	2/28/17 9:00 AM
2801380	1 RAOM Pandrol Clips Missing RA 1B 344+15	344WSWRA1B	APPR	2/28/17 9:09 AM
2579848	1 RAOM Rail Pumping RA5 345+50	345W	APPR	9/14/16 6:37 AM
2668835	1 RAOM Rail Battered / Chipped 348+50	348W	APPR	11/17/16 7:23 AM
2013337	1 RAOM Coverboard Missing / Bracket Broken 349+80 - 350	349W	MONITOR	7/21/15 10:53 AM
2835303	1 RAOM Frog Riser Worn RA 7B 348W	349WSWRA7B	MONITOR	3/21/17 2:31 PM
2255968	1 RAOM Contact Rail Metal Bracket Bent 357+45	357W	APPR	1/18/16 8:27 AM
2751439	1 RAOM Pad Missing / Clip Missing 358+70	358W	APPR	1/24/17 10:50 AM
2014149	1 RAOM Hixson Clips Loose (9) 359+80 - 359+90	359W	APPR	7/21/15 5:52 PM
2013831	1 RAOM Contact Rail Anchor Rod Broken 360+50	360W	APPR	7/21/15 12:38 PM
2013751	1 RAOM Crosswalk Plank Missing 373+70 RPE	373W	APPR	7/21/15 11:17 AM
2255971	1 RAOM IJ Battered (S) 373+80	373W	MONITOR	1/18/16 8:33 AM
2013939	1 RAOM IJ Battered (N) 373+80 RPE	373W	APPR	7/21/15 2:12 PM
2256176	1 RAOM Expansion Joint Chipped / Battered 374+30	374W	MONITOR	1/18/16 2:07 PM
2966289	1 RAOM Rail Pumping/Shims Missing (S) 374+60-374+80	374W	APPR	12/28/12 10:00 AM
2110271	1 RAOM 9 " Expansion Joint Bolt Missing 374+30	374W	APPR	10/1/15 4:15 PM
2729091	1 RAOM Pandrol Clips Missing RP 17 374+90	374WSWRP17	APPR	1/5/17 10:20 AM
2801383	1 RAOM Frog Point Battered/ Riser Worn RP 19 375+90 - (Comp)	375W	REVIEW	2/28/17 9:18 AM
2579853	1 RAOM Stock Rail Battered RP21 375+50	375W	INPRG	9/14/16 6:42 AM
2 191	1 RAOM Expansion Joints (2) Chipped/Battered (N/S) 376+85	376W	MONITOR	1/18/16 2:20 PM
2256182	1 RAOM Stock Rails Chipped / Battered (N/S) 376+60 19B	376WSWRP19B	MONITOR	1/18/16 2:14 PM
2870560	1 RAOM Closure Rail Battered (N) RP-19B 376+32	376WSWRP19B	MONITOR	4/15/17 1:16 PM
2256202	1 RAOM Insulated Joints Battered (2) (N/S) 377+20	377W	MONITOR	1/18/16 2:24 PM
2738784	1 RAOM Expansion Joint Nuts Loose (4) 377+00	377W	APPR	1/13/17 7:08 AM
2013835	1 RAOM Safety Walk Pad Broken 385+80	385W	APPR	7/21/15 12:42 PM
2013753	1 RAOM Safety Walk Pad Broken 386+10	386W	APPR	7/21/15 11:24 AM
2013747	1 RAOM Safety Walk Pad Broken (2) 386+35	387W	APPR	7/21/15 11:15 AM
2013833	1 RAOM Safety Walk Pad Broken 377+60	388W	APPR	7/21/15 12:39 PM
2902105	1 RAOM Safety Walk Pad Broken 388+40	388W	APPR	5/6/17 8:21 AM
2718153	1 RAOM Frog Pumping RP 1B 390+70	390W	APPR	12/28/16 9:34 AM
2718150	1 RAOM Frog Pumping RP 3B 390+30	390W	APPR	12/28/16 9:28 AM
2692084	1 RAOM Rail Out of Surface / Ties Pumping 418-426	418W	APPR	12/5/16 9:09 PM
3063386	1 RAOM Corrugation Running Rail (N) 420 - 431	420W	WAPPR	8/31/17 2:44 PM
2014156	1 RAOM Contact Rail Plates Loose (4) 421+20-431+60	421W	APPR	7/21/15 6:05 PM
2203970	1 RAOM Warp (1.93"-34') cm#421+16 (Holland Report) URGENT	421W	APPR	12/7/15 3:06 AM
2822754	1 RAOM Coverboard Sagging 422+40	422W	APPR	3/14/17 11:30 AM
2751441	1 RAOM Coverboard Sagging 422+00	422W	APPR	1/24/17 10:54 AM
2692858	1 RAOM Metal Coverboard Bracket/Cup Missing 422+50	422W	APPR	12/6/16 6:48 AM
2923865	1 RAOM Insulator Cup Loose (N) 423+40	423W	APPR	5/23/17 9:13 AM
2692973	1 RAOM Metal Coverboard Bracket Broken 426+40	426W	APPR	12/6/16 8:24 AM
3 376	1 RAOM Tie Saver Pad Deteriorated (N) 424+00	432W	APPR	8/31/17 2:37 PM
2692080	1 RAOM Drain Fouled MM Platform 436	433W	MONITOR	12/5/16 8:45 PM
2136109	1 RAOM IJ Battered (2) (N/S) 437+ 80	437W	MONITOR	10/22/15 5:09 AM

2534093	1 RAOM Ties Deteriorating (20) 438+80	438W	APPR	8/12/16 8:49 AM
2013870	1 RAOM Vegetation Overgrowth (Tree) 435+50	438W	APPR	7/21/15 1:12 PM
2 589	1 RAOM Out of Suface / Out of Line MM 3 438 - 440+90	439WSWMM3	APPR	8/25/15 6:49 AM
2692081	1 RAOM Frog Riser Worn/Battered MM 3B 439+00	439WSWMM3	APPR	12/5/16 8:56 PM
2013811	1 RAOM IJ Battered (S) MM 440+30	440W	HOLD	7/21/15 12:09 PM
2973215	1 RAOM Switch Timbers Deteriorated MM 1B 440+00	440WSWMM1B	APPR	7/24/15 2:40 PM
2136114	1 RAOM Rail Corrugation (S) 445 - 451	445W	MONITOR	10/22/15 5:22 AM
2136121	1 RAOM Mono Block Ties Pumping (5) 466+35	446W	APPR	10/22/15 5:30 AM
3018178	1 RAOM Rail Out of Line / Low Ballast 446+50	446W	INPRG	7/29/17 2:57 PM
2571740	1 RAOM Ties Ballast Low 452-456	452W	APPR	9/7/16 8:54 PM
2256215	1 RAOM Rail Head Chipped (3) 466+35	466W	MONITOR	1/18/16 2:30 PM
2256224	1 RAOM Rail Side Worn (28 Deg) 468-489	468W	MONITOR	1/18/16 2:36 PM
2256260	1 RAOM Crosswalk Planks Missing 472+30	472W	APPR	1/18/16 2:46 PM
2136133	1 RAOM Hixon Clips Missing Sudbrook Tunnel 472+30	472W	APPR	10/22/15 6:02 AM
2257322	1 RAOM Crosswalk Planks Missing 477+75	477W	APPR	1/19/16 2:30 PM
2136139	1 RAOM Ties Pumping 478 - 481	478W	INPRG	10/22/15 6:15 AM
2136143	1 RAOM Rail Head Pitted (N) 486+50	486W	MONITOR	10/22/15 6:32 AM
2141367	1 RAOM Rail Pumping (S) 493+50 - 494+00	493W	INPRG	10/23/15 5:22 AM
2652826	1 RAOM Coverboard Sagging/Bracket Missing 503+80	503W	APPR	11/4/16 10:41 AM
2257331	1 RAOM Rail Side Worn (28 Deg) 508-516	503W	MONITOR	1/19/16 2:33 PM
2141368	1 RAOM Bridge Approach Out of Surface/Mud 503+75	503W	INPRG	10/23/15 5:27 AM
2812582	1 RAOM Fence Hole 504+00	504W	APPR	3/7/17 8:10 AM
2141369	1 RAOM Bridge Approach Out of Surface 507+60	507W	APPR	10/23/15 5:33 AM
2 173	1 RAOM Rail Wheel Burns (N/S) 507+60	507W	MONITOR	10/23/15 5:40 AM
2013786	1 RAOM Coverboard Missing (40') 507+70-507+90	507W	APPR	7/21/15 11:51 AM
2257347	1 RAOM Rail Wheel Burns (N/S) 510+60	510W	MONITOR	1/19/16 2:38 PM
2141375	1 RAOM Ties Low Ballast (S) 511-518+30	511W	INPRG	10/23/15 5:49 AM
2923893	1 RAOM Rail Wheel Burns (S) 519+00	519W	APPR	5/23/17 9:32 AM
2652835	1 RAOM Contact Rail Worn 519+80 ✓	519W	APPR	11/4/16 10:48 AM
2141381	1 RAOM IJ's Out of Surface 519+80-520+00 ✓	519W	INPRG	10/23/15 5:59 AM
2013866	1 RAOM Standard Plate Bolt Broken 521+20	521W	APPR	7/21/15 1:09 PM
2245833	1 RAOM Rail Top Worn/Deteriorating 523+00	523W	MONITOR	1/8/16 9:06 AM
2013767	1 RAOM Vegetation Site Obstruction OC Station 520-524	524W	APPR	7/21/15 11:37 AM
2017774	1 RAOM IJ Pumping (2) (N/S) 524+60	524W	APPR	7/24/15 11:20 AM
2017756	1 RAOM Frog Point Battered OC 1B 528+10	525WSWOC1B	APPR	7/24/15 11:06 AM
3047816	1 RAOM L/H Switch Point Wheel Burns OC 1B 526+80	525WSWOC1B	MONITOR	8/18/17 2:47 PM
3047814	1 RAOM Cross Ties 8'6" Rotted (34) 526+40-527+85	526W	APPR	8/18/17 2:46 PM
2579857	1 RAOM Frog Bolt Broken OC 5A 526+10	526W	APPR	9/14/16 6:46 AM
3047807	1 RAOM Rail Wheel Burns (Multiple) 527 - 527+80	527W	MONITOR	8/18/17 2:43 PM
2061512	1 RAOM Interlocking Out of Surface OC 1B-3B 527+80-530	527W	APPR	8/27/15 2:47 PM
2017743	1 RAOM Ties Deteriorated (9 Consecutive) OC 1B 528+10	528W	APPR	7/24/15 11:02 AM
3047793	1 RAOM Switch Point Wheel Burn 529+25 OC 3B	529W	MONITOR	8/18/17 2:33 PM
2014034	1 RAOM Heel Block Pumping OC 3B 529+75	529W	APPR	7/21/15 3:11 PM
2961262	1 RAOM Switch Ties Rotted (9) OC 3B 529+50 5 Con Sec	532WSWOC3B	APPR	6/17/17 2:06 PM
2 384	1 RAOM Ties Pumping 532+40 ROTTED	532WSWOC3B	INPRG	2/28/17 9:24 AM
2051468	1 RAOM Frog Riser Worn OC 3B 530+00	532WSWOC3B	MONITOR	8/19/15 7:32 AM
2013882	1 RAOM Heel Block Bolt Bent / Hardware Missing OC 3B	532WSWOC3B	APPR	7/21/15 1:29 PM

2013744	1 RAOM Vegetation Obstruction 540 - 544	540W	MONITOR	7/21/15 11:05 AM
3047825	1 RAOM Mono Block Ties Pumping (7) 544+20	544W	APPR	8/18/17 2:53 PM
2 264	1 RAOM Rail Side Worn (31 deg) 546+70	546W	MONITOR	6/17/17 2:13 PM
2552832	1 RAOM Bridge Approach Ties Pumping (10) 546+30	546W	APPR	8/25/16 5:36 AM
2014085	1 RAOM Bridge Approach Ties Pumping (8) 552+20	552W	INPRG	7/21/15 4:18 PM
2965277	1 RAOM Rail Out of Surface / Pumping 558+20 - 558+40	558W	INPRG	6/21/17 3:40 PM
2041936	1 RAOM Rail Side Worn (N) (30 deg) 567+80	567W	MONITOR	8/11/15 2:56 PM
3047832	1 RAOM Bridge Approach Out of Surface/Pumping 567+80	567W	APPR	8/18/17 3:01 PM
3047831	1 RAOM Brg App Out of Surface/Pumping 571+60 - 571+70	571W	APPR	8/18/17 3:00 PM
3047845	1 RAOM Contact/Running Rail Melted 597+00	597W	APPR	8/18/17 3:17 PM
2961269	1 RAOM Rail Side Worn (25-27 deg) 606 -620	606W	MONITOR	6/17/17 2:19 PM
3047840	1 RAOM Ballast Needs Regulated 608 - 610	608W	APPR	8/18/17 3:11 PM
3047846	1 RAOM Contact Rail Mounting Plate Broken 628+80 - 629	628W	APPR	8/18/17 3:19 PM
2013740	1 RAOM Vegetation Sight Obstruction 626 - 631	631W	MONITOR	7/21/15 11:01 AM
2961276	1 RAOM Ties Pumping (5) 632+30	632W	INPRG	6/17/17 2:22 PM
2961277	1 RAOM Rail Side Worn (29 deg) 654+00	654W	MONITOR	6/17/17 2:27 PM
2961280	1 RAOM Ties Pumping (10) 653+80 - 654	654W	INPRG	6/17/17 2:31 PM
2961286	1 RAOM Bridge Approach Ties Pumping (5) 657+90	657W	INPRG	6/17/17 2:39 PM
2014097	1 RAOM Vegetation Sight Obstruction 648 - 662	662W	APPR	7/21/15 5:02 PM
2041940	1 RAOM Rail Head Severly Chipped (N) 664+50	664W	MONITOR	8/11/15 2:57 PM
2014099	1 RAOM Vegetation Sight Obstruction 664 - 670	670W	APPR	7/21/15 5:04 PM
2571744	1 RAOM Switch Point Side Worn OM 1B 682+10	682WSWOM1B	APPR	9/7/16 9:02 PM
2053304	1 RAOM Frog Riser Side Worn OM 1B 682+35	682WSWOM1B	MONITOR	8/20/15 8:02 AM
2 748	1 RAOM Frog Riser Worn OM 1B 683+45	683W	APPR	9/7/16 9:07 PM
2571750	1 RAOM Frog Point Chipped 3B 687+40	687W	APPR	9/7/16 9:11 PM
2014100	1 RAOM Vegetation Sight Obstruction 682 - 690	690W	APPR	7/21/15 5:06 PM
2923757	1 RAOM Rail Corrugation (N) 420-430		APPR	5/23/17 8:04 AM

Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety F

Work Order: 3065652 (2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CHAIN_MARK Metro Chain Markers

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 09/01/17 05:33:40 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 09/01/17 04:27:18 AM

Quick PM?

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Costs

Total Planned Cost: 0.00

Total Actual Cost: 0.00

Repair Limit Amount:

Current Asset Value:

GL Account: J05-#####-047

MARYLAND DEPARTMENT OF TRANSPORTATION

MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY INSPECTION REPORT

Inspection Date: 9/8/17 **Inspection Area:** 2 RAJH ● **Walking** ○ **Riding** **Parent WO #** 3065652

Item	Exception Chain Marker Number		Track	Position	Switch	Exception Codes		Priority	Alias
	From	To	No.		No.	Component	Defect	1-5	
1	066+90E		2	North	JH1A	T 03	T 013	3	2869377
2									
3									
4									
5									
6									
7									
8									

EXCEPTION REMARKS

1	49" chip on r/h switch point. 1/8" deep	WO #
2		WO #
3		WO #
4		WO #
5		WO #
6		WO #
7		WO #
8		WO #

Inspection Completed? Yes ● No ○ **If No, Why?**

Rick Nelson
Track Inspector (Print)

Richard Nelson
Track Inspector (Signature)

Track Inspector (Print)

Track Inspector (Signature)

Michael Alchin
Watchman (Print)

Michael Alchin
Watchman (Signature)

Reading Rudisa
Supervisory (Signature)

Date

Work	Description	Work Location	Status	Reported Date
3006585	2 RAJH IJ Battered (S) 332+60	332W	MONITOR	7/20/17 8:36 AM
2 725	2 RAJH Vegetation / Sight Restriction 328 - 328+05	328W	APPR	7/24/15 9:56 AM
2013863	2 RAJH Coverboard Sagging 307+65	307W	APPR	7/21/15 1:05 PM
2043011	2 RAJH Rail Side Worn (S) (27 Deg) 278+90-275	278W	MONITOR	8/12/15 7:52 AM
3006633	2 RAJH IJ's Battered (2) (S) 272+10	272W	MONITOR	7/20/17 9:59 AM
2013781	2 RAJH Crosswalk Board Missing 272+10	272W	HOLD	7/21/15 11:48 AM
2571760	2 RAJH Drains Fouled 270 - 266	270W	MONITOR	9/7/16 9:41 PM
2041956	2 RAJH Rail Side Worn (S) (27 Deg) 264-261	264W	MONITOR	8/11/15 3:08 PM
3006643	2 RAJH Vegetation Obstruction 258+80	258W	APPR	7/20/17 10:16 AM
3006647	2 RAJH Rail Side Worn (31 deg) 257-248	257W	MONITOR	7/20/17 10:25 AM
2013860	2 RAJH CM Sign 248 Vegetation Obstruction	248W	APPR	7/21/15 1:03 PM
2014946	2 RAJH Rail Side Worn (N) (28 Deg) (1" Comb) 243-241	241W	APPR	7/22/15 6:13 AM
2141689	2 RAJH 1 JHRA Vegetation Overgrowth ML1/2 233+90W	233W	APPR	10/23/15 2:34 PM
2924067	2 RAJH Dogbone Bolts Missing 229+85	229WSWPO1A	MONITOR	5/23/17 1:16 PM
2571765	2 RAJH Rail Side Worn (N) (27-30 Deg) 220+00-226+00	226W	APPR	9/7/16 9:52 PM
2043032	2 RAJH Direct Fixation Pad Deteriorating 224+20-224+10	224W	APPR	8/12/15 8:22 AM
2626213	2 RAJH Rail Wheel Burns N/S 221+80W	221W	APPR	10/18/16 11:13 PM
2062903	2 RAJH Contact Rail End Approach Joint Burnt/Arcing 221+45	221W	APPR	8/28/15 6:20 PM
2013861	2 RAJH Coverboard Sagging 208+50	208W	APPR	7/21/15 1:03 PM
2088344	2 RAJH Tunnel Wall Section Broken 194+20	194W	APPR	9/16/15 2:47 PM
2597297	2 RAJH Pandrol Clips Broken / Corroded 193+00	193W	APPR	9/28/16 11:19 PM
2014143	2 RAJH Rail Corroded/Clips Broken N/S 193+20-192+70W	193W	APPR	7/21/15 5:39 PM
2 018	2 RAJH Tunnel Water Leak 192+80	192W	MONITOR	1/3/17 8:44 AM
2940347	2 RAJH Rail Side Worn 186 -180+00	186W	APPR	6/2/17 10:52 AM
2554632	2 RAJH Bracket Broken 184W	184W	APPR	8/26/16 11:39 PM
2198166	2 RAJH warp (-2.00 - 8ft) at cm#181+48 (Holland Report) URGENT	181W	INPRG	12/2/15 12:18 AM
2541458	2 RAJH Pandrol Clips Missing 173+00	173W	APPR	8/16/16 6:31 PM
2571328	2 RAJH Rail Top Worn/Corrugation (S) 170-160	170W	APPR	9/7/16 9:53 AM
2060123	2 RAJH Rail Side Worn (N) (26 Deg) /Top Worn (1/4") 170-166	170W	MONITOR	8/26/15 10:37 AM
2268178	2 RAJH Pandrol Clips Broken (4 Consec) 165+80	165W	APPR	1/30/16 5:19 AM
2060139	2 RAJH Rail Deteriorated / Corroded 165+80 - 165+65	165W	MONITOR	8/26/15 10:47 AM
2060141	2 RAJH Rail Base Deteriorated / Corroded (S) 164 -163+15	164W	MONITOR	8/26/15 10:51 AM
3029594	2 RAJH Coverboard Missing 163+40 - 163+20	163W	APPR	8/4/17 2:59 PM
2013895	2 RAJH Insulator Cup Smoking (Wet) 163+20	163W	APPR	7/21/15 1:47 PM
2060144	2 RAJH Rail Base Deteriorated/Corroded (S) 161+75-161+00	161W	MONITOR	8/26/15 10:56 AM
2015097	2 RAJH Coverboard Misssing 161+70 -161+40	161W	APPR	7/22/15 8:10 AM
2861525	2 RAJH Contact Rail Corroded 159+45	159W	APPR	4/8/17 6:52 AM
2015109	2 RAJH Coverboard Missing 158+10 - 157+60	158W	APPR	7/22/15 8:34 AM
2060146	2 RAJH Rail Base Deteriorated/Corroded (N) 158+65-156+40	158W	MONITOR	8/26/15 11:03 AM
3029616	2 RAJH Coverboard Sagging 158+60 - 158+40	158W	APPR	8/4/17 3:15 PM
2013890	2 RAJH Rail Deteriorated / Tunnel Water Leak (N)156+40	156W	APPR	7/21/15 1:44 PM
2060151	2 RAJH Rail Wheel Burn/Shelling (S) 153+15	153W	MONITOR	8/26/15 11:07 AM
2268179	2 RAJH Rail Wheel Burn (S) 142+15	142W	MONITOR	1/30/16 5:25 AM
2 356	2 RAJH Drain Blocked 111+50-108	110W	MONITOR	7/21/15 1:00 PM
3038446	2 RAJH Coverboard Sagging CM 108	108W	APPR	8/11/17 6:28 PM
2015099	2 RAJH Coverboard Bracket Broken/Hardware Missing 102+70	102W	APPR	7/22/15 8:12 AM

2025642	2 RAJH Rail Head Chipped/Pitted (N) 101-088	101W	MONITOR	7/31/15 2:24 PM
2202878	2 RAJH LB Foster Pads Concrete Base Broken 101+90	101W	APPR	12/5/15 6:24 AM
2861496	2 RAJH Tunnel Water Leak 096+00W	096W	MONITOR	4/8/17 5:49 AM
3029603	2 RAJH Coverboard Missing 096 - 096+10W	096W	APPR	8/4/17 3:05 PM
2013887	2 RAJH Coverboard Sagging 094-092	093W	APPR	7/21/15 1:38 PM
2202885	2 RAJH Rail Corrugation / Pitting (S) 082-071W	082W	MONITOR	12/5/15 7:00 AM
2060167	2 RAJH Coverboard Sagging 081+50 EAST OR WEST	081W	APPR	8/26/15 11:30 AM
2013854	2 RAJH Coverboard Sagging 080+20W	080W	APPR	7/21/15 12:59 PM
2060168	2 RAJH Coverboard Sagging/Burnt/Arcing 079+10	079W	APPR	8/26/15 11:35 AM
3029608	2 RAJH Coverboard Missing 079+15 - 078+75W	079W	APPR	8/4/17 3:09 PM
2013849	2 RAJH Drain Blocked / Fouled 080+20-072W	072W	MONITOR	7/21/15 12:55 PM
2014923	2 RAJH Switch Point Fastener Blocks Loose (4) 070+20E -	070ESWJH1A	APPR	7/22/15 5:45 AM
1673460	2 RAJH Coverboard Missng 20' JH 1A 068+10E	070ESWJH1A	APPR	10/15/14 1:01 PM
2043020	2 RAJH Stock Rail Side Worn (25 Deg) 070 - 070+5 JH 1A	070ESWJH1A	MONITOR	8/12/15 8:00 AM
2877826	2 RAJH Machine Timbers Deteriorated BH 3A 069+45W	069WSWBH3A	APPR	4/21/17 5:30 AM
2877832	2 RAJH Frog Riser Top Worn BH 3A 068+90W	069WSWBH3A	MONITOR	4/21/17 5:47 AM
2877829	2 RAJH 12" Heel Block Bolt Broken BH 3A 069+25W	069WSWBH3A	APPR	4/21/17 5:39 AM
2013791	2 RAJH Crosswalk Missing BH 3A 069+00W	069WSWBH3A	APPR	7/21/15 11:54 AM
2958666	2 RAJH Coverboard Missing 067- 069W	069W	APPR	6/15/17 2:31 PM
2014043	2 RAJH Ties Pumping BH 068+50 - 067+70W	068W	MONITOR	7/21/15 3:16 PM
2202890	2 RAJH Concrete Deteriorating 068+60-067W	068W	APPR	12/5/15 7:11 AM
2877848	2 RAJH 1 JHRA West Frog Cracked / JH Diamond 068+40E	068E	MONITOR	4/21/17 6:09 AM
2841524	2 RAJH Diamond S Frog Throat Cracked/Broken 068+65E	068E	MONITOR	3/25/17 10:40 AM
2877835	2 RAJH IJ's Battered & Chipped N/S 067+90W	067W	MONITOR	4/21/17 5:53 AM
2877842	2 RAJH Frog Risers Top Worn JH 3A 067+70E	067ESWJH3A	MONITOR	4/21/17 6:02 AM
2869377	2 RAJH Switch Point Chipped (N) JH ~~3A~~ 66+90E 1A Not 3A	~~067ESWJH3A~~	MONITOR	4/14/17 7:40 AM
2015103	2 RAJH Coverboard Missing 056+50 - 056+75E	056E	APPR	7/22/15 8:21 AM
2100249	2 RAJH Lord Pads Flexing (Gauge Rod Installed) 055+60E	055E	APPR	9/25/15 5:37 AM
2597312	2 RAJH Door Broken 046+00W	046W	APPR	9/28/16 11:29 PM
3018184	2 RAJH Pandrol Clips Broken (48) 046-050E	046E	APPR	7/29/17 3:33 PM
2861523	2 RAJH Pandrol Clips Broken (S) (8) 034+00W	034W	APPR	4/8/17 6:37 AM
2541446	2 RAJH Tunnel Water Leak 034+00 (EAST OR WEST)	034W	MONITOR	8/16/16 6:16 PM
2218384	2 RAJH Tunnel Water Leak (S) 034 - 032W	034W	MONITOR	12/17/15 8:13 AM
3018182	2 RAJH Rail Shelled /Pitted 028E - 031E (N)	028E	APPR	7/29/17 3:17 PM
2571333	2 RAJH Water Condition / Track Fouled 009 - 014E	014W	WAPPR	9/7/16 10:09 AM
2253600	2 RAJH Tunnel WaterLeak / Rail Chipped (N) 014+25E	014E	MONITOR	1/15/16 3:15 PM
2013908	2 RAJH Closure Rail Chipped CC 3A NEEDS CM	007WSWCC3A	APPR	7/21/15 1:57 PM