

Name A. Ribotte S. Sell Date 5-30-17 Page _____ of _____

(Please Print)

Watchman _____

WO # 2929635

Inspected From Coldspring

To Comden - Penn

Item	Exception Chain Marker No		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	<u>Riding Inspection — Rain</u>

Were switches in the area inspected? Yes _____ No ✓

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

A. Ribotte S. Sell

Track Inspectors Signature

James Row

Supervisory Certification

5/31/17

Date

Name Pillard Lam Date 5-30-2017 Page 1 of 1

(Please Print)

Watchman Schisher WO # 2929619

Inspected From Lutheruille To Cold Spring

Item	Exception Chain Marker No		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

Were switches in the area inspected? Yes ✓ No _____

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

5/31/17
Date



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 2929619 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
No new defects noted in area, Track inspection complete .

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading	
CI:					
		Mileage Meter:			
Sched Start:		Site:	LTRAIL	Job Plan:	2955
Sched Finish:		Priority:	1	Job Desc:	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Target Start:	5/31/17	Work Type:	PM	Supervisor:	
Target Finish:	5/31/17	Status:	CLOSE	Lead:	JREAVES3
Actual Start:	5/30/17	Parent:		Owner:	
Actual Finish:	5/30/17	Person Group:	MTA527	Owner Group:	
Report Date:	5/27/17	GL Account:	J05-####-05270-#####-0901-#####-#####-####-####-#####-000-30-00	Service:	
Reported By:	MTACRON	Warranty Situation Present?	N	Service Group:	
Requestor of Work:		PM Num:	48476	Classification:	2732
				Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2929619 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
No new defects noted in area, Track inspection complete .

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
20	AREPAIR		GLAM				10		N		08:00	00:00	210.32
20	AREPAIR		TSCHISLI				10		N		08:00	00:00	210.32
Total Actual Labor:												630.96	



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2929619 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
No new defects noted in area, Track inspection complete .

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor

Name Richard Lam Date 5-30-2017 Page 1 of 1

(Please Print)

Watchman Schisher WO # 2929619

Inspected From Lutherville To Collierville

Item	Exception Chain Marker No		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No new defects noted
	Track inspection complete

Were switches in the area inspected? Yes No

Is this a Special Inspection? Yes No

Reason for Special Inspection? _____

Richard Lam
Track Inspectors Signature

Jimm Rowe
Supervisory Certification

5/31/17
Date

3

5/31



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2929635 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
s5 5-31-17 No new defects noted in area.

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	6/1/17
Target Finish:	6/1/17
Actual Start:	5/31/17
Actual Finish:	5/31/17
Report Date:	5/27/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2929635 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
s5 5-31-17 No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR		ARABETT					10		N		08:00	00:00	217.36
AREPAIR		SSELL					10		N		08:00	00:00	212.00
Total Actual Labor:												429.36	



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2929635 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
s5 5-31-17 No new defects noted in area.

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor

Name A. Ribatte S. SELL Date 5-30-17 Page _____ of _____

(Please Print)

Watchman _____ WO# 2929635

Inspected From Cold Spring To Camden - Penn

Item	Exception Chain Marker No		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	<u>Riding Inspection - Rain</u>

Were switches in the area inspected? Yes _____ No ✓

Is this a Special Inspection? Yes _____ No ✓

Reason for Special Inspection? _____

A. Ribatte
Track Inspectors Signature

Jimm Row
Supervisory Certification

5/31/17
Date

3

Name A. Robette S.S.L.L Date 5-31-17 Page of

(Please Print)
Watchman A. Robette S.S.L.L WO# 2929635

Inspected From Linthicum To Cromwell - BWI

Item	Exception Chain Marker No		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	<u>No New Defects Noted in Area.</u>

Were switches in the area inspected? Yes ✓ No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

A. Robette S.S.L.L
Track Inspectors Signature

James Rowan
Supervisory Certification

6/1/17
Date

3

(Please Print)

Watchman A. Robette S. Sell WO# 2929635

Inspected From Linthicum To Cromwell - BWI

Item	Exception Chain Marker No		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	<u>No New Defects Noted in Area.</u>

Were switches in the area inspected? Yes No

Is this a Special Inspection? Yes No

Reason for Special Inspection?

A. Robette
Track Inspectors Signature

James Rowan
Supervisory Certification

6/1/17
Date

Name Rollard Schisher Date 5-31-2017 Page 1 of

(Please Print)

Watchman ham WO# 2929632

Inspected From Luthoum To Camden yards

Item	Exception Chain Marker No		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	288400		112				329	Y	N	
2.					269-3A	S305	301	Y	N	
3.					269-1A		301	Y	N	
4.	237430	237490	1			M307	316	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1	W's on both tracks are down 5/8" and pump 1 1/4"
2	Frog point is battered
3	1 rotted 9' tie
4	Field side crib are low on ballast
	Track inspection

Were switches in the area inspected? Yes No

Is this a Special Inspection? Yes No

Reason for Special Inspection? _____

Rollard Schisher Track Inspectors Signature Janna Rean Supervisory Certification 6/1/17 Date