



# Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

Crew ID: DAY-A  
WO # 2574239 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S  
no new defects noted in area

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	
Sched Start:	Site:	LTRAIL	Job Plan:	2958
Sched Finish:	Priority:	1	Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Target Start:	Work Type:	PM	Supervisor:	
Target Finish:	Status:	CLOSE	Lead:	JREAVES3
Actual Start:	Parent:		Owner:	
Actual Finish:	Person Group:	MTA527	Owner Group:	
Report Date:	GL Account:	J05-####-05270-#####-0901-#####-#####-####-####-#####-000-30-00	Service:	
Reported By:	Warranty Situation Present?	N	Service Group:	
Requestor of Work:	PM Num:	48297	Classification:	2732
			Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		



### Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2574239      TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S  
no new defects noted in area

Actual Labor												
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
AREPAIR			GLAM						N	08:00	00:00	210.32
AREPAIR			ARABETT						N	08:00	00:00	217.36
<b>Total Actual Labor:</b>											<b>427.68</b>	



### Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2574239      TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S  
no new defects noted in area

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor





# Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

Crew ID: DAY-A

WO # 2576321 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S  
rideing inspection no new defects lam for interviewtoday otts ride

Alias:	Location:	CHAIN_MARKER\LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading	
CI:				Mileage Meter:	
Sched Start:		Site:	LTRAIL	Job Plan:	2956
Sched Finish:		Priority:	1	Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Target Start:	9/15/16	Work Type:	PM	Supervisor:	
Target Finish:	9/15/16	Status:	CLOSE	Lead:	JREAVES3
Actual Start:	9/13/16	Parent:		Owner:	
Actual Finish:	9/13/16	Person Group:	MTA527	Owner Group:	
Report Date:	9/11/16	GL Account:	J05-####-05270-#####-0901-#####-#####-###-####-#####-000-30-00	Service:	
Reported By:	MTACRON	Warranty Situation Present?	N	Service Group:	
Requestor of Work:		PM Num:	48477	Classification:	2732
				Part Failure:	

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
	LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		



### Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2576321 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S  
rideing inspection no new defects lam for interviewtoday otts ride

Actual Labor												
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiur Hours	Line Cost
AREPAIR			GLAM						N	08:00	00:00	210.32
AREPAIR			ARABETT						N	08:00	00:00	217.36
<b>Total Actual Labor:</b>												<b>427.68</b>



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2576321 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
rideing inspection no new defects lam for interviewtoday otts ride

Table with columns: Task ID, Description, Status, Component, Position, Reason for Repair, Work Accomplished, Part Failure, Warranty?. Contains two rows of task data.

Date Completed

Completed By

Supervisor









## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2576230      TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N  
 1) Trk-2 CM 332+85 Field weld is battered and low.  
 2) Trks - 1 & 2 CM 333+00 - 338+50 Vegetation has grown high and & thick , this is causing a clearance and safety issue.  
 3) Trks - 1 & 2 CM - 321+00 - 315+00 Vegetation has grown high and thick, this is causing a clearance and safety issue.  
 Track inspection complete.

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		



## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2576230 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N  
 1) Trk-2 CM 332+85 Field weld is battered and low.  
 2) Trks - 1 & 2 CM 333+00 - 338+50 Vegetation has grown high and & thick , this is causing a clearance and safety issue.  
 3) Trks - 1 & 2 CM - 321+00 - 315+00 Vegetation has grown high and thick, this is causing a clearance and safety issue.  
 Track inspection complete.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiur Hours	Line Cost	
20	AREPAIR		MPOLLAF				10		N	08:00	00:00	210.32	
20	AREPAIR		RNELSON				10		N	08:00	00:00	210.32	
<b>Total Actual Labor:</b>												<b>420.64</b>	



Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2576230 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N  
 1) Trk-2 CM 332+85 Field weld is battered and low.  
 2) Trks - 1 & 2 CM 333+00 - 338+50 Vegetation has grown high and & thick , this is causing a clearance and safety issue.  
 3) Trks - 1 & 2 CM - 321+00 - 315+00 Vegetation has grown high and thick, this is causing a clearance and safety issue.  
 Track inspection complete.

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

\_\_\_\_\_ Date Completed \_\_\_\_\_ Completed By \_\_\_\_\_ Supervisor \_\_\_\_\_

Name R. Nelson Date 9/13/16 Page 1 of 1  
 (Please Print)  
 Watchman M. Pollard WO# 2576230  
 Inspected From Lutherville To Coldspring

Item	Exception Chain Marker No		Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N	W. O. #
	From	To				Comp.	Defect			
1.	332+85		2	E		R301	301	Y	N	
2.	333+00	338+50	142			M-306	355	Y	N	
3.	321+00	315+00	142			M-306	355	Y	N	
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
1.	Field weld is battered & low.
243	Vegetation growth is High & thick, clearance issue safety issue.

COPY

Were switches in the area inspected? Yes  No

Is this a Special Inspection? Yes  No

Reason for Special Inspection? \_\_\_\_\_

Richard Nelson  
Track Inspectors Signature

Juanne Remora  
Supervisory Certification

9/14/16  
Date



### Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2575606 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD  
no new defects noted in area

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	9/15/16
Target Finish:	9/15/16
Actual Start:	9/14/16
Actual Finish:	9/14/16
Report Date:	9/10/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270-#####-0901-#####-#####-###-###-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		



## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2575606 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD  
no new defects noted in area

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			GLAM						N		08:00	00:00	210.32
AREPAIR			ARABETT						N		08:00	00:00	217.36
<b>Total Actual Labor:</b>													<b>427.68</b>



### Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 2575606 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD  
no new defects noted in area

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor