

Work Order Tracking (Tr)

Bulletins: (2)

Go To

Work Order Select Action

List **Work Order** Plans Actuals Activities Measurements Axle Configuration Related Records Safety Plan Log Failure Reporting

Work Order: 2268886 **AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH IN:**

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: OLDCOURTF/ Old Court Maintenance Facility

Work Location:

Work Type: PM

Status: APPR

Status Date: 02/06/16 12:27:36 PM

Reported By: MTACRON

Phone:

Reported Date: 01/31/16 04:14:23 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address:

City:

Formatted Address: State/Province:

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#		R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	OM-5A	704+10	2-14-16	Y	Y	Y	S	Y	S	S	S	S	S	S
2	OM-7A	704+10	2-14-16	Y	Y	Y	S	S	S	S	S	S	S	S
2	OM-3A	688+30	2-14-16	S	S	S	Y	S	S	S	S	S	S	S
2	OM-1A	682+36	2-14-16	S	S	S	S	S	S	S	S	S	S	S
1	OM-1B	682+36	2-14-16	S	Y	S	S	Y	S	S	S	S	S	S
1	OM-3B	688+30	2-14-16	S	Y	S	Y	S	S	S	S	S	S	S
1	OC-5A	525+65	2-14-16	S	S	S	S	S	S	S	S	S	S	S
1	OC-1B	525+75	2-14-16	R	Y	S	S	S	S	Y	S	S	S	S
1	OC-3B	632+26	2-14-16	R	Y	Y	S	S	S	Y	S	S	S	S
2	OC-3A	632+26	2-14-16	R	R	Y	S	Y	Y	Y	S	R	S	Y
2	OC-1A	525+75	2-14-16	R	Y	Y	R	Y	Y	Y	S	S	S	S

COMMENTS DM3A Frog Area work, OM1B is in the stock rail + 14 CM. see pt side work

OM7A frog pulled + wear RH curved switch pt + RH straight stock rail wear
 OC1B wheel burn on 1st st switch point OC3B wheel burn on RH str. see so pt
 OC3A RH straight switch pt checked, point and str. closure April side wear y ties
 wheel ok point is deteriorated
 OC1A - RH stock rail has wheel burn

WORK ORDER # 2268886

Inspectors C. Goodwin / W. Garwood Date 2/14/16 Supervisor _____

Work Order Tracking (Tr)

Benefits: (2) Go To

Work Order Select Action

List
Work Order
Plans
Actuals
Activities
Measurements
Axle Configuration
Related Records
Safety Plan
Log
Failure Reporting

Work Order: 2268890 **AREA #2(MM-RP) MOW MONTHLY MAINLINE SWITCH IN:**

Classification: MTA \ METRO >>

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: OLDCOURTF/ >> Old Court Maintenance Facility

Work Location: >>

Work Type: PM

Status: APPR

Status Date: 02/06/16 12:28:54 PM

Reported By: MTACRON >>

Phone:

Reported Date: 01/31/16 04:14:25 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: >>

City:

Formatted Address: State/Province:

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #2 MM-RP

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	MM-3	439+35	2/11/16	R	S	Y	Y	S	S	R	S	S	S	S
2	MM-1A	439+35	2/11/16	Y	S	S	Y	S	S	S	Y	S	S	S
1	RP-3B	389+35	2/11/16	Y	Y	S	Y	Y	S	R	Y	Y	S	S
1	RP-1B	391+05	2/11/16	R	Y	Y	R	Y	S	R	Y	Y	S	S
2	RP-3A	391+05	2/11/16	R	Y	Y	S	Y	S	R	Y	Y	S	S
2	RP-1A	389+35	2/11/16	R	Y	Y	R	Y	S	R	S	S	S	S
2	RP-17	376+60	2/11/16	R	S	S	Y	S	S	S	S	S	S	N/A
1	RP-21	376+80	2/11/16	R	S	S	S	S	S	S	S	Y	S	N/A
1	RP-19B	376+60	2/11/16	R	S	S	Y	S	S	S	Y	S	S	N/A

COMMENTS

WORK ORDER # **2268890**

Inspectors A. Stephenson

Date 2/11/16

Supervisor _____

Work Order Tracking (Tr)

Bulletins: (2) Go Tr



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log
- Failure Reporting

Work Order: 2268894 **AREA #3(RA-PO) MOW MONTHLY MAINLINE SWITCH INS**

Classification: MTA \ METRO >>

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: OLDCOURTF/ >> Old Court Maintenance Facility

Work Location: >>

Work Type: PM

Status: APPR

Status Date: 02/06/16 12:30:08 PM

Reported By: MTACRON >>

Phone:

Reported Date: 01/31/16 04:14:28 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: >>

City:

Formatted Address: State/Province:

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #3 RA-PO

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
RA TO OM		CM#	Date	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	RA-3B	351+25		Y	Y	Y	S	Y	S	Y	S	S	Y	S
1	RA-1B	344+15		R	S	S	Y	S	S	Y	S	S	Y	S
1	RA-5A	348+55		S	S	S	S	S	S	S	S	S	Y	Y
1	RA-7B	349+10		S	S	S	S	S	S	S	S	S	Y	Y
2	RA-9A	348+10		S	S	S	Y	S	S	S	S	S	Y	S
2	RA-3A	344+15		Y	Y	R	S	Y	S	Y	Y	S	Y	S
2	RA-1A	341+25		Y	Y	R	Y	R	S	Y	S	S	Y	S
1	PO-3B	229+10		S	Y	Y	S	R	S	Y	S	S	Y	S
1	PO-1B	230+80		S	Y	Y	S	R	S	Y	S	S	Y	S
2	PO-7B	332+46		Y	Y	S	S	Y	Y	Y	Y	Y	Y	S
2	PO-3A	230+80		S	Y	R	S	R	Y	Y	Y	S	Y	S
2	PO-1A	229+10		S	Y	Y	Y	Y	S	S	Y	S	Y	S
2	PO-5B	227+40		S	R	Y	S	R	Y	Y	Y	S	Y	S

COMMENTS:

WORK ORDER # **2268894**

Inspectors

A. Schneider / S. Williams

Date

2/14/14

Supervisor

Work Order Tracking (Tr)

BUMETHS: (2) Go To

Work Order Select Action

List **Work Order** Plans Actuals Activities Measurements Axle Configuration Related Records Safety Plan Log Failure Reporting

Work Order: 2268898 **AREA #4(BH-JH) MOW MONTHLY MAINLINE SWITCH INS**

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: OLDCOURTF/ >> Old Court Maintenance Facility

Work Location: >>

* Work Type: PM

Status: APPR

Status Date: 02/06/16 12:32:54 PM

Reported By: MTACRON >>

Phone:

Reported Date: 01/31/16 04:14:30 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: >>

City:

Formatted Address:

State/Province:

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2266886

AREA #1(OM-OC) MOW MONTHLY MAINLINE SWITCH IN

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: OLDCOURTF/ >> Old Court Maintenance Facility

Work Location: >>

Work Type: PM

Status: APPR

Status Date: 02/06/16 12:27:36 PM

Reported By: MTACRON >>

Phone:

Reported Date: 01/31/16 04:14:23 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: >>

Formatted Address:

City:

State/Province:

MOW MONTHLY MANILINE SWITCH INSPECTION AREA #1 OM-OC

Track	Switch I.D.	Location	Inspection Date	The Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
OM TO RA	CM#			R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	OM-5A	704+10	2-27-16	Y	Y	Y	S	Y	S	S	S	S	S	S
2	OM-7A	704+10	2-27-16	Y	Y	Y	S	S	S	S	S	S	S	S
2	OM-3A	688+30	2-27-16	S	S	S	Y	S	S	S	S	S	S	S
2	OM-1A	682+36	2-27-16	S	S	S	S	S	S	S	S	S	S	S
1	OM-1B	682+36	2-27-16	S	Y	S	S	Y	S	S	S	S	S	S
1	OM-3B	688+30	2-27-16	S	Y	S	Y	S	S	S	S	S	S	S
1	OC-5A	525+65	2-27-16	S	S	S	S	S	S	S	S	S	S	S
1	OC-1B	525+75	2-27-16	R	Y	S	Y	S	S	S	S	S	S	S
1	OC-3B	632+26	2-27-16	R	Y	Y	S	S	S	Y	S	S	S	S
2	OC-3A	632+26	2-27-16	R	R	Y	S	Y	Y	Y	S	R	S	Y
2	OC-1A	525+75	2-27-16	R	Y	Y	R	Y	Y	Y	S	S	S	S

COMMENTS OM 3A Frog RiseK badly worn. OM 1B LEFT HAND STRAIGHT STOCK RAIL AND LEFT HAND CURVED SWITCH POINT S/C'S WORN. OM 3B FROG PITTED AND WORN RIGHT HAND CURVED SWITCH POINT AND RIGHT STRAIGHT STOCK RAIL HAVE S/C'S WEAR. OC 3A RIGHT HAND STRAIGHT SWITCH POINT IS CRACKED. SWITCH POINT AND STRAIGHT CLOSURE RAIL S/C'S WORN 4 TIES AHEAD POINT DETERIORATED.

WORK ORDER # 2268896

Inspectors A. JEFFERSON J. Williams Date 2/27/16 Supervisor 