

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2600306

Tri-Monthly Yard SWINSP Track 5,6,7,9,11,12

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD

Chain Marker Wabash Yard

Work Location:

Work Type: PM

Status: WSCH

Status Date: 09/30/16 04:21:12 AM

Reported By: MTACRON

Phone:

Reported Date: 09/30/16 04:21:11 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and CIs : Filter

0 - 0 of 0

MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK 5,6,7,9,11,&12

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Point Rail L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
Wabash	YARD	DATE	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
5	141	WEST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
6	143	WEST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
7	145	WEST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
11	151	WEST	10/2/16	S	S	S	S	R	S	S	S	S	S	S
12	153	WEST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
12	159-A	WEST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
6	119	EAST	10/2/16	S	S	S	S	Y	S	S	S	S	S	S
6	117	EAST	10/2/16	S	Y	S	S	Y	S	S	S	S	S	S
6	103	EAST	10/2/16	S	S	S	S	S	Y	S	S	S	S	S
9	121	EAST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
9	105	EAST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
11	123	EAST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
11	107	EAST	10/2/16	S	S	S	S	S	S	S	S	S	S	S
12	9A/7B	OM	10/2/16	S	S	S	S	S	S	S	S	S	S	S

COMMENTS:

2600306

Inspectors Charles

Date 10/2/16

Supervisor 

Work Order Tracking (Tr)

Find Work Order

Select Action



List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2611462

Tri-Monthly Yard SWINSP Track 13,14,15,MM,OM,PO,OC

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD Chain Marker Wabash Yard

Work Location:

Work Type: PM

Status: WSCH

Status Date: 10/07/16 04:17:20 AM

Reported By: MTACRON

Phone:

Reported Date: 10/07/16 04:17:20 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and CIs Filter

0 - 0 of 0

MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRK #13,14,15,MM,OM,PO,OC

Track	Switch I.D.	Location	Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
WABASH	YARD	DATE	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
15	171A	WEST	10-20-16	Y	Y	S	S	S	S	S	S	S	S	S
13	161	WEST	10-20-16	S	Y	S	S	S	S	S	S	S	S	S
13	139	WEST	10-20-16	S	Y	S	S	S	S	S	S	S	S	S
13	155	WEST	10-20-16	S	S	S	S	S	S	S	S	S	S	S
13	157	WEST	10-20-16	S	S	S	S	S	S	S	S	S	S	S
13	159B	WEST	10-20-16	S	S	S	S	S	S	S	S	S	S	S
15	19A	WEST	10-20-16	S	S	S	S	S	S	S	S	S	S	N/A
13	109A	EAST	10-20-16	S	S	S	S	S	S	S	S	S	S	S
14	109B	EAST	10-20-16	S	S	S	S	S	S	S	S	S	S	S
15	7A	EAST	10-20-16	S	S	S	S	S	S	S	S	S	S	S
15	9B	EAST	10-20-16	S	S	S	S	S	S	S	S	S	S	S
OM	9A/7B	TAIL	10-20-16	Y	Y	S	S	S	S	S	S	S	S	S
OM	9B	TAIL	10-20-16	Y	S	S	S	S	S	S	S	S	S	S
OC	9	SIDING	10-20-16	S	S	S	S	S	S	S	S	S	S	S
MM	1B	POCKET	10-20-16	Y	S	S	S	S	S	S	S	S	S	S
PO	7A	SIDING	10-20-16	S	S	S	S	S	S	S	S	S	S	S
PO	5A	SIDING												

COMMENTS: 171A concrete tie cracked

WORK ORDER # 2611462

Inspectors Joe Brockmeyer
 Joe Puly
 John Williams
 Jeff Woe

Date 10-20-16

Supervisor



Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2705333

Tri-Monthly Yard SWINSP Track 1

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD Chain Marker Wabash Yard

Work Location:

Work Type: PM

Status: WSCH

Status Date: 12/16/16 04:19:29 AM

Reported By: MTACRON

Phone:

Reported Date: 12/16/16 04:19:29 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and Cls Filter

0 - 0 of 0

MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK #1

Track	Switch I.D.	Location		Inspection Date	Tie Condition		Switch Pnts L/R		Closure S/C		Frog		Stock Rail		Plates		Lags/Clips		Standard Joints		Insulated Joints		Welds		Ballast	
		YARD	WEST		DATE	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S	R/Y/S
1	167-A	WEST		12-18-16	S	Y	Y	Y	S	Y	Y	Y	Y	Y	S	S	S	S	S	S	S	S	S	S	S	S
1	171-B	WEST		12-18-16	S	S	S	S	S	S	Y	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S
1	135-A	WEST		12-18-16	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S
1	133-A	WEST		12-18-16	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S
1	131-A	MIDDLE		12-18-16	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S
1	129-A	MIDDLE		12-18-16	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S
1	127-A	EAST		12-18-16	S	Y	S	Y	S	S	S	Y	S	Y	S	S	S	S	S	S	S	S	S	S	S	S
1	125-A	EAST		12-18-16	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S
COMMENTS: Switch 167-A side worn stock rail, closure rail, switch point AND SELF CONDUCTED PROS																										

WORK ORDER # 2705333

Inspectors A. JEFFERSON

John Williamson

Date 12-18-16

12-18-16

Supervisor



Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2713970

Tri-Monthly Yard SWINSP Track 2,3,4

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD Chain Marker Wabash Yard

Work Location:

Work Type: PM

Status: WSCH

Status Date: 12/23/16 04:18:38 AM

Reported By: MTACRON

Phone:

Reported Date: 12/23/16 04:18:38 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locatlons and CIs Filter

0 - 0 of 0

MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK #2,3,&4

Track	Switch I.D.	Location		Inspection Date	Tie Condition	Switch Pnts L/R	Closure S/C	Frog	Stock Rail	Plates	Lags/Clips	Standard Joints	Insulated Joints	Welds	Ballast
		YARD	DATE												
2	169	WEST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
2	167-B	WEST	12-29-16	S	S	S	S	Y	S	S	S	S	S	S	S
2	165	WEST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
2	163	WEST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
2	133-B	WEST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
2	135-B	WEST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
3	137	WEST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
2	129-B	MIDDLE	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
2	131-B	MIDDLE	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
2	125-B	EAST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
2	127-B	EAST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
3	101	EAST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S
3	113	EAST	12-29-16	S	S	Y	Y	Y	Y	S	S	S	S	S	S
3	111	EAST	12-29-16	S	S	S	S	Y	S	S	S	S	S	S	S
4	115	EAST	12-29-16	S	S	S	S	S	S	S	S	S	S	S	S

COMMENTS:

WORK ORDER # 2713970

Inspectors A. Jefferson

Date 12-29-16

Supervisor [Signature]