

Work Order Tracking (Tr)

8011

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2451531 (2OM-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 06/17/16 04:18:20 AM

Reported By: MTACRON

Phone:

Reported Date: 06/17/16 04:18:20 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1208

6301 Wabash Ave Relisterstown Plaza Baltimore

City: BALTIMOF

Formatted Address:

State/Province: MD



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report





Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 333
 END_CHAIN_MARKER: 705
 Include History: N

Inspection Completed? Yes No If No Why?

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1	360+00	388+00	2	N		M04	D03	2	TMW2
2	348+00	347+50	2	N/S		F03	D16	3	TMW2
3									
4									
5									
6									
7									
8									

Notes: ① 2 3 foot holes and 1w fence along track
 ② 20-30 wedges and missing

Track Walker: Curtis Chute  Date: 6/20/16
 Print Sign
 Watchman: Phil Williams  Date: _____
 Print Sign
 Track Inspection Supervisor: [Signature] Date: _____
 Print Sign

Work Order Tracking (Tr)

Bull

Find Work Order



Select Action



List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2451539

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO



Classification Description: MTA - METRO

Asset:



Alias:

Location: CHAIN_MARK



Metro Chain Markers



Work Location:



Work Type: PM



Status: WSCH

Status Date: 06/17/16 04:18:30 AM

Reported By: MTACRON



Phone:

Reported Date: 06/17/16 04:18:30 AM



On Behalf Of:



Consist:



Asset Details

Year:

Manufacturer:



Model:



Serial #:

Type:



Status:

Asset Condition:

Address Information

Service Address: 1206



6301 Wabash Ave Reisterstown Plaza Baltimore



City: BALTIMOF

Formatted Address:

State/Province: MD



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 75
 END_CHAIN_MARKER: 333
 Include History: N

Inspection Completed? Yes No If No Why? _____

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1	054-70	007-65	I	--	--	MOW T06	DOS	3	TMEI
2	043	042	I	--	--	MOW T01	SOI	3	TMEI
3	0067	007-5	I		1B	MOW T06	DOS	3	TMEP
4									
5									
6									
7									
8									

Notes: _____

Track Walker: John Collins
 Print: Nathaniel Cole
 Sign: [Signature] Date: 6/22/16
 Print: _____ Date: 6/22/16
 Sign: _____ Date: _____
 Watchman: _____ Date: _____
 Sign: _____ Date: _____
 Track Inspection Supervisor: [Signature] Date: _____
 Sign: [Signature] Date: _____



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 75
 END_CHAIN_MARKER: 333
 Include History: N

TMW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2106102 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	107	15	107	15	9/30/15
1 JHRA Coverboard Bracket Broken 107+15	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2014921 (APPR)	MOW-M00	1	THIRD RAIL	MOW-010	CM	MOW-C01	0	140	70	140	90	7/22/15
1 JHRA Insulator Cup Burnt (4) 140+70 -140+90	TRACK MISCELLANEOUS			BURNT (LUMBER)		INSULATOR						
2015378 (APPR)	MOW-R00	1	SOUTH	MOW-014	CM	MOW-R01	0	141	0	141	0	7/22/15
1 JHRA Rail Web/Base Deteriorated (S) 141+00	RAIL			CORRODED		RUNNING RAIL						
2015388 (APPR)	MOW-R00	1	THIRD RAIL	MOW-014	CM	MOW-C05	0	141	0	141	0	7/22/15
1 JHRA 3rd Rail Corroded 141+00	RAIL			CORRODED		THIRD RAIL						
2106112 (APPR)	MOW-C00	1	THIRD RAIL	MOW-061	CM	MOW-C05	0	148	0	148	0	9/30/15
1 JHRA 3rd Rail Unseated/Out of Insulator Cups 148+00	CONTACT RAIL			POOR SUPPORT		THIRD RAIL						
2106126 (APPR)	MOW-R00	2	NORTH	MOW-014	CM	MOW-R00	0	154	0	165	0	9/30/15
1 JHRA Rail Web/Base Corroded (N) 154-165	RAIL			CORRODED		RAIL						
2106138 (APPR)	MOW-X00	1	BOTH	MOW-016	CM	MOW-X00	0	161	25	161	25	9/30/15
1 JHRA Two Block Tie Broken 161+25	TIES			CRACKED / SPLIT		TIES						
2015101 (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	194	90	195	25	7/22/15
1 JHRA Coverboard Brackets Missing 194+90 & 195+25	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
2013746 (APPR)	MOW-R00	2	BOTH	MOW-046	CM	MOW-F05	0	230	0	230	0	7/21/15
1 JHRA Saddles Loose (5) Pandrols Missing PO1B	RAIL			MISSING		CLIP						
2013748 (APPR)	MOW-R00	2	NORTH	MOW-025	CM	MOW-R01	0	230	0	230	0	7/21/15
1 JHRA Running Rail Wheel Burns (N) 230+00	RAIL			ENGINE BURN FRACTURE (EBF)		RUNNING RAIL						

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan
- Log

Work Order: 2481668 (1RA-OM) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 08/17/16 04:18:44 AM

Reported By: MTACRON

Phone:

Reported Date: 08/17/16 04:18:44 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOR

Formatted Address:

State/Province: MD



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report

Site: METRO

Workgroup: MTA472

START_CHAIN_MARKER: 333

END_CHAIN_MARKER: 705

Include History: N



Inspection Completed?

Yes

No

If No Why?

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1									
2									
3									
4									
5									
6									
7									
8									

NO New Defects

Notes:

Track Walker:

Abraham Gale

Print

Daniel Bynum

Print

[Signature]

Sign

[Signature]

Sign

Date: 06-24-16

Date: 6-24-2016

Date: _____

Date: _____

Date: _____

Watchman:

Print

Print

Track Inspection

Supervisor: [Signature]

7.5.16

Work Order Tracking (Tr)

Bull

Find Work Order

Select Action

List

Work Order

Plans

Actuals

Activities

Measurements

Axle Configuration

Related Records

Safety Plan

Log

Work Order: 2451525

(2RA-JH) METRO MOW WEEKLY TRACK INSPECTION WA

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 06/17/16 04:18:16 AM

Reported By: MTACRON

Phone:

Reported Date: 06/17/16 04:18:16 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

City: BALTIMOF

Formatted Address:

State/Province: MD



Site: METRO
Workgroup: MTA472
START_CHAIN_MARKER: 75
END_CHAIN_MARKER: 333
Include History: N

Inspection Completed? Yes No

If No Why? _____

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1									
2									
3									
4									
5									
6									
7									
8									

Notes: Riding Insp.

Track Walker: Alvin JEFFERSON
Print

Alvin Jefferson
Sign

Date: 6-26-16

Print

Sign

Date: _____

Print

Sign

Date: _____

Track Inspection Supervisor: [Signature]
Print

F.S. 16
Sign

Date: _____



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 75
 END_CHAIN_MARKER: 333
 Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2060168 (WAPPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	79	10	79	10	8/26/15
2 RAJH Coverboard Sagging/Burnt/ Arcing 079+10	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2013854 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-C02	0	80	20	80	20	7/21/15
2 RAJH Coverboard Sagging 380+20W	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2433286 (APPR)	MOW-R00	3	SOUTH	MOW-069	CM	MOW-R01	0	81	0	102	0	6/1/16
Running rail is side worn	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2060167 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	81	50	81	50	8/26/15
2 RAJH Coverboard Sagging 381+50	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2013887 (APPR)	MOW-M00	1	THIRD RAIL	MOW-044	CM	MOW-C02	0	93	0	93	0	7/21/15
2 RAJH Coverboard Sagging 393+00	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2015099 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	102	70	102	70	7/22/15
2 RAJH Coverboard Bracket Broken/Hardware Missing 102+70	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2292436 (APPR)	MOW-B00	1	PLATFORM	MOW-042	CM	MOW-B00	0	107	80	107	80	2/18/16
2 RA-JH west end of upton water tank track 2	TUNNEL			LEAKING		TUNNEL						
2013856 (APPR)	MOW-L00	1	BOTH	MOW-004	CM	MOW-B01	0	110	0	108	0	7/21/15
2 RAJH Drain Blocked 110-108	LEAKS			BLOCKAGE		TUNNEL DRAIN						
2013890 (APPR)	MOW-R00	1	BOTH	MOW-022	CM	MOW-R01	0	156	40	156	40	7/21/15
2 RAJH Running Rail Deteriorated 156+40	RAIL			DETERIORATING		RUNNING RAIL						
2433131 (COMP)	MOW-M00	4	THIRD RAIL	MOW-022	CM	MOW-C01	0	163	0	163	0	6/1/16
insulator cup	TRACK MISCELLANEOUS			DETERIORATING		INSULATOR						



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 75
 END_CHAIN_MARKER: 333
 Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2013895 (APPR)	2 RAJH Insulator Cup Smoking (Wet) 163+20	1	THIRD RAIL	MOW-084	CM	MOW-C01	0	163	20	163	20	7/21/15
2433283 (APPR)	2 RAJH Insulator Cup Smoking (Wet) 163+20					INSULATOR						
2088344 (APPR)	2 RAJH Tunnel Wall Section Broken 194+20	2	SOUTH	MOW-016	CM	MOW-B03	0	194	20	194	20	9/16/15
2013861 (APPR)	2 RAJH Coverboard Sagging 208+50	1	NORTH	MOW-044	CM	MOW-C02	0	208	50	208	50	7/21/15
2063554 (APPR)	2 RAJH 3rd Rail Metal Bracket Broken/Bent 221+35	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	221	35	221	35	8/29/15
2062903 (APPR)	2 RAJH 3rd Rail End Approach Joint Burnt/Arcing 221+45	2	THIRD RAIL	MOW-002	CM	MOW-C06	0	221	45	221	45	8/28/15
2043032 (APPR)	2 RAJH Direct Fixation Pad Deteriorating 224+20-224+10	2	BOTH	MOW-022	CM	MOW-G00	0	224	20	224	10	8/12/15
2017792 (APPR)	2 RAJH Concrete Tie Cracked PO 227+40	1	BOTH	MOW-016	CM	MOW-X00	0	227	40	227	40	7/24/15
2014950 (APPR)	2 RAJH Wheel Burns (7) (S) PO 228+50-228+30	2	SOUTH	MOW-003	CM	MOW-R01	0	228	30	228	50	7/22/15
2017776 (APPR)	2 RAJH Wheel Burns (6) (S) PO 229+90	1	SOUTH	MOW-025	CM	MOW-R01	0	229	90	229	90	7/24/15



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 75
 END_CHAIN_MARKER: 333
 Include History: N

TMW2 (TRACK METRO WEST 2) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2014946 (APPR)	MOW-R00	2	NORTH	MOW-069	CM	MOW-R01	0	241	0	241	0	7/22/15
2 RAJH Rail Side Worn (N) (25 Deg) 241+00	RAIL			SIDE WEAR (RAIL)		RUNNING RAIL						
2013860 (APPR)	MOW-Q00	1	NORTH	MOW-081	CM	MOW-Q03	0	248	0	248	0	7/21/15
2 RAJH Vegetation Obstructing CM Sign 248	RIGHT OF WAY			VEGETATION (EXCESSIVE GROWTH)		ROW VEGETATION						
2014146 (APPR)	MOW-F00	2	BOTH	MOW-046	CM	MOW-F05	0	268	0	236	0	7/21/15
2 RAJH Pandrol Clips Missing 268 - 236+00	FASTENERS			MISSING		CLIP						
2013863 (APPR)	MOW-M00	1	NORTH	MOW-044	CM	MOW-C02	0	307	50	307	50	7/21/15
2 RAJH Coverboard Sagging 307+50	TRACK MISCELLANEOUS			LOOSE / SLACK		COVERBOARD						
2017725 (APPR)	MOW-M00	1	SOUTH	MOW-081	CM	MOW-Q03	0	328	0	328	5	7/24/15
2 RAJH Vegetation / Sight Restriction 328 - 328+05	TRACK MISCELLANEOUS			VEGETATION (EXCESSIVE GROWTH)		ROW VEGETATION						

Number of Records: 25



TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2017775 (APPR)	MOW-R00	2	BOTH	MOW-059	CM	MOW-R00	0	227	40	231	30	7/24/15
2 RAJH Interlocking Out of Surface PO 231+30-227+40	RAIL			OUT OF SURFACE		RAIL						
2014955 (APPR)	MOW-X00	3	BOTH	MOW-063	CM	MOW-X02	0	228	40	228	40	7/22/15
2 RAJH 14' Frog Timber Rotted PO 5B 228+40	TIES			ROTTED		SWITCH TIES						
2017777 (APPR)	MOW-T00	1	LEFT	MOW-085	CM	MOW-T03	0	228	70	228	90	7/24/15
2 RAJH LH Switch Point Wheel Burns PO 5B 228+70 - 228+90	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2097064 (APPR)	MOW-M00	1	BOTH	MOW-017	CM	MOW-T07	0	228	70	228	70	9/23/15
2 RAJH Heel Block Bolts (2) / Washer Broken (1) PO 5B 228+70	TRACK MISCELLANEOUS			DAMAGED HARDWARE		HEEL BLOCK BOLTS						
2014958 (APPR)	MOW-M00	1	LEFT	MOW-044	CM	MOW-R09	0	228	75	228	75	7/22/15
2 RAJH Switch Point Stop Braces Loose PO 5B 228+75	TRACK MISCELLANEOUS			LOOSE / SLACK		RESTRAINING RAIL BRACE						
2014145 (APPR)	MOW-R00	1	LEFT	MOW-025	CM	MOW-T01	0	229	0	229	0	7/21/15
2 RAJH Stock Rail Wheel Burns PO 5B 229+00	RAIL			ENGINE BURN FRACTURE (EBF)		STOCK RAIL						
2017793 (APPR)	MOW-R00	2	BOTH	MOW-003	CM	MOW-T06	0	229	0	229	0	7/24/15
2 RAJH Frog Point/Riser Battered PO 1A 229	RAIL			BATTERED		FROG						
2058572 (WAPPR)	MOW-M00	1	BOTH	MOW-044	CM	MOW-M00	0	229	0	229	0	8/25/15
1 JHRA Front Rod Nut Loose PO 3B 229+00	TRACK MISCELLANEOUS			LOOSE / SLACK		TRACK MISCELLANEOUS						
2017780 (APPR)	MOW-R00	1	LEFT	MOW-025	CM	MOW-T01	0	229	10	229	30	7/24/15
2RAJH CM 229+10 - 229+30, Sw# PO-1A, 5 wheel burns on left hand straight switch point.	RAIL			ENGINE BURN FRACTURE (EBF)		STOCK RAIL						



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 75
 END_CHAIN_MARKER: 333
 Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2017781 (APPR)	MOW-T00	1	RIGHT	MOW-085	CM	MOW-T03	0	229	10	229	20	7/24/15
2 RAJH Switch Point Wheel Burns(4) PO 1A 229+10 - 229+20	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2017678 (APPR)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	229	70	229	70	7/24/15
1 JHRA Adjustable Brace Plate Missing 229+70 PO-3B	PLATES			MISSING		PLATES						
2017696 (APPR)	MOW-M00	1	BOTH	MOW-046	CM	MOW-R02	0	229	70	229	70	7/24/15
1 JHRA Guard Rail Screw Spikes Missing PO 3B	TRACK MISCELLANEOUS			MISSING		GUARD RAIL						
2034599 (APPR)	MOW-M00	1	BOTH	MOW-046	CM	MOW-T06	0	229	75	229	75	8/6/15
2 RAJH Frog Joint Bolt Missing PO 1A 229+75	TRACK MISCELLANEOUS			MISSING		FROG						
2050074 (WAPPR)	MOW-R00	2	BOTH	MOW-076	CM	MOW-T06	0	230	0	230	0	8/18/15
1 JHRA Frog Point/Riser Worn PO 1B	RAIL			TOP WEAR (RAIL)		FROG						
2080383 (APPR)	MOW-P00	1	BOTH	MOW-046	CM	MOW-P01	0	230	15	230	15	9/10/15
1 JHRA Insulated Tie Plate Missing 230+15	PLATES			MISSING		STANDARD TIE PLATE						
2014968 (APPR)	MOW-P00	1	BOTH	MOW-046	CM	MOW-P05	0	230	20	230	20	7/22/15
2 RAJH Frog Plate Missing PO 3A 230+20	PLATES			MISSING		FROG PLATE						
2017716 (APPR)	MOW-M00	2	BOTH	MOW-046	CM	MOW-X22	0	230	20	230	20	7/24/15
1 JHRA Guard Rail Screw Spikes Missing PO 1B	TRACK MISCELLANEOUS			MISSING		SCREW SPIKE						
2014972 (APPR)	MOW-P00	1	SOUTH	MOW-046	CM	MOW-P00	0	230	55	230	55	7/22/15
2 RAJH Heel Block Tie Plate Missing PO 3A 230+55	PLATES			MISSING		PLATES						



Site: METRO
 Workgroup: MTA472
 START_CHAIN_MARKER: 75
 END_CHAIN_MARKER: 333
 Include History: N

TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2077038 (APPR)	1 JHRA #3 Switch Rod Striking Timber PO 1B 230+70	1	BOTH	MOW-055	CM	MOW-T00	0	230	70	230	70	9/8/15
	TURNOUTS SWITCHES			OUT OF ADJUSTMENT		TURNOUTS / SWITCHES						
2017784 (APPR)	2 RAJH Closure Rail/Switch Points Wheel Burns PO 3A	2	BOTH	MOW-085	CM	MOW-T03	0	230	84	230	84	7/24/15
	TURNOUTS SWITCHES			WHEEL BURNS		SWITCH POINT						
2014978 (APPR)	2 RAJH Insulator Cup & Bracket Loose PO 3A 230+85	1	THIRD RAIL	MOW-044	CM	MOW-C03	0	230	85	230	85	7/22/15
	TRACK MISCELLANEOUS			LOOSE / SLACK		COVER BOARD BRACKET						
2017785 (APPR)	2 RAJH Standard Joint/Stock Rail Battered PO 3A 230+90	2	BOTH	MOW-003	CM	MOW-T01	0	230	90	230	90	7/24/15
	RAIL			BATTERED		STOCK RAIL						
2110269 (APPR)	2 RAJH Standard Joint/Huck Bolts Loose (2) 230+90 PO 3A	1	NORTH	MOW-044	CM	MOW-R07	0	230	90	230	90	10/1/15
	TRACK MISCELLANEOUS			LOOSE / SLACK		JOINT BAR BOLT						
2014982 (APPR)	2 RAJH Stock Rail Out of Surface PO 7B 231+00	2	BOTH	MOW-059	CM	MOW-T01	0	231	0	231	0	7/22/15
	RAIL			OUT OF SURFACE		STOCK RAIL						
2013845 (APPR)	2 RAJH Switch Point/Stock Rail Pumping (S) PO 7B 231+10	2	BOTH	MOW-062	CM	MOW-T03	0	231	10	231	10	7/21/15
	TURNOUTS SWITCHES			PUMPING		SWITCH POINT						
2110263 (APPR)	2 RAJH Frog Wing Bolt Broken PO 7B 231+50	2	BOTH	MOW-017	CM	MOW-T11	0	231	50	231	50	10/1/15
	TRACK MISCELLANEOUS			DAMAGED HARDWARE		FROG BOLT						
2013904 (APPR)	2 RAJH Frog Screw Spikes Missing/Frog Wing Battered PO 7B 231+65	2	BOTH	MOW-059	CM	MOW-X00	0	231	65	231	65	7/21/15
	TURNOUTS SWITCHES			OUT OF SURFACE		TIES						

Number of Records: 27