

Work Order Tracking (Tr)

Query

- List View**
- Work Order
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records

Work Order: [Attachments](#)

Classification: Site:

Classification Description: Failure Class:

Asset: Problem Code:

Alias: Priority:

Location: Asset/Location Priority:

Work Location: Is Task?

* Work Type: Parent WO:

Status: Warranty Situation Present: N

Status Date: Maintenance Alert?

Reported By: Repair Order?

Phone: Has Follow-up Work?

Reported Date: Quick PM?

On Behalf Of:

Consist:

Asset Details

Costs

Year: <input type="text"/>	Total Planned Cost: <input type="text" value="0.00"/>
Manufacturer: <input type="text"/>	Total Actual Cost: <input type="text" value="0.00"/>
Model: <input type="text"/>	Repair Limit Amount: <input type="text"/>
Serial #: <input type="text"/>	Current Asset Value: <input type="text"/>
Type: <input type="text"/>	GL Account: <input type="text" value="J05-####-04"/>
Status: <input type="text"/>	Accepts Charges? <input checked="" type="checkbox"/>

RIGHT OF WAY TRACK INSPECTION REPORT

Inspection Date: 1/31/18 Inspection Area: 2 RAJH Walking Riding * Parent WO # 3266174

Item	Exception Chain Marker Number		Track No.	Position	Switch No.	Exception Codes		Priority 1-5	Alias
	From	To				Component	Defect		
1	067	90W	2	Both		R08	003	3	TMW2
2									
3									
4									
5									
6									
7									

EXCEPTION REMARKS

Use Priority Coding: 1 2 3 4 5

1	Both U's battered and pumping								Child WO #	2877835
									Child WO #	
									Child WO #	
									Child WO #	
									Child WO #	
									Child WO #	
									Child WO #	

Inspection Completed? Yes No If No, Why? _____

Track Inspector (Print) Michael Alchin

Track Inspector (Signature) *Michael Alchin*

Track Inspector (Print) Richard Nelson

Track Inspector (Signature) _____

Watchman (Print) _____

Watchman (Signature) *Richard Nelson*

Richard Nelson
 Supervisor (Signature)

* A slow speed (less than 5 mph) rail vehicle inspection

Right Of Way Track Section Inspectors Report

2RA-JH - Workgroup: MTA472

START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	ALIAS	COMPONENT	QTY	DEFECT	PRI CODE	POSITION	REPORT DATE	WORK ORDER
0	0	0	0	TMW2CC3A	LEAD OR CLOSURE RAIL	0	CHIPPED / PITTED	2	LEFT	7/21/15	2013908
9	0	14	0	TME2	TUNNEL DRAIN	0	TRASH AND DEBRIS	2	BOTH	9/7/16	2571333
14	25	0	0	TME2	RUNNING RAIL	0	CHIPPED / PITTED	3	NORTH	1/15/16	2253600
28	0	31	0	TME2	RUNNING RAIL	0	SHELLED	2	NORTH	7/29/17	3018182
34	0	32	0	TMW2	TUNNEL STRUCTURE	0	LEAKING	2	SOUTH	12/17/15	2218384
34	0	0	0	TMW2	TUNNEL LEAK	0	LEAKING	2	BOTH	8/16/16	2541446
34	0	34	0	TMW2	CLIP	8	BROKEN/SHEARED	2	SOUTH	4/8/17	2861523
46	0	0	0	TMW2	TUNNEL SHAFT	1	DAMAGED HARDWARE	2	SOUTH	9/28/16	2597312
46	40	0	0	TME2	RAIL	0	CORRUGATED		NORTH	6/15/17	2958710
46	0	50	0	TME2	CLIP	0	BROKEN/SHEARED	3	BOTH	7/29/17	3018184
46	40	0	0	TMW2	RUNNING RAIL	0	CORRODED	2	NORTH	10/13/17	3127426
46	0	50	0	TME2	TUNNEL INVERT (TRACKBED)	0	TRASH AND DEBRIS	3	BOTH	11/29/17	3186993
49	85	50	10	TME2	TUNNEL INVERT (TRACKBED)	0	BLOCKAGE	3	BOTH	11/29/17	3187001
55	60	0	0	TME2	LORD	0	LATERAL MOVEMENT	3	BOTH	9/25/15	2100249
56	50	56	75	TME2	COVERBOARD	0	SAFETY HAZARD	3	THIRD RAIL	7/22/15	2015103
59	50	54	0	TME2	RAIL	0	CHIPPED / PITTED		NORTH	6/15/17	2958693
59	50	54	0	TMW2	RUNNING RAIL	0	CHIPPED / PITTED	3	SOUTH	10/13/17	3127421
60	0	60	90	TMW2	TUNNEL DRAIN	0	TRASH AND DEBRIS	2	BOTH	10/13/17	3127422
66	90	0	0	TME2JH1A	SWITCH POINT	0	CHIPPED / PITTED	3	RIGHT	4/14/17	2869377
67	0	68	0	TMW2	CONTINUOUS GROUT PLINTH	0	DETERIORATING	3	BOTH	12/5/15	2202890
67	90	0	0	TMW2	INSULATED JOINT	0	BATTERED		BOTH	4/21/17	2877835
67	70	0	0	TME2JH3A	FROG	0	TOP WEAR (RAIL)	2	SOUTH	4/21/17	2877842
67	0	69	0	TMW2	COVERBOARD	0	SAFETY HAZARD	3	THIRD RAIL	6/15/17	2958666
67	0	0	0	TME2JH3A	SWITCH POINT	0	CHIPPED / PITTED	3	LEFT	10/5/17	3115055
67	0	68	10	TME2JH1A	COVERBOARD	100	MISSING	2	THIRD RAIL	10/15/14	3140927
68	50	67	70	TMW2	CROSSTIES 8' 6"	55	PUMPING	4	BOTH	7/21/15	2014043
68	65	0	0	TMEXJH	FROG	0	CRACKED / SPLIT	3	WEST	3/25/17	2841524
68	90	0	0	TMW2BH3A	FROG	0	NEEDS WELDING	2	SOUTH	4/21/17	2877832
69	0	0	0	TMW2BH3A	SAFETY WALK	0	MISSING	2	SOUTH	7/21/15	2013791
69	45	0	0	TMW2	SWITCH TIES	2	DETERIORATING	3	BOTH	4/21/17	2877826
69	25	0	0	TMW2BH3A	HEEL BLOCK BOLTS	1	DAMAGED HARDWARE	3	SOUTH	4/21/17	2877829
70	0	70	5	TME2JH1A	STOCK RAIL	25	SIDE WEAR (RAIL)	3	RIGHT	8/12/15	2043020
79	10	0	0	TMW2	COVERBOARD	0	ARCING	3	THIRD RAIL	8/26/15	2060168

No Charge Comment 3

Sw Pt Side

Right Of Way Track Section Inspectors Report

2RA-JH - Workgroup: MTA472

START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	ALIAS	COMPONENT	QTY	DEFECT	PRI CODE	POSITION	REPORT DATE	WORK ORDER
79	15	78	75	TMW2	COVERBOARD	0	SAFETY HAZARD	3	THIRD RAIL	8/4/17	30296608
80	20	72	0	TMW2	TUNNEL DRAIN	0	TRASH AND DEBRIS	2	BOTH	7/21/15	2013849
80	20	0	0	TMW2	COVERBOARD	0	POOR SUPPORT	2	NORTH	7/21/15	2013854
81	50	0	0	TMW2	COVERBOARD	0	LOOSE / SLACK	2	THIRD RAIL	8/26/15	2060167
82	0	71	0	TMW2	RUNNING RAIL	0	CORRUGATED	3	SOUTH	12/5/15	2202885
92	0	94	0	TMW2	COVERBOARD	0	POOR SUPPORT	2	THIRD RAIL	7/21/15	2013887
96	0	0	0	TMW2	TUNNEL	0	LEAKING	3	SOUTH	4/8/17	2861496
96	0	0	0	TMW2	COVERBOARD	0	MISSING	2	THIRD RAIL	8/4/17	3029603
101	0	88	0	TMW2	RUNNING RAIL	0	CHIPPED / PITTED	2	NORTH	7/31/15	2025642
101	90	0	0	TMW2	CONTINUOUS GROUT PLINTH	0	BROKEN/SHEARED	3	BOTH	12/5/15	2202878
102	70	0	0	TMW2	COVER BOARD BRACKET	0	BROKEN/SHEARED	2	THIRD RAIL	7/22/15	2015099
108	0	0	0	TMW2	COVERBOARD	0	POOR SUPPORT	2	THIRD RAIL	8/11/17	3038446
111	50	108	0	TMW2	TUNNEL DRAIN	0	TRASH AND DEBRIS	2	BOTH	7/21/15	2013856
142	15	0	0	TMW2	RUNNING RAIL	1	ENGINE BURN FRACTURE (EBF)	2	SOUTH	1/30/16	2268179
153	15	0	0	TMW2	RUNNING RAIL	0	ENGINE BURN FRACTURE (EBF)	3	SOUTH	8/26/15	2060151
156	40	0	0	TMW2	RUNNING RAIL	0	DETERIORATING	3	NORTH	7/21/15	2013890
158	10	157	60	TMW2	COVERBOARD	0	SAFETY HAZARD	3	THIRD RAIL	7/22/15	2015109
158	40	158	65	TMW2	RUNNING RAIL	0	CORRODED	3	NORTH	8/26/15	2060146
158	60	158	40	TMW2	COVERBOARD	0	POOR SUPPORT	2	THIRD RAIL	8/4/17	3029616
159	45	0	0	TMW2	THIRD RAIL	0	CORRODED	3	NORTH	4/8/17	2861525
161	70	161	40	TMW2	COVERBOARD	0	SAFETY HAZARD	3	THIRD RAIL	7/22/15	2015097
161	0	161	75	TMW2	RUNNING RAIL	0	CORRODED	3	SOUTH	8/26/15	2060144
163	0	0	0	TMW2	INSULATOR	0	BURNT (LUMBER)	2	THIRD RAIL	7/21/15	2013895
163	15	164	0	TMW2	RUNNING RAIL	0	CORRODED	3	SOUTH	8/26/15	2060141
163	40	163	20	TMW2	COVERBOARD	0	SAFETY HAZARD	3	THIRD RAIL	8/4/17	3029594
165	65	165	80	TMW2	RUNNING RAIL	0	CORRODED	3	NORTH	8/26/15	2060139
165	80	0	0	TMW2	CLIP	4	CORRODED	2	SOUTH	1/30/16	2268178
170	0	166	0	TMW2	RUNNING RAIL	26	WORN BEYOND TOLERANCE	3	NORTH	8/26/15	2060123
170	0	160	0	TMW2	RUNNING RAIL	0	CORRUGATED	3	SOUTH	9/7/16	2571328
173	0	0	0	TMW2	CLIP	0	MISSING	2	BOTH	8/16/16	2541458
181	48	0	0	TMW2	RUNNING RAIL	0	IMPROPER CROSSLEVEL	3	BOTH	12/2/15	2198166
184	0	0	0	TMW2	COVER BOARD BRACKET	2	BROKEN/SHEARED	2	THIRD RAIL	8/26/16	2554632
192	80	0	0	TMW2	TUNNEL LEAK	0	LEAKING	2	SOUTH	1/3/17	2726018

Right Of Way Track Section Inspectors Report

2RA-JH - Workgroup: MTA472

START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	ALIAS	COMPONENT	QTY	DEFECT	PRI CODE	POSITION	REPORT DATE	WORK ORDER
194	20	0	0	TMW2	TUNNEL STRUCTURE	0	SAFETY HAZARD	3	SOUTH	9/16/15	2088344
208	50	0	0	TMW2	COVERBOARD	0	POOR SUPPORT	2	NORTH	7/21/15	2013861
214	0	202	0	TMW2	RUNNING RAIL	1200	CHIPPED / PITTED	3	NORTH	11/15/17	3170741
214	0	202	0	TMW2	RUNNING RAIL	0	CHIPPED / PITTED	3	NORTH	11/21/17	3178162
220	0	226	0	TMW2	RUNNING RAIL	30	WORN BEYOND TOLERANCE	3	NORTH	9/7/16	2571765
221	45	0	0	TMW2	END APPROACH	0	ARCING	3	THIRD RAIL	8/28/15	2062903
221	80	0	0	TMW2	RUNNING RAIL	0	ENGINE BURN FRACTURE (EBF)		BOTH	10/18/16	2626213
224	20	224	10	TMW2	CONTINUOUS GROUT PLINTH	0	CRACKED / SPLIT	3	BOTH	8/12/15	2043032
229	85	0	0	TMW2	CROSSTIE EXTENDER/DOG BONE	1	MISSING	2	00	5/23/17	2924067
243	0	240	0	TMW2	RUNNING RAIL	28	WORN BEYOND TOLERANCE	3	NORTH	7/22/15	2014946
257	0	248	0	TMW2	RUNNING RAIL	31	WORN BEYOND TOLERANCE	4	NORTH	7/20/17	3006647
264	0	261	0	TMW2	RUNNING RAIL	27	SIDE WEAR (RAIL)	3	SOUTH	8/11/15	2041956
270	0	266	0	TMW2	RIGHT OF WAY	0	TRASH AND DEBRIS	2	BOTH	9/7/16	2571760
272	10	0	0	TMW2	SAFETY WALK	0	MISSING	2	NORTH	7/21/15	2013781
272	10	0	0	TMW2	INSULATED JOINT	2	BATTERED	2	BOTH	7/20/17	3006633
278	90	275	0	TMW2	RUNNING RAIL	27	SIDE WEAR (RAIL)	3	SOUTH	8/12/15	2043011
305	75	0	0	TMW2	COVER BOARD BRACKET	1	BROKEN/SHEARED	3	THIRD RAIL	11/15/17	3170728
307	65	307	50	TMW2	COVERBOARD	15	POOR SUPPORT	2	NORTH	7/21/15	2013863
307	50	307	70	TMW2	COVERBOARD	2	MISSING	3	THIRD RAIL	11/15/17	3170726
332	60	0	0	TMW2	INSULATED JOINT	0	BATTERED	2	SOUTH	7/20/17	3006585

