## Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2720291 Tri-Monthly Yard SWINSP Track 5,6,7,9,11,12
Classification: MTA \ METRO
Classification Description: MTA - METRO
Asset:
Alias:
Location: CMWABYARD Chain Marker Wabash Yard
Work Location:
Work Type: PM
Status: WSCH
Status Date: 12/30/16 04:16:23 AM
Reported By: MTACRON
Phone:
Reported Date: 12/30/16 04:16:23 AM
On Behalf Of:
Consist:

### Asset Details

Year:
Manufacturer:
Model:
Serial #:
Type:
Status:
Asset Condition:

### Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore
Formatted Address:
Street Address: 6301 Wabash Ave

**Multiple Assets.Locations and Cis** : Filter 0 - 0 of 0

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK 5,6,7,9,11,&12

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Point Rail L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Wabash | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 5 | 141 | WEST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 143 | WEST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 7 | 145 | WEST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 11 | 151 | WEST | 1/16/17 | S | S | S | S | R | S | S | S | S | S | S |
| 12 | 153 | WEST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 12 | 159-A | WEST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 119 | EAST | 1/16/17 | S | S | S | S | Y | S | S | S | S | S | S |
| 6 | 117 | EAST | 1/16/17 | S | Y | S | S | Y | S | S | S | S | S | S |
| 6 | 103 | EAST | 1/16/17 | S | S | S | S | S | Y | S | S | S | S | S |
| 9 | 121 | EAST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 9 | 105 | EAST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 11 | 123 | EAST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 11 | 107 | EAST | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |
| 12 | 9A/7B | OM | 1/16/17 | S | S | S | S | S | S | S | S | S | S | S |

COMMENTS:

WORK ORDER # 2720291

Inspectors Jefferson / Chandler Date 1/16/17 Supervisor 2.8.17

## Work Order Tracking (Tr)

Find Work Order | Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2730383 Tri-Monthly Yard SWINSP Track 13,14,15,MM,OM,PO,OC

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD Chain Marker Wabash Yard

Work Location:

Work Type: PM

Status: WSCH

Status Date: 01/06/17 04:19:00 AM

Reported By: MTACRON

Phone:

Reported Date: 01/06/17 04:18:59 AM

On Behalf Of:

Consist:

### Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

### Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

**Multiple Assets.Locations and CIs** Filter 0 - 0 of 0

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRK #13,14,15,MM,OM,PO,OC

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 15 | 171A | WEST | 1-26-17 | Y | Y | S | S | S | S | S | S | S | S | S |
| 13 | 161 | WEST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 139 | WEST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 155 | WEST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 157 | WEST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 159B | WEST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 19A | WEST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | N/A |
| 13 | 109A | EAST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 14 | 109B | EAST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 7A | EAST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 9B | EAST | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9A/7B | TAIL | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9B | TAIL | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| OC | 9 | SIDING | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| MM | 1B | POCKET | 1-26-17 | R | S | S | S | S | S | S | S | S | S | S |
| PO | 7A | SIDING | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| PO | 5A | SIDING | 1-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |

COMMENTS: 171A TIES CRACKED

WORK ORDER # 2730383

Inspectors A. JEFFERSON
C. CHANDLER

Date 1/26/17

Supervisor 2.8.17

**Work Order Tracking (Tr)**

Find Work Order Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan | Log

Work Order: 2829876 Tri-Monthly Yard SWINSP Track 1
Classification: MTA \ METRO
Classification Description: MTA - METRO
Asset:
Alias:
Location: CMWABYARD Chain Marker Wabash Yard
Work Location:
Work Type: PM
Status: WSCH
Status Date: 03/17/17 04:17:17 AM
Reported By: MTACRON
Phone:
Reported Date: 03/17/17 04:17:17 AM
On Behalf Of:
Consist:

**Asset Details**

Year:
Manufacturer:
Model:
Serial #:
Type:
Status:
Asset Condition:

**Address Information**

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore
Formatted Address:
Street Address: 6301 Wabash Ave

**Multiple Assets.Locations and Cls** Filter 0 - 0 of 0

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK #1

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 1 | 167-A | WEST | 3-26-17 | S | Y | Y | Y | Y | S | S | S | S | S | S |
| 1 | 171-B | WEST | 3-26-17 | S | S | S | Y | S | S | S | S | S | S | S |
| 1 | 135-A | WEST | 3-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 133-A | WEST | 3-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 131-A | MIDDLE | 3-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 129-A | MIDDLE | 3-26-17 | Y | S | S | S | S | S | S | S | S | S | S |
| 1 | 127-A | EAST | 3-26-17 | Y | S | S | S | S | S | S | S | S | S | S |
| 1 | 125-A | EAST | 3-26-17 | S | S | S | S | S | S | S | S | S | S | S |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |

COMMENTS: 167-A switch point side worn - stock rail side worn 171-B frog point side worn
129-A Tie at IJ cracked 127-A - ties in IJ. cracked

WORK ORDER # 2829876

Inspectors [signature] Joe Brockway [signature]

Date 3-26-17

Supervisor [signature]

Work Order Tracking (Tr)

Find Work Order Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan

Work Order: 2839777 Tri-Monthly Yard SWINSP Track 2,3,4

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD Chain Marker Wabash Yard

Work Location:

* Work Type: PM

Status: APPR

Status Date: 04/06/17 10:08:22 AM

Reported By: MTACRON

Phone:

Reported Date: 03/24/17 04:16:31 AM

On Behalf Of:

Consist:

**Asset Details**

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

**Address Information**

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

**Multiple Assets.Locations and CIs** Filter 0 - 0 of 0

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK #2,3,&4

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 2 | 169 | WEST | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 167-B | WEST | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 165 | WEST | 4-14-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 2 | 163 | WEST | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 133-B | WEST | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 135-B | WEST | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 3 | 137 | WEST | 4-14-17 | S | S | S | S | S | S | S | Y | S | S | S |
| 2 | 129-B | MIDDLE | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 131-B | MIDDLE | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 125-B | EAST | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 127-B | EAST | 4-14-17 | S | S | S | S | S | S | S | S | S | S | S |
| 3 | 101 | EAST | 4-14-17 | Y | Y | S | S | Y | S | S | Y | Y | S | S |
| 3 | 113 | EAST | 4-14 | S | S | S | S | S | S | S | Y | S | S | S |
| 3 | 111 | EAST | 4-14-17 | S | S | S | Y | S | S | S | S | S | S | S |
| 4 | 115 | EAST | 4-14-17 | S | S | S | Y | S | S | S | S | S | S | S |

COMMENTS: 165- Switch point sideworn 137- bolt missing in standard joint
111- frog point chipped 115 frog bolt Loose 113- standard joints gapped
101- Engine burn stock rail 101- standard joint and I is battered
101- Switch point top and side worn. 101: concrete ties cracked

**WORK ORDER #** 2839777

Inspectors Joe Brockmeyer Joe Brockmeyer Date 4-14-17 Supervisor

Alan Perkins Alan Perkins 4-14-17

## Work Order Tracking (Tr)

Find Work Order  Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan

Work Order: 2860185 Tri-Monthly Yard SWINSP Track 13,14,15,MM,OM,PO,OC

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD Chain Marker Wabash Yard

Work Location:

Work Type: PM

Status: APPR

Status Date: 04/10/17 07:56:14 AM

Reported By: MTACRON

Phone:

Reported Date: 04/07/17 04:19:09 AM

On Behalf Of:

Consist:

### Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

### Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

**Multiple Assets,Locations and Cls** Filter 0 - 0 of 0

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRK #13,14,15,MM,OM,PO,OC

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 15 | 171A | WEST | 4-18-17 | S | Y | S | S | Y | S | S | S | S | S | S |
| 13 | 161 | WEST | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 139 | WEST | 4-18-17 | S | Y | Y | S | S | S | S | S | S | S | S |
| 13 | 155 | WEST | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 157 | WEST | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 159B | WEST | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 19A | WEST | 4-18-17 | S | S | S | Y | S | S | S | S | S | S | N/A |
| 13 | 109A | EAST | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| 14 | 109B | EAST | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 7A | EAST | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 9B | EAST | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9A/7B | TAIL | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9B | TAIL | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| OC | 9 | SIDING | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| MM | 1B | POCKET | 4-18-17 | Y | S | S | S | S | S | S | S | S | S | S |
| PO | 7A | SIDING | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| PO | 5A | SIDING | 4-18-17 | S | S | S | S | S | S | S | S | S | S | S |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |

COMMENTS: 171 A - Switch point and stock rail side work 139 - Switch point and Closure rail side work RP19A frog point battered MM-1B - Bad ties

WORK ORDER # 2860185

Inspectors Joe Brockney Alan Perkins Date 4-18-17 Supervisor

Joe Brockney Alan Perkins 4-18-17

## Work Order Tracking (Tr)

Find Work Order  Select Action

List | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan

Work Order: 2848643 Tri-Monthly Yard SWINSP Track 5,6,7,9,11,12
Classification: MTA \ METRO
Classification Description: MTA - METRO
Asset:
Alias:
Location: CMWABYARD Chain Marker Wabash Yard
Work Location:
Work Type: PM
Status: APPR
Status Date: 04/06/17 09:16:40 AM
Reported By: MTACRON
Phone:
Reported Date: 03/31/17 04:19:19 AM
On Behalf Of:
Consist:

### Asset Details

Year:
Manufacturer:
Model:
Serial #:
Type:
Status:
Asset Condition:

### Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore
Formatted Address:
Street Address: 6301 Wabash Ave

### Multiple Assets,Locations and Cis

Filter 0 - 0 of 0

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK 5,6,7,9,11,&12

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Point Rail L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Wabash | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 5 | 141 | WEST | 4-20-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 6 | 143 | WEST | 4-20-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 7 | 145 | WEST | 4-20-17 | S | S | S | S | S | S | Y | S | S | S | S |
| 11 | 151 | WEST | 4-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 12 | 153 | WEST | 4-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 12 | 159-A | WEST | 4-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 119 | EAST | 4-20-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 6 | 117 | EAST | 4-20-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 6 | 103 | EAST | 4-20-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 9 | 121 | EAST | 4-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 9 | 105 | EAST | 4-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 11 | 123 | EAST | 4-20-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 11 | 107 | EAST | 4-20-17 | Y | Y | S | S | S | S | S | S | S | S | S |
| 12 | 9A/7B | OM | 4-20-17 | S | S | S | S | S | S | S | S | S | S | S |

COMMENTS: 141 switch point side worn 143 switch point side worn 143 loose lag spike 117 switch point side worn 119 switch point side worn 107 Tie cracked switch point side worn. 123 - switch point side worn 103 switch point side worn

WORK ORDER # 2848643

Inspectors Joe Brechueyer Alan Perkins Date 4-20-17 Supervisor [signature]

[signature] Alan Perkins 4-20-17

## Work Order Tracking (Tr)

BMXAA4591I - Status change

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records

Work Order: 2959594 Tri-Monthly Yard SWINSP Track 1

Attachments

Classification: MTA \ METRO

Site: MET

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CMWABYARD Chain Marker Wabash Yard

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 06/18/17 08:35:40 AM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 06/16/17 04:16:32 AM

Quick PM?

On Behalf Of:

Consist:

### Asset Details

Year:

### Costs

Total Planned Cost: 442.08

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK #1

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 1 | 167-A | WEST | 6-22-17 | S | Y | Y | S | S | S | S | S | S | S | S |
| 1 | 171-B | WEST | 6-22-17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 135-A | WEST | 6-22-17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 133-A | WEST | 6-22-17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 131-A | MIDDLE | 6-22-17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 129-A | MIDDLE | 6-22-17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 127-A | EAST | 6-22-17 | S | Y | S | S | Y | S | S | S | S | S | S |
| 1 | 125-A | EAST | 6-22-17 | S | S | S | S | S | S | S | S | S | S | S |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |

COMMENTS: 167-A · curved switch point side worn - closure rail side worn
127-A switch point + stock rail side worn

WORK ORDER # 2959594

Inspectors M. Alchin, R. Nelson Date 6/23/17 Supervisor 7.10.17

# Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related

Work Order: 2967613 Tri-Monthly Yard SWINSP Track 2,3,4

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD Chain Marker Wabash Yard

Work Location:

Work Type: PM

Status: APPR

Status Date: 07/11/17 11:32:00 AM

Reported By: MTACRON

Phone:

Reported Date: 06/23/17 04:16:30 AM

On Behalf Of:

Consist:

At

Fail

Prob

Asset/Locati

P

Warranty Situatio

Maintena

Rep

Has Follow

## Asset Details

Year:

## Costs

Total Planned Cost:

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK #2,3,&4

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 2 | 169 | WEST | 7/15/17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 167-B | WEST | | S | S | S | Y | S | S | S | S | Y | S | S |
| 2 | 165 | WEST | | S | S | S | Y | Y | S | S | S | S | S | S |
| 2 | 163 | WEST | | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 133-B | WEST | | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 135-B | WEST | | S | S | S | S | S | S | S | S | S | S | S |
| 3 | 137 | WEST | | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 129-B | MIDDLE | | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 131-B | MIDDLE | | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 125-B | EAST | | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 127-B | EAST | | S | S | S | S | S | S | S | S | S | S | S |
| 3 | 101 | EAST | | S | Y | Y | S | Y | S | S | Y | S | S | S |
| 3 | 113 | EAST | | S | Y | Y | S | Y | S | S | S | S | S | S |
| 3 | 111 | EAST | | S | Y | Y | S | S | S | S | S | S | S | |
| 4 | 115 | EAST | | S | S | S | S | S | S | S | S | S | S | S |

COMMENTS:

**WORK ORDER # 2967613**

Inspectors [signature] Date 7-15-17 Supervisor [signature]

# Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records

Work Order: 2978187 Tri-Monthly Yard SWINSP Track 5,6,7,9,11,12

Attachments

Classification: MTA \ METRO

Site: MET

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CMWABYARD Chain Marker Wabash Yard

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 07/14/17 12:02:42 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 06/30/17 04:18:31 AM

Quick PM?

On Behalf Of:

Consist:

## Asset Details

Year:

## Costs

Total Planned Cost: 442.08

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK 5,6,7,9,11,&12

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Point Rail L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Wabash | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 5 | 141 | WEST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 143 | WEST | 7-23-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 7 | 145 | WEST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 11 | 151 | WEST | 7-23-17 | S | Y | S | S | Y | S | S | S | S | S | S |
| 12 | 153 | WEST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 12 | 159-A | WEST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 119 | EAST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 117 | EAST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 103 | EAST | 7-23-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 9 | 121 | EAST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 9 | 105 | EAST | 7-23-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 11 | 123 | EAST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 11 | 107 | EAST | 7-23-17 | S | S | S | S | S | S | S | S | S | S | S |
| 12 | 9A/7B | OM | 7-23-17 | S | Y | S | S | S | S | S | S | S | S | S |

COMMENTS: 143 curve switch point sidewarn 151 straight stock rail and straight switch point sidewarn 105 straight switch point sidewarn 103 straight switch point sidewarn

WORK ORDER # 2978187

Inspectors Joe Brockmeyer Date 7-23-17 Supervisor Arnold Ruiz

Joe Brockmeyer

# Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plan

Work Order: 2987839 Tri-Monthly Yard SWINSP Track 13,14,15,MM,OM,PO,OC

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority: 1

Location: CMWABYARD Chain Marker Wabash Yard

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: WSCH

Warranty Situation Present: N

Status Date: 07/07/17 04:14:54 AM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 07/07/17 04:14:54 AM

Quick PM?

On Behalf Of:

Consist:

## Asset Details

Year:

Manufacturer:

## Costs

Total Planned Cost: 442.08

Total Actual Cost: 0.00

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRK #13,14,15,MM,OM,PO,OC

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 15 | 171A | WEST | 8-8-17 | S | Y | S | S | Y | S | S | S | S | S | S |
| 13 | 161 | WEST | 8-8-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 139 | WEST | 8-8-17 | S | Y | Y | S | S | S | S | S | S | S | S |
| 13 | 155 | WEST | 8-8-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 157 | WEST | 8-8-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 159B | WEST | 8-8-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 19A | WEST | 8-8-17 | S | S | S | Y | S | S | S | S | S | S | N/A |
| 13 | 109A | EAST | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| 14 | 109B | EAST | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 7A | EAST | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 9B | EAST | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9A/7B | TAIL | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9B | TAIL | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| OC | 9 | SIDING | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| MM | 1B | POCKET | 8-11-17 | Y | S | S | S | S | S | S | S | S | S | S |
| PO | 7A | SIDING | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| PO | 5A | SIDING | 8-11-17 | S | S | S | S | S | S | S | S | S | S | S |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |

COMMENTS: 171A - switch point and stock rail side worn
139 - switch point and closure rail side worn

WORK ORDER # 2987839

Inspectors Curtis Chandler / Dedan Spitlufski Date 8-8-17 Supervisor Reading Rodriguez

# Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plar

Work Order: 3093369 Tri-Monthly Yard SWINSP Track 2,3,4

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority: 1

Location: CMWABYARD Chain Marker Wabash Yard

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 09/23/17 12:25:40 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 09/22/17 04:20:05 AM

Quick PM?

On Behalf Of:

Consist:

## Asset Details

Year:

Manufacturer:

## Costs

Total Planned Cost: 442.08

Total Actual Cost: 0.00

MARYLAND DEPARTMENT OF TRANSPORTATION

MARYLAND TRANSIT ADMINISTRATION

# MOW TRI-MONTHLY YARD SWITCH INSPECTION TRACK # 2,3,4

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 2 | 169 | WEST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 167-B | WEST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 165 | WEST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 163 | WEST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 133-B | WEST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 135-B | WEST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 3 | 137 | WEST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 129-B | MIDDLE | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 131-B | MIDDLE | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 125-B | EAST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 127-B | EAST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 3 | 101 | EAST | 9-25-17 | S | Y | Y | S | S | S | S | S | S | S | S |
| 3 | 113 | EAST | 9-25-17 | S | Y | Y | S | S | S | S | S | S | S | S |
| 3 | 111 | EAST | 9-25-17 | S | S | S | Y | S | S | S | S | S | S | S |
| 4 | 115 | EAST | 9-25-17 | S | S | S | S | S | S | S | S | S | S | S |

COMMENTS: 111 - chipped frog point 113 - closure rail and switch point side wear
101 - curve closure and switch point side wear

Inspection Completed? ● Yes ○ No If No, Why?

WORK ORDER # 3093369

Joe Brook-meyer
Track Inspector (Print)

Joe Brook
Track Inspector (Signature)

Alan Perkins
Track Inspector (Print)

Alan Perkins
Track Inspector (Signature)

AF Reding Reding
Supervisory (Signature)

9-25-17
Date

# Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety Plar

Work Order: 3084105 Tri-Monthly Yard SWINSP Track 1 OM,OC

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority: 1

Location: CMWABYARD Chain Marker Wabash Yard

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 09/23/17 12:22:32 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 09/15/17 04:17:31 AM

Quick PM?

On Behalf Of:

Consist:

## Asset Details

Year:

Manufacturer:

## Costs

| | |
|---|---|
| Total Planned Cost: | 442.08 |
| Total Actual Cost: | 0.00 |

MARYLAND DEPARTMENT OF TRANSPORTATION

MARYLAND TRANSIT ADMINISTRATION

# MOW TRI-MONTHLY YARD SWITCH INSPECTION TRACK # 1 OM,OC

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 1 | 167-A | WEST | 9/28/17 | S | R | R | Y | Y | S | S | S | S | S | S |
| 1 | 171-B | WEST | 9/28/17 | S | S | S | Y | S | S | S | S | S | S | S |
| 1 | 135-A | WEST | 9/28/17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 133-A | WEST | 9/28/17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 131-A | MIDDLE | 9/28/17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 129-A | MIDDLE | 9/28/17 | S | S | S | S | S | S | S | S | S | S | S |
| 1 | 127-A | EAST | 9/28/17 | S | Y | S | S | Y | S | S | S | S | S | S |
| 1 | 125-A | EAST | 9/28/17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9A/7B | TAIL | 9-28-17 | Y | Y | S | S | S | S | S | S | S | S | S |
| OM | 9B | TAIL | 9-28-17 | Y | Y | S | S | S | S | S | S | S | S | S |
| OC | 9 | SIDING | 9-28-17 | S | S | S | S | S | S | S | S | S | S | S |

COMMENTS: 9-B RH sw. PT. side wear; 9-A LH sw PT side worn;
167-A- LH stock, sw. PT. curve closure and frog have extreme side wear
171B- Side wear on point of frog (Turnout side)
127A- LH sw. PT and stock rail have side wear

Inspection Completed? ● Yes ○ No If No, Why?

WORK ORDER # 3084105

Michael Aldridge
Track Inspector (Print)

Michael A Aldridge
Track Inspector (Signature)

Richard Nelson
Track Inspector (Print)

Richard Nelson
Track Inspector (Signature)

RF Reding Reding
Supervisory (Signature)

10/2/17
Date

# Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records

Work Order: 3105013 Tri-Monthly Yard SWINSP Track 5,6,7,9,11,12

Attachments

Classification: MTA \ METRO

Site: MET

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CMWABYARD Chain Marker Wabash Yard

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 10/01/17 06:44:13 AM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 09/29/17 04:18:38 AM

Quick PM?

On Behalf Of:

Consist:

## Asset Details

Year:

## Costs

Total Planned Cost: 442.08

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRACK 5,6,7,9,11,&12

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Point Rail L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Wabash | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 5 | 141 | WEST | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 6 | 143 | WEST | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 7 | 145 | WEST | 10-5-17 | S | Y | S | S | S | S | Y | S | S | S | S |
| 11 | 151 | WEST | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 12 | 153 | WEST | 10-5-17 | S | S | S | S | S | S | S | S | S | S | S |
| 12 | 159-A | WEST | 10-5-17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 119 | EAST | 10-5-17 | S | S | S | S | S | S | S | S | S | S | S |
| 6 | 117 | EAST | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 6 | 103 | EAST | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 9 | 121 | EAST | 10-5-17 | S | S | S | S | S | S | S | S | S | S | S |
| 9 | 105 | EAST | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 11 | 123 | EAST | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 11 | 107 | EAST | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |
| 12 | 9A/7B | OM | 10-5-17 | S | Y | S | S | S | S | S | S | S | S | S |

COMMENTS: 141 Side worn curve switch point 143 side worn curve switch point 145 side worn curve switch point Loose lags 3 151 straight and curve switch point side worn. 117 side worn curve switch point. 123 Side worn curve switch point 107 side worn curve switch point 105 side worn curve switch point 103 side worn straight switch point OM 9A/7B curve switch point side worn

WORK ORDER # 3105013

Inspectors Joe Brockney
Joe Baker
Allen Perkins

Date 10-5-17

Supervisor Arnz Ruz

# Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related

Work Order: 3116558 Tri-Monthly Yard SWINSP Track 13,14,15,MM,PO

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CMWABYARD Chain Marker Wabash Yard

Work Location:

* Work Type: PM

Status: APPR

Status Date: 10/08/17 07:25:27 AM

Reported By: MTACRON

Phone:

Reported Date: 10/06/17 04:17:55 AM

On Behalf Of:

Consist:

At

Fail

Prob

Asset/Locati

P

Warranty Situatio

Maintena

Rep

Has Follow

(

## Asset Details

Year:

## Costs

Total Planned Cost:

# MOW TRI-MONTHLY YARD SWITCH INSPECTION AREA TRK #13,14,15,MM,OM,PO,OC

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 15 | 171A | WEST | 10-20-17 | S | Y | S | S | Y | S | S | S | S | S | S |
| 13 | 161 | WEST | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 139 | WEST | 10-20-17 | S | Y | Y | S | S | S | S | S | S | S | S |
| 13 | 155 | WEST | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 157 | WEST | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 13 | 159B | WEST | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 19A | WEST | 10-20-17 | S | S | S | Y | S | S | S | S | S | S | N/A |
| 13 | 109A | EAST | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 14 | 109B | EAST | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 7A | EAST | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| 15 | 9B | EAST | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9A/7B | TAIL | 10-19-17 | S | S | S | S | S | S | S | S | S | S | S |
| OM | 9B | TAIL | 10-19-17 | S | S | S | S | S | S | S | S | S | S | S |
| OC | 9 | SIDING | 10-19-17 | S | S | S | S | S | S | S | S | S | S | S |
| MM | 1B | POCKET | 10-20-17 | Y | S | S | S | S | S | S | S | S | S | S |
| PO | 7A | SIDING | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| PO | 5A | SIDING | 10-20-17 | S | S | S | S | S | S | S | S | S | S | S |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |

COMMENTS: 171 A - switch point and stock rail side worn
139 - switch point and closure rail side worn

**WORK ORDER # 3116558**

Inspectors Chandler / Miles Date 10/20/17 Supervisor [illegible]

# Work Order Tracking (Tr)

Query | Find Work Order | Select Action

List View | Work Order | Plans | Actuals | Activities | Measurements | Axle Configuration | Related Records | Safety F

Work Order: 3093369 Tri-Monthly Yard SWINSP Track 2,3,4

Attachments

Classification: MTA \ METRO

Site: METRO

Classification Description: MTA - METRO

Failure Class:

Asset:

Problem Code:

Alias:

Priority:

Location: CMWABYARD Chain Marker Wabash Yard

Asset/Location Priority:

Work Location:

Is Task?

Work Type: PM

Parent WO:

Status: APPR

Warranty Situation Present: N

Status Date: 09/23/17 12:25:40 PM

Maintenance Alert?

Reported By: MTACRON

Repair Order?

Phone:

Has Follow-up Work?

Reported Date: 09/22/17 04:20:05 AM

Quick PM?

On Behalf Of:

Consist:

## Asset Details

Year:

Manufacturer:

Model:

Serial #:

## Costs

Total Planned Cost: 442.08

Total Actual Cost: 0.00

Repair Limit Amount:

Current Asset Value:

MARYLAND DEPARTMENT OF TRANSPORTATION

MARYLAND TRANSIT ADMINISTRATION

# MOW TRI-MONTHLY YARD SWITCH INSPECTION TRACK # 2,3,4

| Track | Switch I.D. | Location | Inspection Date | Tie Condition | Switch Pnts L/R | Closure S/C | Frog | Stock Rail | Plates | Lags/Clips | Standard Joints | Insulated Joints | Welds | Ballast |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WABASH | | YARD | DATE | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S | R/Y/S |
| 2 | 169 | WEST | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 167-B | WEST | 11-25-17 | S | S | S | Y | S | S | S | S | Y | S | S |
| 2 | 165 | WEST | 11-25-17 | S | S | S | Y | Y | S | S | S | S | S | S |
| 2 | 163 | WEST | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 133-B | WEST | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 135-B | WEST | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 3 | 137 | WEST | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 129-B | MIDDLE | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 131-B | MIDDLE | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 125-B | EAST | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 2 | 127-B | EAST | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |
| 3 | 101 | EAST | 11-25-17 | S | Y | Y | S | Y | S | S | Y | S | S | S |
| 3 | 113 | EAST | 11-25-17 | S | Y | Y | S | Y | S | S | S | S | S | S |
| 3 | 111 | EAST | 11-25-17 | S | Y | Y | S | Y | S | S | S | S | S | |
| 4 | 115 | EAST | 11-25-17 | S | S | S | S | S | S | S | S | S | S | S |

COMMENTS: 111- Chipped Frog point. 113 closure Rail and switch point side wore
101- Curve Closure and switch point side wore,

Inspection Completed? ● Yes ○ No If No, Why?

WORK ORDER # 3093369

DeJuan Satterfield
Track Inspector (Print)

Track Inspector (Signature)

James E. Chase
Track Inspector (Print)

Track Inspector (Signature)

Supervisory (Signature)

Date