Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3266121 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
riding inspection - rain no new defects noted.

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:	**Year:**		**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	2/2/18
Target Finish:	2/2/18
Actual Start:	1/28/18
Actual Finish:	1/28/18
Report Date:	1/26/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3266121 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
riding inspection - rain no new defects noted.

Log

Date	Class	Created By	Subject	Description	Long Description
1/28/18	WORKORDER	ARABETTE		track inspection	riding inspection - rain no defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3266121 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
riding inspection - rain no new defects noted.

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		GLAM						N		08:00	00:00	210.32
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3266121 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
riding inspection - rain no new defects noted.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabetto Date 1-28-18 Page ___ of ___

Watchman G. Lam WO# 3266121

Inspection From Camden To Linthicum

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

Riding Inspection - Rain No Defects Noted

Were switches in area inspected? YES ___ NO ✓

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Arthur Rabetto
Track Inspectors Signature

Supervisory Certification

1/29/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331693 Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:			**Location:**	CHAIN_MARKER: LT Rail Chain Markers	**Status:**
Asset:	**Year:**		**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331693 **Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Related Records

WO	Description	Class	Status	Relationship
3264071	Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331695 Attachment work order TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S riding inspection - rain no new defects noted.

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:	**Year:**		**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331695 **Attachment work order TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S riding inspection - rain no new defects noted.**

Related Records

WO	Description	Class	Status	Relationship
3266121	Attachment work order TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabatte Date 1-28-18 Page ____ of ____

Watchman G. Lam WO# 3266121

Inspection From Camden To Linthicum

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

Riding Inspection - Rain No Defects Noted

Were switches in area inspected? YES ____ NO ✓

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Arthur Rabatte
Track Inspectors Signature

Supervisory Certification

1/29/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3266121 **TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S**
riding inspection - rain no new defects noted.

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	2/2/18
Target Finish:	2/2/18
Actual Start:	1/28/18
Actual Finish:	1/28/18
Report Date:	1/26/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3266121 **TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S**
riding inspection - rain no new defects noted.

Log

Date	Class	Created By	Subject	Description	Long Description
1/28/18	WORKORDER	ARABETTE		track inspection	riding inspection - rain no defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3266121 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
riding inspection - rain no new defects noted.

Related Records

WO	Description	Class	Status	Relationship
3331695	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		GLAM						N		08:00	00:00	210.32
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3266121 **TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S**
riding inspection - rain no new defects noted.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 1-28-18 Page ___ of ___

Watchman G. Lam WO# 3266121

Inspection From Camden To Linthicum

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

Riding Inspection - Rain No Defects Noted

Were switches in area inspected? YES ___ NO ✓

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

1/29/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331689 Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:	**Year:**		**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331689 **Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Related Records

WO	Description	Class	Status	Relationship
3264071	Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 1-29-18 Page ___ of ___

Watchman G. Lam WO# 3264071

Inspection From Hunt Valley To ~~Lam~~ LutherVille

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ems Comments

No New Defects Noted in Area

Were switches in area inspected? YES ✓ NO ___

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Track Inspectors Signature

Supervisory Certification

1/30/18
Date

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 1-29-18 Page ___ of ___

Watchman G. Lam WO# 3264071

Inspection From Hunt Valley To ~~Lam~~ LutherVille

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ems Comments

No New Defects Noted in Area

Were switches in area inspected? YES ✓ NO ___

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

1/30/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3264071 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	1/28/18
Target Finish:	1/28/18
Actual Start:	1/29/18
Actual Finish:	1/29/18
Report Date:	1/25/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3264071 **TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Log

Date	Class	Created By	Subject	Description	Long Description
1/29/18	WORKORDER	ARABETTE		track inspection	no new defects noted in area.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3264071 **TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Related Records

WO	Description	Class	Status	Relationship
3331689	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		GLAM						N		08:00	00:00	210.32
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3264071 **TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 1-29-18 Page ___ of ___

Watchman G. Lamm WO# 3264071

Inspection From Hunt Valley To Lutherville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ems Comments

No New Defects Noted in Area

Were switches in area inspected? YES ✓ NO ___

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

1/30/18
Date

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 1-29-18 Page ___ of ___

Watchman G. Lam WO# 3264071

Inspection From Hunt Valley To ~~Lutherville~~ Lutherville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ems Comments

No New Defects Noted in Area

Were switches in area inspected? YES ✓ NO ___

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

1/30/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3267544 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:	**Year:**		**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading

CI: **Mileage Meter:**

Sched Start:	
Sched Finish:	
Target Start:	1/31/18
Target Finish:	1/31/18
Actual Start:	1/30/18
Actual Finish:	1/30/18
Report Date:	1/27/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3267544 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Log

Date	Class	Created By	Subject	Description	Long Description
1/30/18	WORKORDER	ARABETTE		track inspection	riding inspection - snow - no new defects noted.
1/30/18	WORKORDER	ARABETTE		track inspection	riding inspection - snow - no new defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3267544 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		GLAM						N		08:00	00:00	210.32
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3267544 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

C

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 1-30-18 Page ___ of ___

Watchman G. Lam WO# 32675 44

Inspection From Coldspring To Camden – Penn

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

Riding Inspection - Snow - No New Defects Noted.

Were switches in area inspected? YES ___ NO C

Is this a Special Inspection? YES ___ NO C

Reason for Inspection ___

Track Inspectors Signature

Supervisory Certification

1/31/19
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331681 Attachment work order TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:	**Year:**		**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331681 **Attachment work order TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**

Related Records

WO	Description	Class	Status	Relationship
3267544	Attachment work order TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

C

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 1-30-18 Page ___ of ___

Watchman G. Lam WO# 32675744

Inspection From Coldspring To Camden - Penn

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

Riding Inspection - Snow - No New Defects Noted.

Were switches in area inspected? YES _____ NO ~

Is this a Special Inspection? YES _____ NO ~

Reason for Inspection _____

Track Inspectors Signature

Supervisory Certification

1/31/19
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3267544 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	1/31/18
Target Finish:	1/31/18
Actual Start:	1/30/18
Actual Finish:	1/30/18
Report Date:	1/27/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3267544 **TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**

Log

Date	Class	Created By	Subject	Description	Long Description
1/30/18	WORKORDER	ARABETTE		track inspection	riding inspection - snow - no new defects noted.
1/30/18	WORKORDER	ARABETTE		track inspection	riding inspection - snow - no new defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3267544 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Related Records

WO	Description	Class	Status	Relationship
3331681	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		GLAM						N		08:00	00:00	210.32
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3267544 **TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3331678 Attachment work order TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:	**Year:**		**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/16/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3331678 **Attachment work order TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N**

Related Records

WO	Description	Class	Status	Relationship
3267522	Attachment work order TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

L

Light Rail MOW

Daily Track Inspection

Name Pollard Date 1-30-18 Page 1 of 1

Watchman Schisler WO# 3267522

Inspection From Lutherville 585 to To Coldspring 235 to

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	NO new defects noted in area
	Inspection complete

Were switches in area inspected? YES ✓ NO _____

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____

Track Inspectors Signature

Supervisory Certification

1/31/18
Date