MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3277474 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/9/18
Target Finish:	2/9/18
Actual Start:	2/4/18
Actual Finish:	2/4/18
Report Date:	2/2/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277474 **TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S**

Log

Date	Class	Created By	Subject	Description	Long Description
2/4/18	WORKORDER	GLAM		track inspection	riding inspection due to rain no new defects noted

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277474 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Related Records

WO	Description	Class	Status	Relationship
3330200	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		00:00	03:00	118.31
												Total Actual Labor:	118.31

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277474 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name G LAM Date 2/4/18 Page ___ of ___

Watchman N/A WO# 3277474

Inspection From CAMDEN YD To Linthicum

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

RIDING INSPECTION DUE TO RAIN
NO NEW DEFECTS NOTED

Were switches in area inspected? YES VISUAL ONLY NO ___

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

G Lam
Track Inspectors Signature

Supervisory Certification

2/7/18
Date

Light Rail MOW

Daily Track Inspection

Name G LAM Date 2/4/18 Page ___ of ___

Watchman N/A WO# 3277474

Inspection From CAMDEN YD To Lawthicum

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

RIDING INSPECTION DUE TO RAIN
NO NEW DEFECTS NOTED

Were switches in area inspected? YES VISUAL only NO ___

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

G Lam
Track Inspectors Signature

Supervisory Certification

2/7/18
Date

- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3277474 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/9/18
Target Finish:	2/9/18
Actual Start:	2/4/18
Actual Finish:	2/4/18
Report Date:	2/2/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277474 **TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S**

Log

Date	Class	Created By	Subject	Description	Long Description
2/4/18	WORKORDER	GLAM		track inspection	riding inspection due to rain no new defects noted

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277474 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Related Records

WO	Description	Class	Status	Relationship
3330200	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP
3345537	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		00:00	03:00	118.31
												Total Actual Labor:	118.31

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277474 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3345537 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/27/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3345537 **TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S**

Related Records

WO	Description	Class	Status	Relationship
3277474	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name G LAM Date 2/4/18 Page ___ of ___

Watchman N/A W.O# 3277474

Inspection From CAMDEN YD To Lindbergh

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

RIDING INSPECTION DUE TO RAIN
NO NEW DEFECTS NOTED

Were switches in area inspected? YES VISUAL ONLY NO ___

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

G Lam
Track Inspectors Signature

Supervisory Certification

2/7/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading

CI: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	2/4/18
Target Finish:	2/4/18
Actual Start:	2/5/18
Actual Finish:	2/5/18
Report Date:	2/1/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Log

Date	Class	Created By	Subject	Description	Long Description
2/5/18	WORKORDER	ARABETTE		track inspection	riding inspection no new defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	217.36

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 2-5-18 Page ____ of ____

Watchman ____ WO# 3274425

Inspection From Hunt Valley To Luther Ville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

ems	Comments
	Riding Inspection No New Defects Noted

Were switches in area inspected? YES ____ NO ✓

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

2/7/18
Date

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 2-5-18 Page ____ of ____

Watchman ____ WO# 3274425

Inspection From Hunt Valley To Luther Ville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding Inspection No New Defects Noted

Were switches in area inspected? YES ____ NO ✓

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

2/2/18
Date

MARYLAND DEPARTMENT OF TRANSPORTATION - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3344400 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:		Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:		Mileage Meter:		

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/26/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3344400 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Related Records

WO	Description	Class	Status	Relationship
3274425	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 2-5-18 Page ____ of ____

Watchman ____ WO# 3274425

Inspection From Hunt Valley To Luther Ville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding Inspection No New Defects Noted

Were switches in area inspected? YES ____ NO ✓

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

2/7/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	**Year:**	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:	
Sched Finish:	
Target Start:	2/4/18
Target Finish:	2/4/18
Actual Start:	2/5/18
Actual Finish:	2/5/18
Report Date:	2/1/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## ####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 **TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Log

Date	Class	Created By	Subject	Description	Long Description
2/5/18	WORKORDER	ARABETTE		track inspection	riding inspection no new defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Related Records

WO	Description	Class	Status	Relationship
3330208	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	CLOSE	FOLLOWUP
3344400	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	217.36

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:		Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/4/18
Target Finish:	2/4/18
Actual Start:	2/5/18
Actual Finish:	2/5/18
Report Date:	2/1/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Log

Date	Class	Created By	Subject	Description	Long Description
2/5/18	WORKORDER	ARABETTE		track inspection	riding inspection no new defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	217.36

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 2-5-18 Page ____ of ____

Watchman ____ WO# 3274425

Inspection From Hunt Valley To Luther Ville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding Inspection No New Defects Noted

Were switches in area inspected? YES ____ NO ✓

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

2/7/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330208 Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	**Year:**	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330208 **Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Related Records

WO	Description	Class	Status	Relationship
3274425	Attachment work order TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 2-5-18 Page ____ of ____

Watchman ____ WO# 3274425

Inspection From Hunt Valley To Luther Ville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding Inspection No New Defects Noted

Were switches in area inspected? YES ____ NO ✓

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

2/7/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330200 Attachment work order TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Alias:		Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330200 Attachment work order TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S

Related Records

WO	Description	Class	Status	Relationship
3277474	Attachment work order TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/4/18
Target Finish:	2/4/18
Actual Start:	2/5/18
Actual Finish:	2/5/18
Report Date:	2/1/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Log

Date	Class	Created By	Subject	Description	Long Description
2/5/18	WORKORDER	ARABETTE		track inspection	riding inspection no new defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Related Records

WO	Description	Class	Status	Relationship
3330208	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	217.36

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3274425 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 2-5-18 Page ____ of ____

Watchman ____ WO# 3274425

Inspection From Hunt Valley To Luther Ville

	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W.O
Items	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding Inspection No New Defects Noted

Were switches in area inspected? YES ____ NO ✓

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

2/7/18
Date

- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3278618 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/7/18
Target Finish:	2/7/18
Actual Start:	2/6/18
Actual Finish:	2/6/18
Report Date:	2/3/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	COMP
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278618 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Log

Date	Class	Created By	Subject	Description	Long Description
2/6/18	WORKORDER	GLAM		cs to camden,penn line	1.cm 235 in cross walk s/e there are 4 missing pandrols on field side, also 2 missing on gage side . 2. cm 227n to 215n low ballast, no shoulder. 3.cm214 to 200n low ballast, no shoulder. 4.cm186n union avenue xing dirty flange ways. 5.switch 91-1 rotted head block timbers ,will not even hold latches. machine arm bent. 6.83n field side of station track 2 low ballast no shoulder. 7.79s to 82s trk 2 cross level improper on curved track down hill coming off direct fixation 8.70s track 2 no washers on bolts in newly installed weld strap bars. track 2 inspected track 1 overview only.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278618 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Log

Date	Class	Created By	Subject	Description	Long Description

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278618 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Related Records

WO	Description	Class	Status	Relationship
3281844	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	COMP	FOLLOWUP
3283262	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	COMP	FOLLOWUP
3283290	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	COMP	FOLLOWUP
3330086	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	COMP	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36

Total Actual Labor: 427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3278618 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	COMP						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	COMP						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330086 Attachment work order TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:		**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**	
Asset:	Year:	**Manufacturer:**		**Type:**	
Serial Number:		**License:**			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330086 **Attachment work order TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**

Related Records

WO	Description	Class	Status	Relationship
3278618	Attachment work order TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor