MDOT MARYLAND DEPARTMENT OF TRANSPORTATION
MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY TRACK INSPECTION REPORT

Inspection Date: 2-26-18 Inspection Area: Hunt Valley Lutherville ☑ Walking ☐ Riding * Parent WO# 3301088

Item	Exception Chain Marker Number		Track No.	Position	Switch No.	Exception Codes		Priority 1-5	Alias
	From	To				Component	Defect		
1	740+00 N	760+50 N	1	W		M 313	316	3	
2	740+00 N	760+50 N	2	E		M 313	316	3	
3									
4	729+50 N		2	W.E		W 301	329-332	3	
5									
6									
7									

Use Priority Coding: 1 2 3 4 5

EXCEPTION REMARKS

1	No Shoulder Ballast	Child WO #
2	No Shoulder Ballast	Child WO #
		Child WO #
4	North End of Industry Lane Road crossing Track out	Child WO #
	of Surface 20' Area 1½" Low & 8 Ties Pumping in row	Child WO #
	1" = 2½" out of Surface East + West Rails.	Child WO #
		Child WO #

Inspection Completed? Yes ☑ No ☐ If No, Why?

A. Rabette — Track Inspector (Print)

Track Inspector (Signature)

Track Inspector (Print)

Track Inspector (Signature)

Watchman (Print)

Watchman (Signature)

Supervisory (Signature)

Date 2/27/18

Page

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3303643 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/28/18
Target Finish:	2/28/18
Actual Start:	2/27/18
Actual Finish:	2/27/18
Report Date:	2/24/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	COMP
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48476

Job Plan:	2955
Job Desc:	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303643 **TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N**

Log

Date	Class	Created By	Subject	Description	Long Description
2/27/18	WORKORDER	MPOLLARD		track inspection	1) TKs 1 & 2 CM 359+57 Running rails at the cross walk are deteriorating especially at the base , the cross walk is also deteriorating (creating a tripping hazard) because of salt use. 2) SW 342 - 1B Straight switch point has micro cracks that are starting to shell out . 3) SW - 3A Same as no. 2 4 SW - 3B Same as no. 2 Inspection complete

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303643 **TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N**

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		TSCHISLI				10	N		08:00	00:00	210.32
20	AREPAIR		MPOLLAF				10	N		08:00	00:00	210.32
											Total Actual Labor:	420.64

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303643 **TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N**

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	COMP						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	COMP						N

Date Completed

Completed By

Supervisor

MDOT MARYLAND DEPARTMENT OF TRANSPORTATION
MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY TRACK INSPECTION REPORT

Inspection Date: 2-27-2018 Inspection Area: 2 ☑ Walking ☐ Riding * Parent WO# 3303643

Item	Exception Chain Marker Number From	Exception Chain Marker Number To	Track No.	Position	Switch No.	Exception Codes Component	Exception Codes Defect	Priority 1-5	Alias
1	359+57		1+2			R301	311	4	
2			2		342-1B	S304	310	3	
3			1		342-3A	S304	310	3	
4			2		342-3B	S304	310	3	
5									
6									
7									

Use Priority Coding: 1 2 3 4 5

EXCEPTION REMARKS

1	Running rails at the crossing are deteriorating, especially at the railhouse	#1	Child WO # 3314331
	Crosswalk is deteriorating also (tripping Hazard) because of salt use.		Child WO #
			Child WO #
2-4	Straight switch point has micro cracks that are	#2	Child WO # 3315465
	starting to shell out	#3	Child WO # 3315466
		#4	Child WO # 3315467
	Inspection complete		Child WO #

Inspection Completed? Yes ☑ No ☐ If No, Why?

Michael L Folland
Track Inspector (Print)

Track Inspector (Signature)

Track Inspector (Print)

Track Inspector (Signature)

THOMAS J SCHISLER
Watchman (Print)

Watchman (Signature)

Supervisory (Signature)

2/28/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3303651 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:	
Sched Finish:	
Target Start:	2/28/18
Target Finish:	2/28/18
Actual Start:	2/27/18
Actual Finish:	2/27/18
Report Date:	2/24/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303651 **TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**

Log

Date	Class	Created By	Subject	Description	Long Description
2/27/18	WORKORDER	ARABETTE		track inspection	broken rail track #1 east rail Howard St cm 14+50.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303651 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Related Records

WO	Description	Class	Status	Relationship
3347105	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	LEAD		WBRYAN						N		08:00	00:00	224.24
												Total Actual Labor:	441.60

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303651 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3347105 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/28/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3347105 **TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**

Related Records

WO	Description	Class	Status	Relationship
3303651	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

MDOT MARYLAND DEPARTMENT OF TRANSPORTATION
MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY TRACK INSPECTION REPORT

Inspection Date: 2-28-18 Inspection Area: Linthicum Camden – BWI [✓] Walking [ ] Riding * Parent WO# 3303651

Item	Exception Chain Marker Number		Track No.	Position	Switch No.	Exception Codes		Priority 1-5	Alias
	From	To				Component	Defect		
1									
2									
3									
4									
5									
6									
7									

Use Priority Coding: 1 2 3 4 5

EXCEPTION REMARKS

	No New Defects Noted in Area.	Child WO #
		Child WO #
		Child WO #
		Child WO #
		Child WO #
		Child WO #
		Child WO #

Inspection Completed? Yes [✓] No [ ] If No, Why?

A. Robette
Track Inspector (Print)

Track Inspector (Signature)

Track Inspector (Print)
W. Bryant
Watchman (Print)

Track Inspector (Signature)
Watchman (Signature)

Supervisory (Signature)

3/1/18
Date

Page _____

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3303654 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	3/1/18
Target Finish:	3/1/18
Actual Start:	2/28/18
Actual Finish:	2/28/18
Report Date:	2/24/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	COMP
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48479

Job Plan:	2959
Job Desc:	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303654 **TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S**

Log

Date	Class	Created By	Subject	Description	Long Description
2/28/18	WORKORDER	MPOLLARD		TRACK INSPECTION	
2/28/18	WORKORDER	MPOLLARD		Track inspection	1) Tks 1 & 2 CM 263+40 - 260+00 Numerous bridge timbers are deteriorating and in need of replacement in the near future. 2) Tks 1 & 2 CM 263+40 - 260+00 bridge walkways and railing are deteriorating and in need of service. 3) Tk - 1 CM 237+40 Roadway adjacent to track has a hole measuring 3 1/2 ' L x 2 1/4 ' W x 2 1/2 ' D . Hole has left a slight void under the track of 2" . Inspection complete

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303654 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	COMP						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	COMP						N

Date Completed

Completed By

Supervisor

MDOT MARYLAND DEPARTMENT OF TRANSPORTATION
MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY TRACK INSPECTION REPORT

Inspection Date: 2-28-2018 Inspection Area: Sect 4 [✓] Walking [ ] Riding * Parent WO# 330 3654

Item	Exception Chain Marker Number From	Exception Chain Marker Number To	Track No.	Position	Switch No.	Exception Codes Component	Exception Codes Defect	Priority 1-5	Alias
1	263+40	260+00	1+2			T307	311	3	
2	263+40	260+00	1+2			M315	311	3	
3	237+40		1			M315	348	3	
4									
5									
6									
7									

Use Priority Coding: 1 2 3 4 5

EXCEPTION REMARKS

1	Numerous bridge timbers are deteriorating	Child WO #
2	Bridge walkways and railing are deteriorating and in need	Child WO #
	of Rehab	Child WO #
		Child WO #
3	Roadway adjacent to track area has a sink Hole measuring	Child WO #
	3 1/2' Lx 2 1/4' W x 2 1/2 D Hole has left a slight void under	Child WO #
	the track ballast of 2"	Child WO #

Inspection Completed? Yes [✓] No [ ] If No, Why?

Michael L Pollard
Track Inspector (Print)

Track Inspector (Signature)

Track Inspector (Print)

Track Inspector (Signature)

THOMAS J SCHISLER
Watchman (Print)

Thomas J Schisler
Watchman (Signature)

Supervisory (Signature)

3/1/18
Date

Page _____

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3303657 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	3/1/18
Target Finish:	3/1/18
Actual Start:	2/28/18
Actual Finish:	2/28/18
Report Date:	2/24/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	COMP
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303657 **TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD**

Log

Date	Class	Created By	Subject	Description	Long Description
2/28/18	WORKORDER	ARABETTE		track inspection	no new defects noted in area.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303657 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	LEAD		WBRYAN						N		08:00	00:00	224.24
												Total Actual Labor:	441.60

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3303657 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	COMP						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	COMP						N

Date Completed

Completed By

Supervisor

MDOT MARYLAND DEPARTMENT OF TRANSPORTATION
MARYLAND TRANSIT ADMINISTRATION

RIGHT OF WAY TRACK INSPECTION REPORT

Inspection Date: 02-28-18 Inspection Area: CROMEK YARD ☑ Walking ☐ Riding * Parent WO# 3303657

Item	Exception Chain Marker Number		Track No.	Position	Switch No.	Exception Codes		Priority 1-5	Alias
	From	To				Component	Defect		
1									
2									
3									
4									
5									
6									
7									

Use Priority Coding: 1 2 3 4 5

EXCEPTION REMARKS

	No new defect's noted in area.	Child WO #
	Track inspection completed.	Child WO #
		Child WO #
		Child WO #
		Child WO #
		Child WO #
		Child WO #

Inspection Completed? Yes ☑ No ☐ If No, Why?

Walter W. Bryant
Track Inspector (Print)

Walter W. Bryant
Track Inspector (Signature)

Track Inspector (Print)

Track Inspector (Signature)

A. Rabette
Watchman (Print)

Watchman (Signature)

Supervisory (Signature)

3/1/18
Date

Page _____