C

Light Rail MOW

Daily Track Inspection

Name A. Rabette G. Lam Date 2-11-18 Page ___ of ___

Watchman ___ WO# 32855513

Inspection From Camden To Lin-thicum

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

Riding Inspection - Rain - No New Defects Noted.

Were switches in area inspected? YES ___ NO ✓

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Arthur Rabette
Track Inspectors Signature

Supervisory Certification

2/12/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3285513 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
riding inspection -rain- no new defects noted.

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/16/18
Target Finish:	2/16/18
Actual Start:	2/11/18
Actual Finish:	2/11/18
Report Date:	2/9/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-#### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3285513 **TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S**
riding inspection -rain- no new defects noted.

Log

Date	Class	Created By	Subject	Description	Long Description
2/11/18	WORKORDER	ARABETTE		track inspection	
2/11/18	WORKORDER	ARABETTE		track inspection	riding inspection-rain- no new defects noted.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3285513 **TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S**
riding inspection -rain- no new defects noted.

Related Records

WO	Description	Class	Status	Relationship
3339583	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP
3345764	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		GLAM						N		08:00	00:00	210.32
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3285513 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S
riding inspection -rain- no new defects noted.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330041 Attachment work order TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330041 **Attachment work order TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD**

Related Records

WO	Description	Class	Status	Relationship
3277457	Attachment work order TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name Billaid Date 2-9-18 Page 1 of 3

Watchman Bryant WO# 3277457

Inspection From Coldspring To Camden yards

N 235+00 Penline S 16+00

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.	234+00		2			M311	311	Y	NO	
2.	234+00		2	W		R301	311	Y	NO	
3.	150+60		2	W		F310	318	Y	NO	
4.					88-1	S304	311	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	Crosswalk removed because of broken rail. there are 3 cracked ties and 4 ties with deteriorated saddles.
2	Running rail (west) is deteriorated on the North and South ends of crosswalk
3	4 ties west rail missing pandrol
4	Micro Fractures in straight switch point are starting to breakout

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES NO ✓

Reason for Inspection

Track Inspectors Signature

Supervisory Certification

Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3277457 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/9/18
Target Finish:	2/9/18
Actual Start:	2/9/18
Actual Finish:	2/9/18
Report Date:	2/2/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48478

Job Plan:	2957
Job Desc:	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277457 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD

Log

Date	Class	Created By	Subject	Description	Long Description
2/9/18	WORKORDER	MPOLLARD		track inspection	1) TK - 2 CM 234+00 Crosswalk removed because of broken rail . There are 3 ties that are cracked . There are 4 ties whose saddles have deteriorated with pandrols that rusted in the saddles and can not be removed 2) TK - 2 CM 234+00 Running rail in crosswalk has deteriorated on the north and south ends . 3) TK - 2 CM 150 5 ties missing 1 pandrol . 4) SW 88 - 1 Straight switch point has micro fractures that are starting to break out . 5) TK - 2 CM 76+00 - 73+80 4 sets of strap joints without washers and no J clips (16 total) holding rails (east and west) 6) SW 70 - 1 1 loose bolt in the restraining rail . track and yard Inspection complete.

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277457 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD

Related Records

WO	Description	Class	Status	Relationship
3330041	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	LEAD		WBRYAN				10		N		00:00	08:00	336.36
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
												Total Actual Labor:	546.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3277457 **TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD**

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3281385 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	2/14/18
Target Finish:	2/14/18
Actual Start:	2/10/18
Actual Finish:	2/10/18
Report Date:	2/6/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-######## ######## #### #### ######-000-30-00
Warranty Situation Present?	N
PM Num:	48481

Job Plan:	2961
Job Desc:	TEAM TWO - SECT 5: LINT/CROM/ BWI CM 355S TO 488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3281385 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Log

Date	Class	Created By	Subject	Description	Long Description
2/10/18	WORKORDER	MPOLLARD		track inspection	no new defects noted in area .

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3281385 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Related Records

WO	Description	Class	Status	Relationship
3329955	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		GLAM				10	N		00:00	08:00	315.48
20	AREPAIR		MPOLLAF				10	N		08:00	00:00	210.32
											Total Actual Labor:	525.80

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3281385 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 2-12-18 Page ____ of ____

Watchman ____ WO# 3284085

Inspection From Hunt Valley To Lutherville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding Inspection No New Defects Noted.

Were switches in area inspected? YES ____ NO ✓

Is this a Special Inspection? YES ____ NO ✓

Reason for Inspection ____

Arthur Rabette
Track Inspectors Signature

Supervisor Certification

2/13/18
Date

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3284085 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/11/18
Target Finish:	2/11/18
Actual Start:	2/12/18
Actual Finish:	2/12/18
Report Date:	2/8/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-######## ######## #### #### ######-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3284085 **TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Log

Date	Class	Created By	Subject	Description	Long Description
2/12/18	WORKORDER	ARABETTE		track inspection	riding inspection no new defects noted

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3284085 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N

Related Records

WO	Description	Class	Status	Relationship
3339589	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	CLOSE	FOLLOWUP
3345636	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	CLOSE	FOLLOWUP

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3284085 **TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N**

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3345791 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/27/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3345791 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Related Records

WO	Description	Class	Status	Relationship
3286624	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 2-13-18 Page ___ of ___

Watchman G. Lam WO# 3286624

Inspection From Coldspring To Camden – Penn

	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W.O
Items	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	No New Defects Noted in Area.

Were switches in area inspected? YES ✓ NO ___

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Track Inspectors Signature

Supervisory Certification

2/16/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3345782 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		**Year:**	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/27/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3345782 **TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N**

Related Records

WO	Description	Class	Status	Relationship
3286608	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

2

Light Rail MOW

Daily Track Inspection

Name Pollard Date 2-13-18 Page 1 of 1

Watchman Bryant WO# 3286608

Inspection From Lutherville N 585+00 To Cold spring N 235+00

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.	220+28		1			M301	302	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	Drain is clogged, this is causing track area At the North end of station to flood

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES NO ✓

Reason for Inspection

Track Inspectors Signature

Supervisory Certification

2/14/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3286624 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: **Description** **Unit of Measure** **Last Reading Date** **Last Reading**

CI: **Mileage Meter:**

Sched Start:	
Sched Finish:	
Target Start:	2/14/18
Target Finish:	2/14/18
Actual Start:	2/13/18
Actual Finish:	2/13/18
Report Date:	2/10/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3286624 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Log

Date	Class	Created By	Subject	Description	Long Description
2/13/18	WORKORDER	GLAM		track inspection	no new defects noted in area

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3286624 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Related Records

WO	Description	Class	Status	Relationship
3345791	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36
												Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3286624 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3286608 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	2/14/18
Target Finish:	2/14/18
Actual Start:	2/13/18
Actual Finish:	2/13/18
Report Date:	2/10/18
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48476

Job Plan:	2955
Job Desc:	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3286608 **TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N**

Log

Date	Class	Created By	Subject	Description	Long Description
2/13/18	WORKORDER	MPOLLARD		track inspection	1) TK - 1 CM 330+28 Drain is clogged , this is causing track area in the station to flood . Inspection complete

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3286608 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

Related Records

WO	Description	Class	Status	Relationship
3345782	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	LEAD		WBRYAN				10		N		08:00	00:00	224.24
20	AREPAIR		MPOLLAF				10		N		08:00	00:00	210.32
												Total Actual Labor:	434.56

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3286608 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3345804 **TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S**

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/27/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3345804 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Related Records

WO	Description	Class	Status	Relationship
3286627	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name Pollard Date 2-14-18 Page 1 of 1

Watchman Byrd WO# 3286627

Inspection From Linthicum S 355+00 To Camden yards S 16+00

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.	204+00		1			M307	316	Y	N	
2.					208-1A	S304	310	Y	N	
3.					208-1A	S305	309	Y	N	
4.					269-1B	S305	305	Y	N	
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
1	20 outer cribs are Low due to sink Hole in area.
2	Straight switch point has micro Fractures that are starting to break out.
3	Frog has 4" crack in the point along the side.
4	Frog point has 1"W x 1/8"D x 2 1/2"L chip missing with another chip measuring 1" x 1 3/4 ready to breakout
	inspection complete

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES NO ✓

Reason for Inspection

Track Inspectors Signature

Supervisory Certification

2/14/18
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3345808 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:		**Mileage Meter:**		

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/27/18
Reported By:	SSMITH3
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3345808 **TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD**

Related Records

WO	Description	Class	Status	Relationship
3286630	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor