Light Rail MOW

Daily Track Inspection

Name A. Rabette Date 11-30-17 Page ___ of ___

Watchman ___ WO# 318 1472

Inspection From Luther Ville To Coldspring

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items	Comments
	Riding Inspection No Defects Noted.

COPY

Were switches in area inspected? YES ___ NO ✓

Is this a Special Inspection? YES ___ NO ✓

Reason for Inspection ___

Track Inspectors Signature

Supervisory Certification

12/1/17
Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

11/30

WO # 3181439 **TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N**

Alias:			**Location:**	CHAIN_MARKERS LT Rail Chain Markers	**Status:**
Asset:		Year:	**Manufacturer:**		**Type:**
Serial Number:			**License:**		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	**Description**	**Unit of Measure**	**Last Reading Date**	**Last Reading**
CI:			**Mileage Meter:**	

Sched Start:	
Sched Finish:	
Target Start:	11/30/17
Target Finish:	11/30/17
Actual Start:	12/1/17
Actual Finish:	12/1/17
Report Date:	11/24/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48474

Job Plan:	2953
Job Desc:	TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3181439 **TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N**

Log

Date	Class	Created By	Subject	Description	Long Description
12/1/17	WORKORDER	MPOLLARD		trtack inspection	No new notable defects Inspection complete

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3181439 **TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N**

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
20	AREPAIR		GLAM				10	N		08:00	00:00	210.32
20	AREPAIR		MPOLLAF				10	N		08:00	00:00	210.32
											Total Actual Labor:	420.64

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3181439 **TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N**

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Light Rail MOW

Daily Track Inspection

Name Bollard Date 11-30-17 Page 1 of 1

Watchman Lam WO# 3181439

Inspection From Hunt Valley To Lutherville

Items	Exception Chain Marker No. From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W.O #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Items Comments

No New defects noted

inspection complete

COPY

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES NO ✓

Reason for Inspection

Track Inspectors Signature

Supervisory Certification

12/1/17
Date