

# Work Order Details (Tr)

Org ID: MTA  
 Site: LTRAIL

Crew ID: DAY-A

WO # 2688572 TEAM ONE - SECT 4: CYLINT - CM 16S TO 355S  
 no new defects noted in area

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Manufacturer:		Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading

Cl: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	12/9/16
Target Finish:	12/9/16
Actual Start:	12/4/16
Actual Finish:	12/4/16
Report Date:	12/2/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48297

Job Plan:	2958
Job Desc:	TEAM ONE - SECT 4: CYLINT - CM 16S TO 355S
Supervisor:	JREAVES3
Lead:	
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
---------------	-----------	-------------	-----------	---------------	-----------------

LTRAIL_DESCRIPTION		LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CYLINT - CM 16S TO 355S		
--------------------	--	--------------------	--	--	--



# Work Order Details (Tr)

Org ID: MTA  
 Site: LTRAIL

WO # 2688572 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S  
 no new defects noted in area

Related Records		WO	Description	Class	Status	Relationship							
		3330401	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP							
Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			GLAM				N				08:00	00:00	210.32
AREPAIR			ARABETT				N				08:00	00:00	217.36
											<b>Total Actual Labor:</b>	<b>427.68</b>	

# Work Order Details (Tr)

Org ID: MTA  
 Site: LTRAIL

WO # 2688572 TEAM ONE - SECT 4: CYLINT - CM 16S TO 355S  
 no new defects noted in area

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed \_\_\_\_\_ Completed By \_\_\_\_\_ Supervisor \_\_\_\_\_

# Work Order Details (Tr)

Org ID: MTA  
 Site: LTRAIL

Crew ID: null

WO # 3330401 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order)  
 no new defects noted in area

Alias:	Location:	CHAIN_MARKER; LT Rail Chain Markers	Status:
Asset:	Manufacturer:		Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading

CI: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-#####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

## Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

## Work Order Details (Tr)

Org ID: MTA  
Site: LTRAIL

WO # 3330401 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order)  
no new defects noted in area

Related Records	WO	Description	Class	Status	Relationship
	2688572	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S (Attached Work Order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

