MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330175 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S (Attachment work order)
no new defects noted in area

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330175 TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S (Attachment work order)
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
2629922	TEAM ONE - SECT 4: CY/LINT - CM 16S TO 355S (Attachment work order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed _____ Completed By _____ Supervisor _____

Name A. Rabette G. Lam Date 10-23-16 Page ____ of ____
(Please Print)
Watchman A. Rabette G. Lam WO # 2629922

Inspected From Camden To Linthicum

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area.

COPY

Were switches in the area inspected? Yes ✓ No ____

Is this a Special Inspection? Yes ____ No ✓

Reason for Special Inspection? ____

A. Rabette — Track Inspectors Signature

J. Kearney — Supervisory Certification

10/24/16 — Date

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2629874 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in araea

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	10/24/16
Target Finish:	10/24/16
Actual Start:	10/24/16
Actual Finish:	10/24/16
Report Date:	10/21/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48475

Job Plan:	2952
Job Desc:	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2629874 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in araea

Related Records

WO	Description	Class	Status	Relationship
3330151	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure	Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		ARABETT						N		08:00	00:00	217.36

Total Actual Labor: 645.04

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2629874 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in araea

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEP OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330151 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attachment work order)
no new defects noted in araea

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-#######-#######-#### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330151 TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attachment work order)
no new defects noted in araea

Related Records

WO	Description	Class	Status	Relationship
2629874	TEAM ONE - SECT 1: HV/LU - CM 902N TO 586N (Attachment work order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Name A. Robette G. Lam Date 10-24-16 Page of
(Please Print)
Watchman A. Robette G. Lam WO # 26299874

Inspected From Hunt Valley To Luther Ville

	Exception Chain Marker No		Track	Rail	Switch	Codes		Status	Repair	W. O.
Item	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area.

Were switches in the area inspected? Yes ✓ No

Was this a Special Inspection? Yes No ✓

Reason for Special Inspection?

Track Inspectors Signature

Supervisory Certification

10/25/16
Date

COPY

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 2632445 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
no new defects noted in area

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	10/27/16
Target Finish:	10/27/16
Actual Start:	10/25/16
Actual Finish:	10/25/16
Report Date:	10/23/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-######## #### ####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2632445 **TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S**
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
3330197	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplishec	Part Failure Warranty	Contract Num	Regular Hours	Premiun Hours	Line Cost
	AREPAIR		GLAM					N		08:00	00:00	210.32
	AREPAIR		ARABETT					N		08:00	00:00	217.36
											Total Actual Labor:	427.68

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2632445 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
no new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

MARYLAND DEPT OF TRANSPO - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: null

WO # 3330197 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attachment work order)
no new defects noted in area

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading

CI: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	
Target Finish:	
Actual Start:	
Actual Finish:	
Report Date:	3/15/18
Reported By:	TSAVAGE
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	LOG
Status:	WAPPR
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	

Job Plan:	
Job Desc:	
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3330197 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attachment work order)
no new defects noted in area

Related Records

WO	Description	Class	Status	Relationship
2632445	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S (Attachment work order)	WORKORDER	WAPPR	ORIGINATOR

Date Completed

Completed By

Supervisor

Name A. Rabette G. Lam (Please Print) Date 10/25/16 Page of

Watchman A. Rabette G. Lam WO # 263 ~~2245~~ 2445

Inspected From Coldspring To Camden - Penn

Item	Exception Chain Marker No From	To	Track No.	Rail E/W	Switch No.	Codes Comp.	Defect	Status S/Y/R	Repair Y/N	W. O. #
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

Item	Comments
	No New Defects Noted in Area.

Were switches in the area inspected? Yes — No

Is this a Special Inspection? Yes No ✓

Reason for Special Inspection?

COPY

Track Inspectors Signature — Supervisory Certification — Date 10/26/16

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2631403 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
10-26-2016

Caged clamp loose on SW 208 3B
Caged clamp loose on SW 208 1A

Alias:			Location:	CHAIN_MARKERS LT Rail Chain Markers	Status:
Asset:		Year:	Manufacturer:		Type:
Serial Number:			License:		
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters:	Description	Unit of Measure	Last Reading Date	Last Reading
CI:			Mileage Meter:	

Sched Start:	
Sched Finish:	
Target Start:	10/27/16
Target Finish:	10/27/16
Actual Start:	10/26/16
Actual Finish:	10/26/16
Report Date:	10/22/16
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-##########-0901-########-########-####-####-######-000-30-00
Warranty Situation Present?	N
PM Num:	48479

Job Plan:	2959
Job Desc:	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2631403

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
10-26-2016

Caged clamp loose on SW 208 3B
Caged clamp loose on SW 208 1A

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2631403

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
10-26-2016

Caged clamp loose on SW 208 3B
Caged clamp loose on SW 208 1A

Related Records

WO	Description	Class	Status	Relationship
3330186	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S	WORKORDER	CLOSE	FOLLOWUP

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		MPOLLAF						N		08:00	00:00	210.32
	AREPAIR		TSCHISLI						N		08:00	00:00	210.32
												Total Actual Labor:	420.64

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 2631403

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
10-26-2016

Caged clamp loose on SW 208 3B
Caged clamp loose on SW 208 1A

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor