

Work Order Tracking (Tr)

Find Work Order

Select Action

- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan

Work Order: 2839787 (1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset: >>

Alias:

Location: CHAIN\_MARK >> Metro Chain Markers

Work Location: >>

Work Type: PM

Status: WSCH

Status Date: 03/24/17 04:16:44 AM

Reported By: MTACRON >>

Phone:

Reported Date: 03/24/17 04:16:44 AM

On Behalf Of: >>

Consist: >>

Asset Details

Year:

Manufacturer: >>

Model: >>

Serial #:

Type: >>

Status:

Asset Condition:

Address Information

Service Address: 1206 >> 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets, Locations and Cls Filter 0 - 0 of 0





Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report

Site: METRO  
 Workgroup: MTA472

START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N



Inspection Completed?

Yes

No

If No Why? \_\_\_\_\_

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Comp.	Codes	Defect	Priority	Alias
	From	To								
1	116100W	119100W	I			M01		CP1R	1	THU1Z
2	158100W		I			FO1		CP1R	3	THU1Z
3	159100W	164100W	I	N/S		FO1		CP1R	3	THU1Z
4	163180W		I	S		FO1		CP1R	2	THU1Z
5	163100W		I	N		FO1		CP1R	2	THU1Z
6										
7										
8										

Notes: 1. Trash in drain

2. Regulator cup Arching  
 3. Federal clips missing, broken, deteriorating, water condition, smart TOTs clips.  
 4.5. Kuning rail severely pitted due to wet condition.

Track Walker:

Richard Nelson  
 Michael Michin

Richard Nelson  
 Michael Michin

Date: 3/28/17  
 Date: 3/28/17

Watchman:

Track Inspection  
 Supervisor: Print  
 Aray Ruditsky

Aray Ruditsky

Date: 4/13/17



**Maryland Department of Transportation**  
**Maryland Transi. Administration**  
**Right Of Way Inspectors Report**

Site: METRO

Workgroup: MTA472

START\_CHAIN\_MARKER: 0

END\_CHAIN\_MARKER: 333

Include History: N



TMWX (TRACK METRO WEST CROSSOVERS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2013791</u> (HOLD)	MOW-M00	2	SOUTH	MOW-046	CM	MOW-M09	0	69	0	69	0	7/21/15
2 RAJH Crosswalk Missing BH 3A 069+00W	TRACK MISCELLANEOUS			MISSING		SAFETY WALK						
<u>2030709</u> (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	69	30	69	30	8/3/15
1 JHRA Switch Point Chipped BH-1B 069+30W	RAIL			CHIPPED / PITTED		SWITCH POINT						
<u>2549819</u> (APPR)	MOW-R00	2	BOTH	MOW-003	PM	MOW-T06	0	230	0	230	0	8/23/16
1 JHRA frog 1B needs grinding 230	RAIL			BATTERED		FROG						
<b>Number of Records:</b>		13										



**Maryland Department of Transportation**  
**Maryland Transit Administration**  
**Right Of Way Inspectors Report**

Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N



TWIX (TRACK METRO WEST CROSSOVERS) - Work group: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2053299</u> (MONITOR)	MOW-R00	2	RIGHT	MOW-013	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA RH Switch Point Chipped / Pitted CC 3B	RAIL			CHIPPED / PITTED		SWITCH POINT						
<u>2053301</u> (MONITOR)	MOW-R00	2	LEFT	MOW-069	CM	MOW-T03	0	4	73	4	73	8/20/15
1 JHRA LH Switch Point Chipped / Pitted CC 3B	RAIL			SIDE WEAR (RAIL)		SWITCH POINT						
<u>2694291</u> (APPR)	MOW-M00	3	BOTH	MOW-046	CM	MOW-F05	0	7	0	7	0	12/7/16
1 JHRA 3 pandrol blocks and clips missing 1B 007+00	TRACK MISCELLANEOUS			MISSING		CLIP						
<u>2017699</u> (APPR)	MOW-M00	1	THIRD RAIL	MOW-046	CM	MOW-C03	0	7	50	7	50	7/24/15
1 JHRA 3rd Rail Side Approach Hardware Missing CC 1B 007+50	TRACK MISCELLANEOUS			MISSING		COVER BOARD BRACKET						
<u>2573520</u> (APPR)	MOW-M00	2	BOTH	MOW-018	CM	MOW-M02	0	8	0	8	0	9/9/16
1 JHRA lights out charles interlocking 008	TRACK MISCELLANEOUS			DEFECTIVE - NO LONGER FUNCTIONING		ETS BOX / LIGHT						
<u>2571333</u> (APPR)	MOW-M00	3	BOTH	MOW-080	CM	MOW-B01	0	10	0	14	0	9/7/16
2 RAJH trash 10-14	TRACK MISCELLANEOUS			TRASH AND DEBRIS		TUNNEL DRAIN						
<u>2493075</u> (APPR)	MOW-Q00	2	BOTH	MOW-080	CM	MOW-B01	0	66	0	70	0	7/21/16
2 RAJH trash build up 070-066	RIGHT OF WAY			TRASH AND DEBRIS		TUNNEL DRAIN						
<u>2030698</u> (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R08	0	66	80	66	80	8/3/15
1 JHRA ID Battered BH-3B 066+80W	RAIL					INSULATED JOINT						
<u>2014043</u> (HOLD)	MOW-X00	2	BOTH	MOW-062	CM	MOW-X00	0	67	70	68	50	7/21/15
2 RAJH Ties Pumping BH 068+50 - 067+70W	TIES			PUMPING		TIES						
<u>2449048</u> (APPR)	MOW-M00	3	THIRD RAIL	MOW-017	CM	MOW-C03	0	68	70	68	70	6/15/16
2 RAJH switch point battered	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						



**Maryland Department of Transportation**  
**Maryland Transit Administration**  
**Right Of Way Inspectors Report**



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

**TMWI (TRACK METRO WEST 1) - Workgroup: MTA472**

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2014064</u> (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	267	50	272	0	7/21/15
1 JHRA Coverboard Brackets Bent 267+50 - 272	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
<u>203074Z</u> (MONITOR)	MOW-R00	2	SOUTH		CM	MOW-R01	0	274	0	274	0	8/3/15
1 JHRA Rail Side Worn (22 Deg) 274+00	RAIL					RUNNING RAIL						
<b>Number of Records:</b>												<b>32</b>



Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report

Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N



TW1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2208897 (APPR)	1 JHRA Chain Marker Sign 160NW Loose/Hanging	1	SOUTH	MOW-044 LOOSE / SLACK	CM	MOW-M01 CHAIN MARKER	0	160	0	160	0	12/10/15
2212343 (APPR)	1 JHRA Pandrol Clips Broken/Deteriorating 160W-170W	3	BOTH	MOW-022 DETERIORATING	CM	MOW-F05 CLIP	0	160	0	170	0	12/12/15
2106138 (APPR)	1 JHRA Two Block Tie Broken 161+25	1	BOTH	MOW-016 CRACKED / SPLIT	CM	MOW-X00 TIES	0	161	25	161	25	9/30/15
2212358 (MONITOR)	1 JHRA Rail Head Pitted 180 - 186 deteriorating rail	4	NORTH	MOW-022 DETERIORATING	CM	MOW-R01 RUNNING RAIL	0	180	0	188	0	12/12/15
2015101 (APPR)	1 JHRA Coverboard Brackets Missing 194+90 & 195+25	1	THIRD RAIL	MOW-046 MISSING	CM	MOW-C03 COVER BOARD BRACKET	0	194	90	195	25	7/22/15
2043013 (MONITOR)	1 JHRA Rail Corrugation (N) 202 - 214+00	2	NORTH	MOW-015 CORRUGATED	CM	MOW-R01 RUNNING RAIL	0	202	0	214	0	8/12/15
2013741 (APPR)	1 JHRA Shim Plate Loose 237+50	1	BOTH	MOW-044 LOOSE / SLACK	CM	MOW-P00 PLATES	0	237	50	237	50	7/21/15
2017722 (APPR)	1 JHRA LB Foster Plates Deteriorating 238 - 268	2	BOTH	MOW-018 DEFECTIVE - NO LONGER FUNCTIONING	CM	MOW-P00 PLATES	0	238	0	268	0	7/24/15
2030745 (APPR)	1 JHRA Shim Plate Missing 248+10W	1	SOUTH	MOW-046 MISSING	CM	MOW-P00 PLATES	0	248	10	248	10	8/3/15
2549815 (APPR)	1 JHRA coverboard bent 262-272	3	SOUTH	MOW-044 LOOSE / SLACK	PM	MOW-C02 COVERBOARD	0	262	0	272	0	8/23/16



**Maryland Department of Transportation**  
**Maryland Transit Administration**  
**Right Of Way Inspectors Report**

Site: METRO

Workgroup: MTA472

START\_CHAIN\_MARKER: 0

END\_CHAIN\_MARKER: 333

Include History: N



TMWI (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2468951 (APPR)	MOW-C00	2	THIRD RAIL	MOW-014	CM	MOW-C05	0	73	0	73	0	7/1/16
1 JHRA Third rail corrosion	CONTACT RAIL			CORRODED		THIRD RAIL						
2106102 (APPR)	MOW-M00	1	THIRD RAIL	MOW-017	CM	MOW-C03	0	107	15	107	15	9/30/15
1 JHRA Coverboard Bracket Broken 107+15	TRACK MISCELLANEOUS			DAMAGED HARDWARE		COVER BOARD BRACKET						
2774280 (APPR)	MOW-B00	1	BOTH	MOW-004	CM	MOW-B01	0	110	0	114	60	2/8/17
1 JHRA drain clogged 110+00 - 114+60	TUNNEL			BLOCKAGE		TUNNEL DRAIN						
2014921 (APPR)	MOW-M00	3	THIRD RAIL	MOW-010	CM	MOW-C01	0	140	70	140	90	7/22/15
1 JHRA Insulator Cup Burnt (4) 140+70 -140+90	TRACK MISCELLANEOUS			BURNT (LUMBER)		INSULATOR						
2015378 (APPR)	MOW-R00	1	SOUTH	MOW-014	CM	MOW-R01	0	141	0	141	0	7/22/15
1 JHRA Rail Web/Base Deteriorated (S) 141+00	RAIL			CORRODED		RUNNING RAIL						
2015388 (APPR)	MOW-R00	1	THIRD RAIL	MOW-014	CM	MOW-C05	0	141	0	141	0	7/22/15
1 JHRA 3rd Rail Corroded 141+00	RAIL			CORRODED		THIRD RAIL						
2106112 (APPR)	MOW-C00	1	THIRD RAIL	MOW-061	CM	MOW-C05	0	148	0	148	0	9/30/15
1 JHRA 3rd Rail Unseated/Out of Insulator Cups 148+00	CONTACT RAIL			POOR SUPPORT		THIRD RAIL						
2106126 (APPR)	MOW-R00	2	NORTH	MOW-014	CM	MOW-R00	0	154	0	165	0	9/30/15
1 JHRA Rail Web/Base Corroded (N) 154-165	RAIL			CORRODED		RAIL						
2051473 (MONITOR)	MOW-C00	2	THIRD RAIL	MOW-014	CM	MOW-C05	0	158	0	166	0	8/19/15
1 JHRA 3rd Rail Deteriorated 158 -166+00	CONTACT RAIL			CORRODED		THIRD RAIL						
2208896 (APPR)	MOW-X00	2	BOTH	MOW-016	CM	MOW-X17	0	158	40	158	40	12/10/15
1 JHRA Two Block Tie Broken 158+40W	TIES			CRACKED / SPLIT		CONCRETE TIE RAIL SEAT PAD						





Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report

Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N



TWV1 (TRACK METRO WEST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2767245</u> (APPR) 1 JHRA pandrol blocks missing/off 009+00	MOW-F00 FASTENERS	2	BOTH	MOW-046 MISSING	CM	MOW-F05 CLIP	0	9	0	9	0	2/2/17
<u>2043305</u> (INPRG) 1 JHRA Two Block Tie Deteriorating (N) 013+85W	MOW-X00 TIES	2	BOTH	MOW-022 DETERIORATING	CM	MOW-X00 TIES	0	13	85	13	85	8/12/15
<u>2043299</u> (INPRG) 1 JHRA Two Block Tie Deteriorating (N) 015+75W	MOW-X00 TIES	2	BOTH	MOW-022 DETERIORATING	CM	MOW-X00 TIES	0	15	75	15	75	8/12/15
<u>2013812</u> (HOLD) 1 JHRA Fastener Pad Cracked/ Broken (6) 018+60W	MOW-G00 GROUT PADS	2	BOTH	MOW-016 CRACKED / SPLIT	CM	MOW-X08 CONCRETE G10 PAD	0	18	60	18	60	7/21/15
<u>2469642</u> (APPR) 1 JHRA	MOW-X00 TIES	2	BOTH	MOW-016 CRACKED / SPLIT	CM	MOW-X00 TIES	0	18	85	18	85	7/1/16
<u>2106086</u> (APPR) 1 JHRA Drain Clogged/Fouled (60') 053W-059W	MOW-L00 LEAKS	1	BOTH	MOW-004 BLOCKAGE	CM	MOW-B01 TUNNEL DRAIN	0	53	0	59	0	9/30/15
<u>2668041</u> (APPR) 1 JHRA lites in tunnel 068	MOW-M00 TRACK MISCELLANEOUS	2	BOTH	MOW-065 SAFETY HAZARD	CM	MOW-M02 ETS BOX / LIGHT	0	68	0	68	0	11/16/16
<u>2080337</u> (APPR) 1 JHRA 3rd Rail Severely Corroded 068+70 - 068+90	MOW-C00 CONTACT RAIL	3	THIRD RAIL	MOW-014 CORRODED	CM	MOW-C05 THIRD RAIL	0	68	70	68	90	9/10/15
<u>2618075</u> (APPR) 1 JHRA water leak 068+80	MOW-B00 TUNNEL	1	BOTH	MOW-042 LEAKING	CM	MOW-L02 TUNNEL LEAK	0	68	80	68	80	10/12/16
<u>2030720</u> (APPR) 1 JHRA IJ Battered BH 1B 069+35W	MOW-R00 RAIL	1	NORTH	MOW-003 BATTERED	CM	MOW-R08 INSULATED JOINT	0	69	35	69	35	8/3/15



**Maryland Department of Transportation**  
**Maryland Transit Administration**  
**Right Of Way Inspectors Report**

Site: METRO

Workgroup: MTA472

START\_CHAIN\_MARKER: 0

END\_CHAIN\_MARKER: 333

Include History: N



TMEX1H (TRACK METRO EAST CROSSOVER JOHN HOPKINS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2014923</u> (APPR)	MOW-M00	1	LEFT	MOW-044	CM	MOW-T12	0	70	20	70	30	7/22/15
2 RAJH LH Switch Point Fastener Blocks Loose (4) JH 1A	TRACK MISCELLANEOUS			LOOSE / SLACK		SPACER BLOCK BOLT						
<u>2573519</u> (WAPPR)	MOW-M00	2	WEST		CM	MOW-T06	0	75	0	75	0	9/8/16
1 JHRA blocks missing wing of frog	TRACK MISCELLANEOUS					FROG						
<u>2573518</u> (APPR)	MOW-M00	1	SOUTH	MOW-044	CM	MOW-R09	0	79	0	79	0	9/8/16
1 JHRA brace plate loose 1B 079	TRACK MISCELLANEOUS			LOOSE / SLACK		RESTRAINING RAIL BRACE						
<b>Number of Records:</b>												13



**Maryland Department of Transportation**  
**Maryland Transit Administration**  
**Right Of Way Inspectors Report**



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TMEJH (TRACK METRO EAST CROSSOVER JOHN HOPKINS) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
<u>2726017</u> (APPR)	MOW-R00	4	BOTH	MOW-009	CM	MOW-T09	0	15	0	15	0	1/3/17
2 RAJH guard rail in diamond broken 15+00	RAIL			BROKEN/SHEARED		FROG GUARD						
<u>2493058</u> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	67	0	67	0	7/21/16
1 JHRA frog point 1b pitted/battered	RAIL			BATTERED		FROG						
<u>2665965</u> (COMP)	MOW-R00	2	G5	MOW-013	CM	MOW-T09	0	67	0	67	0	11/15/16
1 JHRA point in diamond chipped and pitted 68+70	RAIL			CHIPPED / PITTED		FROG GUARD						
<u>2449051</u> (APPR)	MOW-R00	3	BOTH	MOW-013	CM	MOW-T06	0	68	40	68	40	6/15/16
2 RAJH Frog Cracked / Chipped 3A 067+00E	JH RAIL			CHIPPED / PITTED		FROG						
<u>2841524</u> (MONITOR)	S4	4	WEST	S405	CM	MOW	0	68	65	68	65	3/25/17
1 JHRA Diamond w Frog Throat Cracked / Broken 068+65E	SWITCH / TURNOUT			FROG GUARDED		MAINTENANCE OF WAY						
<u>2841489</u> (MONITOR)	S4	4	NORTH	S405	CM	MOW	0	68	70	68	70	3/25/17
1JHRA Diamond Frog Wing Cracked 068+70E	SWITCH / TURNOUT			FROG GUARDED		MAINTENANCE OF WAY						
<u>2449070</u> (APPR)	MOW-R00	4	BOTH	MOW-003	CM	MOW-T06	0	69	0	69	0	6/15/16
2 RAJH Frog point battered 1A	RAIL			BATTERED		FROG						
<u>2692082</u> (APPR)	MOW-R00	3	NORTH	MOW-003	CM	MOW-T06	0	69	30	69	30	12/5/16
1 JHRA 3B frog point cracked 69+30	RAIL			BATTERED		FROG						
<u>2043020</u> (MONITOR)	MOW-R00	2	RIGHT	MOW-069	CM	MOW-T01	0	70	0	70	0	8/12/15
2 RAJH RH Stock Rail Side Worn (25 Deg) JH 1A	RAIL			SIDE WEAR (RAIL)		STOCK RAIL						
<u>2493055</u> (APPR)	MOW-R00	3	BOTH	MOW-003	CM	MOW-T06	0	70	6	70	6	7/21/16
1 JHRA JH 3B frog point battered	RAIL			BATTERED		FROG						



Maryland Department of Transportation  
 Maryland Transit Administration  
 Right Of Way Inspectors Report



Site: METRO  
 Workgroup: MTA472  
 START\_CHAIN\_MARKER: 0  
 END\_CHAIN\_MARKER: 333  
 Include History: N

TWE1 TRACK METRO EAST 1) - Workgroup: MTA472

Work Order	Problem	Priority	Position	Reported Defect	Work Type	Component	Quantity	START CHAIN MARKER	CM START OFFSET	END CHAIN MARKER	CM END OFFSET	Report Date
2651904 (APPR)	1 JHRA lites out 008+00	5	BOTH	MOW-065	CM	MOW-B00	0	8	0	8	0	11/3/16
	TUNNEL			SAFETY HAZARD		TUNNEL						
2735166 (APPR)	1 JHRA dlogged drain 34+00	2	BOTH	MOW-004	CM	MOW-B01	0	34	0	34	0	1/10/17
	TUNNEL			BLOCKAGE		TUNNEL DRAIN						
2015100 (APPR)	1 JHRA Coverboard Broken / Bracket Missing 036+65E	1	THIRD RAIL	MOW-046	CM	MOW-C02	0	36	65	36	65	7/22/15
	TRACK MISCELLANEOUS			MISSING		COVERBOARD						
2651902 (APPR)	1 JHRA water leak on rail 45+00	1	SOUTH	MOW-042	CM	MOW-L02	0	45	0	45	0	11/3/16
	LEAKS			LEAKING		TUNNEL LEAK						
2033296 (MONITOR)	1 JHRA Curve Closure Rail Chipped 067+60E JH 1B	2	SOUTH	MOW-013	CM	MOW-T02	0	67	60	67	60	8/5/15
	RAIL			CHIPPED / PITTED		LEAD OR CLOSURE RAIL						
2013865 (APPR)	1 JHRA Restraining Rail 1J Bolts Loose 067+70E	1	NORTH	MOW-044	CM	MOW-R08	0	67	70	67	70	7/21/15
	TRACK MISCELLANEOUS			LOOSE / SLACK		INSULATED JOINT						
2665961 (APPR)	1 JHRA 1J battered chipped and pitted 68+00	2	NORTH	MOW-003	CM	MOW-R08	0	68	0	68	0	11/15/16
	RAIL			BATTERED		INSULATED JOINT						
2767242 (APPR)	1 JHRA frog chipped & pitted 069+10	4	BOTH	MOW-013	CM	MOW-T06	0	69	0	69	0	2/2/17
	RAIL			CHIPPED / PITTED		FROG						

Number of Records: 8

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan

Work Order: 2839773 (2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN\_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: WSCH

Status Date: 03/24/17 04:16:29 AM

Reported By: MTACRON

Phone:

Reported Date: 03/24/17 04:16:29 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206 6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave

Multiple Assets.Locations and Cls Filter

0 - 0 of 0





Inspection Completed?  Yes  No If No Why?

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1	230+00		2	N/S	PO1A PO3A	SOS	D28	2	TMW2
2	231+70		2	N/S	PO7B	SOS	D28	2	TMW2
3									
4									
5									
6									
7									
8									

Notes: 1. Fross pumping PO1A PO3A 2. Fross pumping PO7B

Track Walker: Joe Brockmeyer Print Joe Rubin Sign Date: 3-27-17

Watchman: Alan Perkins Print Alan Perkins Sign Date: 3-27-17

Track Inspection Supervisor: Arkady Ruditskiy Print Arkady Ruditskiy Sign Date: 4/3/17

