

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan

Work Order: 2877751

(2RA-JH) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: APPR

Status Date: 04/23/17 06:54:03 AM

Reported By: MTACRON

Phone:

Reported Date: 04/21/17 04:17:58 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report

Site: METRO
 Workgroup: MTA472



Include History: N

Inspection Completed? Yes No If No Why? _____

Item	Exception Chain Marker No.		Track No.	Position	Switch No.	Comp.	Codes		Priority	Alias
	From	To					Defect			
1	068760		2	N/S	BH3H	T02		N01	2	TMW2
2	061+00		2	S		R01		D38	2	TMW2
3	033050		2	S		R01		D38	2	TMW2
4										
5										
6										
7										
8										

Notes: 1) Joint Rotated 2) Water leak east end of State Center platform clips
Missing 4 total 3) Water leak

Track Walker: Joe Brockmeyer Date: 4-24-17
 Print Sign

Watchman: Alan Perkins Date: 4-24-17
 Print Sign

Track Inspection Supervisor: Bradley Ruditsky Date: 5-1-17
 Print Sign

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan

Work Order: 2877769

(1JH-RA) METRO MOW WEEKLY TRACK INSPECTION W/

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: APPR

Status Date: 04/23/17 06:56:47 AM

Reported By: MTACRON

Phone:

Reported Date: 04/21/17 04:18:15 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave



Maryland Department of Transportation
Maryland Transit Administration
Right Of Way Inspectors Report

Workgroup: MTA472
Site: METRO
START_CHAIN_MARKER: 0
END_CHAIN_MARKER: 333
Include History: N



Inspection Completed?

Yes

No

If No Why?

Item	Exception Chain Marker No.		Track No.	Position N/S	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1	183700 W1		I	N		W02	D-38	PR	TMW1
2	189700 W1		I	N		W02	D-38	PR	TMW1
3	201750		I	N		T04	D-03	PR	TMW1
4	202705		I	N		T04	D-03	PR	TMW1
5	202706		I	N/S		T04	D-11	PR	TMW1
6	218700		I	N/S		M02	M18/008	PR	TMW1
7	221700		I	N		R01	R00-141	PR	TMW1
8									

Notes: 1. Tunnel Water level. 2. Tunnel Water level.

344. One two block tie broken & deteriorating under north rail.

5. Auger iron corroded in hole on 10 ties in-a-row.

6. Water runs over ties on north rail. 7. North rail 31' 0" gap facing north

Track Walker: Mike Atkhan
Print: _____
Sign: *Michael Atkhan*

Date: 4-27-17

Print: _____
Sign: _____

Date: _____

Watchman: Richard Nelson
Print: *Richard Nelson*
Sign: _____

Date: 4-27-17

Track Inspection Supervisor: Aracady Ruditskiy
Print: *Aracady Ruditskiy*
Sign: _____

Date: 5-1-17

Work Order Tracking (Tr)

Find Work Order



Select Action



- List
- Work Order**
- Plans
- Actuals
- Activities
- Measurements
- Axle Configuration
- Related Records
- Safety Plan

Work Order: 2877761

(20M-RA) METRO MOW WEEKLY TRACK INSPECTION W

Classification: MTA \ METRO

Classification Description: MTA - METRO

Asset:

Alias:

Location: CHAIN_MARK Metro Chain Markers

Work Location:

Work Type: PM

Status: APPR

Status Date: 04/23/17 06:55:42 AM

Reported By: MTACRON

Phone:

Reported Date: 04/21/17 04:18:04 AM

On Behalf Of:

Consist:

Asset Details

Year:

Manufacturer:

Model:

Serial #:

Type:

Status:

Asset Condition:

Address Information

Service Address: 1206

6301 Wabash Ave Reisterstown Plaza Baltimore

Formatted Address:

Street Address: 6301 Wabash Ave



Maryland Department of Transportation
 Maryland Transit Administration
 Right Of Way Inspectors Report

Workgroup: MTA472
 Site: METRO
 START_CHAIN_MARKER: 712
 END_CHAIN_MARKER: 333
 Include History: N



Inspection Completed? Yes No

If No Why? _____

Item	Exception Chain Marker No.		Track No.	Position	Switch No.	Codes		Priority	Alias
	From	To				Comp.	Defect		
1	686140		2	S	OM-34	S05	D01	2	TMW2
2	685140		2	S		J02	D21	1	TMW2
3	682130		2	N/S		R01	D28	2	TMW2
4	434400		2	S	M4-1A	S05	D01	2	TMW2
5	377165		2	N/S		U01	D01	3	TMW2
6	377130		2	N/S		R04	D01	2	TMW2
7	375180		2	S	RP-12	S05	D41	2	TMW2
8	375140		2	S		U01	D01	3	TMW2

Notes:

① Fros point battered worn riser ② Bolt missing in joint
 ③ Track bumper ④ Fros point battered ⑤ TJS battered ⑥ Expansior
 joints battered. top worn ⑦ RP-12 riser top worn ⑧ T.V. batteries

Track Walker: Joe Brockmeyer

Print Joe Brockmeyer

Sign _____ Date: 4-30-17

Print _____

Sign _____

Date: _____

Watchman: Alan Perkins

Print Alan Perkins

Sign _____ Date: 4-30-17

Track Inspection Supervisor: Print _____

Sign _____

Date: _____

